



governmentattic.org

"Rummaging in the government's attic"

Description of document:	Washington Metropolitan Area Transit Authority (WMATA) Emergency Egress Inspection Reports, 2012
Requested date:	2012
Released date:	31-July-2012
Posted date:	18-September-2012
Title of documents:	WMATA Emergency Egress Inspection Report
Source of document:	Office of General Counsel PARP Administrator Washington Metropolitan Area Transit Authority 600 Fifth Street, NW Washington, D.C. 20001

The governmentattic.org web site ("the site") is noncommercial and free to the public. The site and materials made available on the site, such as this file, are for reference only. The governmentattic.org web site and its principals have made every effort to make this information as complete and as accurate as possible, however, there may be mistakes and omissions, both typographical and in content. The governmentattic.org web site and its principals shall have neither liability nor responsibility to any person or entity with respect to any loss or damage caused, or alleged to have been caused, directly or indirectly, by the information provided on the governmentattic.org web site or in this file. The public records published on the site were obtained from government agencies using proper legal channels. Each document is identified as to the source. Any concerns about the contents of the site should be directed to the agency originating the document in question. GovernmentAttic.org is not responsible for the contents of documents published on the website.

July 31, 2012



Re: PARP Request No. 12-0178

This is in response to your request for a copy of the 900 Metrorail Station Inspection Reports that were recently released under the Public Access to Records Policy (PARP) in digital form. You request notes that you want the most recent reports completed in 2012 if the records are not available digitally. Your request was processed pursuant to the PARP. Please note that the inspection reports that were previously released are not digitally available. Therefore, we have enclosed the most recent Emergency Egress Inspection Reports for calendar year 2012. Pursuant to PARP Exemption 6.1.1 (safety and security), we have redacted detailed locations of the emergency exits and phone numbers for access to the facilities. In accordance with PARP Exemption 6.1.6 (personal privacy), we have redacted staff names and signatures.

If you wish to appeal WMATA's decision, in accordance with WMATA's PARP § 9.1, you may file a written appeal of the action with the Chief of Staff within 30 business days of the date of this decision letter. The appeal panel will inform you of its determination concerning the appeal within 30 business days of receipt of the appeal. Further details about our appeals process can be found on our website.

There is no charge for processing your request because the first two hours of staff time and minor copying are free of charge. Future correspondence regarding your request should reference the PARP request number noted above and be directed to my attention. You may also contact me via telephone at 202-962-2058 or via email at kthom@wmata.com.

Sincerely,

Keysia A. Thom
PARP/Privacy Policy Administrator

Enclosures

**Washington
Metropolitan Area
Transit Authority**

600 Fifth Street, NW
Washington, DC 20001
202/962-1234

By Metrorail:
Judiciary Square—Red Line
Gallery Place-Chinatown—
Red, Green and
Yellow Lines
By Metrobus:
Routes D1, D3, D6, P6,
70, 71, 80, X2

Emergency Egress Inspection Reports

First Quarter of CY2012

WMATA Emergency Egress Inspection Report

Shaft No: [REDACTED]	Defects / Remarks ✓
Station: A02 Farragut North	NONE
Location: [REDACTED]	
Hatch Door Pull Weight: 35lbs	
Date 1/25/12	
Inspected By: [REDACTED]	

Shaft No: [REDACTED]	Defects / Remarks ✓
Station: A03 Dupont Circle	① RELAMP EXIT LIGHT TRACK #1
Location: [REDACTED]	
Hatch Door Pull Weight: 35lbs	
Date 1/25/12	
Inspected By: [REDACTED]	

Shaft No: [REDACTED]	Defects / Remarks ✓
Station: A03 Dupont Circle	① WHEN THE LEFT LEAF HATCH DOOR IS OPENED THERE IS A FALL HAZARD (DOOR HAS BEEN SEVERED SHOT.)
Location: [REDACTED]	
Hatch Door Pull Weight: 35lbs	
Date 1/25/12	
Inspected By: [REDACTED]	

Shaft No: [REDACTED]	Defects / Remarks ✓
Station: A04 Woodley Park - Zoo	① LOCK CYLINDER MISSING w/p # 8883118 LCK-1
Location: [REDACTED]	
Hatch Door Pull Weight: 35lbs	
Date 1/25/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

1/31/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: A05 Cleveland Park	① RELAMP / REPLACE EXIT LIGHT THAT WAS BROKEN OFF CM 151+00 ✓
Location: [REDACTED]	② NO EXIT LIGHT / SIGN / GRAPHICS ON SHUTTLE DOOR AT TRACK LVL W/O 9195927 (GMR)
Hatch Door Pull Weight: 35lbs	① - W/O 9057976 (PWR)
Date: 1/25/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A05 Cleveland Park	NONE
Location: [REDACTED]	
Hatch Door Pull Weight: 35lbs	
Date: 1/25/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A06 Van Ness - UDC	① LEFT HATCH DOOR - PANIC BAR CATCHING ON FRAME MAKING IT HARD TO CLOSE ✓
Location: [REDACTED]	(PANIC BAR HAS TO BE PUSHED IN TO CLOSE DOOR W/O 9195935 (GMR6))
Hatch Door Pull Weight: 35lbs	
Date: 1/25/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A06 Van Ness - UDC	① LOCK CYLINDER MISSING BUT LATCH WORKS W/O # 8883118 LCK-1 ✓
Location: [REDACTED]	
Hatch Door Pull Weight: 35lbs	
Date: 1/25/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

1/31/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks ✓
Station: A06 Van Ness - UDC	
Location: [REDACTED]	None
Hatch Door Pull Weight: 35 lbs	
Date 1-25-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks ✓
Station: A07 Tenleytown	✓ ① Shaft Door at Vent Shaft Needs C/L
Location: [REDACTED]	Lock Cylinder (W/O 8678639 C/L-1)
Hatch Door Pull Weight: 35 lbs	
Date 1-25-12	✓ ② Trk Level, Trk #2 Exit Light Needs
Inspected By: [REDACTED]	To be Replaced - Broken # 9058009 (P/R)

Shaft No. [REDACTED]	Defects / Remarks ✓
Station: A07 Tenleytown	
Location: [REDACTED]	None
Hatch Door Pull Weight: 35 lbs	
Date 1-25-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks ✓
Station: A08 Friendship Hgts.	Missing ID Plate on
Location: [REDACTED]	6" Riser
Hatch Door Pull Weight: 35 lbs	Added to ID Plate Instruction List
Date 1-25-12	1/30/12
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

1/31/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: A08 Friendship Hgts.	
Location: [REDACTED]	✓ (1) Relamp Shaft (New)
Hatch Door Pull Weight: 35 lbs	
Date: 1-25-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A08 Friendship Hgts.	✓ (1) Replace Missing Exit Light Trk #1
Location: [REDACTED]	C/O
Hatch Door Pull Weight: 35 lbs	(10) Relamp Lights over Catwalk C/O
Date: 1-25-12	(13) Relamp Exit Light Track #2
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A08 Friendship Hgts.	✓ (1) Relamp Exit Light Track #1 side C/O
Location: [REDACTED]	(2) Relamp Light over Catwalk C/O
Hatch Door Pull Weight: 35 lbs	
Date: 1-25-12	(3) Tools, Appliances & Construction
Inspected By: [REDACTED]	Debris at Track level
	✓ (1)+(2) # 9058041 (PWR)

Shaft No. [REDACTED]	Defects / Remarks
Station: A09 Bethesda	
Location: [REDACTED]	None
Hatch Door Pull Weight: 35 lbs	
Date: 1-25-12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

1/31/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: A09 Bethesda	1) UNABLE TO GAIN ACCESS THRU NEW BOMB PROOF DOOR TO TRACK FROM SHAFT; LOCK SPINS AROUND IN DOOR #8676747 (LCK1) C/O
Location: [REDACTED]	
Hatch Door Pull Weight: 35/lbs.	
Date 01/25/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A10 Medical Center	1) EXIT LIGHT OUT IN BOUND TRK#1 W/O 9195930 (PNE)
Location: [REDACTED]	
Hatch Door Pull Weight: 35/lbs.	
Date 01/25/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A10 Medical Center	1) NEEDS GRAPHICS TRK LEVEL DOOR C/O NEW DOOR NEEDS EXIT GRAPHICS W/O 9197793 (GRP)
Location: [REDACTED]	
Hatch Door Pull Weight: 35/lbs.	
Date 01/25/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A10 Medical Center	NONE
Location: [REDACTED]	
Hatch Door Pull Weight: 35/lbs.	
Date 01/25/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

[REDACTED]

DATE

1/28/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: A10 Medical Center	1) RELAMP EXIT LIGHT TRACK #1 ✓ (BROKEN OFF w/o #9058085) c/o
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 01/25/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A11 Grosvenor	NONE ✓
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 01/25/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A11 Grosvenor	1) FAN SHAFT DOOR HAS SIGN THAT ✓ READS "EXIT TO TRACK LEVEL"; DOES NOT EXIT TO TRACK LEVEL.
Location: [REDACTED]	
Hatch Door Pull Weight: 35/lbs.	W/O 9195953 (GPR)
Date 01/25/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: A12 White Flint	1) BRAND NEW 6" TRI-MESE. NEEDS ✓ I.D. PLATE (ADDED TO ID PLATE INST LIST) c/o
Location: [REDACTED]	
Hatch Door Pull Weight: 35/lbs.	ADDED TO ID PLATE INSTALLATION LIST
Date 01/25/12	1/30/12
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

1/31/12

WMATA Emergency Egress Inspection Report

raft No. [REDACTED]	Defects / Remarks
ation: A12 White Flint	NONE
ocation: [REDACTED]	
atch Door Pull Weight: 35/lbs	
ate 01/25/12	
nspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

[REDACTED]

DATE

1/31/12

WMATA Emergency Egress Inspection Report

Shaft No: [REDACTED]	Defects / Remarks
Station: B03 Union Station	Shaft Good
Location: [REDACTED]	
Hatch Door Pull Weight: < 35lbs	Needs ID Plate on 4" Simese
Date 3-13-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: B09 Forest Glen	
Location: [REDACTED]	Shaft Good
Hatch Door Pull Weight:	
Date 3-13-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: B09 Forest Glen	<i>New</i>
Location: [REDACTED]	① Replace Exit Light, Missing Track 1
Hatch Door Pull Weight:	② Relamp Mid Shaft Pur c/o
Date 3-13-12	
Inspected By: [REDACTED]	① & ② w/o 9288893 (PWL)

Shaft No. [REDACTED]	Defects / Remarks
Station: B09 Forest Glen	HATCH DOORS OVERWEIGHT (IP ENG.)
Location: [REDACTED]	
Hatch Door Pull Weight: 35lb+	
Date 03/12/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/15/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: B09 Forest Glen	① Shaft door at Top of Shaft, 1 st
Location: [REDACTED]	Slight of stairs below Hatch door, door lock
Hatch Door Pull Weight:	is jamming in open position & does not
Date 03/12/12	Latch. c/o w/o 9290955 (LCK1)
Inspected By: [REDACTED]	② Track #1, Track Level outer door has
	new door but needs lock & Graphics
	(work in progress)

Shaft No. [REDACTED]	Defects / Remarks
Station: B09 Forest Glen	① TRK LEVEL DOOR KEY NOT TURNS, DOOR
Location: [REDACTED]	IS STILL BINDED
Hatch Door Pull Weight:	(Bottom) w/o 867647 (LCK1)
Date 03/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: B09 Forest Glen	NONE
Location: [REDACTED]	
Hatch Door Pull Weight: 35lbs. +	
Date 03/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: B10 Wheaton	* UPPER DOOR INACCESSIBLE, LOCK DOES NOT
Location: [REDACTED]	WORK c/o 8334496 (LCK1)
Hatch Door Pull Weight: 35lbs. +	* LOWER LEVEL DOOR, LOCK DOES NOT WORK
Date 03/12/12	c/o INACCESSIBLE (BOTH w/o 8334496 (LCK1))
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/15/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: B10 Wheaton	1. HATCH DOORS OVERWEIGHT (IN ENG) C/O
Location: [REDACTED]	2. NEW BOTTOM DOORS @ BOTTOM OF SHAFT
Hatch Door Pull Weight: 35 lbs.	TRK SIDE #2, LOCK CYLINDER JUST TURNS
Date 03/12/12	CAN NOT EXIT FROM SHAFT THROUGH THAT
Inspected By: [REDACTED]	DOOR TO CATWALK W/O # 867647

Shaft No. [REDACTED]	Defects / Remarks
Station: B10 Wheaton	HATCH DOORS OVERWEIGHT (IN ENG) C/O
Location: [REDACTED]	
Hatch Door Pull Weight: 35 lbs.	
Date 03/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: B10 Wheaton	1. STREET LEVEL ID SIGN HAS BEEN BROKEN OFF (SIGN IS MISSING) # 8973105 (CARR) C/O FROM 9/10/11
Location: [REDACTED]	2. TRACK #1 ELRESS HALF BLOCK BY PLYWOOD FENCE & PROBABLY W/ 3" HOSE W/O 9129338 (CARR) C/O
Hatch Door Pull Weight: 35 lbs.	
Date 03/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: B10 Wheaton	NONE
Location: [REDACTED]	
Hatch Door Pull Weight: 35 lbs.	
Date 03/12/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE [REDACTED]

DATE

3/15/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: B11 Glenmont	NEED TO CUT BACK SHRUBS FROM HATCH DOOR.
Location: [REDACTED]	IMMEDIATE AT STREET
Hatch Door Pull Weight: 35/lbs	(1) RELIEF MID LEVEL OF SHAFT (C/O FROM 9/12)
Date 03/12/12	(2) PIN CUTTER ON HATCH DOOR NEED TO BE WELDED
Inspected By: [REDACTED]	SECURE W/O 9129343 (WLDI) (2)
	(1) W/O 9288898 (PWR)

Shaft No. [REDACTED]	Defects / Remarks
Station: B11 Glenmont	HATCH DOORS ARE OVERWEIGHT (IN ENG)
Location: [REDACTED]	9/0 9/24/11
Hatch Door Pull Weight: 35/lbs	
Date 03/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: B11 Glenmont	HATCH DOORS IN ENGINEERING ARE
Location: [REDACTED]	OVERWEIGHT 9/0 9/30/11
Hatch Door Pull Weight: 35/lbs +	
Date 03/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: B11 Glenmont	HATCH DOORS OVERWEIGHT (IN ENG)
Location: [REDACTED]	
Hatch Door Pull Weight: 35/lbs +	
Date 03/12/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/15/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: C04 Foggy Bottom	
Location: [REDACTED]	HATCH DOORS OVERWEIGHT (IN ENG.)
Hatch Door Pull Weight:	
Date 3/13/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: C04 Foggy Bottom	(1) CONCRETE MID LEVEL DOOR NEEDS PLATE AT BOTTOM (SAFETY ISSUE)
Location: [REDACTED]	(2) CONCRETE MID LEVEL DOOR IS BINDING AND WILL NOT LATCH PROPERLY (CAN ONLY BE HAND)
Hatch Door Pull Weight:	(W.D. 9104587) (4) (3) W/O 9288924 (4)
Date 3/13/12	(3) REPAIR EXIT LIGHT 1/B END TRACK
Inspected By: [REDACTED]	(4) REPAIR SHAFT FROM MID LEVEL TO TRACK

Shaft No. [REDACTED]	Defects / Remarks
Station: C05 Rosslyn	none
Location: [REDACTED]	
Hatch Door Pull Weight: 30/lbs.	
Date 3/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: C05 Rosslyn	none
Location: [REDACTED]	
Hatch Door Pull Weight: 30/lbs.	
Date 3/12/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/15/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: C05 Rosslyn	1) need to relamp entire shaft
Location: [REDACTED]	2) w/o 9288905 (PWA)
Hatch Door Pull Weight: 35 lbs	2) need to re-attach "excessive air pressure" sign to wall @ top of shaft (on the ground)
Date 3/12/12	2) w/o 9291023 (GRPI)
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: C07 Pentagon	For Access: Pentagon Police Communications (703) 697-1001
Location: [REDACTED]	1) relamp exit light @ track #2 C/O
Hatch Door Pull Weight: 35 lbs	2) need to install ID plate on 6" siamese
Date 3/12/12	(added to list 12/15/11)
Inspected By: [REDACTED]	1) - w/o 9288913 (PWA)

Shaft No. [REDACTED]	Defects / Remarks
Station: C07 Pentagon	For Access: Pentagon Police Communications (703) 697-1001
Location: [REDACTED]	none
Hatch Door Pull Weight: 30 lbs	
Date 3/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: C08 Pentagon City	1) Relamp shaft C/O
Location: [REDACTED]	w/o 92889021 (PWA)
Hatch Door Pull Weight: 35 lbs	
Date 3/12/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE [REDACTED]

DATE

3/15/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: C09 Crystal City	none
Location: [REDACTED]	
Hatch Door Pull Weight: 35 lbs.	
Date 3/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: C08 Crystal City	none
Location: [REDACTED]	
Hatch Door Pull Weight: N/A (Door)	
Date 3/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: C12 Braddock Rd.	none
Location: [REDACTED]	
Hatch Door Pull Weight: 35 lbs.	
Date 3/12/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: C14 Eisenhower Ave.	1) Hatch doors overweight
Location: [REDACTED]	2) Fall hazard Left Top of Stairs.
Hatch Door Pull Weight: 35 lbs.	No railing - w/o 9104672 (WLD)
Date 3/12/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/15/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: C15 Huntington	1) Siamese needs ID plate (6")
Location: [REDACTED]	(on list)
Hatch Door Pull Weight: 35/lbs.	
Date 3/12/12	
Inspected By: [REDACTED]	
[REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/15/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: D01 Federal Triangle	① SAND FROM BROKEN SAND BAGS
Location: [REDACTED]	GETTING INTO FRAME & HINGES OF
Hatch Door Pull Weight: 35lbs	HATCH DOOR MAKING IT DIFFICULT TO
Date 3/27/12	OPEN & CLOSE 9316851 (Gen 2)
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: D04 Federal Center, SW	① HATCH DOORS OVERWEIGHT (IN ENG)
Location: [REDACTED]	
Hatch Door Pull Weight: > 35lbs	
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: D04 Federal Center, SW	① HATCH DOORS OVERWEIGHT (IN ENG)
Location: [REDACTED]	
Hatch Door Pull Weight: > 35lbs	
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: D05 Capitol South	
Location: [REDACTED]	None
Hatch Door Pull Weight: 35lbs	
Date 3/27/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks ① HATCH DOORS OVERWEIGHT (IN ENG)
Station: D05 Capitol South	
Location: [REDACTED]	
Hatch Door Pull Weight: 235lbs	
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: D06 Eastern Market	NONE
Location: [REDACTED]	
Hatch Door Pull Weight: 35lbs	
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: D07 Potomac Ave	
Location: [REDACTED]	NONE
Hatch Door Pull Weight: 35lbs	
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: D07 Potomac Ave.	① PERAMP EXIT LIGHT TRK #2
Location: [REDACTED]	w/o # 9076206 (PWR) ✓
Hatch Door Pull Weight: 35lbs	② HAND OPER ARM (R) HATCH DOOR
Date 3/27/12	WENT BROKEN w/o 9076202 (GEM)
Inspected By: [REDACTED]	9316806 (WLD)

SUPERVISOR'S SIGNATURE

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: E01 Mt. Vernon Sq.- UDC	
Location: [REDACTED]	① Need To Relamp exit Light @
Hatch Door Pull Weight: < 35lbs	Track level Track #2
Date 3-27-12	w/o 9100353 PWR ✓ c/o
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: E04 Columbia Hgts.	
Location: [REDACTED]	① Hatch doors are overweight c/o
Hatch Door Pull Weight: > 35lbs	
Date 3-27-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: E04 Columbia Hgts.	
Location: [REDACTED]	2 doors Leading from Shaft
Hatch Door Pull Weight: < 35lbs	To AORA & From AORA To
Date 3-27-12	Track do not lock (Locksmith)
Inspected By: [REDACTED]	9316856 (LCKI)

Shaft No. [REDACTED]	Defects / Remarks
Station: E05 Georgia Ave. / Petworth	
Location: [REDACTED]	Track 2 Exit Light is out
Hatch Door Pull Weight: < 35lbs	Needs To be Relamped
Date 3-27-12	w/o 9100367 ✓ PWR c/o
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: E05 Georgia Ave. / Petworth	None
Location: [REDACTED]	
Hatch Door Pull Weight: < 35 lbs	
Date 3-27-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: E05 Georgia Ave. / Petworth	① Hatch doors overweight (Im Eng)
Location: [REDACTED]	② Inbound Track # 2 - need to replace missing exit sign (PWR) 8723 259 ✓
Hatch Door Pull Weight: > 35 lbs	③ Door To Traction Power jamming
Date 3-27-12	await close & lock. 1st level down
Inspected By: [REDACTED]	from STREET Level Hatch 9345863 (CRP)

Shaft No. [REDACTED]	Defects / Remarks
Station: E05 Georgia Ave. / Petworth	① Hatch doors overweight (Im Eng)
Location: [REDACTED]	② ⁴ Doors, on both sides of Tracks, need lock Assemblies (Lck-1)
Hatch Door Pull Weight: < 35 lbs	#8723164 (CRP) 8723174 CRP 9100230 (CRP)
Date 3-27-12	③ 2nd door Track Level will not lock
Inspected By: [REDACTED]	④ Track Door Binding & Needs Exit Graphics Door Binding 9100230 (CRP) ✓
	Graphics 9100226 (CRP) ✓

Shaft No. [REDACTED]	Defects / Remarks
Station: E05 Georgia Ave. / Petworth	
Location: [REDACTED]	None
Hatch Door Pull Weight: < 35 lbs	
Date 3-27-12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: E06 Ft. Totten	
Location: [REDACTED]	① Egress Blocked by Cable
Hatch Door Pull Weight: 35lbs	at Bottom of Shaft / Stairs
Date 3-27-12	C/O from 9-21-11
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: E06 Ft. Totten	
Location: [REDACTED]	① Relamp Shaft
Hatch Door Pull Weight: 35 lbs	1317025 PWR
Date 3-27-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: : E06 Ft. Totten	
Location: [REDACTED]	None
Hatch Door Pull Weight: 35lbs	
Date 3-27-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: E06 Ft. Totten	
Location: [REDACTED]	None
Hatch Door Pull Weight: 35lbs	
Date 3-27-12	ETEC OK
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: E07 West Hyattsville	
Location: [REDACTED]	NONE
Hatch Door Pull Weight: < 35	
Date 3-27-12	
Inspected By: [REDACTED]	Note: Will need Extinguisher Replaced in Tie Breaker next year

Shaft No. [REDACTED]	Defects / Remarks
Station: E07 West Hyattsville	
Location: [REDACTED]	NONE
Hatch Door Pull Weight: > 35 lbs	
Date 3-27-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: E08 PG Plaza	
Location: [REDACTED]	NONE
Hatch Door Pull Weight: 35 lbs	
Date 3-27-12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: E08 PG Plaza	
Location: [REDACTED]	NONE
Hatch Door Pull Weight: 35 lbs	
Date 3-27-12	
Inspected By: [REDACTED]	Note: DPS Extinguisher will need Replace next year

SUPERVISOR'S SIGNATURE

DATE

3/29/12

WMATA Emergency Egress Inspection Report

raft No. [REDACTED]	Defects / Remarks
ation: E09 College Park - U of Md.	
ocation: [REDACTED]	① Exit light over Shost Door,
atch Door Pull Weight:	2 Levels down from Street, Need
ate 3-27-12	To be Relamped. 93117032 (PWR)
ispected By: [REDACTED]	ETEC - OK

SUPERVISOR'S SIGNATURE

[REDACTED]
[Signature]

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: F02 Archives - Navy Memorial	NONE
Location [REDACTED]	
Hatch Door Pull Weight: 30lbs.	
Date 3/28/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F03 L'Enfant Plaza	NONE
Location [REDACTED]	
Hatch Door Pull Weight: 30lbs	
Date 3/28/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F04 Waterfront - SEU	1.) TRACK #2 SIDE - BOTH THE EAST DOOR + TRACK
Location [REDACTED]	DOOR NEED GRAPHICS
Hatch Door Pull Weight: 30lbs.	9316878 (G2P1)
Date 3/28/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F04 Waterfront - SEU	1.) HATCH DOOR OVERWEIGHT (IN ENG)
Location [REDACTED]	
Hatch Door Pull Weight: 35lbs	(MECH. ROOM #200 WILL NOT SECURE)
Date 3/27/12	W/O # 8947008 9316818 (LCK)
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: F05 Navy Yard	NONE
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F05 Navy Yard	NONE
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F06 Anacostia	NONE
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 03/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F06 Anacostia	NONE
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 3/27/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: F07 Congress Heights	NO ACCESS THRU TRACK #2 DOOR, LOCK
Location: [REDACTED]	BROKEN
Hatch Door Pull Weight: 35 lbs.	9316883 (LOCK)
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F07 Congress Heights	HATCH DOORS OVER WEIGHT 9/0
Location: [REDACTED]	
Hatch Door Pull Weight: 55 lbs +	
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F07 Congress Heights	HATCH DOORS OVER WEIGHT 9/0
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F07 Congress Heights	1) HATCH DOORS OVERWEIGHT 9/0
Location: [REDACTED]	2) AORA DOOR AT PLATFORM LEVEL HAS
Hatch Door Pull Weight: 35 lbs. +	NO ENTRY FROM TRACKSIDE WITHOUT A
Date 3/27/12	KEY (NOTED TO SAFETY) 9/0
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: F07 Congress Heights [REDACTED]	1.) HATCH DOOR OVERWEIGHT IN ENG. 9/10
Location: [REDACTED]	2.) LOCK ON HATCH FOUND OPEN
Hatch Door Pull Weight: 35 lbs.	
Date: 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F08 Southern Ave.	1.) HATCH DOORS OVERWEIGHT IN ENG. 9/10
Location: [REDACTED]	
Hatch Door Pull Weight: 35 lbs.	
Date: 3/27/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: F08 Southern Ave.	1.) HATCH DOORS OVERWEIGHT
Location: [REDACTED]	2.) MUD SLIDE COVERS EXIT HATCHES, NEED RETAINING WALL W/ 08156879
Hatch Door Pull Weight: 35 lbs.	3.) MUD, HILL EROSION BURYING SIAMESE W/ 8156893
Date: 3/27/12	4.) BASE OF SHAFT NEEDS RELIGHTING
Inspected By: [REDACTED]	5.) BOTH EXIT LIGHTS NEEDS RELAMPED
	6.) BLUE LIGHT STATIONS ARE OUT (RELAMPED)
	7.) WARPED HATCH DOOR (5) (6) 9317190 (FWR)

Shaft No. [REDACTED]	Defects / Remarks
Station: F08 Southern Ave.	1.) NEEDS EXIT GRAPHICS ON DOOR TO AORA RM #105 9/10 W/ #7991881 9316821 (GRP)
Location: [REDACTED]	
Hatch Door Pull Weight: N/A	
Date: 3/27/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

[REDACTED]

DATE

3/29/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: G01 Benning Rd.	① HATCH DOOR - OK (REPAIRED)
Location: [REDACTED]	
Hatch Door Pull Weight:	② DOOR TO FAN SHAFT WILL NOT
Date 3/21/12	STAY CLOSED
Inspected By: [REDACTED]	9305930 (CPL)

Shaft No. [REDACTED]	Defects / Remarks
Station: G01 Benning Rd	① BOTH BOMB DOOR LOCK MECHANISMS
Location: [REDACTED]	ARE INOPERATIVE (W/ 8676747 KK-1)
Hatch Door Pull Weight: 35lbs	* CHECK W/O TO ENSURE BOTH LOCKS ARE
Date 3/21/12	ON IT.
Inspected By: [REDACTED]	② SMALL EXTERIOR DOOR TO LOCK WON'T
	OPEN. (HAD TO ACCESS SHAFT FROM
	9305944 (GEM4) SECTION)

Shaft No. [REDACTED]	Defects / Remarks
Station: G01 Benning Rd	PASSIVE HATCH DOOR LATCH
Location: [REDACTED]	NEEDS ADJUSTMENT - DIFFICULT TO
Hatch Door Pull Weight: 35lb	OPEN 9305978 (GEM4)
Date 3/21/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: G02 Capitol Heights	① TOP SHAFT LIGHT FIXTURE HANGING
Location: [REDACTED]	DOWN OFF OF WALL (PWR)
Hatch Door Pull Weight: 35lbs	② PANIC HANDLE TO TRACK 2
Date 3/21/12	BOMB DOOR BROKE OFF - UNABLE
Inspected By: [REDACTED]	TO OPEN DOOR FROM TRUCK SIDE
	* ITEMS FROM LAST QTR REPAIRED
	② - 9305986 (GEM4)

SUPERVISOR'S SIGNATURE [REDACTED]

DATE 3/26/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: G02 Capitol Heights	① 6" SIAMENSE COUPLER HAD CRACKS & SPLIT ON SLEEVE & AIR C/O W/ #7627394 PART # 8925729 ② CYLINDER ON TRACK LEVEL DOOR IS BROKEN & 8925730 (LCK-1)
Location: [REDACTED]	
Hatch Door Pull Weight: 3516.	
Date 3/21/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: G02 Capitol Heights	NONE
Location: [REDACTED]	
Hatch Door Pull Weight: 3516.5	
Date 3/22/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: G03 Addison Rd.	DOOR TO/FROM TRACK DIFFICULT TO OPEN FROM TRACK SIDE 7305990 (LCK-2)
Location: [REDACTED]	
Hatch Door Pull Weight: 3516.	
Date 3/21/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: G04 Morgan Blvd.	NONE
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 3/22/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/26/12

WMATA Emergency Egress Inspection Report

R No. [REDACTED] Station: G04 Morgan Blvd. Location: [REDACTED] Hatch Door Pull Weight: Date: 3/22/12 Inspected By: [REDACTED]	Defects / Remarks NONE
---	---------------------------

Shaft No. [REDACTED] Station: G04 Morgan Blvd. Location: [REDACTED] Hatch Door Pull Weight: Date: 3/22/12 Inspected By: [REDACTED]	Defects / Remarks NONE
---	---------------------------

Shaft No. [REDACTED] Station: G04 Morgan Blvd. Location: [REDACTED] Hatch Door Pull Weight: N/A Date: 3/22/12 Inspected By: [REDACTED]	Defects / Remarks NONE
---	---------------------------

Shaft No. [REDACTED] Station: G04 Morgan Blvd. Location: [REDACTED] Hatch Door Pull Weight: 30 lbs Date: 3/22/12 Inspected By: [REDACTED]	Defects / Remarks NONE
--	---------------------------

SUPERVISOR'S SIGNATURE

DATE

3/26/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: G05 Largo	NONE
Location: [REDACTED]	
Hatch Door Pull Weight: 30 lbs	
Date 3/21/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: G05 Largo	① RAIN GUTTER ON LEFT LEAF OF
Location: [REDACTED]	HATCH DOOR NEEDS TO BE
Hatch Door Pull Weight: 30 lbs	SPOT WELDED
Date 3/21/12	W/O 8925739 (WLD) (C/O)
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: G05 Largo	① LATCH ON CONCAVE DOOR IS
Location: [REDACTED]	TRAIL LVL DOES NOT LATCH
Hatch Door Pull Weight: 30 lbs	W/O 8925704
Date 3/21/12	(8357804?)
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: G05 Largo	NONE
Location: [REDACTED]	
Hatch Door Pull Weight: 30 lbs	
Date 3/21/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/23/12

WMATA Emergency Egress Inspection Report

raft No. [REDACTED]	Defects / Remarks
ation: K01 Courthouse	none
ocation: [REDACTED]	
atch Door Pull Weight: 35 lbs	
ate 3/14/12	
inspected By: [REDACTED]	

raft No. [REDACTED]	Defects / Remarks
ation: K01 Courthouse	none
ocation: [REDACTED]	
atch Door Pull Weight: 35 lbs	
ate 3/14/12	
inspected By: [REDACTED]	

raft No. [REDACTED]	Defects / Remarks
ation: K02 Clarendon	none
ocation: [REDACTED]	
atch Door Pull Weight: 35 lbs	
ate 3/14/12	
inspected By: [REDACTED]	

raft No. [REDACTED]	Defects / Remarks
ation: K03 Virginia Square - GMU	none
ocation: [REDACTED]	
atch Door Pull Weight: 35 lbs	
ate 3/14/12	
inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/15/12

WMATA Emergency Egress Inspection Report

ft No. [REDACTED]	Defects / Remarks
ion: K04 Ballston - MU	1) Hatch doors overweight (In Eng)
ation: [REDACTED]	C/O From 2/28/14
ch Door Pull Weight: 35/lbs. +	
e 3/14/12	
pected By: [REDACTED]	

ft No. [REDACTED]	Defects / Remarks
ation: K04 Ballston - MU	none
ocation: [REDACTED]	
atch Door Pull Weight: 35/lbs.	
ate 3/14/12	
spected By: [REDACTED]	

haft No. [REDACTED]	Defects / Remarks
ation: K04 Ballston - MU	none
ocation: [REDACTED]	
atch Door Pull Weight: 35/lbs	
Date 3/14/12	
inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/15/12

WMATA Emergency Egress Inspection Report

Shaft No. [REDACTED]	Defects / Remarks
Station: F03 L'Enfant Plaza	None
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 3/13/12	
Inspected By: [REDACTED]	

Shaft No. [REDACTED]	Defects / Remarks
Station: C07 Pentagon	None
Location: [REDACTED]	
Hatch Door Pull Weight:	
Date 3/13/12	
Inspected By: [REDACTED]	

SUPERVISOR'S SIGNATURE

DATE

3/15/12