

governmentattic.org

"Rummaging in the government's attic"

Description of document: Federal Aviation Administration (FAA) Domestic Events

Network event logs, April 2013

Request date: 08-May-2013

Released date: 29-May-2014

Posted date: 09-June-2014

Title of documents: FAA Air Traffic Organization, NAS Daily Events Log

Source of document: FOIA Coordinator

Federal Aviation Administration

National Freedom of Information Act Staff, AFN-140

800 Independence Avenue, SW

Washington, DC 20591 Fax: (202) 493-5032

Electronic request: Washington, DC FOIA

The governmentattic.org web site ("the site") is noncommercial and free to the public. The site and materials made available on the site, such as this file, are for reference only. The governmentattic.org web site and its principals have made every effort to make this information as complete and as accurate as possible, however, there may be mistakes and omissions, both typographical and in content. The governmentattic.org web site and its principals shall have neither liability nor responsibility to any person or entity with respect to any loss or damage caused, or alleged to have been caused, directly or indirectly, by the information provided on the governmentattic.org web site or in this file. The public records published on the site were obtained from government agencies using proper legal channels. Each document is identified as to the source. Any concerns about the contents of the site should be directed to the agency originating the document in question. GovernmentAttic.org is not responsible for the contents of documents published on the website.



System Operations Services 600 Independence Avenue SW. Washington, DC 20597

MAY 2 9 2014

This is in response to your Freedom of Information Act (FOIA 2013-004686) request dated May 8, 2013. Your request sought a copy of the event logs at the Federal Aviation Administration (FAA) Domestic Events Network for the period April 1 to April 30, 2013. Your request was assigned to the Air Traffic Organization office of System Operations Services for processing.

A search was conducted and enclosed are 190 pages of records responsive to your request. However, portions of these records have been redacted under FOIA exemption title 5, United States Code (U.S.C.), section 552(b)(7)(A) and (b)(7)(E), which protects from disclosure "records or information compiled for law enforcement purposes." Specifically, section 552(b)(7)(A) protects those records which "could reasonably be expected to interfere with enforcement proceedings," Section 552(b)(7)(E) protects those records which "would disclose techniques and procedures for law enforcement investigations or prosecutions, or would disclose guidelines for law enforcement investigations or prosecutions if such disclosure could reasonably be expected to risk circumvention of the law."

It was also determined the Transportation Security Administration (TSA) has an interest in the responsive records. Therefore, under title 49, Code of Federal Regulations, part 7, section 7.16(a), we sought its input for any added redactions. The TSA determined that portions of this record are to be redacted under FOIA exemption 3. This exemption allows withholding information prohibited from disclosure by another Federal statute. The applicable statute, title 49, U.S.C., section 114(r)(1)(C), prohibits the release of sensitive security information because its disclosure would "be detrimental to the security of transportation."

If you owe fees for processing this request, an invoice containing the amount due and payment instructions will be enclosed with this letter.

The undersigned is responsible for this partial denial. You may request reconsideration of this determination by writing the Assistant Administrator for Finance and Management (AFN-1), FAA, 800 Independence Avenue SW., Washington, D.C. 20591. Your request for reconsideration must be made in writing within 30 days from the date of receipt of this letter and must include all information and arguments relied upon. Your letter must state that it is an appeal from the above-described denial of a request made under the FOIA. The envelope containing the appeal should be marked "FOIA."

Sincerely,

Nancy H. Kalinowski

Vice President, System Operations Services

Air Traffic Organization

Enclosures



Date: 04/01/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RGotz,
 04/02/2013 0404Z
 RV

Security Event Statistics:				
EMERGENCY: 14 EMERGENCY- MEDICAL:			COD: 49 LASER: 11	
			MOR: 2	

Log:	
Time (UTC	Remarks
04/01/2013	
0400	2
0400	LASER OPERATION; ATSC (NCRCC); NASA Goddard Space Center laser ranging operations underway.
0400	
0400 0414	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZSE; SWA679; B737; OAK.,SEA; Sick PAX,
0530	NCR-COORDINATION; ATSC (NCRCC).
0542	COD; ATSC (FAA HQ DEN); ZLA; EJA929; C750; SDMCMA New Destination: LAX; WX.
0545	COB, ATOC (CATTING DEAY), 2D Y, 20/1020, CIVIC, CEMILONIA THOM DESIGNATION. DAY, VAX.
0618	COD; ATSC (NCRCC); PCT; VTE920; ECG. IAD New Destination: BWI; Due to weather.
0655	NORDO; ATSC (FAA HQ DEN); ZLA; SWA258; B737; SFOPHX; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 0656.
0906	LASER; ATSC (FAA HQ DEN); S46; ASA15; B739; BOSSEA; 0435, 14 miles southeast of SEA, at 5,000 feet,
	heading 160 degrees; ACFT illuminated by a green LASER from 11 o'clock. No injuries reported; (a) 5.1
0000	(b) (7) (a) & (e) (b) (a) & (e) (b) (b) (b) (b) (b) (b) (b) (b) (b) (b
0909	LASER; ATSC (FAA HQ DEN); S46; ASA23; B738; ORDSEA; 0452, 14 miles southeast of SEA, at 4,500 feet, heading 160 degrees; ACFT illuminated by a green LASER from 11 o'clock. No injuries reported;
	(b) (7) (a) & (e)
0928	B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(
0942	COD; ATSC (FAA HQ DEN); ZBW; RLI811; BE58; DXRCQX New Destination: HYA; Company request.
1000	
1000	
1000	
1000 1013	
1013	7E
	7 <u>E</u>
	?E
1015	AND ATTO MODELS OF AWARES OF DAMES OF THE PROPERTY OF THE PROP
1040	COD: ATSC (NCRCC); PCT; AWI4022; CRJ2; ORFDCA New Destination: RIC; Wx divert.
1041 1042	COD; ATSC (FAA HQ DEN); PHL; AWI3929; CRJ2; PHLDCA New Destination: PHL; WX. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); PHL; PHL authorized to suspend change of destination
1042	reporting for AOR until 1500 due to WX.
1050	COD; ATSC (FAA HQ DEN); ZNY; RPA3345; E170; SYRDCA New Destination: RIC; WX.
1052	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDC; ZDC, ZNY, PCT authorized to suspend change of
	destination reporting for AOR until 1500 due to WX.

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RGotz,
 04/02/2013 0404Z
 RV

Log:	
Time (UTC)	Remarks
1054	EMERGENCY,COD; ATSC (FAA HQ DEN); ZMA; AWE1894; B734; PBIPHL New Destination: MCO; Indicator light. 1056 COD to MIA. 1101 HQ DEN called AWE Dispatch to obtain more information, landing gear issue. 1103 emergency declared due to landing gear issue. Aircraft landed at 1203.
1055	COD; ATSC (NCRCC); ZDC; AWE49; A320; LASDCA New Destination: BWI; Wx divert.
1107	EMERGENCY,COD; ATSC (FAA HQ DEN); ZDC; PDT8820; DH8C; PGVCLT New Destination: PGV; Lost number one engine. Aircraft landed at 1120.
1130	
1200	75
1200	
1200	
1225	COD; ATSC (FAA HQ DEN); ZME; EJA841; C560; CMHNEW New Destination: HSA; WX.
1226	COD; ATSC (FAA HQ DEN); OPT327; E55P; SRQFA54 New Destination: SRQ; Fort Meyers report, for WX.
1234	EMERGENCY- MEDICAL; ATSC (NCRCC); PCT; EGF4436; E135; BNADCA; PAX medical.
1236	COD; ATSC (FAA HQ DEN); ZMA; AAY9418; MD83; SFBPGD New Destination: SFB; WX.
1243	B3; 49 U.S.C. 114(r)
1243	B3; 49 U.S.C. 114(r)
1250	COD; ATSC (FAA HQ DEN); ZMP; IFL8016; FA20; CYWG. GFK New Destination: RRT; Company request.
1259	NORDO; ATSC (FAA HQ DEN); ZME; N155TH; SR22; CEUOLV; Aircraft reported on course, at assigned attitude. Attempting contact on Guard. No satellite phone available. 1315 HQ DEN asked ZME for update. Communications re-established at 1316.
1303	CONFERENCES, ADMIN; ATSC (N/NC); B3; 49 U.S.C. 114(r) WCLC.
1304	COD; ATSC (FAA HQ DEN); ZID; AAL33; B763; JFKLAX New Destination: ORD; Fuel. 1324 HQ DEN called AAL Dispatch, they report COD due to mechanical issue, HQ DEN notified ZAU.
1307	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); TYS; TYS authorized to suspend change of destination reporting for AOR until 1600 due to WX.
1308	COD; ATSC (FAA HQ DEN); MSP; DAL1464; MD90; MSPDCA New Destination: MSP; Pressurization issue.
1309	NORDO; ATSC (FAA HQ DEN); ZJX; N605BX; LJ45; SUAHKY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1318.
1321	COD; ATSC (FAA HQ DEN); ZJX; EJA203; F2TH; PBITEB New Destination: HPN; Company request.
1337	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MIA; AAL662; B752; MDSDMIA; Sick PAX.
1400	B3; 49 U.S.C. 114(r)
1400	ADMIN; ATSC (FAA HQ DEN); DR on HQW. CU on HQE. WCLC.
1409	TOI-US ADIZ,TOI; ATSC (CONR/AOC); (b) (7) (a) & (e) (b) (7) (a) & (e) (c) (7) (a) & (e)
1415	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); LFT; LFT authorized to suspend change of destination reporting for AOR until 1800 due to WX.
1417	NCR-COORDINATION, PAGED; ATSC (NCRCC); Exercise Only message received and disseminated.
1430	NORDO,MOR,PAGED; ATSC (FAA HQ DEN); SHV; N834KC; DA40; OLVIWS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1439 HQ DEN asked ZFW for update. At 1448 ZFW OMIC reported no change in status, conducting voice tape review. At 1449 aircraft transitioned into ZHU airspace, OMIC advised. 1457 HQ DEN asked ZHU for update. 1500 NORDO 0+30. At 1505 ZFW OMIC reported unable to conduct voice tape review due to equipment malfunction. At 1507 contacted SHV TRACON, OMIC reported communications lost when transitioning aircraft in Polk TRACON. Las frequency assigned was 123.75, requested ZHU OMIC to attempt aircraft relay. Communications re-established at 1514, PIC issued BRASHER to contact SHV OMIC for MOR Action.

Page 2



Element:	Created by:	Created on:	Checked by:
ALL	RGotz,	04/02/2013 0404Z	RV

Log:	
Time (UTC)	Remarks
1430	B3; 49 U.S.C. 114(r)
	B3, 49 U.S.C. 114(r)
1435	EMERGENCY ; ATSC (FAA HQ DEN); ZHU; JUMP21; T38; DLFSKF; Generator malfunction. Aircraft landed at 1448.
1457	NORDO; ATSC (FAA HQ DEN); ZHU; N1057L; BE9L; MLUJKA; Aircraft reported on course, at assigned
1, 10,	altitude. Attempting contact on Guard and previous frequencies. No satellite phone available, aircraft
	transitioned into ZJX airspace. Communications re-established at 1502.
1500	B3; 49 U.S.C. 114(r)
1500	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful.
1502	CONFERENCES; ATSC (N/NC); ONEC test successful.
1530	COD; ATSC (FAA HQ DEN); ZAU; ASH3780; CRJ2; ORD. ATL New Destination: ORD; Mechanical.
1542	COD; ATSC (FAA HQ DEN); ZDV; EJA900; C750; HPNASE New Destination: EGE; WX.
1547	COD; ATSC (FAA HQ DEN); ZTL; CYO915; LJ55; MAF. CHS New Destination: JZI; Company request.
1600	COD; ATSC (FAA HQ DEN); ZJX; EJA280; F2TH; HPNPBI New Destination: MTH; Company request. NORDO,NOTIFICATION-LATE,MOR,PAGED; ATSC (FAA HQ DEN); ZME; N566KA; BE30; FLLROG; ACFT
1608	went NORDO approximately 1540, Aircraft reported on course, at assigned altitude. Attempting contact on
	Guard. No satellite phone available. 1610 NORDO 0+30. Communications re-established at 1612, Brasher
	warning will be read to PIC, MOR to follow.
1611	COD; ATSC (FAA HQ DEN); ZDC; EJA745; GALX; TEBMIA New Destination: BNA; Company request.
1622	COD; ATSC (FAA HQ DEN); ZID; AAL19; B762; JFK. LAX New Destination: ORD; No water on ACFT.
1654	NORDO; ATSC (FAA HQ DEN); ZAU; DAL1529; B738; JFK. LAS; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company, aircraft transitioned into ZMP airspace, OMIC
	advised. Communications re-established at 1657.
1655	COD, ATSC (FAA HQ DEN); ZDV; UAL268; B752; DENSFP New Destination: DEN; Backed up sewage.
1700	
1702	B3; 49 U.S.C. 114(r)
1705	EMERGENCY; ATSC (FAA HQ DEN); ZKC; N123ZC; TBM7; SAFAVK New Destination: EGT; Engine
4740	overheating. Aircraft landed at 1732. EMERGENCY,COD; ATSC (FAA HQ DEN); ZOB; N1237M; C210; 1A5FNT New Destination: ADG; Lost fuel
1710	pump. Aircraft landed at 1717.
1711	COD; ATSC (FAA HQ DEN); ZDC; EMPR99; F18; NTUVFR New Destination: NTU; Mechanical.
1712	(b) (7) (a) & (e)
1	(b) (7) (a) & (e)
•	(b) (7) (a) &(e)
1713	EMERGENCY ; ATSC (FAA HQ DEN); ZKC; AAL680; MD83; DFWMCI; Pressurization system malfunction.
1.700	Aircraft landed at 1730.
1720	COD; ATSC (FAA HQ DEN); ZDC; PAT05; H60; JSTHGR New Destination: DAA; WX.
1722	COD; ATSC (FAA HQ DEN); ZHU; PHM038A; S76; GLSVFR New Destination: GLS; WX. COD; ATSC (FAA HQ DEN); ZDC; VNR179; P180; HPNCKI New Destination: FLO; Company request.
1728 1732	COD; ATSC (FAA HQ DEN); ZDC; VNR 179, F160, HPN.:CRI New Destination: FLO; Company request. COD; ATSC (FAA HQ DEN); ZAN; BRG850; B190; OMA.:SVA New Destination: GAM; WX.
1732	EMERGENCY; ATSC (FAA HQ DEN); ZMP; COBRA14; C135; OFFOFF; Fuel tank issue. Aircraft landed at
1,3,	1827.
1739	EMERGENCY; ATSC (FAA HQ DEN); ZMA; PJC32; C56X; APFBCT; Hydraulics issue. Aircraft landed at
1	1747.
1747	
1750	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAN; ZAN authorized to suspend change of destination

Page 3



 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RGotz,
 04/02/2013 0404Z
 RV

Log:	
Time (UT	c) Remarks
	reporting for western AOR until 2200 due to WX.
1750	COD; ATSC (FAA HQ DEN); ZAN; VTS99; DC6; ANC. ENM New Destination: UNK; WX.
1757	EMERGENCY ; ATSC (FAA HQ DEN); ZAÜ; AAL1458; B738; RSWORD; Nose wheel steering malfunction. Aircraft landed at 1823.
1800	alicialitatique at 1625.
1800	
1800	
1804	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLA; VRD231; A320; ORDLAX; Passenger medical emergency.
1824	7E (b) (7) (a) & (e)
4000	(b) (7) (a) & (e)
1830	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOB; DAL86; B752; LAXJFK; Passenger medical emergency.
1831	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMA; ZMA authorized to suspend change of destination reporting for MIA AOR until 2200 due to WX.
1832	NORDO; ATSC (FAA HQ DEN); ZJX; N950RL; F2TH; ILNOCF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1835.
1848	NOTAM-VIP; SOSC (FAA HQ); FDC ZDV 3/8738 has been published B3; 49 0.5.C. 114(x)
1849	B3; 49 U.S.C. 114 (r) COD; ATSC (FAA HQ DEN); ZHU; ASQ4592; E145; IAH. VPS New Destination: IAH; Mechanical.
1850	NOTAM-PUBLISHED; SOSC (FAA HQ); FDC 3/8757 & 3/8760 Special Notices have been published for the Coachella Music Festival being held in Indio, CA on April 12th-14th and the 19th. 20,248 SPANS email notifications have been transmitted in support of this event.
1857	EMERGENCY ; ATSC (FAA HQ DEN); S56; SKW4756; CRJ7; ONTSLC; Lightning strike causing port side engine failure. Aircraft landed at 1900.
1858	NORDO; ATSC (FAA HQ DEN); ZAU; SWA3947; B737; MDWALB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1902.
1859	NORDO; ATSC (FAA HQ DEN); ZNY; N427PA; COL4; M254B8; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. At 1912 requeste status, no change. Communications re-established at 1920.
1900	
1907	COD; ATSC (FAA HQ DEN); ZNY; EGF3967; E145; CVGJFK New Destination: ORF; Fuel.
1908	COD; ATSC (FAA HQ DEN); ZDC; JBU16; E190; FLLJFK New Destination: RDU; Fuel and holding at JFK.
1915	COD; ATSC (FAA HQ DEN); ZDC; AAL1048; B752; MIAJFK New Destination: IAD; Fuel and holding.
1922	(b) (7) (a) &(e)
	(b) (7) (a) 5 (e)
1923	(b) (7) (a) § (e) NOTAM-PUBLISHED; ATSC (FAA HQ DEN); FDC NOTAM 3/8765 published
1927	B3; 49 U.S.C. 114 (r) WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDC; ZNY/ZDC/ZOB authorized to suspend change of destination reporting for NYC AOR until 2200 due to WX and holding.
1022	EMERGENCY; ATSC (FAA HQ DEN); ZME; N8345U; C172; VFR7M8; Engine failure. Aircraft landed at 1934
1932	EMERGENO I, A 130 (FAA 114 DEN), ZWE, 1903430, O 172, VFA/1910, Eligilie lailidie. Aliciant lailided at 1934
2000	COD ATSC (FAA HO DEN): 79/M: VARIATA: CARS: ROC MSS Novi Destination, ROS Marather
2003	COD; ATSC (FAA HQ DEN); ZBW; KAP174; C402; BOS. MSS New Destination: BOS; Weather.
2012	SIF; ATSC (FAA HQ DEN); ZMP; CKK227; B744; ANCORD; HQ DEN approved deviation vector off route to meet ZAU 30 mile in trail requirement.

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/01/2013

Element: ALL Created by: RGotz,

Created on: 04/02/2013 0404Z

Checked by: RV

Log:	
Time (UT	© Remarks
2046	NORDO,PAGED; ATSC (NCRCC); PCT; N880DB; SR22; CPCHZL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. ADW runway alert. Communications re-established at 2047. ADW stood down. NFA.
2058	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); NCT; VRD927; A320; LAXSFO; Passenger medical emergency.
2100 2101 2105 2107	EMERGENCY; ATSC (FAA HQ DEN); N90; UAL366; B763; IAHEWR; Low fuel. Aircraft landed at 2104. COD; ATSC (FAA HQ DEN); ZMA; LMO6429; C208; MYATOPF New Destination: FLL; Company request. COD; ATSC (FAA HQ DEN); ZJX; EJA726; GALX; PDKMIA New Destination: SSI; Company request.
21107	NORDO; ATSC (FAA HQ DEN); ZTL; SLI0637; E190; ATLMMMX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. Communications re-established at 2113.
2118 2138	B3; 49 U.S.C. 114 (r) TOI-US ADIZ,PAGED,TOI; ATSC (CONR/AOC); (b) (7) (a) & (e)
	(b) (7) (a) & (e) (b) (7) (a) & (e)
2144 2145 2200	
2210 2211	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; AA1692; B738; MMUNDFW; Sick passenger.
2222 2250	EMERGENCY, COD; ATSC (FAA HQ DEN); ZID; JZA7896; DH8D; CMHCYYZ New Destination: CMH; Unstable engine. At 2255 CMH advised aircraft declared emergency. Aircraft landed at 2258.
2306 2314	NORDO; ATSC (FAA HQ DEN); ZBW; JBU1017; E190; BOSJFK; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2309. COD; ATSC (FAA HQ DEN); ZAN; FDX84; MD11; ANCMEM New Destination: ANC; Bleed air problem.
04/02/201 0000	3 B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r)
0001 0025	B37, 49 U.S.C. 134 (r) COD, ATSC (FAA HQ DEN); ZAU; ASQ5642; CRJ7; ATLMSP New Destination: DSM; Pilot request. NORDO; ATSC (FAA HQ DEN); EADS; N9529W; C172; EKXBWG; 7600 code observed 20SW Louisville; ZID investigating. 0027 SDF TRACON advised that IFR clearance was issued, but PIC squawked 7600 immediately after takeoff. Aircraft appears to be continuing on to destination. 0048 BWG FBO advised PIC is in comm via cellphone.
0038 0048	COD; ATSC (FAA HQ DEN); ZJX; VNR195; P180; BEDRSW New Destination: JAX; Company request. COD; ATSC (FAA HQ DEN); ZSE; AMF1991; PA31; LMTCVO New Destination: PDX; Company request.
0100 0117	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZNY; AFR695; B744; MIALFPG New Destination: BOS; Captain of the aircraft with medical issues. Aircraft landed at 0301.
0122 0133	COD; ATSC (FAA HQ DEN); ZBW; FDX1254; B752; PVDFWA New Destination: BOS; Company request. LASER; ATSC (FAA HQ DEN); CVG; N1PG; GLF4; LUKTEB; At 0055, N1PG reported the cockpit was illuminated by a green LASER, at 3,400 feet 3.5 miles west of Clermont County Airport, heading northwest,

Page 5



Date: 04/01/2013

Element:	Created by:	Created on:	Checked by:
ALL	RGotz,	04/02/2013 0404Z	RV

Log:	
Time (UTC	Remarks
	LASER at 12 O'clock from intersection of State Route 32 and Interstate 275. No injuries reported.
	(b) (7) (a) &(e)
0145	LASER; ATSC (FAA HQ DEN); ZMA; AAL850; B738; MIA. IAD; At 0125 aircraft reported cockpit was
	illuminated by a green LASER, at 14,300 feet on the FLL285016, northbound, from the 12 O'clock position. No injuries reported. (a) (7) (a) (e)
0147	COD; ATSC (FAA HQ DEN); ZTL; GJS6304; CRJ7; CHSSTL New Destination: BNA; Fuel stop.
0150	LASER; ATSC (FAA HQ DEN); ZMA; AAL1616; B738; MIA. DCA; At 0130 aircraft reported cockpit was
0.00	illuminated by a green LASER, at 12,000 feet on the FLL275018, northbound, from the left side. No injuries
	reported. (b) (7) (a) & (e)
0156	LASER; ATSC (FAA HQ DEN); ZTL; N68842; C172; K18AVFR; At 0125 aircraft reported cockpit was
	illuminated by a green LASER, at 5,000 feet, 3.3 miles south of K18A, eastbound, from the right side. No
	injuries reported.
0200	<u> </u>
0200	
0215 0221	COD, EMERGENCY; ATSC (FAA HQ DEN); ZDC; SIL4064; SF34; IADMGW New Destination: IAD; Hydraulic
0221	failure. Aircraft landed 0318. 0338: Aircraft unable to taxi to the gate and UAL unable to provide a tow bar.
	Passengers deplaned to mobile lounge on the runway.
0235	B3; 49 U.S.C. 114(x)
	B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r)
0249	LASER; ATSC (FAA HQ DEN); PCT; SWA3573; B737; INDBWI; 0230, 6 miles east of MRB airport, at 11,000
	feet, heading 100 degrees; cockpit illuminated by two green LASERs from a farm house at 2 o'clock. No
0254	injuries reported; (b) (7) (a) 5 (e) LASER; ATSC (FAA HQ DEN); PHX; N131TC; BE9L; 0236 aircraft reported cockpit illuminated by a green
0254	LASER, at 3,000 feet, 8 miles east of PHX, heading 280, from right side of aircraft. No injuries reported.
	(b) (7) (a) & (e)
0312	LASER; ATSC (FAA HQ DEN); BDL; UPS1063; A306; BDLSDF; 0158 aircraft reported cockpit illuminated by
	a green LASER, 6 miles northwest of BDL, heading northwest, at 3,000 feet, from the right side. No injuries
	reported. (b) (7) (a) & (e)
0320	COD; ATSC (FAA HQ DEN); ZAN; PEN255; SF34; ANC. DLG New Destination: ANC; WX,.
0343	LASER; ATSC (FAA HQ DEN); ZBW; ASQ206T; E45X; EWRBTV; 0344, vicinity of Cambridge, NY, at 24,000
	feet, heading northeast; ACFT illuminated by a green LASER from just west of Cambridge VOR. No injuries reported: (b) (7) (a) (e)
0346	reported; (b) (7) (a) & (e) COD; ATSC (FAA HQ DEN); ZAB; AWE140; A319; PHXANC New Destination: PHX; Mechanical issue.
0348	COD; ATSC (FAA HQ DEN); ZTL; UPS9853; B763; MIASDF New Destination: ATL; Company request.
0358	2
0358	LASER; ATSC (FAA HQ DEN); LIT; PSA272; CRJ7; 0248 aircraft reported cockpit illuminated by green LASER
1	at 2,000 feet, 10 miles south of LIT, heading 220, from 11 O'Clock position 8-10 miles. No injuries reported.
	(b) (7) (a) & (e)
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 6

FAA Air Traffic Organization NAS Daily Events Log	'n
---	----

Element:	Created by:	Created on:	Checked by:
ALL	RGotz,	04/03/2013 0404Z	RV

Security Event Statistics:				
EMERGENCY: 18 EMERGENCY- MEDICAL: 11		NORDO: 23 B3; 49 U.S.C. 114(r)	33; 49 U.S.C. 114(COD: 41 LASER: 8 MOR: 2	

Log:	
Time (UTC)	Remarks
04/02/2013	
0400	
0400	
0400 0400	LASER TESTING; ATSC (NCRCC); NCRCC; NASA Goddard Space Center laser ranging operations underway.
0407	B3; 49 U.S.C. 114(r) B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r) B3; 49 U.S.C. 114(r)
0411	LASER; ATSC (FAA HQ DEN); MFE; N192A; HELO; VFRMFE; 0233 aircraft reported cockpit illuminated by a green LASER, at 1,000 feet, 8 miles west of MFE, heading eastbound, laser penetrated from unknown direction No injuries reported. (b) (7) (a) & (e)
0412	NORDO; ATSC (FAA HQ DEN); ZHU; AFR439; B744; MMMXLFPG; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0417.
0415 0421	COD; ATSC (FAA HQ DEN); ZAB; UAL404; A320; IAH. SNA New Destination: TUS; Mechanical issue. LASER; ATSC (NCRCC); PCT; DCM1234; F2TH; PBIDMW; Aircraft reported cockpit illuminated by a green LASER, at 4,000 feet, 5 miles west of EMI, heading NW, laser penetrated from the left,. No injuries reported.
0430 0450	ADMIN; ATSC (FAA HQ DEN); RV off. EMERGENCY,COD; ATSC (FAA HQ DEN); ZLC; DAL2312; B752; SLCANC New Destination: SLC; Engine
0454	issue. Aircraft landed at 0504. EMERGENCY,NOTIFICATION-LATE; ATSC (FAA HQ DEN); N90; ASQ5643; CRJ7; DSMEWR; Smoke in cockpit. Aircraft landed at 0319.
0502	LASER; ATSC (FAA HQ DEN); MEM; FDX1299; MD11; IAHMEM; 0415, 8 miles northeast of UTA, at 6,000 feet, heading northeast; ACFT illuminated by a green LASER (no bearing provided). No injuries reported;
0506	(b) (7) (a) & (e) LASER; ATSC (FAA HQ DEN); MCI; SWA2073; B733; BWIMCI; 0355, 8 miles southeast of MCI, at 5,500 feetheading south; right side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e)
0508	(b) (7) (a) & (e) LASER; ATSC (FAA HQ DEN); P50; AWE288; A319; SJCPHX; 0341, 8 miles southeast of PHX, at 7,000 feet heading east; right side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e)
0513	LASER; ATSC (FAA HQ DEN); S46; ASA755; B738; STLSEA; 0320, 7 miles southeast of SEA, at 10,000 feet heading north; left side of ACFT illuminated by a red LASER. No injuries reported; (b) (7) (a) & (e)

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security. Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/02/2013

Element: Created by: Created on: Checked by: RGotz, 04/03/2013 0404Z RV

Log:	
Time (UTC)	Remarks
0550	
	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); HCF; WJA1864; B737; CYVRHNL; Sick PAX. LASER; ATSC (FAA HQ DEN); PDX; ASA475; B739; LAXPDX; 0653, 4 miles east of PDX, at 1,400 feet, heading west; left side of ACFT illuminated by a green LASER. No injuries reported (b) (7) (a) & (e)
	NORDO; ATSC (FAA HQ DEN); ZKC; UAL824; B752; SFOJFK; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0916.
0937	EMERGENCY,COD; ATSC (FAA HQ DEN); ZTL; FDX1445; B752; MEMCAE New Destination: BHM; Electrical issues. Aircraft landed at 1004.
1000	
1000	
1000	OOD ATOO (TAA HO DEN), OVO, AMERICA CINIA OVO, OMANO NEL DE LE COMO O
1002 1005	COD; ATSC (FAA HQ DEN); CVG; AMF916; SW4; CVGCYWG New Destination: CVG; Gear stuck down.
1005	COD; ATSC (FAA HQ DEN); ZJX; FDX1465; B752; MEM. FLL New Destination: RSW; WX.
1015	COD, ATOC (FACTING DEIT), 20X, FDX 1400, DTS2, MEMTEL NEW Destination, NOVV, VVX.
1015	
1016	COD; ATSC (FAA HQ DEN); ZMA; UPS1348; B752; SDFMIA New Destination: RSW; Weather improved at RSW.
1130	
1140	NORDO; ATSC (FAA HQ DEN); ZAU; ASQ6044; E145; LNKORD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1141.
1200	
1208 1212	NORDO; ATSC (FAA HQ DEN); ZJX; VQBAA; FA7X; GVACHOU; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. Satellite phone available. 1220 ZJX contacted ARINC, ARINC in contact with PIC, will relay frequency. 1227 HQ DEN called satellite phone, no answer. Communications re-established at 1229.
1245	(b) (7) (a) & (e)
	(b) (7) (a) & (e)
	(b) (7) (a) s (e)
	(b) (7) (a) s (e)
1300	CONFERENCES,ADMIN; ATSC (N/NC); TACOPS complete B3; 49 U.S.C. 314 (r)
1300	EMERGENCY, COD; ATSC (FAA HQ DEN); ZAU; CPZ5717; E170; MSPMDW New Destination: ORD; PIC requested longer RY, HQ DEN calling CPZ Dispatch. 1303 CPZ report ACFT has a mechanical issue with brakes. 1306 PIC declared an emergency due to degraded braking. Aircraft landed at 1325.
1333	NORDO; ATSC (FAA HQ DEN); JAX; N517RC; BE36; GNVCLW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1338.
1336	COD; ATSC (FAA HQ DEN); ZLC; SKW4674; CRJ2; MFRSLC New Destination: MFR; Retract gear issue.
1343	(b) (7) (a) % (e) (b) (7) (a) % (e)
	(b) (7) (a) & (e)
	(p) (7) (a) ŝ (e)

Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RGotz,
 04/03/2013 0404Z
 RV


Log:	
Time (UT	C) Remarks
1346	NORDO; ATSC (FAA HQ DEN); ZKC; N123HK; H25B; HOUAPA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1347.
1358	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDC; ASH2681; CRJ9; RICCLT New Destination: GSO; Passenger medical emergency.
1359	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZOB; SWA2520; B737; MHTDEN New Destination: DTW; Sick PAX.
1406	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); DFW; AAL1107; MD83; CLE.,DFW; Sick PAX.
1409	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); GSO; ASH2681; CRJ9; RIC. CLT New Destination: GSO: Sick PAX.
1419	COD; ATSC (FAA HQ DEN); ZMA; EGF3505; E145; MIACVG New Destination: MIA; Bleed valve issue.
1420	COD; ATSC (FAA HQ DEN); ZKC; GLA85D; B190; DENDDC New Destination; LBL; WX.
1421	EMERGENCY; ATSC (FAA HQ DEN); ZKC; FDX820; MD11; MSPMEM; Fuel emergency. Aircraft landed at 1445.
1430	B3; 49 U.S.C. 114(r)
1438	EMERGENCY,COD,NORDO; ATSC (FAA HQ DEN); HTS; N7582H; C182; HTSGKT New Destination: HTS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1446 ZID lost radar contact, HQ DEN lost track. Communications re-established at 1453. PIC declared emergency due to electrical failure. Aircraft landed at 1457.
1438	COD; ATSC (FAA HQ DEN); ZMP; GLA255; B190; MSPDVL New Destination: MSP; Weather.
1456	COD, ATSC (FAA HQ DEN); ZMA; HPJ178; LJ60; OPF. TKPK New Destination: MDST; PAX request.
1508	COD; ATSC (FAA HQ DEN); A11; CON151; B737; ANCUBW New Destination: ANC; Gear will not retract.
1515	B3; 49 U.S.C. 114(r)
1516	
1519	
1534	COD; ATSC (FAA HQ DEN); ZFW; OPT429; BE40; HUMLBL New Destination: EGE; Intermediate fuel stop not required.
1538	NORDO; ATSC (FAA HQ DEN); ZAB; N235TW; P46T; UDDPHX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1546.
1545	B3; 49 U.S.C. 114(v)
1545	TE CONTRACTOR OF THE CONTRACTO
1605	18
1613	COD; ATSC (FAA HQ DEN); ZMA; AWE9241; B734; MIA. CLT New Destination: PHL; Company positioning.
1622	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZOA; ZOA authorized to suspend change of destination reporting for AOR until 1800 due to WX.
1627	MECHANICAL,SIF; ATSC (FAA HQ DEN); A11; VDA2731; A124; ANCAFW; ACFT departing after VDA2731 noticed debris on RY, debris may be from brakes of VDA2731, PIC advised. Aircraft landed at 2254.
1634	NORDO; ATSC (FAA HQ DEN); ZNY; CNS16; PC12; ROC. TEB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1237.
1636	COD; ATSC (FAA HQ DEN); ZAN; ACA7162; B77W; WSSSCYVR New Destination: CYYZ; Company reposition.
1654	COD; ATSC (FAA HQ DEN); ZDV; SKW329T; CRJ7; DENASE New Destination: MTJ; Anti icing equipment failed.
1656	EMERGENCY ; ATSC (FAA HQ DEN); ZSE; TRUCK2; F15; LMTLMT; Cabin pressure issue. Aircraft landed at 1704.
1700	2

Page 3



 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RGotz,
 04/03/2013 0404Z
 RV



Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RGotz,
 04/03/2013 0404Z
 RV

Log:	
Time (UTC)	Remarks
2015 2018	COD; ATSC (FAA HQ DEN); AUS; RAIL63; BE20; AUSGRK New Destination: AUS; Weather. EMERGENCY ; ATSC (FAA HQ DEN); I90; TULSA91; F16; EFDEFD; Engine warning light. Aircraft landed at 2025.
2030 2042	EMERGENCY,COD; ATSC (FAA HQ DEN); ZOB; TCF3500; E170; DTWORD New Destination: DTW; Engine out. Aircraft landed at 2059.
2053	
2118	78
0420	E
2129	
2132 2139	COD; ATSC (FAA HQ DEN); ZOA; VNR178; P180; SFOUDD New Destination: SFO; Company request. At 2207 ZOA advised destination now changed to OAK, per company request.
2142	EMERGENCY ; ATSC (FAA HQ DEN); ZLA; RAIDR50; C130; NKXNKX; Drogue shoot fell off. Aircraft landed at 2200.
2151	EMERGENCY; ATSC (FAA HQ DEN); ZJX; CHECK61; F16; NKTNBC; Check valve issue. Aircraft landed at 2211.
2215	(b) (7) (a) & (e) (b) (7) (a) & (e) (b) (7) (a) & (
2221	COD; ATSC (FAA HQ DEN); ZLA; EJA685; C56X; PHXVNY New Destination: BUR; Company request.
2223	EMERGENCY; ATSC (FAA HQ DEN); DAA; SENTRY7; H60; VFRDAA; Equipment malfunction indication. Aircraft landed at 2224. DAA terminated the emergency at 2237. MK.
2224	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); PBI; JBU581; E190; HPNPBI; Sick passenger.
2226	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZNY; BWA600; B738; TTPPCYYZ New Destination: MYNN; Sick passenger.
2232	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZME; AAL1281; B738; BOSDFW New Destination: LiT; Sick passenger.
2239	COD; ATSC (FAA HQ DEN); ZHU; XSR637; E50P; ALSAUS New Destination: SAT; Weather.
2243	NORDO; ATSC (FAA HQ DEN); ZNY; UAL563; B752; LAXJFK; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2245.
2248	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZHU; ZHU and ZFW authorized to suspend change of destination reporting for western part of their AOR until 0100 due to weather.
2251	NORDO; ATSC (FAA HQ DEN); ZKC; N618KA; C525; RVSFNL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2253.
2256	EMERGENCY ; ATSC (FAA HQ DEN); NCT; N584PC; BE58; NCT advised they observed 7700 code 10 miles south SMF. 2259 NCT advised aircraft was squawking emergency code in error; no further action required.
2301	EMERGENCY ; ATSC (FAA HQ DEN); E10; E10 reported observing aircraft squawking 7700 15 miles southwest of China Lake (NID). 2315 HQ DEN contacted SCT to advise them of the aircraft; they were able to
	locate target and will attempt to identify it. 2348 Unable to identify track, dropped from ADAPT.
2343	COD; ATSC (FAA HQ DEN); ZAB; EJA669; C56X; PHXTUS New Destination: SNA; Company request.
2344	NORDO; ATSC (FAA HQ DEN); ZDV; ELJ72; CL60; CVG36U; Aircraft reported on course, at assigned attitude. Attempting contact on Guard and with Company. Communications re-established at 2344.
2347	NORDO; ATSC (FAA HQ DEN); ZAB; SKW6511; CRJ2; ABQLAX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2357.
2356	COD; ATSC (FAA HQ DEN); NCT; SKW1352; CRJ7; FATSFO New Destination: FAT; Flap problem.
04/03/2013	

Page 5




Element:	Created by:	Created on:	Checked by:
ALL	RGotz,	04/03/2013 0404Z	RV

Log:	
Time (UT	C) Remarks
0024	NORDO; ATSC (FAA HQ DEN); ZOB; ASQ5846; E145; ORDCYQB; Aircraft reported on course, at assigned altitude; NORDO 0+10. Attempting contact on Guard and with Company. Communications re-established at 0025.
0027 0100	COD; ATSC (FAA HQ DEN); ZDV; EJA667; C56X; APATUS New Destination: BJC; Company request.
0124	NORDO; ATSC (FAA HQ DEN); ZMP; FFT535; A318; MDWDEN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with company. Communications re-established at 0126.
0137	NORDO; ATSC (FAA HQ DEN); ZAB; N1999; F2TH; CPSSDL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0138.
0144	EMERGENCY, COD; ATSC (FAA HQ DEN); ZFW; AAL1658; MD82; DFWDAY New Destination: DFW; Engine problem. Aircraft landed at 0207.
0200	
0200 0200	
0200	ADMIN; ATSC (FAA HQ DEN); RS/RV on HQE/HQW.
0215	ADMIN; ATSC (NCRCC); NCRCC; MK off.
0229	NORDO; ATSC (FAA HQ DEN); ZMP; UAL1661; B752; EWRSFO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0230.
0234	B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r)
0235	NORDO; ATSC (FAA HQ DEN); ZID; SWG540; B738; MMBTCYYZ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0243.
0239	EMERGENCY, ATSC (FAA HQ DEN); ZMP; BATT22; K35R; SUXSUX; Engine issue. Aircraft landed at 0322.
0250	LASER; ATSC (FAA HQ DEN); N90; TCF5956; E170; ORDLGA; Aircraft reported a green LASER illuminated the cockpit at 4,000 feet 9 ENE of La Guardia, heading north, from the left side. No injuries reported.
0259	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZKC; AAL2376; MD82; DFW. ORD; Sick passenger.
0301	COD; ATSC (FAA HQ DEN); ZLA; CJZ469; LJ35; HOU. SAC New Destination: SMF; PAX request.
0302	B3; 49 U.S.C. 114(r)
0318	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); 190; 190/ZHU authorized to suspend change of destination reporting for AOR until 0530 due to weather.
0320	NCR-COORDINATION, PAGED; ATSC (NCRCC); Dulles Tower requested approval for QTR052, B773, KIAD-OTBD to depart without an operative transponder. Conferred with ZDC and they were concerned about radar outages enroute. Departure was denied. 0345; QTR052 departed with operative transponder.
0330	COD; ATSC (FAA HQ DEN); ZAB; FIV413; C25B; SATHHF New Destination: AMA; Weather.
0338	COD; ATSC (FAA HQ DEN); ZJX; FDX1339; B752; SAVMEM New Destination: TLH; Company request.
0345	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAN; DAL1089; B752; MSPANC; Sick passenger.
0349	COD; ATSC (FAA HQ DEN); ZAB; EJA608; C56X; FTWPSP New Destination: SMO; Company request.
0359	

Page 6

FAA Air Traffic Organization NAS Daily Events Log					Date: 04/03/2013
Element: ALL	Created by: BSadler,	Created on: 04/04/2013 04	07Z	Checked by: RS	

Security Event Statistics:				
7.E.	26	NORDO: 21	COD: 38	
FILEDOENOV 46	7 B	T.E.	LASER: 3	
EMERGENCY: 10 EMERGENCY- MEDICAL: 7			7F	



Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Mashington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/03/2013

Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/04/2013 0407Z	RS
	L	1	

Log:	
Time (UTC)	Remarks
1122	NORDO; ATSC (FAA HQ DEN); ZOB; ASQ5827; E145; CYOWORD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1128.
1130 1154	COD; ATSC (FAA HQ DEN); ZNY; CHQ6045; E145; LGACLE New Destination: LGA; Pressurization issue.
1200 1220	EMERGENCY; ATSC (FAA HQ DEN); ZHU; SWA2717; B735; TPAHOU; Pressurization system malfunction. Aircraft landed at 1310.
1250	7E
1254	COD; ATSC (FAA HQ DEN); ZJX; DAL1670; DC95; ATLCHS New Destination: AGS; WX.
1255 1258 1258	NORDO; ATSC (FAA HQ DEN); ZJX; VNR161; P180; PDKAPF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1303. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDV; SWA1379; B733; SLCDEN; Passenger medical
	emergency.
1300 1304	NORDO; ATSC (FAA HQ DEN); ZHU; N328JP; PC12; DWH. COT; 7600 squawk observed ADAPT 10 miles W EYQ, HQ DEN asked ZHU to respond. No satellite phone available. Communications re-established at 1308.
1312 1317 1329 1335 1335 1335 1428 1430 1431	COD; ATSC (FAA HQ DEN); ZAB; AMF1792; BE99; LBB. PPA New Destination: AMA; WX. *** COD; ATSC (FAA HQ DEN); ZDC; EJA648; C56X; TTPPFLL New Destination: GSO; Company request. COD; ATSC (FAA HQ DEN); LFT; ASQ4094; E145; IADIAH; WX. COD; ATSC (FAA HQ DEN); LFT; FDX1437; B722; MSYLFT New Destination: MEM; WX. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); LFT; LFT authorized to suspend change of destination reporting for AOR until 1800 due to WX. COD; ATSC (FAA HQ DEN); ZAB; CMF815; PA31; PTKBED New Destination: BAF; Fuel. *** *** *** *** *** *** ***
1440 1450	COD; ATSC (FAA HQ DEN); ZSE; SKW5335; E120; SMFACV New Destination: RDD; Weather.
1453	EMERGENCY, COD; ATSC (FAA HQ DEN); ZJX; AAL693; B738; FLLDFW New Destination: ATL; Both speed indicators unreliable. Aircraft landed at 1944.
1500 1516 1521 1524 1534 1543	COD; ATSC (FAA HQ DEN); ZAN; PEN2940; SF34; ANCSDP New Destination: ANC; Possible bird strike. COD; ATSC (FAA HQ DEN); ZDV; AWE153; A320; PHLSAN New Destination: PHX; Company request. COD; ATSC (FAA HQ DEN); SBA; AMF110; PA31; BURSBP New Destination: SMX; WX.
1545	7E

Page 2

	Traffic Organization ily Events Log		
Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/04/2013 0407Z	RS

Log:	
Time (∪	TC) Remarks
1548	
1550	7B
1603	COD; ATSC (FAA HQ DEN); ZFW; EJA385; C680; FSM. PHX New Destination: ICT; Mechanical.
1606	EMERGENCY; ATSC (FAA HQ DEN); ZKC; FLG4102; CRJ2; MEMSTL; Generator failure. Aircraft landed at 1619.
1613	7E
1631	
1633	COD; ATSC (FAA HQ DEN); ZOA; TWY501; GLEX; SJCAGS New Destination: PBI; PAX request.
1652	COD; ATSC (FAA HQ DEN); HCF; AAH4400; SF34; HNLKOA New Destination: HNL; Mechanical.
1654	NORDO; ATSC (FAA HQ DEN); ZAB; N20UA; FA20; FTWTRM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1702.
1700	7E
1700	75
1700	NCR-COORDINATION, ATSC (NCRCC); Military exercise activity within NCR. KLAXON received.
1709	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAB; SCOUT01; E3TF; TIKTIK; Crew member feeling nausea. Aircraft landed at 1805.
1724	NORDO; ATSC (FAA HQ DEN); ZTL; N876FM; SR22; MSY52A; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1731.
1800	
1800	
1800	
1805	
1807	
1807	COD; ATSC (FAA HQ DEN); ZKC; VANDY25; BE40; END. FOE New Destination: END; Mechanical issue.
1810	NORDO; ATSC (FAA HQ DEN); ZKC; N8166J; PA34; DSMLQR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1816.
1813	NORDO; ATSC (FAA HQ DEN); ZFW; FFT702; PA34; DENMSY; Aircraft reported on course, at assigned
1015	altitude. Attempting contact on Guard and with Company. Communications re-established at 1814.
1815	CONFERENCES; ATSC (CONR/AOC); CFACC convened for Preamble of FDC NOTAM 3/8738 for VIP movement to Denver, CO.
1815	
1834	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZMP; UAL726; B752; LAXJFK New Destination: DSM; Male PAX heart attack. 1931 DSM ATCT confirms PAX did pass away.
1900	2
1906	NORDO; ATSC (FAA HQ DEN); ZOB; N559DM; H25B; BEHHPN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1913.
1915	76
	रह
	ਾਰ
1917	NORDO: ATSC (NCRCC): PCT: N997M.I: PA46: I40. CGS: Aircraft reported on course, at assigned altitude.

Page 3

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552





	· · · · · · · · · · · · · · · · · · ·		
Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/04/2013 0407Z	RS

Log:	
Time (∪⁻	C) Remarks
1920	Attempting contact on Guard. No satellite phone available. Communications re-established at 1924. NORDO; ATSC (FAA HQ DEN); ZFW; N340SP; C25A; DALRNO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1927.
1927 1935	COD; ATSC (FAA HQ DEN); ZBW; EJA696; C56X; TEBBOS New Destination: BTV; Mechanical.
1935 1941	NORDO; ATSC (FAA HQ DEN); ZMA; N493RP; C56X; TJIGOPF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2002.
1958 2000	NORDO; ATSC (FAA HQ DEN); ZNY; TWY24; GLF5; OPFCYUL; Aircraft reported on course, at assigned
2005	altitude. Attempting contact on Guard and with Company. Communications re-established at 2007. COD; ATSC (FAA HQ DEN); ZNY; EJA935; C750; BFITEB New Destination: EWR; Due to winds at TEB.
2014 2019	COD; ATSC (FAA HQ DEN); ZOB; EJA122; BE40; HPNMDW New Destination: UES; Company request. NCR-COORDINATION; ATSC (NCRCC); PCT; PCT had report from Cessna Citation that a large fire on the ground at the DCA236026 was growing larger and no apparent ground effort was being initiated to combat fire. NYG ATCT was queried on the DEN and they report fire personnel were on the way to combat fire.
2022	OTHER; ATSC (FAA HQ DEN); TMB; N3101H; R44; TMBTMB; Tower reported the aircraft crashed 2 miles east of the airport, no response from pilot. Two other helos circling overhead the accident site, response vehicles enroute, ROC notified.
2024	EMERGENCY ; ATSC (FAA HQ DEN); GSB; TITAN13; F15; GSBGSB; Electrical failure. Aircraft landed at 2030.
2033	COD; ATSC (FAA HQ DEN); ZHU; RPN416; B734; MDTfAH New Destination: AEX; WX improving. Original destination.
2041	2
2101	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); SLC; AAL1006; MD83; PDXDFW New Destination: SLC: PAX heart attack.
2103	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZHU; ZHU authorized to suspend change of destination reporting for AOR until 2400 due to WX/ thunderstorms.
2112	SIF: ATSC (FAA HQ DEN); ZMP: ABW301; B744; UUEE. ORD; Drifted off course, back on course by ZMP.
2121	COD; ATSC (FAA HQ DEN); ZKC; MRC85; C525; MKCFYV New Destination: ELD; Fuel.
2122	COD; ATSC (FAA HQ DEN); ZSE; CONDR26; SW4; TCM. PDT New Destination; PSC; PIC request.
2129	EMERGENCY, COD; ATSC (FAA HQ DEN); ZAB; N9915Y; C210; ALS. IPL New Destination: GXF; Turbo OTS. Aircraft landed at 2132.
2140	78 78
	76
2146	
2154 2155	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLA; SWA602; B738; BWILAS; PAX throwing up, sick. NORDO; ATSC (FAA HQ DEN); ZJX; N42766; C182; CHALRQ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2209.
2156	Gladde, Alternating contact on Search the eatening phone are industries. Communications to complicing at 2200,
2158	
2210	ng .
2211	TYP

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552





Page 5


Date:

04/03/2013



Date: 04/03/2013

Element: Created by: Created on: Checked by: BSadler, 04/04/2013 0407Z RS



Page 6

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552.



1

Date: 04/04/2013

7			
Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/05/2013 0408Z	RS

Security Event Statistics:			
EMERGENCY: 13 EMERGENCY- MEDICAL:	NORDO: 14	COD: 27 LASER: 15	
14			

Log:	
Time (UTC	Remarks
04/04/2013	
0400	
0400	
	7F
	. TK
0400	LASER OPERATION; ATSC (NCRCC); NCRCC; NASA Goddard Space Center LASER ranging operations underway.
0400	
0403 0411	COD; ATSC (FAA HQ DEN); ZMP; EJA918; C750; BDLBFI New Destination: FAR; Oil pressure issue. LASER; ATSC (FAA HQ DEN); PDX; SWA733; B737; DENPDX; 0346, 3 mile final for RY28L, at 1,500 feet;
V411	left side of ACFT illuminated by a green LASER. No injuries reported;
0414	LASER; ATSC (FAA HQ DEN); NCT; AMF1461; BE99; UKIMHR; 0313, vicinity of McClellan Airport, at 3,000
	feet, heading west; left side of cockpit illuminated by a green LASER. No injuries reported;
0417	LASER; ATSC (FAA HQ DEN); PHL; UPS1139; B752; SYRPHL; 0305, 20 miles north of PHL, at 9,000 feet, heading south; left side of cockpit illuminated by a green LASER. Captain reported eye pain for 30 seconds;
	T-F
0426	LASER; ATSC (FAA HQ DEN); PDX; QXE632; DH8D; SMFPDX; 0412, 5 miles east of PDX, at 1,800 feet, heading west; left side of cockpit illuminated by a green LASER. No injuries reported;
0429	LASER; ATSC (FAA HQ DEN); SAT; UAL442; A320; EWR., SAT; 0400, 16 miles southeast of SAT, at 3,000
0.120	feet5, heading southwest; left side of ACFT illuminated by a green LASER. No injuries reported;
0441	LASER; ATSC (FAA HQ DEN); P50; DAL8893; B752; SFOPHX; 0321, 3 miles east of PHX, at 2,100 feet,
0441	heading west; left side of ACFT illuminated by a green LASER. No injuries reported;
0452	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDV; JBU677; A320; JFKLAX New Destination: DEN;
0541	Sick PAX.
	7E
0550 0603	
10000	Page 1

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552




Date: 04/04/2013

Element: Created by: Created on: Checked by: BSadler, 04/05/2013 0408Z RS

Loa: Time (UTC) Remarks 0622 LASER: ATSC (FAA HQ DEN); ZOA; JBU90; A320; OAK..JFK; 0550, vicinity of SAC, climbing through 19,000 feet, heading northeast; left side of ACFT illuminated by a green LASER. No injuries reported: COD; ATSC (FAA HQ DEN); NCT; AMF107; BE99; BUR, OAK New Destination; HWD; Company request. 0716 NORDO; ATSC (NCRCC); ZDC; LN317TT; LJ35; TPA., IAD; Aircraft reported on course, at assigned altitude. 0731 Attempting contact on Guard. Communications re-established at 0732. 1000 1000 1000 1000 1000 1015 1021 NORDO; ATSC (FAA HQ DEN); ZOB; ABX552; B763; CVG..JFK; Aircraft reported on course, at assigned 1037 altitude. Attempting contact on Guard and with Company. Communications re-established at 1840. 1105 1130 1136 EMERGENCY,COD; ATSC (FAA HQ DEN); ZDC; EGF3554; E145; RIC..MIA New Destination: RIC; Smoke in 1143 cabin. Aircraft landed at 1200. 1145 1200 NORDO; ATSC (FAA HQ DEN); ZFW; GJS3616; CRJ7; AUS..ORD; Aircraft reported on course, at assigned 1203 altitude. Attempting contact on Guard and with Company. Communications re-established at 1204. 1217 EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZNY; JBU1251; E190; JFK..IAD; Flight Attendant with possible broken arm caused by wake turbulence when following B777 on final. 1220 COD: ATSC (FAA HQ DEN); ZHU: ASQ4634; E135; LRD..IAH New Destination; LRD; Small animal lose in cabin. 1258 EMERGENCY: ATSC (FAA HQ DEN); ZBW; CHQ6137; E145; LGA..CYUL; Electrical emergency impacting 1304 radio communications. Aircraft landed at 1343. 1330 1330 1330 COD: ATSC (FAA HQ DEN); SBA; AMF1944; SW4; BUR .SMX New Destination: SBA; Weather. 1345 1356 NORDO; ATSC (FAA HQ DEN); ZMA; N300TS; MU30; PBI. MDLR; Aircraft reported on course, at assigned 1357 altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1408. 1400 EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; TRS10; B712; ATL..MEM; Passenger medical 1407 emergency.

Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552




Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/05/2013 0408Z	RS

Log:	
Time (UTC)	Remarks
1410	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; SWA365; B737; DTWSTL; Passenger medical
1419	emergency. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZJX; ZJX authorized to suspend change of destination reporting for AOR until 2000 due to WX. 1853 Extended to 2300.
1432	COD; ATSC (FAA HQ DEN); ZKC; GJS3614; CRJ7; ORD. AUS New Destination: STL; Mechanical.
1436	EMERGENCY; ATSC (FAA HQ DEN); ZHU; UAL1023; B735; MMMXIAH; Asymmetrical flap configuration. Aircraft landed at 1507.
1454	EMERGENCY; ATSC (FAA HQ DEN); S56; DAL1408; A320; OAKSLC; Asymmetrical slat configuration. Aircraft landed at 1459.
1500	
1500	
1502	6
1503	
1506	COD; ATSC (FAA HQ DEN); ZJX; ASQ5034; CRJ2; ATLTLH New Destination: ATL; Company request.
1508	NORDO; ATSC (FAA HQ DEN); IND; N73FS; PA34; KY8D98; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1517.
1516	SIF; ATSC (FAA HQ DEN); ZMA; AFL154; A332; UUEE. MMUN; Deviating around weather. (JV).
1530	7g
1510	
1546	
1550 1608	NORDO; ATSC (FAA HQ DEN); ZAU; DAL824; B752; PHX. DTW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1609.
1610	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMA; ZMA authorized to suspend change of destination reporting for AOR until 2000 due to WX.
1619	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZTL; EJM525; PRM1; PBISDF; Passenger medical emergency.
1620	COD; ATSC (FAA HQ DEN); ZMA; SWA1977; B737; TPAEYW New Destination: TPA; Mechanical.
1700	
1700	75
1702	NORDO; ATSC (FAA HQ DEN); ZAB; N4190E; PA32; AVQUDD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1704.
1703	NORDO; ATSC (FAA HQ DEN); ZAU; AAY182; A319; IWAGRR; Aircraft reported on course, at assigned attitude. Attempting contact on Guard and with Company. Communications re-established at 1704.
1730	VIP; ATSC (FAA HQ DEN); WOC; N3; C56X; DCAEWR; S1.
1738	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZME; ASQ5416; CRJ2; SGFATL; ZME OMIC Aircraft advised of receiving report from PIC indicating medical issue on aircraft. Subsequently, flight crew reported medical issue involved the PIC, no change of destination requested. Subsequently, another report from the flight crew indicated medical issue with pilot resolved, requested normal handling. ASQ Corporate advised of

Page 3



Element: Created by: Created on: Checked by: BSadler, 04/05/2013 0408Z RS



Page 4



Date: 04/04/2013

Element: Created by: Created on: Checked by: BSadler, 04/05/2013 0408Z RS

Log:	
Time (UTC)	Remarks
2036	EMERGENCY; ATSC (FAA HQ DEN); A80; TRS350; B712; JAXATL; Went around once. Hydraulic issue.
2052	Aircraft landed at 2035.
2053 2056	COD; ATSC (FAA HQ DEN); P50; AWE146; B752; PHXOGG New Destination: PHX; Mechanical.
2100	EMERGENCY, COD; ATSC (FAA HQ DEN); D10; AWE73; A320; DFWPHX New Destination: DFW; Landing gear problem, Aircraft landed at 2113.
2101	EMERGENCY; ATSC (FAA HQ DEN); MIA; YV448T; LJ25; FXEFXE; Possible electrical problem. Aircraft landed at 2112.
2110	VIP; ATSC (FAA HQ DEN); WOC; N3; C56X; LGADCA; S1.
2120	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; AAL288; B772; ZSPDORD; PAX iII.
2130	
2132	
2136	
2138	(b) [7] (a) &(e)
	(b) (7) (a) & (e)
2142	COD; ATSC (FAA HQ DEN); ZTL; LXJ263; LJ60; GSOFTY New Destination: ATL; Company request.
2147	COD, MECHANICAL; ATSC (NCRCC); ZDC; AAL564; B738; MIALGA New Destination: DCA; RIC190032; FL340; COD: Instrumentation issue. NON EMRG. 2220: DCA ATCT reports AAL564 landed without further incident.
2151	COD, EMERGENCY, MECHANICAL; ATSC (NCRCC); ZDC; OAE559; B763; NGUEINN New Destination: BWI; ACY119057; FL380; COD upgraded to EMRG by PCT. OAE559 reported an "Indicator Light" was the reason to divert to BWI. 2213: PCT declared EMRG for OAE559 due to overweight landing at BWI. 2231: OAE559 observed landing BWI without further incident.
2155	B3; 49 U.S.C. 114(r) B3; 49 U.S.C. 114(r) B3; 49 U.S.C. 114(r)
2156	B3; 49 U.S.C. 114(s)
2159	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZAU; ACA590; A320; PHXCYYZ New Destination: ORD; Female flight attendant with severe headache. Aircraft landed at 2215.
2200	ADMIN; ATSC (NCRCC); NCRCC; MK off.
2249	B3; 49 U.S.C. 114(r)
2326	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZKC; AWE1580; B737; IAHCLT New Destination: MSY; PAX ill.
2334	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLC; AAL144; B738; LAXIAD New Destination: SLC; Female PAX vomiting, believed to be heart attack by doctor on board.
2336	NORDO; ATSC (FAA HQ DEN); ZME; N834BA; B737; BFL.CHS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. Satellite phone available. Communications re-established at 2337.
2350	B3; 49 U.S.C. 114(r)
2359	EMERGENCY; ATSC (FAA HQ DEN); CLT; PDT4147; DH8C; ROACLT; Number 2 hydraulic failure. Aircraft landed at 0002.
04/05/2013	
0023	LASER; ATSC (FAA HQ DEN); PBI; JBU143; A320; JFKPBI; Aircraft was illuminated by green laser at 700 feet while E bound 1-2 miles W of PBI. No injuries reported. (b) (7) (a) & (e)
0026 0026	COD; ATSC (FAA HQ DEN); ZHU; EJA683; C56X; SATCKB New Destination: SHV; PAX nosebleed. B3; 49 U.S.C. 114(r) B3; 49 U.S.C. 114(r)

Page 5



Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/05/2013 0408Z	RS

Log:	
Time (UTC)	Remarks
0034	NORDO; ATSC (FAA HQ DEN); ZMP; ASA33; B738; PHLSEA; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 0034.
0100	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off.
0112	EMERGENCY ; ATSC (FAA HQ DEN); ZME; ASQ3805; E145; EWRBNA; Loss all fuel indicators. Aircraft landed at 0133.
0114	COD; ATSC (FAA HQ DEN); ZMA; EJA941; C750; PBIFHB New Destination: RSW; Company request.
0116	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZKC; AAL1391; B752; MIADEN New Destination: TUL; PAX difficultly breathing.
0121	LASER; ATSC (FAA HQ DEN); N90; AAL1762; B738; JFK. BOS; Aircraft was illuminated by green laser on left
	side at 4,800 feet while heading NE 7 miles NE of JFK. No injuries reported. (b) (7) (a) (e)
ļ	(b) (7) (a) & (e)
0125	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); HNL; HAL449; A332; HNLRJBB New Destination: HNL; Female PAX with problems breathing.
0127	EMERGENCY; ATSC (FAA HQ DEN); TPA; SWA380; B737; ISPTPA; Flap issue, emergency declared by
	ATC. Aircraft landed at 0144.
0131	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); HNL; UAL112; B753; LAXHNL; Female PAX with asthma.
0200	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW.
0200	ADMIN; ATSC (NCRCC); NCRCC; SH off.
0200	ADMIN; ATSC (FAA HQ DEN); JF off.
0213	MECHANICAL; ATSC (FAA HQ DEN); N90; JZA7745; CRJ2; EWRCYUL; Bird strike.
0215	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW/NCRCC.
0217	COD; ATSC (FAA HQ DEN); ZLA; FDX3785; A306; IND. LAX New Destination: RNO; Company request.
0218	LASER; ATSC (FAA HQ DEN); JAX; N392ER; C172; DABCRG; 0040, 11 miles southeast of St. Augustine, at 5,000 feet, no heading provided; ACFT illuminated by a green LASER. No injuries reported; (5) (7) (a) & (e)
0231	LASER; ATSC (FAA HQ DEN); IND; TCF3442; E170; ORD., IND; 0135, 8 miles northeast of IND, at 4,000 feet,
0201	heading southeast; right side of cockpit illuminated by a green LASER 3 times. No injuries reported;
0235	
0233	B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r) B3; 49 U.S.C. 114(r)
0235	NORDO; ATSC (FAA HQ DEN); ZAB; N31HD; C525; IWADAL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0237.
0240	LASER; ATSC (FAA HQ DEN); SAT; AAL1883; MD82; DFWSAT; 0215, 9 miles east of SAT, at 4,800 feet, heading south; right side of ACFT illuminated by a green LASER multiple times. No injuries reported;
0249	EMERGENCY; ATSC (FAA HQ DEN); XNA; ASQ4980; CRJ2; ATLFSM; Nose gear issue. Aircraft landed at 0244.
0259	MECHANICAL; ATSC (FAA HQ DEN); ZBW; JBU484; A320; LASBOS; Nose gear light issue.
0314	LASER; ATSC (FAA HQ DEN); MCI; AWE1047; A319; CLTMCI; 0256, 8 miles south of MKC, at 5,000 feet,
	heading northwest; left side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e) (b) (7) (a) & (e)
0335	COD; ATSC (FAA HQ DEN); ZNY; UPS9321; B752; PHLSYR New Destination: PHL; Company request.
0352	COD; ATSC (FAA HQ DEN); CHS; ASH2716; CRJ9; CLTCHS New Destination: CLT; WX.
0353	LASER; ATSC (FAA HQ DEN); TPA; SWA906; B733; BWITPA; 0329, 2 miles north of TPA, at 700 feet, heading south; left side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e)
0354	LASER; ATSC (FAA HQ DEN); HRL; SWK471R; CRJ1; IAHHRL; 0318, 4 miles northwest of HRL, at 2,000

Page 6

FOR OFFICIAL USE ONLY



Date: 04/04/2013

Element: Created by: ALL BSadler,	Created on: 04/05/2013 0408Z	Checked by: RS
-----------------------------------	------------------------------	-------------------

Log:	
Time (UTC)	Remarks
	feet, heading southeast; cockpit illuminated by a green LASER from 12 o'clock. No injuries reported;
	(b) (7) (a) & (e) (b) (7) (a) & (e)
0357	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZHU; FLG3417; CRJ9; DTWAUS; Sick FA. Aircraft landed
	at 0353.
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 7

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/05/2013

Element: Created by: Created on: Checked by: CWard, 04/06/2013 0402Z CU

Security Event Statistics:

B3; 49 U.S.

B3; 49 U.S.C. 114

EMERGENCY: 8

EMERGENCY- MEDICAL:

18

NORDO: 32

B3; 49 U.S.C. 114 (x)

B3; 49 U.S.C. 114 (x)

MOR: 3

e"	
Log:	
Time (UT	Remarks
04/05/201	3
0400	ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC.
0400	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW/NCRCC; WCLC. CFPL: None.
0442	LASER; ATSC (FAA HQ DEN); CRP; FDX1265; DC10; HRLMEM; 0415, 5 miles northeast of HRL, at 5,000 feet, heading north; right side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e)
0458	(b) (7) (a) a (e) COD; ATSC (FAA HQ DEN); ZHU; SLI0476; E190; MMMXIAH New Destination: MMMY; Customs closed.
0513	NORDO; ATSC (FAA HQ DEN); ZLA; UAL1544; B735; IAHONT; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 0513.
0550	ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN.
0609	LASER; ATSC (FAA HQ DEN); P50; N928PA; P28A; VFRCHD; 0528, 3 miles east of CHD, at 3,000 feet,
	heading east; right side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e)
2004	(b) (7) (a) & (e)
0621	LASER; ATSC (FAA HQ DEN); MIA; LF1; B06; VFRFLL; 0417, 10 miles southwest of FLL, at 700 feet, heading north; cockpit illuminated by a green LASER. No injuries reported; (b) (7) (a) 8 (e)
	(b) (7) (a) & (e)
0630	LASER; ATSC (FAA HQ DEN); PDX; SWA331; B737; LASPDX; 0548, 4.5 miles east of UAO, at 10,000 feet,
	heading north; front left side of ACFT illuminated by a green LASER. No injuries reported (b) (7) (a) 8 (e)
	(b) (7) (a) & (e)
0633	LASER; ATSC (FAA HQ DEN); PDX; NKS245; A319; SAN. PDX; 0548, 4.5 miles east of UAO, at 10,000 feet,
	heading north; front left side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e)
0637	(5) (7) (a) § (e) LASER: ATSC (FAA HQ DEN); P50; N928PA; P28A; VFRIWA; 0347, 2 miles southeast of IWA, at 2,400 feet.
0637	heading northeast; left side of ACFT illuminated by a green LASER. No injuries reported; (a) (a) (b)
	(b) (7) (a) & (e)
0659	LASER; ATSC (FAA HQ DEN); PDX; SKW899L; CRJ7; SFOPDX; 0605, 4.5 miles east of UAO, at 10,000 feet,
	heading north; left side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e)
	(b) (7) (a) & (e)
0706	LASER; ATSC (FAA HQ DEN); PDX; ASA626; B737; LASPDX; 0615, 4.5 miles east of UAO, at 10,000 feet,
	heading north; left side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e)
0709	(b) (7) (a) & (e) LASER; ATSC (FAA HQ DEN); PDX; ASA475; B734; LAXPDX; 0625, 4.5 miles southeast of UAO, at 10,000
0709	feet, heading north; left side of ACFT illuminated by a green LASER. No injuries reported; (δ) (7) (a) ω(e)
	(b) (7) (a) & (e)
0710	OTHER, LASER; ATSC (FAA HQ DEN); Due to repeated LASER reports 4.5 miles east of UAO, which appears
	to be Canby, OR; HQ DEN contacted the Canby PD (b) (7) (a) & (e) and requested their assistance.
	Canby PD advised their PD vehicles will be watching for LASER activity directed against ACFT during their over
	night patrols.

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/06/2013 0402Z	CU

Log:	
Time (UTC)	Remarks
0715	LASER; ATSC (FAA HQ DEN); L30; AAL1115; B752; MIALAS; 0650, 5 miles east northeast of LAS, at 4,000 feet, heading west southwest; right side of ACFT illuminated by a green LASER. No injuries reported;
0740	(b) (7) (a) & (e) COD; ATSC (FAA HQ DEN); MEM; FDX1380; B752; FATMEM New Destination: STL; Equipment issue. 0752 ACFT changing to BNA at company request.
0832	LASER; ATSC (FAA HQ DEN); D01; SWA1251; B737; PHXDEN; 0748, 16 miles west of DEN, at 11,000 feet, heading northeast; left side of ACFT illuminated by a green LASER. No injuries reported; (b) (7) (a) & (e)
0916	COD; ATSC (FAA HQ DEN); MEM; FDX1468; MD11; MEM. OAK New Destination; MEM; Engine issue,
0917	COD; ATSC (FAA HQ DEN); ZTL; LBQ870; BE58; LZUROA New Destination: LYH; Company request.
0943	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZTL; AWE1660; A320; PDXCLT; Sick PAX.
1000	ADMIN; ATSC (FAA HQ DEN); RS off.
1000	ADMIN; ATSC (FAA HQ DEN); CW on HQE/HQW. WCLC.
1000	ADMIN; ATSC (NCRCC); VP on duty, CFPL: NASA Goddard LASER operations in progress. WCLC.
1010	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZJX; ZJX authorized to suspend change of destination reporting for AOR until 1800 due to weather/T.
1044	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; UAL1190; B739; PITORD; Female PAX in/out of consciousness.
1117	ADMIN; ATSC (FAA HQ DEN); JV on HQC. Off at 1145.
1123	NORDO: ATSC (FAA HQ DEN): FWA: N137D: C310; FWA. DSM; Aircraft reported on course, at assigned
1120	altitude, Attempting contact on Guard. No satellite phone available. Communications re-established at 1129.
1130	ADMIN; ATSC (CONR/AOC); PM on.
1133	ADMIN; ATSC (CONR/AOC); WCLC.
1200	ADMIN; ATSC (N/NC); KN on. Briefed by HQ. WCLC.
1212	EMERGENCY, NOTIFICATION-LATE, COD; ATSC (FAA HQ DEN); CVG; EGF4369; E145; CVG. ORD New Destination; CVG; Aircraft landed at 1211 after declaring EMERG for smoke in the cockpit.
1245	ATC FACILITY; ATSC (FAA HQ DEN); ZOB; Selfridge (MTC) declared ATC Alert due to a RADAR trigger.
1252	CONFERENCES; ATSC (N/NC); TACOPS conference complete. VIP status and movements, no-fly, future reentry and NCR activity discussed.
1255	NORDO; ATSC (FAA HQ DEN); ZMA; N248J; PAY2; TMBTJBQ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1303.
1305	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMA; ZMA authorized to suspend change of destination reporting for AOR until 1800 due to weather/T.
1320	EMERGENCY ; ATSC (FAA HQ DEN); ZTL; DAL1932; B752; JAXATL; Pressurization and hydraulic issues. Aircraft landed at 1351; disabled on runway. ATCSCC advised.
1335	EMERGENCY, COD; ATSC (FAA HQ DEN); M03; N7FE; LJ45; MEMIAD New Destination: MEM; Flight control issues: aircraft holding to burn fuel. EMERG cancelled at 1407.
1338	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZTL; AWE1053; B734; PVDCLT; Female PAX with allergic reaction.
1357	NORDO; ATSC (FAA HQ DEN); ZAU; UAL397; B752; JFKSFO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1358.
1400	ADMIN; SOSC (FAA HQ); MS on SOSC2, briefed by YZ.
1400	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1410	B3; 49 U.S.C. 114 (r)
1416	NORDO; ATSC (FAA HQ DEN); ZBW; SCX251; B737; MSP. BOS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1418.
1417	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); P50; ACA1290; A320; PHX. CYYZ New Destination: PHX; Male PAX with chest pains.

Page 2



Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/06/2013 0402Z	cu

Log:	
Time (U1	C)Remarks
1425	NORDO; ATSC (NCRCC); ZDC; AWI3991; CRJ2; PVDDCA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. B3; 49 U.S.C. 114 (p)
1443	NORDO; ATSC (FAA HQ DEN); ZKC; UPS2859; B763; PHXSDF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1445.
1508	COD; ATSC (FAA HQ DEN); NCT; SKW5539; CRJ2; SFOSLC New Destination: SFO; Pressurization problem.
1520	NORDO; ATSC (FAA HQ DEN); N518SP; C172; FNTBTL; 7600 code observed 55SW Flint (FNT); previous 4340 code. HQ DEN contacted FNT Approach who identified aircraft. Aircraft has reversed course and appears to be returning to FNT. Aircraft landed at 1601.
1541	B3; 49 U.S.C. 114(r)
1544	NORDO; ATSC (FAA HQ DEN); ZHU; RWG420; CVLT; ELPMMIO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1548.
1544	NORDO,MOR; ATSC (FAA HQ DEN); ZHU; N7YR; PC12; HOUBKS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1610. ZHU issuing PIC Brasher and contact number for I90.
1545	ADMIN; ATSC (NCRCC); NCRCC; MK off.
1608	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZOB; CPZ5710; E170; BWIMSP New Destination: DTW; Sick passenger.
1630	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZNY; DLH400; A346; EDDFJFK; Non-specific PAX medical
1638	B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r)
1638	NORDO; ATSC (FAA HQ DEN); ZDC; CGPOT; F900; TTPPPWK; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1650.
1644	COD; ATSC (FAA HQ DEN); GSP; CHQ6062; E145; GSPDTW New Destination: GSP; Minor mechanical.
1652	B3; 49 U.S.C. 114(r) B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r)
1655	NORDO; ATSC (FAA HQ DEN); ZDC; JBU372; A320; FLLLGA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. B3; 49 U.S.C. 114(r)
1704	COD; ATSC (FAA HQ DEN); MIA; AWE9170; B734; MIACLT New Destination: FLL; Pick up PAX due to a broken aircraft.
1710	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); TPA; DAL1502; MD88; CVGTPA; Non-specific PAX medical.
1710	EMERGENCY; ATSC (FAA HQ DEN); ZTL; SKIER00; C130; SCHVPS; Engine out. Aircraft landed at 1745.
1710	NORDO; ATSC (FAA HQ DEN); A80; N735PW; C182; HKYPQL; Aircraft reported on course, at assigned aftitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1712.
1713	COD; ATSC (FAA HQ DEN); ZMA; FIV521; C56X; PBIMDW New Destination: MCO; Pressurization problem.
1721	NORDO; ATSC (FAA HQ DEN); ZDC; ASH3768; CRJ7; IADPVD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications reestablished at 1723.

Page 3



Element:	Created on	Charled but	
	Created by:	Created on:	Checked by:
ALL	CWard,	04/06/2013 0402Z	CU
		{	

Log:	
Time (UT	C) Remarks
1729	NORDO; ATSC (FAA HQ DEN); ZKC; UAL7; B772; IAHRJAA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1731.
1745	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1745	B3; 49 U.S.C. 114 (r)
1800	ADMIN; ATSC (FAA HQ DEN); GR on HQE/HQW. WCLC.
1800	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1900: WCLC.
1800	ADMIN; ATSC (NCRCC); VP off duty.
1806	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZNY; UAL1053; B738; SAN. EWR; Sick passenger.
1810	ADMIN; ATSC (FAA HQ DEN); CW off.
1816	NORDO; ATSC (FAA HQ DEN); JAX; N132DS; DA20; DAB. DAB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1826.
1823	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZLA; ASA224; B739; SFOMMPR New Destination: LAX; Sick passenger.
1829	NOTAM,VIP; SOSC (FAA HQ); FDC NOTAM 3/0012 & 3/0012 published: B3; 49 U.S.C. 114(r)
1850	EMERGENCY, COD; ATSC (FAA HQ DEN); ZHU; N4366Z; P46T; IWSNEW New Destination: IWS; Instrumentallure. Aircraft landed at 1912.
1854	COD; ATSC (FAA HQ DEN); ZMA; EGF3590; E145; MIAMYEH New Destination: MIA; Weather.
1907	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZHU; UAL1546; B737; MMCZIAH; Sick passenger.
1928	NORDO; ATSC (FAA HQ DEN); TRI; N828LE; SR22; CMH. BNL; Aircraft reported on course, at assigned attitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1936.
1930	ADMIN; ATSC (CONR/AOC); CONR combined to NORAD. PM off.
1945	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; AAL2275; MD82; BNADFW; Sick passenger.
1950	NORDO; ATSC (FAA HQ DEN); ZTL; ASH2612; CRJ9; CLTAGS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1951.
2030	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. Briefed by KN.
2033	EMERGENCY; ATSC (FAA HQ DEN); MEI; N196EC; E50P; DTSMEI; Aircraft landed at 2019, upon landing blew both main landing gear tires. Aircraft disabled on runway. No injuries reported. 2213 Runway re-opened. EMERGENCY- MEDICAL.COD; ATSC (FAA HQ DEN); ZMP; SKW4475; CRJ2; MSPISN New Destination:
2045	MOT; Sick passenger.
2051	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; EGF3873; CRJ7; DCAORD; Sick passenger.
2052	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDC; AAL2254; MD82; DFWORF; Sick passenger.
2107	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); NCT; AAL1629; MD83; DFWSJC; Sick passenger.
2111	EMERGENCY, COD; ATSC (FAA HQ DEN); OMA; SNOOP55; R135; OFFOFF New Destination: LNK; Mechanical problem. Aircraft landed at 2134.
2121	COD; ATSC (NCRCC); ATL; VNR179; P180; PDKSUA New Destination: PDK; Trim issue.
2123	NORDO; ATSC (NCRCC); ZDV; HORNT74; V22; OGDCVS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. Communications re-established at 2124.
2124	NORDO; ATSC (NCRCC); ZSE; N851MA; TBM7; BFFUAO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. Communications re-established at 2128.
2125	NORDO; ATSC (NCRCC); HTS; N1626W; BE33; AOHCBE; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. Communications re-established at 2129.
2126	NORDO; ATSC (NCRCC); EADS; N711KK; PA30; VFRI39; Communication Failure: Aircraft is on code 7600 and ZID reports it is landing I39 awaiting downtime. 2214 ZID reported aircraft landed safely.
2146	CONFERENCES: ATSC (N/NC); CONR; CFACC test successful.
2150	B3; 49 U.S.C. 114(r)
	B3; 49 U.S.C. 114(r)

Page 4



Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/06/2013 0402Z	CU

Log:	
Time (UTC)	Remarks
	code is N6851T, C441 landing FDK. ADW is standing down.
2151	83; 49 U.S.C. 114(0)
	B3; 49 U.S.C. 114(r)
2157	B3; 49 U.S.C. 314 (r) WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMP; ZMP authorized to suspend change of destination reporting for AOR until 0359 due to weather.
2159	B3; 49 U.S.C. 114(r) B3; 49 U.S.C. 114(r)
2200 2215	ADMIN; ATSC (NCRCC); NCRCC; MK off. NORDO; ATSC (FAA HQ DEN); ZBW; POE946; DH8D; BOSCYTZ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2222.
2230	NOTAM-VIP,TFR; ATSC (N/NC); FDC NOTAM 3/9374 (b) (7) (a) & (e)
2247	NORDO; ATSC (FAA HQ DEN); ZAB; WOA8530; MD11; ONTGRK; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2254.
2251	B3; 49 U.S.C. 114(x)
2307	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZAN; ERR878; DH8A; ANCHOM New Destination: ANC; Sick passenger.
2314	NORDO; ATSC (FAA HQ DEN); ZOA; ASA458; B738; SEALAX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2315.
2325	NORDO,MOR,PAGED; ATSC (FAA HQ DEN); ZJX; N115MK; AC11; DKXSUA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 2345 ZJX checked tapes, attempting air to air on previous frequencies. 2355 aircraft NORDO +30 minutes. ZJX filed MOR. HQ DEN requested FSOC check flight plan for pilot contact info, none available. FSOC checking with DUATS. 0004 FSOC provided pilot telephone number, HQ DEN attempted contact, got voice mail. Communications reestablished at 0113. Pilot will contact ZJX.
2327	EMERGENCY; ATSC (FAA HQ DEN); SKF; RSTLR1; F16; SKFSKF; Fuel flow problem. Aircraft landed at 2329.
2340	NORDO; ATSC (FAA HQ DEN); ZOB; N525AG; GALX; VNYTEB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2358.
2341	B3; 49 U.S.C. 114(r)
2344	COD; ATSC (FAA HQ DEN); OKC; SKW4705; CRJ2; OKCMSP New Destination: OKC; Mechanical.
2350	NORDO; ATSC (FAA HQ DEN); ZBW; ASA759; B738; BOSSAN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0059.
04/06/2013	
0002	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZID; JBU179; A320; JFKPHX New Destination: CVG;
0005	Sick passenger.
0025 0034	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZNY; AAL1454; B738; TJSJJFK; Sick passenger. NORDO; ATSC (FAA HQ DEN); TPA; CGLBJ; H25B; TPASRQ; Aircraft reported on course, at assigned
0113	altitude. Attempting contact on Guard. No satellite phone available. 0044 aircraft landed SRQ. NORDO; ATSC (FAA HQ DEN); ZAB; RANGR04; C130; NYLNFW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. Communications re-established at 0115.
0200	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC.
0200	NORDO; ATSC (FAA HQ DEN); ZAU; N525BR; C525; ROCSGF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0216.

Page 5



Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/06/2013 0402Z	CU

Log:			
Time (∪	TC) Remarks		
0200	LASER; ATSC (FAA HQ DEN); AUS; GJS3625; CRJ7; DENAUS; Green/Red laser illuminated right side of ACFT at 1,000 feet, 2.5 miles NW Austin. ACFT S bound, no injuries reported.		
0200	ADMIN; ATSC (NCRCC); NCRCC; SH off.		
0208	COD; ATSC (FAA HQ DEN); SJU; FDX58; DC10; TJBQMEM New Destination: TJBQ; Malfunctioning landing gear issue.		
0217	NORDO; ATSC (FAA HQ DEN); ZDC; TRS94; B712; ATLDCA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 0218 EADS placed ADW at RY Alert. Communications re-established at 0218. 0219 ADW standing down.		
0219	COD; ATSC (FAA HQ DEN); ZTL; FLG3814; CRJ9; ATLIAD New Destination: ATL; Maintenance issue.		
0222	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE/NCRCC.		
0239	COD; ATSC (FÀA HQ DEN); ZDV; ASQ6078; E45X; CIDDEN New Destination: COS; Had micro burst at the ARPT, not enough fuel to hold.		
0244	LASER; ATSC (FAA HQ DEN); BNA; C182; MGEBNA; Green laser, left side, illuminated ACFT at 8,500 feet, 4 miles NW Nashville. ACFT WSW bound, no injuries reported.		
0310	LASER; ATSC (FAA HQ DEN); OKC; SWA4452; B737; STLOKC; Green laser illuminated ACFT at 4,000 feet, 10 miles NE Will Rogers. ACFT SSW bound, no injuries reported.		
0359	ADMIN; ATSC (FAA HQ DEN); COB.		

Page 6



Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/07/2013 0405Z	cu

Security Event Statistics:

TOI: 3
TOI-NCR SFRA: 1

EMERGENCY: MEDICAL:
10

AIRPORT: 3
NORDO: 16

COD: 24
LASER: 20
MOR: 2

Log:	
Time (UTC)	Remarks
04/06/2013	
0400	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. CFPL: None.
0400	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE/NCRCC, WCLC. CFPL: NASA Goddard Laser operations in progress.
0404	COD; ATSC (FAA HQ DEN); ZMA; JBU978; E190; FLLBOS New Destination: FLL; Lost of RVSM and Auto- Pilot.
0409	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOA; AAL177; B762; JFKSFO; Sic PAX.
0424	LASER; ATSC (FAA HQ DEN); TPA; PD4; Green, Red, Blue lasers illuminated cockpit at 900 feet, 3 miles E TPA ARPT. Helo in vicinity of local high school covering an event. Helo on patrol, no injuries reported.
0429	COD; ATSC (FAA HQ DEN); ZMP; SWG751; B738; MKJSCYQR New Destination; CYWG; WX.
0431	LASER; ATSC (FAA HQ DEN); BTV; RPA3152; E170; DCABTV; Green laser, on the left side, illuminated cockpit at 3.800 feet, 9 miles SE Burlington. ACFT NW bound, no injuries reported.
0500	LASER; ATSC (FAA HQ DEN); AUS; DAL1837; B752; ATLAUS; Green laser, right side, illuminated ACFT at 2,000 feet, 2 miles NW Austin. ACFT SE bound, no injuries reported.
0521	COD; ATSC (FAA HQ DEN); ZTL; ABX2007; B762; MIACVG New Destination; ATL; Company request.
0545	ADMIN; ATSC (N/NC); N/NC; DH off, Combined to HQ.
0547	EMERGENCY- MEDICAL: ATSC (FAA HQ DEN); NCT; AAL177; B762; JFK.,SFO; Sick PAX.
0644	NORDO; ATSC (FAA HQ DEN); ZBW; KLM686; B744; MMMXEHAM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0646.
0646	LASER; ATSC (FAA HQ DEN); LGB; PD HELO; H269; Green laser, left side, illuminated helicopter at 500 feet, 2 to 3 miles NE Long Beach. Helo W bound, no injuries reported.
0733	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOB; WJA2891; B737; MUVRCYXU; Sick PAX.
0733	LASER; ATSC (FAA HQ DEN); SLC; LF41; Green laser illuminated Helicopter at 5,500 feet, 4 miles SE SLC Int ARPT. Helo N bound, no injuries reported.
1000	ADMIN; ATSC (NCRCC); UL on duty. At 1015: WCLC, De-combined with HQ DEN.
1000	ADMIN; ATSC (FAA HQ DEN); CU off.
1000	ADMIN; ATSC (FAA HQ DEN); CW on HQE/HQW. WCLC.
1005	NORDO; ATSC (FAA HQ DEN); ZBW; NAO1702; B763; LROPIAD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1011.
1057	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Bayflight1, low level flight eastern portion of SFRA active. Operations terminated at 2017.
1100	ATC FACILITY; ATSC (FAA HQ DEN); IND; IND ATCT/TRACON declared ATC Alert due to Surveillance trigge for scheduled maintenance. ATCSCC advised.
1130	ADMIN; ATSC (CONR/AOC); PM on.
1145	[34] 19 (0.8.C. 11-/r)

Page 1



 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 CWard,
 04/07/2013 0405Z
 CU

Log:	
Time (UTC)	Remarks
1200 1225	ADMIN; ATSC (N/NC); XS and KN on, briefed by CW. COD; ATSC (FAA HQ DEN); JAX; TRS9548; B712; VQQATL New Destination: MCO; Training flight. CONFERENCES,ADMIN; ATSC (N/NC); TACOPS complete
1253	WCLC. NORDO; ATSC (FAA HQ DEN); ZMP; JAL10; B77W; RJAAORD; Aircraft reported on course, at assigned
1311	altitude. Attempting contact on Guard and with Company. Communications re-established at 1255. NORDO; ATSC (FAA HQ DEN); ZJX; AWE857; A321; PHLMKJS; Aircraft reported on course, at assigned
1323	altitude. Attempting contact on Guard and with Company. Communications re-established at 1313. NORDO; ATSC (NCRCC); ZOB; AWE943; A321; ORD. PHL; Aircraft reported on course, at assigned altitude.
1345	Attempting contact on Guard and with Company. Communications re-established at 1330. NORDO; ATSC (FAA HQ DEN); ZDC; N560SH; GLF3; PBI. TEB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available.
1356 1411	COD; ATSC (FAA HQ DEN); ZMP; AMF1132; BE99; ESCCMX New Destination: IWD; Weather. TOI; ATSC (NCRCC); EADS; N399CB; C402; GAILRO; TOI: DCA 350/23, primary only, heading 330 degrees, indicating 142 knots. Aircraft appears to have departed GAI. 1413: PCT confirmed identity as N399CB, C402,
1415	inoperative transponder, no assets involved, PIC advised to make repairs at destination. NFA. NORDO; ATSC (FAA HQ DEN); ZMP; VRD11; A320; JFKSFO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1429.
1429	EMERGENCY, COD; ATSC (FAA HQ DEN); M98; SCX731; B738; MSPTNCM New Destination: MSP; Bird strike. Aircraft landed at 1430.
1434	COD, MECHANICAL; ATSC (NCRCC); PCT; DCM3052; GLF4; IADHVN New Destination: IAD; Maintenance issue, non emergency.
1443	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); N90; DAL2185; B738; FLLJFK; 76yo male PAX with chest pains.
1500 1501	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDC; UAL566; A319; ORDIAD; Non-specific PAX medical.
1510	TE
1513	Bri 49 SUBUL IDS F Roy SC MAN O IDS C 1
	Bo. 49 Modern (Asser)
1516	COD; ATSC (FAA HQ DEN); ZDV; FIV705; C750; PHXEGE New Destination: RIL; Weather.
1516 1517	COD; ATSC (FAA HQ DEN); ZDV; RPA4871; DH8D; DENEGE New Destination: DEN; Weather. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDV; ZDV authorized to suspend change of destination reporting for Ski Country Airports until 1800 due to weather.
1518	MECHANICAL; ATSC (FAA HQ DEN); MIA; AAL602; B752; TBPBMIA; Hydraulic leak upon landing; aircraft stopped on runway, awaiting tow.
1549	NORDO; ATSC (FAA HQ DEN); ZID; AAY2854; MD88; PIE. SBN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1550.
1555	ag 49 2.8.6. Has


Page 2



Element: Created by: Created on: Checked by: CWard, 04/07/2013 0405Z CU


Log:	
Time (∪	TC) Remarks
	Ви. 42 (0.3.с. 110 г)
	87; 40 M.S.C. 116 m
1556	COD; ATSC (FAA HQ DEN); ZID; EJA903; C750; LEX.:TEB New Destination: CMH; Company request.
1619	EMERGENCY, COD; ATSC (FAA HQ DEN); ZMA; VNR132; P180; EYWHOU New Destination: RSW; Minor
1630	mechanical. EMERG declared at 1630 due to baggage door indicator light. Aircraft landed at 1647. EQUIPMENT; ATSC (CONR/AOC); CONR ADAPT position CONWSA10 is OTS. Help desk called.
1630	returned call and determined that the hard drive is more than likely hard down and will need to be replaced. A
	new tower will be built for CONR and shipped either Monday or Tuesday. CONRWSO11 is still operating and
	will be used as the primary display. CONR also has a DoD RTAP display that can be used.
1637	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZME; SWA8115; B737; BDLMSY; Elderly PAX ill; physician
	attending.
1638	COD; ATSC (FAA HQ DEN); NCT; SKW6249; CRJ2; PSPSFO New Destination: SJC; Unable to continue
1701	holding. NCR COORDINATION: ATSC (NCRCC): NCRCC: Authorized military activity in the NCR
1701	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Authorized military activity in the NCR. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); PCT; UAL236; A320; LASIAD; PAX with difficulty breathing.
1710	EMERGENCY, COD; ATSC (FAA HQ DEN); ZME; SLASH50; TEX2; BLV., TXK New Destination; LIT; Fuel
17.10	pressure problem. Aircraft landed at 1727.
1714	EMERGENCY, COD; ATSC (FAA HQ DEN); ZMA; N546MG; GLF4; TMBSVPR New Destination: TMB;
	Pressurization problem. Aircraft landed at 1820.
1719	CONFERENCES; ATSC (N/NC); ONEC test successful.
1719	COD; ATSC (FAA HQ DEN); BNA; ASQ4187; E145; BNAEWR New Destination: BNA; Pressurization
1729	problem. NORDO,MOR; ATSC (FAA HQ DEN); ZAU; N761SB; C210; AUWEZI; Aircraft reported on course, at assigned
1729	altitude. Attempting contact on Guard. No satellite phone available. 1733 FSOC attempting contact over DLL
	VORTAC/ZAU freg 125.05. 1744 NORDO 0+15. Communications re-established at 1755. MOR filed by ZAU.
1749	COD; ATSC (FAA HQ DEN); ZOA; PASCO11; PC12; LAXCEC New Destination: RDM; Weather.
1753	324 49 D.C.C. 114 x)
1754	88) 13 T.S.W. 11044;
1754	NORDO; ATSC (FAA HQ DEN); CMH; N620Z; BE58; SRQ. TTF; Aircraft reported on course, at assigned
1800	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1801. ADMIN: ATSC (NCRCC); NCRCC; SH on. 1900: WCLC.
1800 1802	ADMIN, ATSC (NCRCC), NCRCC, SHIGH. 1900. WCLC.
1805	ADMIN: ATSC (FAA HQ DEN); GR on HQE/HQW, WCLC.
1815	ADMIN; ATSC (NCRCC); UL off duty.
1815	ADMIN; ATSC (FAA HQ DEN); CW off.
1817	Bey 09 11.8.01. 11.4.121
	35: 13:0 x 1: Main
	THE RESERVE OF THE PROPERTY OF
	Bar 18 Marata III Fr
	B1; 47 (USLIN, 124.4)
1	20 47 55.00 116
1820	EMERGENCY, COD; ATSC (FAA HQ DEN); ZKC; AAL240; B738; LAXDCA New Destination: STL; Fuel
1920	problem. Aircraft landed at 1835. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); BOS; JBU356; A320; TPA. BOS; Sick passenger.
1829	EMERGENCT- MEDICAL, ATSO (FAA FIG DEN), BOS, 4B0330, A320, TPALBOS, SICK PASSENGER.

Page 3



 Element:
 Created by:
 Created on:
 Checked by:


 ALL
 CWard,
 04/07/2013 0405Z
 CU



Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/07/2013 0405Z	CU



Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/06/2013

Element: Created by: Created on: Checked by: CWard, 04/07/2013 0405Z CU

Log:		
Time (UTC	Remarks	
0144	NORDO; ATSC (FAA HQ DEN); ZDC; GTH650; C650; CHOTEB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0152.	
0155	COD; ATSC (FAA HQ DEN); ZTL; TRS779; B712; MCOATL New Destination: DTW; Engine issue, PIC did no declare an emergency. 0209 HQ DEN called Airtran Dispatch, issue is an oil temperature indicator. 0212 HQ DEN notified ZTL.	
0200	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE/NCRCC, WCLC.	
0205	COD; ATSC (FAA HQ DEN); CLT; AWE1622; A321; CLTDFW New Destination: CLT; Fumes in cabin. ACFT landed 0204.	
0225	LASER; ATSC (FAA HQ DEN); PBI; DAL1181; MD88; ATLPBI; Green laser illuminated cockpit at 600 feet, on 2 mile final to RY10L at PBI. ACFT on approach, no injuries reported.	
0240	LASER; ATSC (FAA HQ DEN); MIA; NKS195; A319; MCOFLL; Green laser illuminated cockpit at 6,000 feet, 5 miles NE Fort Lauderdale. ACFT SW bound, no injuries reported. Law enforcement not notified.	
0251	LASER; ATSC (FAA HQ DEN); LEX; CHQ3059; E145; CLTSDF; Green laser, from left side, illuminated cockpit between 12,000 and 14,000 feet, 28 miles SSW Lexington. ACFT NW bound, no injuries reported.	
0255	LASER; ATSC (FAA HQ DEN); ALB; SWA1194; B737; MCOALB; Green laser illuminated cockpit at 4,000 feet, 12 miles S Albany, ACFT NE bound, no injuries reported.	
0258	LASER; ATSC (FAA HQ DEN); DFW; AAL1317; B738; MIADFW; Green laser illuminated cockpit at 1,500 feet 4 miles N DFW. ACFT S bound, no injuries reported.	
0259	LASER; ATSC (FAA HQ DEN); D10; UAL280; A320; IADDFW; Green laser illuminated cockpit at 1,500 feet, 4 miles N DFW, ACFT S bound, no injuries reported.	
0301	LASER; ATSC (FAA HQ DEN); DFW; NKS747; A319; MSPDFW; Green laser illuminated cockpit at 1,500 feet 4 miles N DFW. ACFT S bound, no injuries reported.	
0301	LASER; ATSC (FAA HQ DEN); DFW, JBU453; A320; BOS. DFW; Green laser illum nated cockpit at 1,500 feet 4 miles N DFW. ACFT S bound, no injuries reported.	
0309	LASER; ATSC (FAA HQ DEN); P50; AWE140; A319; CMHPHX; Green laser, from right side, illuminated ACFT at 7,500 feet, 9 miles W Phoenix. ACFT W bound, no injuries reported.	
0309	LASER; ATSC (FAA HQ DEN); BFL; KERN1; Green laser illuminated cockpit at 1,000 feet, 6 miles SE Bakersfield ARPT. Helicopter maneuvering, no injuries reported.	
0312	LASER; ATSC (FAA HQ DEN); GJT; SKW4636; CRJ2; SLCGJT; Green laser illuminated ACFT at 6,300 feet, on 3 mile final to RY29 at Grand Junction Regional ARPT. ACFT on approach, no injuries reported.	
0323	LASER; ATSC (FAA HQ DEN); VNY; EJA739; GALX; TUSVNY; Green laser illuminated cockpit at 3,800 feet 5 miles NE Van Nuys ARPT. No injuries reported	
0325	NORDO; ATSC (FAA HQ DEN); JAX; RPA3409; E170; CLTJAX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0328.	
0330	ADMIN; ATSC (NCRCC); NCRCC; SH off.	
0340	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; JBU952; A320; MCOBOS; Sick PAX.	
0359	ADMIN; ATSC (FAA HQ DEN); COB.	
0359	LASER; ATSC (FAA HQ DEN); N90; RPA3292; E170; PHLLGA; Green laser illuminated cockpit at 4,000 feet, 6 miles W LGA ARPT. ACFT N bound, over Hudson river, no injuries reported.	

Page 6



Element: Created by: Created on: Checked by: CWard, 04/08/2013 0402Z CU

Security Event Statistics:

DISTURB: 2 TOI: 1 AIRPORT: 1 COD: 28

EMERGENCY: 11 NORDO: 20 LASER: 10

EMERGENCY- MEDICAL: 9 PRACTICE SCRAMBLE: 1

Log:	
Time (UTC)	Remarks
04/07/2013	
0400	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. CFPL: None.
0400	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE/NCRCC, WCLC.
0401	EQUIPMENT; ATSC (FAA HQ DEN); ADAPT released to maintenance. 0416 ZMA and ZBW report their OPSNET inoperative. 0442 ADAPT returned to service, both ZMA and ZBW OPSNET operable.
0431	LASER; ATSC (FAA HQ DEN); P50; SWA929; B737; SNAPHX; Green laser illuminated cockpit at 7,000 feet, 5 miles SE Phoenix. ACFT E bound, no injuries reported.
0432	NORDO; ATSC (FAA HQ DEN); ZME; N31952; PA31; ARGSIF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 0446 HQ DEN asked ZTL for update. Communications re-established at 0448.
0448	LASER; ATSC (FAA HQ DEN); D01; SWA1832; B738; LASDEN; Green laser, from right side, illuminated ACFT at 13,000 feet, 6 miles W Denver. ACFT N bound, no injuries reported.
0454	COD; ATSC (FAA HQ DEN); ZLA; VRD370; A320; LAXBOS New Destination: LAX; Slight vibration issue. ACFT landed 0517.
0513	LASER; ATSC (FAA HQ DEN); MIA; N185ND; P28A; Green laser illuminated cockpit at 2,500 feet, 1.5 miles SW Vero Beach ARPT. ACFT S bound, no injuries reported.
0545	ADMIN; ATSC (N/NC); N/NC; DH off. Combined to HQ.
0555	LASER; ATSC (FAA HQ DEN); HCF; KULA3; DA40; Green laser illuminated cockpit 9 miles W HNL. ACFT W bound, no injuries reported.
0625	LASER; ATSC (FAA HQ DEN); NCT; SWA1209; B737; DEN.,LAS; Green laser, from straight ahead, illuminated ACFT at 8,000 feet, 1 miles W Lawrence Livermore Laboratory. ACFT SW bound, no injuries reported.
0633	LASER; ATSC (FAA HQ DEN); HCF; KULA1; DA40; Green laser illuminated cockpit at 3,000 feet, 9 mile W HNL. ACFT W bound, no injuries reported.
0815	LASER; ATSC (FAA HQ DÉN); HCF; KULA3; DA40; Green laser, from left side, illuminated cockpit at 2,500 feet, 16 miles NW Honolulu. ACFT WE bound, no injuries reported.
1000	ADMIN; ATSC (FAA HQ DEN); CU off.
1000	ADMIN; ATSC (FAA HQ DEN); CW on HQE/HQW. WCLC.
1000	ADMIN; ATSC (NCRCC); UL on duty. At 1015: WCLC, De-combined with HQ DEN.
1130	ADMIN; ATSC (CONR/AOC); PM on. 1142 WCLC.
1133	EMERGENCY- MEDICAL; ATSC (NCRCC); BOS; JBU636; A320; SFOBOS; Infant medical emergency.
1200	ADMIN; ATSC (N/NC); XS on, briefed by CW.
1200	COD; ATSC (FAA HQ DEN); ZMP; GLA31K; E120; ISNDIK New Destination: DEN; Weather.
1206	EMERGENCY, NOTIFICATION-NONE, COD; ATSC (FAA HQ DEN); ZAB; VNR140; P180; AMACOS New Destination: AMA; Aircraft landed at 1156 after EMERG declared by ATC for unspecified mechanical issue.
1310	CONFERENCES, ADMIN; ATSC (N/NC); TACOPS complete including VIP locations and foreign launches. WCLC.
1326	NORDO; ATSC (FAA HQ DEN); ZJX; FFT19; A320; PHLMMUN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1338.

Page 1



Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/08/2013 0402Z	CU

Log:	
Time (U	TC) Remarks
1345	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1357	COD; ATSC (FAA HQ DEN); ZOA; QXE467; DH8D; STSLAX New Destination: SJC; Minor mechanical.
1400	ADMIN; ATSC (FAA HQ DEN); JF on HQW. CW on HQE. WCLC.
1400	NCR-COORDINATION; ATSC (NCRCC); NCRCC; N1165, MG21, coordinated high speed VFR operations north of APG from 1400 until 1445, ATC services provided by ZDC.
1406	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZKC; UAL1283; B753; IAHORD; Male PAX ill.
1419 1449	NORDO; ATSC (FAA HQ DEN); ROA; N416TD; SR22; GMUCHO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1421.
1449	EMERGENCY,NOTIFICATION-LATE ,COD; ATSC (FAA HQ DEN); DEN; GJS3657; CRJ7; DEN.:SAT New Destination: DEN; Mechanical problem. Aircraft landed at 1444.
1500	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful.
1501	CONFERENCES; ATSC (N/NC); ONEC test successful.
1504	COD; ATSC (FAA HQ DEN); ZID; LXJ621; LJ40; CGFBGF New Destination: LUG; Company request.
1527	COD; ATSC (FAA HQ DEN); ZDC; FIV554; C56X; BWIRDU New Destination: GSO; Minor mechanical due to a bird strike.
1527	COD; ATSC (FAA HQ DEN); ZMA; DAL421; B738; ATLTLPL New Destination: MCO; Needs to pick up part for maintenance.
1542	NORDO; ATSC (FAA HQ DEN); ZFW; N1355J; AC11; TE86OUN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1547.
1601	Bry to M.S.F. Higgs
1611	COD; ATSC (FAA HQ DEN); ZKC; VRD108; A320; LAXIAD New Destination: ORD; Maintenance.
1658	29, 49 (MRC, 118,p)
1659	COD; ATSC (FAA HQ DEN); MCI; SWA3154; B737; MCIBWI New Destination: MCI; Birdstrike.
1700	79; 49 U.S.C. 114:23
1700	COD; ATSC (FAA HQ DEN); ZTL; GTH71; C56X; PDKTEB New Destination: HPN; Pilot request.
1708	NORDO; ATSC (FAA HQ DEN); ZME; SWA3778; B737; SANBNA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1718.
1728	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLA; UAL319; B752; IADLAX; Male PAX ill.
1800	ADMIN; ATSC (FAA HQ DEN); CW off.
1800	ADMIN; ATSC (FAA HQ DEN); DR on HQE. WCLC.
1800	ADMIN; ATSC (NCRCC); UL off duty.
1801	NORDO, MOR, PAGED; ATSC (FAA HQ DEN); MEM; N214CE; C208; SYIFTW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1831, 0+30 minutes. 1846, 0+45 minutes. 1856 HQ DEN asked FSS for any contact information, aircraft is flying direct, no VORs. 1901, 1+00 minutes. 1916, 1+15 minutes. 1931, 1+30 minutes. ZME to file MOR. Communications re-established at 1937.
1827	COD; ATSC (FAA HQ DEN); IAH; UAL1634; B739; IAHBOS New Destination: IAH; Equipment/ checklist issue.
1839	NORDO; ATSC (FAA HQ DEN); ZAB; SBE605; LJ60; LASAUS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications reestablished at 1856.
1845	EMERGENCY,NOTIFICATION-LATE,COD; ATSC (FAA HQ DEN); DEN; FFT151; A319; DENJAC New Destination: DEN; Engine OTS. Aircraft landed at 1843. Landed RWY 16R and stopped on runway; not expected to deplane on runway. DEN ATCT was instructed to contact HQ DEN if deplaned on runway. Delays are anticipated, ATCSCC notified by HQ DEN.
1858	COD; ATSC (FAA HQ DEN); ZAN; ASA152; B735; ANC. OME New Destination: ANC; Mechanical.
1900	ADMIN; SOSC (FAA HQ); MS on SOSC2, briefed by TH.
1902	NORDO; ATSC (FAA HQ DEN); ZDC; DAL1425; MD90; ATLBWI; Aircraft reported on course, at assigned

Page 2



Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/08/2013 0402Z	CU

Log:	_og:		
Time (UTC	Remarks		
1905	altitude. Attempting contact on Guard and with Company. Communications re-established at 1906. EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZMA; AAL994; B738; MIACYUL New Destination: MCO; Passenger medical emergency.		
1911	Boy 4.2 2.8.00 11: 10		
1916	NORDO; ATSC (FAA HQ DEN); ZMA; VET711; BE20; MTHCHS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1923.		
1930	ADMIN; ATSC (CONR/AOC); CONR combined to NORAD. PM off.		
1935	CONFERENCES; ATSC (N/NC); TACOPS with HQ on potential foreign launch.		
1948	COD; ATSC (FAA HQ DEN); ZTL; ASQ5637; CRJ2; ATLFYV New Destination: ATL; Mechanical.		
2005	NORDO; ATSC (FAA HQ DEN); ZMA; UAL606; A320; DENMIA; Aircraft reported on course, at assigned attitude. Attempting contact on Guard and with Company. Communications re-established at 2010.		
2014	COD; ATSC (FAA HQ DEN); ZTL; UAL6856; B739; IAHINT New Destination: GSO; Disabled aircraft on runway at INT.		
2022	NORDO; ATSC (FAA HQ DEN); ZAU; DAL1763; MD90; DCAMSP; Aircraft reported on course, at assigned attitude. Attempting contact on Guard and with Company. Communications re-established at 2024.		
2050	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); DSM; UAL329; A320; ORD. DSM; Female PAX ill.		
2100	ADMIN; ATSC (NCRCC); NCRCC; SH on. 2200: WCLC.		
2100	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. Briefed by XS.		
2101	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZNY; AWI3642; CRJ2; PHLBTV New Destination: PHL; Starboard engine problem. Aircraft canceled emergency at 2123. Continuing to BTV.		
2106	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZMP; AAL789; MD83; ORDDEN New Destination: OMA; Passenger medical emergency.		
2108	NORDO; ATSC (FAA HQ DEN); ZHU; N4775F; PA32; BPTMAF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 2112.		
2109	TOI-EQUIPMENT, TOI; ATSC (NCRCC); PCT; DCA011035, N5157K, C172, negative mode C, inbound GAI, aircraft is locally based and has been authorized to continue to GAI. NFA.		
2125	AIRPORT; ATSC (FAA HQ DEN); Castle ATCT (MER) advised of a disabled aircraft on runway (N87TX) whereupon landing, the nose gear collapsed rendering runway unusable.		
2128	EMERGENCY, COD; ATSC (FAA HQ DEN); ZDV; N261GB; BE9L; ASELOT New Destination: EGE; Smoke in cabin. Aircraft landed at 2135.		
2128	Beging a Martine and the second secon		
2130	CONFERENCES; ATSC (N/NC); N/NC; ONEC test successful.		
2131	EMERGENCY ; ATSC (FAA HQ DEN); ZMP; DAL143; MD88; DTWMSP; Smoke in the cockpit. Aircraft landed at 2149.		
2132	ADMIN; ATSC (N/NC); N/NC; WCLC.		
2132	CONFERENCES; ATSC (N/NC); CONR; CFACC test successful.		
2133	NORDO; ATSC (FAA HQ DEN); ZNY; JBU664; A320; MCOSYR; Aircraft reported on course, at assigned		
	altitude. Attempting contact on Guard and with Company. Communications re-established at 2136.		
2134	NORDO, PAGED; ATSC (FAA HQ DEN); ZBW; N789XJ; C750; BED., VNY; Aircraft reported on course, at		
	assigned altitude. Attempting contact on Guard. No satellite phone available. At 2154 requested status, no		
	change, aircraft transitioned into ZOB airspace, ZBW OMIC reviewing tapes. At 2159 ZOB OMIC reported not		
	change in status, aircraft transitioned into Canadian airspace. At 2204 aircraft NORDO 30 minutes.		
	Communications re-established at 2208, PIC issued BRASHER to contact ZBW OMIC for MOR Action.		
2139	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOA; UAL642; B752; JFKSFO; PAX ill.		
2145	ADMIN; ATSC (NCRCC); NCRCC; MK off.		

Page 3




Date: 04/07/2013

Element: Created by: Created on: Checked by: CWard, 04/08/2013 0402Z CU

Log:	
Time (UTC)	Remarks
2150	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZOB; FLG3582; CRJ2; PHLDTW New Destination:
2150	CLE; Passenger medical emergency. EMERGENCY,NOTIFICATION-LATE ,COD; ATSC (FAA HQ DEN); MKE; N44813; PA28; SUEPWK New Destination: MKE; Alternator problem. Aircraft landed at 2147.
2211	fest to Miscel Eligin
2212	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZME; FDX555; MD11; MEMBOS New Destination: MEM; Fuel leak. Aircraft landed at 2237.
2214	NORDO; ATSC (FAA HQ DEN); XNA; N915WM; P28B; NEWRVS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. At 2235 requested status, no change, aircraft transitioned into ZFW airspace, OMIC advised. Requested XNA OMIC to review voice tape recordings. At 2234 XNA OMIC reported voice tape review indicated PIC issued ZFW frequency 132.2, correct PIC readback received. Communications re-established with TUL TRACON at 2236.
2214	NORDO; ATSC (FAA HQ DEN); ZMA; CMP305; B738; IADMPTO; Aircraft reported on course, at assigned attitude. Attempting contact on Guard and with Company. At 2217 aircraft transitioned into ZMA airspace, OMIC advised. At 2223 ZJX OMIC advised ARINC attempting to establish communications. Communications reestablished at 2333.
2300	EMERGENCY; ATSC (FAA HQ DEN); TUL; N57692; M20P; TULMHK; At 2257 TUL OMIC reported simultaneous loss of RADAR/Radio communications approximately 9NM north of TUL, at a time of 2252. Requested assistance from AMOC. At 2330 AMOC reported RADAR Data Replay indicates aircraft last known location: 36:21:41/95:50:23, or the TUL 341/10.2. At 2335 TUL OMIC reported confirmed aircraft crash near the town of Collinsville. SAR on scene, damage or injuries unknown. CLOSEOUT: At 0023 TUL OMIC reported three POB, three fatal, aircraft destroyed.
2306	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZOB; N585VC; H25B; OMATEB New Destination: DTW; Port side engine failure. Aircraft landed at 2323.
2308	EMERGENCY, COD; ATSC (FAA HQ DEN); ZAU; VADER21; C130; MTCARR New Destination: YNG; Number two engine failure. Aircraft landed at 0007.
2339	80: 30 MACC 1130: 80: 10 MORE 11: 10 80: 30 MACC 1130: 80: 10 MS (C. 30) (
0.400.0040	Bry 40 MuSory, 449 (e)
04/08/2013	LACED ODERATION: ATCC (NCDCC): NCDCC: NACA Coddord: LACED apprehints having at 0055 LIEN
0039 0130	LASER OPERATION; ATSC (NCRCC); NCRCC; NASA Goddard: LASER operations begin at 0055 UFN. EMERGENCY- MEDICAL; ATSC (NCRCC); PCT; AAL1520; B738; MIADCA; Aircraft landed at 0139.
0141	NORDO; ATSC (FAA HQ DEN); ZAB; N214MS; EA50; SDLIWS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard, previous frequencies and FSS. No satellite phone available. Communications re-established at 0146.
0151	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC.
0152	NORDO; ATSC (FAA HQ DEN); ZAU; N93LA; CL30; HTOSLC; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0159.
0152	NORDO; ATSC (FAA HQ DEN); N713ZM; BE58; DTSEZM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications reestablished at 0155.
0200	ADMIN; ATSC (FAA HQ DEN); DR off.
0200	ADMIN; ATSC (NCRCC); NCRCC; SH off.
0200	LASER; ATSC (FAA HQ DEN); BNA; SWA520; B733; TPABNA; Cockpit illuminated by a green laser at

Page 4

FOR OFFICIAL USE ONLY



Log:	Log: Fime (UTC) Remarks		
Time (U			
	9,000MSL 13NM W BNA. Heading west, laser emanated from the 1 o'clock position at 4NM. No injuries,		
0200	ADMIN; ATSC (NCRCC); MX on duty, WCLC at 0215.		
0220	COD; ATSC (FAA HQ DEN); ZKC; ASQ5950; E45X; ORDMCI New Destination: DSM; WX.		
0231	COD; ATSC (FAA HQ DEN); OMA; ASQ6076; E145; ORDLNK New Destination: OMA; Wind shear.		
0234	LASER; ATSC (FAA HQ DEN); PCT; ASQ5675; E45X; DCA. EWR New Destination: ADW; Green laser illuminated cockpit at 9,000 feet, over Andrews AFB. ACFT E bound, no injuries reported.		
0310	LASER; ATSC (FAA HQ DEN); PHX; FRBD3; AS350; Red laser illuminated ACFT at 1,500 feet, 6 miles W Phoenix. ACFT orbiting, no injuries reported. ACFT is LE.		
0316	NORDO; ATSC (FAA HQ DEN); ZTL; UAL727; B752; IADTPA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0318.		
0330	NCR-COORDINATION; ATSC (NCRCC); WADS; WADS assumes air sovereignty of NCR until 0530Z.		
0358	ADMIN; SOSC (FAA HQ); MS off, SOSC closed. TH on call.		
0359	ADMIN; ATSC (FAA HQ DEN); COB.		

Page 5

Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/09/2013 0401Z	CU

Security Event Statistics:			
S91-30 Nation 15	TOI: 3	AIRPORT: 1	B3; 49 U.S.C. 111(c)
EMERGENCY: 12 EMERGENCY- MEDICAL:	1	DIVERT: 1 NORDO: 11	COD: 44 LASER: 12
9		77) 49 U.H.C. 111(x.	MOR: 1

Log:	
Time (UTC)	Remarks
04/08/2013	
0400	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC.
0400	ADMIN; ATSC (NCRCC); MX on duty. CFPL: NASA Goddard laser operations UFN. WCLC.
0400	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. CFPL: None.
0403	COD; ATSC (FAA HQ DEN); NCT; SKW729H; CRJ2; DENMRY New Destination: SJC; MRY tower closed.
0420	COD; ATSC (FAA HQ DEN); ZAN; ASA70; B737; ANCJNU New Destination: ANC; Equipment issue.
0433	AIRPORT; ATSC (FAA HQ DEN); L30; Unknown Security breach at McCarron, TSOC responding, 0442 L30 report security breach has been cleared.
0436	LASER; ATSĆ (FAA HQ DEN); LAX; SWA389; B737; SJCLAX; Purple laser, from right side, illuminated cockpit at 1,500 feet, 5 miles NE Los Angeles. ACFT on final approach to RY24R, no injuries reported.
0436	LASER; ATSC (FAA HQ DEN); LAX; JBU101; A320; FLL.,LAX; Purple laser, from right side, illuminated cockpi at 1,100 feet, 5 miles NE Los Angeles. ACFT on final approach to RY24R, no injuries reported.
0436	LASER; ATSC (FAA HQ DEN); LAX; ASA702; B734; CYVRLAX; Purple laser, from right side, illuminated cockpit at 1,100 feet, 5 miles NE Los Angeles. ACFT on final approach to RY24R, no injuries reported.
0500	EQUIPMENT: ATSC (NCRCC): PCT performed successful cold start of RACD.
0521	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZMA; AWE800; B762; CLTSBGL New Destination:
0021	CLT: Sick PAX. 0604 COD to FLL.
0545	COD; ATSC (FAA HQ DEN); ZMP; SKW572H; CRJ2; DEN. BIS New Destination: RAP; WX.
0545	ADMIN; ATSC (N/NC); N/NC; DH off. Combined to HQ.
0806	NORDO, FAM-ONBRD; ATSC (FAA HQ DEN); ZBW; DAL7; B77L; OMDB. ATL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0816.
0818	LASER; ATSC (FAA HQ DEN); I90; AAL272; B752; SFOMIA; Green laser illuminated cockpit at FL370, 10 miles W Reserve. ACFT SE bound, no injuries reported.
0848	5H, 44 1.8.C. 11/4
	Ber 30 (L.S. C. 111) k
0906	Bs; 39 (0.5.0) 214 20
	B-g 40 7.8.0. 1140.
0927	37, 33 N.A.C. 143 S.
1000	ADMIN; ATSC (NCRCC); UL on duty. At 1015: WCLC.
1000	ADMIN; ATSC (NCRCC); MX off duty.
1000	ADMIN; ATSC (FAA HQ DEN); CU off.
1000	ADMIN; ATSC (FAA HQ DEN); JF on HQE/HQW. WCLC.
1041	Bry 19 Chell. 183 As

Page 1



Date: 04/08/2013

Element: Created by: Created on: Checked by: CWard, 04/09/2013 0401Z CU

Log:	
Time (UTC)	Remarks
1113	Big 17 HAVE LOG L
4400	
1130	ADMIN; ATSC (CONR/AOC); PM on.
1131	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZTL; AAL831; MD82; CLTDFW New Destination: ATL
4440	Male PAX ill.
1140 1155	ADMIN; ATSC (CONR/AOC); WCLC.
1199	36; 43 °C,8,25, 114 15
	54 m 4 7 m 4 7 m 4 m 4 m
	Box 1.5 U.S. ct. 111000
1200	ADMIN; ATSC (N/NC); XS on, briefed by JF.
1201	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMP; ZMP authorized to suspend change of destination
	reporting for AOR until 1400 due to WX/ thunderstorms.
1237	CONFERENCES, ADMIN; ATSC (N/NC); TACOPS complete including VIP locations, VIP movement with TFR,
	VIP TELCON, LRA, foreign launches, and practice scrambles. WCLC.
1241	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); DTW; FLG3679; CRJ2; BMIDTW; Male PAX trouble
	breathing.
1243	NORDO; ATSC (FAA HQ DEN); ZJX; TRS732; B712; TPAPHL; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1246.
1245	COD; ATSC (FAA HQ DEN); ZMA; JBU464; A320; RSW. BOS New Destination: MCO; Birdstrike.
1258	EMERGENCY, NOTIFICATION-LATE; ATSC (FAA HQ DEN); IAH; ASQ4384; E145; CMHIAH; Oil light
1040	number 1 engine. Aircraft landed at 1256.
1310 1316	COD; ATSC (FAA HQ DEN); A11; GTI628; B742; ANCORD New Destination: ANC; Flap drive problem. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMP; SKW4628; CRJ9; BILMSP; Sick passenger, Doctor in
1316	attendance.
1 31 7	CONFERENCES; ATSC (N/NC); TACOPS for potential launch.
1340	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1353	29 (49 U.S.). 11 U.S.
,,,,,,	54, 13 Marc. 1114
1405	25, 15 T. A. A. 11. C.
1416	COD; ATSC (FAA HQ DEN); ZLC; SIL3577; B190; HVRLWT New Destination: BIL; Icing conditions at LWT.
1443	COD; ATSC (FAA HQ DEN); ZID; ASQ5922; E45X; ORDCHS New Destination: TYS; Company request.
1444	EMERGENCY,COD; ATSC (FAA HQ DEN); ZJX; DAL2380; MD88; JAXATL New Destination: JAX; Lost an
	engine. Aircraft landed at 1514.
1500	ADMIN; SOSC (FAA HQ); MS on SOSC2, briefed by YZ.
1502	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful.
1505	ADMIN; ATSC (FAA HQ DEN); DR on HQW. JF on HQE. WCLC.
1506	CONFERENCES; ATSC (N/NC); ONEC test successful.
1533	ENERGENCY COD, ATCC /EAA UA DENI), 7011, DAMOON, CDOO, UALL DAL Man Dankarian, DIZE, Lancel
1540	EMERGENCY, COD; ATSC (FAA HQ DEN); ZHU; DCM2201; SR22; HOUDAL New Destination: DKR; Low of
1540	pressure, Aircraft landed at 1552. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAU; ZAU authorized to suspend change of destination
1540	reporting for AOR until 1900 due to WX.
1540	PRINCE SEEC. 113-10
1.5-0	Ber 69 C.S.C. 111.19

Page 2




Element: Created by: Created on: Checked by: CWard, 04/09/2013 0401Z CU

<u> </u>	
Log:	
Time (UTC)	Remarks
	30 40 M.C. 114 ±0
	33 y 34 454 124 a
1542	COD; ATSC (FAA HQ DEN); ZAU; AAL1452; MD83; RSWORD New Destination: MKE; Low fuel due to excessive holding for arrivals into ORD attributable to weather.
1545	NORDO; ATSC (FAA HQ DEN); ZJX; FFT932; A319; TPATTN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1548.
1603	NORDO; ATSC (FAA HQ DEN); ZDV; N628TL; SR22; APA. FSM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. At 1612 requested status, no change, ZDV OMIC advised attempting contact via all available resources. At 1634 requested status, no change, aircraft transitioned into ZKC airspace. TT NORDO: 30 minutes. Communications re-established at 1641, PIC issued BRASHER to contact ZDV OMIC for MOR Action.
1605	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDC; AWE707; A332; EDDFCLT; PAX ill.
1623	COD; ATSC (FAA HQ DEN); ZHU; FIV571; C56X; SAT. OBE New Destination: MCO; Company request.
1633	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMP; ZMP authorized to suspend change of destination reporting for AOR until 2000 due to WX.
1647	COD; ATSC (FAA HQ DEN); C90; EGF3996; E145; ORDBWI New Destination: ORD; Electrical failure.
1700	ADMIN; ATSC (NCRCC); UL off duty.
1724	NORDO; ATSC (FAA HQ DEN); ZJX; SWA526; B737; HOURDU; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1727.
1734	EMERGENCY ; ATSC (FAA HQ DEN); ABI; N7803P; PA24; CWSABI; Nose gear will not cycle down. Aircraft landed at 1804.
1759	COD; ATSC (FAA HQ DEN); ZOB; EJA729; GALX; LGAPWK New Destination: MDW; Company request.
1800	ADMIN; ATSC (NCRCC); VP on duty.
1800	ADMIN; ATSC (FAA HQ DEN); RS/RV on HQT.
1801	COD; ATSC (FAA HQ DEN); ZJX; LXJ550; CL30; DBN. TPA New Destination: PBI; Customer request.
1815	ar is vidgi line
1815	ADMIN; ATSC (NCRCC); WCLC.
1827	COD; ATSC (FAA HQ DEN); ZDV; OPT730; C750; DEN36U New Destination: SLC; WX.
1830	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Received coordination for a military exercise commencing in the NCR. 1730: Klaxon for the exercise.
1905	
1909	COD; ATSC (FAA HQ DEN); ZHU; AAL1180; B752; DFWTJSJ New Destination: MIA; Ran out of water.
1911	NORDO; ATSC (FAA HQ DEN); M98; N503CB; BE9L; GSHFCM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1915.
1915	CONFERENCES; ATSC (CONR/AOC); CFACC preamble conference conducted for FDC 3/0206 NOTAM (ZBW) and FDC NOTAM 3/0208 (ZNY) for VIP TFR at Windsor Locks/Hartford, CT.
1922	NORDO; ATSC (FAA HQ DEN); ZTL; N594WR; RV8; DBNDED; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. At 1935 aircraft transitioned into ZJX airspace, requested status, no change. Communications re-established at 1939.
1923	EMERGENCY, COD; ATSC (FAA HQ DEN); ZTL; AAY833; MD83; TYSPIE New Destination: TYS; Starboard engine failure. Aircraft landed at 1937.
1930	CONFERENCES; ATSC (CONR/AOC); CONR combined to NORAD. PM off.

Page 3



Element: Created by: Created on: Checked by: CWard, 04/09/2013 0401Z CU



Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/09/2013 0401Z	CU

Log:	
Time (UTC)	Remarks
	BY A POLICY DATE
	Res 10 2 d 2 14 3
0040	000 AT00 (FAA HO DEN), 71A BOUGTO 047 OHH MINN D. (1. C. BOU BY 4.D.
2319 2328	COD; ATSC (FAA HQ DEN); ZLA; RCH279; C17; SUUYUM New Destination: RIV; Pilot Request.
2520	7-7-3-1-2-3-3-3-3-3-3-3-3-3-3-3-3-3-3-3-3-3
	. 211 11 13450, \$174
	STATE OF THE PARTY
2332	EMERGENCY , COD; ATSC (FAA HQ DEN); ZTL; ASQ5644; CRJ7; GTRATL New Destination: BHM; Engine issue: Aircraft landed at 2343.
2335	COD; ATSC (FAA HQ DEN); ZDV; GLA08Y; E190; DENCYS New Destination: DEN; Weather.
2341	EMERGENCY, COD; ATSC (FAA HQ DEN); ZOA; E23516; K35R; HIK. PGUA New Destination; PWAK;
	Mechanical Issue. Aircraft landed at 2351.
2355	SIF,PAGED; ATSC (FAA HQ DEN); ZOB; BUN600; C525; CLTHMZ; 2351 ZOB questions ACFT route as
	Russian Federation ACFT in western ZDC airspace. SOSC investigating and confirmed BUN is a SIF flight.
	After consultation with management team; HQ DEN contacted ZDC to inform status as SIF flight; advise PIC the ACFT is ground stopped at HMZ until contacting the SOSC for approved routing. SOSC has contacted CLT for
	further investigation and to confirm status as a Russian ACFT. 2359 ZDC advised flight plan error; ACFT is
	actually BNA600 (Baronair); not BUN (Bural); ZOB advised.
04/09/2013	
0000	94, 1) 0.8.C. 114 St
0001	COD; ATSC (FAA HQ DEN); ZOA; SKW5362; E120; FAT. LAS New Destination: FAT; Mechanical Issue.
0012 0039	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; AAL881; B738; DTWDFW; Sick PAX. NORDO; ATSC (FAA HQ DEN); ZDV; N777FZ; ASTR; GTFABI; Aircraft reported on course, at assigned
0000	altitude, Attempting contact on Guard. No satellite phone available. Communications re-established at 0049.
0050	EMERGENCY, COD; ATSC (FAA HQ DEN); ZDV; SKW6266; CRJ2; DEN. TUL New Destination: DEN;
	Pressurization problem. Aircraft landed at 0105.
0057	COD; ATSC (FAA HQ DEN); ZOB; EJA758; GALX; LGAMDW New Destination: CMH; Weather.
0110	LASER; ATSC (FAA HQ DEN); C90; SKW5510; CRJ2; ASEORD; 0100, 25 miles southwest of ORD, at 8,000 feet, heading northeast; cockpit illuminated by a green LASER from 9 o'clock. No injuries reported;
	reet, heading northeast, cockpit liturilinated by a green LASEK from 9 0 clock. No injuries reported,
0111	EMERGENCY; ATSC (FAA HQ DEN); ZHU; TCF5999; E170; LGAIAH; Loss of breaking indication. Aircraft
	landed at 0202.
0114	EMERGENCY; ATSC (FAA HQ DEN); NCT; UPS902; MD11; HNLONT; Braking issue. Aircraft landed at
0444	0112.
0114	LASER; ATSC (FAA HQ DEN); PHL; AWI3657; CRJ2; BDLPHL; Aircraft reported a green LASER illuminated the cockpit at 9,000 feet, 35 SE of PHL, while northbound. No injuries reported.
	the cockpit at 3,000 feet, as de of the, white northboard. The injuries reported.
0118	COD; ATSC (FAA HQ DEN); ZAB; RPN836; MD83; HRLNYL New Destination: IWA; WX.
0133	COD; ATSC (FAA HQ DEN); ZMP; EGF4035; E145; ORDSAW New Destination: ORD; Weather.
0140	NORDO; ATSC (FAA HQ DEN); ZHU; N582DT; PC12; LNK. SAT; Aircraft reported on course, at assigned
0155	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0146. LASER; ATSC (FAA HQ DEN); DSM; ASQ24T; E145; ORDDSM; Green laser struck ACFT at 2,500 feet, .5
0155	mile E Des Moines. ACFT on downwind for RY13, no injuries reported
	0201 Pilot reported eye issues and seeking medical attention.
0157	COD; ATSC (FAA HQ DEN); ZFW; SWA420; B733; AUSDEN New Destination: AUS; No de-icing equipment.
0159	COD; ATSC (FAA HQ DEN); ZKC; SWA105; B737; STLDEN New Destination: STL; Weather.
0159	COD; ATSC (FAA HQ DEN); ZKC; SWA364; B737; PHLDEN New Destination: PHL; WX.

Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/08/2013

Element: Created by: Created on: Checked by: CWard, 04/09/2013 0401Z CU

Log:	
Time (U	TC) Remarks
0200	ADMIN; ATSC (NCRCC); VP off duty.
0200	ADMIN; ATSC (FAA HQ DEN); RS/RV off.
0200	Beg 48 (1.80% 111 1)
0200	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC.
0200	ADMIN; ATSC (NCRCC); MX on duty, WCLC at 0215.
0201	COD; ATSC (FAA HQ DEN); ZKC; SWA555; B733; TULDEN New Destination: TUL; WX.
0202	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZKC; ZKC/ZDV/ZLA authorized to suspend change of
	destination reporting for DEN arrivals until 0359 due to WX.
0202	COD; ATSC (FAA HQ DEN); ZLA; SWA521; B733; LAXDEN New Destination: LAX; No de-icing equipment available at DEN.
0205	COD; ATSC (FAA HQ DEN); ZLC; SWA511; B737; SMFDEN New Destination: SMF; WX.
0206	LASER; ATSC (FAA HQ DEN); SJU; N9654H; C172; Green laser, from 12 O'Clock (.5 mile), at 1,500 feet, over
	San Juan ARPT illuminated cockpit. ACFT SE bound, no injuries reported.
0218	LASER; ATSC (FAA HQ DEN); LEX; CHQ3059; E145; CLTSDF; Green laser illuminated cockpit at 12,500
02.10	feet, 60 miles SW Lexington. ACFT NW bound, no injuries reported.
0220	LASER; ATSC (FAA HQ DEN); C90; EGF9807; CRJ7; CMHORD; Green laser, from left, illuminated cockpit at 9,000 feet, 25 miles SE ORD. ACFT NW bound, no injuries reported.
0236	EMERGENCY,COD; ATSC (FAA HQ DEN); ZDC; ASQ5699; CRJ2; IADROA New Destination: IAD; Problem
0230	with brakes. 0247 PIC declared an emergency due to brake issue. 0248 HQ DEN asked IAD OMIC to report
	arrival. ACFT landed 0303.
0236	COD: ATSC (FAA HQ DEN); ZAB: SWA3578; B733; SAT. DEN New Destination: ABQ: Not enough hotel
	rooms available.
0237	COD; ATSC (FAA HQ DEN); ZME; UPS701; B752; MSYSDF New Destination: PNS; Company request.
0243	COD; ATSC (FAA HQ DEN); ZMP; SUB22; C208; OMALBF New Destination: OMA; WX.
0254	COD; ATSC (FAA HQ DEN); ZLA; GLA170; B190; LAXIGM New Destination: PRC; Equipment on ARPT.
0319	LASER; ATSC (FAA HQ DEN); ZAU; EGF3762; CRJ7; SLC. ORD; Green laser, from right, illuminated cockpit
	at 12,000 feet, 12 miles SE Janesville. ACFT SE bound, no injuries reported.
0321	LASER; ATSC (FAA HQ DEN); ALB; GJS3710; CRJ7; ORDALB; Green laser, from right, illuminated cockpit at
0321	2,400 feet, 7 miles S Albany. ACFT N bound, no injuries reported.
0327	EMERGENCY, COD; ATSC (FAA HQ DEN); ZLA; FDX1204; MD11; LAX. MEM New Destination: LAX;
1002	Unknown mechanical issue. 0328 engine number three had to be shut down. Aircraft landed at 0351.
0347	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; NKS356; A319; LASORD; Sick PAX.
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 6

A CONTRACTOR OF THE PARTY OF TH	EAA Air Traffic	Organization
	FAA Air Traffic NAS Daily Even	its Log

111

Date: 04/09/2013

LASER: 12

Created by: Element: Created on: Checked by: 04/10/2013 0428Z ALL CWard. CU

Security Event Statistics: TOI: 3 AIRPORT: 2 TOI-US ADIZ: 3 EMERGENCY: 10 NORDO: 25 COD: 39 EMERGENCY- MEDICAL:

Log: Time (UTC) Remarks 04/09/2013 0400 ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC. ADMIN: ATSC (NCRCC); MX on duty, CFPL: NASA Goddard laser operations UFN, WCLC. 0400 ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC. 0400 LASER; ATSC (FAA HQ DEN); ZLA; SWA185; B733; OAK. SAN; Blue laser illuminated cockpit at FL270, 2 0401 miles W Camarillo. ACFT S bound, no injuries reported. LASER; ATSC (FAA HQ DEN); LAX; SWA533; B737; OAK. LAX; Green laser, from left side, illuminated cockpit 0405 at 2,000 feet, while on 4 mile final approach to RY24R. No injuries reported. NORDO; ATSC (FAA HQ DEN); ZHU; N444AH; SR22; CRP..BTR; Aircraft reported on course, at assigned 0409 altitude. Attempting contact on Guard, No satellite phone available, 0412 HQ DEN asked FSOC to broadcast over SBI, frequency 132.25. 0420 HQ DEN called I90 for update, communications re-established at 0420. COD; ATSC (FAA HQ DEN); ZDV; USC421A; LJ35; PHX..COS New Destination: APA; Pilot request. 0413 OTHER; ATSC (FAA HQ DEN); ZME; Two ACFT reported a high speed moving ACFT, from left to right, above 0423 FL350 in the vicinity 40 miles NE Little Rock (LIT). ZME had no primary or Mode-C targets, the unknown ACFT was moving from NE to SW and flashed its' lights at one of the ACFT reporting this occurrence. 0430 HQ DEN asked WADS to help monitor the area, 0517 while descending through FL330 FDX1252 was head-on with unknown ACFT, and stated that the closure rate too fast to be an ACFT. LASER: ATSC (FAA HQ DEN); ZSE; WJA1699; B736; LAX..CYVR; Green laser illuminated ACFT at FL400, 15 0424 miles SSE Lakeview. ACFT N bound, no injuries reported. No LE notified because jurisdiction unknown. NORDO; ATSC (FAA HQ DEN); ACA7033; A319; BOS. RDU; 7600 observed on ADAPT 10 miles E RDU, HQ 0442 DEN called RDU ATCT, 0443 RDU stated communication in and out, hitting ACFT with lights. ACFT landed RDU 0451 NCR-COORDINATION; ATSC (NCRCC); NCRCC; Citizen called to inquire about a low flying helicopter 0442 conducting maneuvers in the vicinity of Fairfax Hospital. ARCR4 was the only helo in the area and was not conducting any maneuvers, only a medical lift from the hospital. As we spoke, ARCR 4 departed the area to west. I advised the caller it was an approved medical flight and should not return to the hospital this evening. LASER; ATSC (FAA HQ DEN); A90; UAL444; A320; SFO. BOS; Green laser, from left, illuminated cockpit at 0454 6,000 feet, 6 mile NE Boston, ACFT SE bound, no injuries reported. EQUIPMENT; ATSC (NCRCC); NCRCC; PCT performed successful cold start of RACD. 0500 LASER; ATSC (FAA HQ DEN); N90; N724JS; LJ60; HOU. TEB; Green laser, from left, illuminated cockpit at 0510 5,000 feet, 25 miles NE Robbinsville. ACFT NE bound, no injuries reported. NORDO; ATSC (FAA HQ DEN); ZAB; ABX403; B763; LAX..CVG; Aircraft reported on course, at assigned 0512 altitude. Attempting contact on Guard and with Company. Communications re-established at 0519. ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN. 0550 COD; ATSC (FAA HQ DEN); AUS; CTL5; AC50; OKC. EDC New Destination: T74; PIC not RNAV capable. 0551 LASER; ATSC (FAA HQ DEN); HCF; MKU232; DH8D; LNY. HNL; Green laser, from right side, illuminated 0554 ACFT at 1,500 feet, while departing Honolulu. ACFT NW bound, no injuries reported.



Date: 04/09/2013

Element: Created by: Created on: Checked by: CU

ALL CWard, 04/10/2013 0428Z CU

Log:	
Time (UTC)	Remarks
0555	LASER; ATSC (FAA HQ DEN); HCF; HAL392; B712; HNLITO; Green laser, from left side, illuminated cockpit at 2,000 feet, while landing. ACFT SE bound, no injuries reported.
0708	NORDO; ATSC (FAA HQ DEN); ZBW; WJA2916; B737; MMUNCYHZ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0713.
0745	COD; ATSC (FAA HQ DEN); ZDV; FLX386; C210; OMACOS New Destination: APA; Centennial was original destination.
0947	221 24 MACC 122 II
1000	ADMIN; ATSC (FAA HQ DEN); CU off.
1000	ADMIN; ATSC (NCRCC); UL on duty. At 1015: WCLC.
1000	ADMIN: ATSC (FAA HQ DEN); GR on HQE/HQW, WCLC.
1123	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMP; ZMP/ZLC authorized to suspend change of destination reporting for AOR until 1800 due to weather.
1130	ADMIN; ATSC (CONR/AOC); BD on. 0638 WCLC.
1200	ADMIN; ATSC (N/NC); XS on, briefed by GR.
1242	CONFERENCES, ADMIN; ATSC (N/NC); TACOPS complete including VIP locations, LRA, Felix Hawk and Falcon Virgo exercises, multiple practice scrambles, and foreign launches. WCLC.
1249	COD; ATSC (FAA HQ DEN); ZAU; CHQ5093; E135; TOLORD New Destination: PIA; Approach plate issue.
1252	24) 44 M.M.D. 11:02
1302	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZJX; DAL2352; B752; RSWATL; Sick passenger.
1329	COD; ATSC (FAA HQ DEN); UPS2967; B763; OGGKOA New Destination: OGG; No weather reporting.
1333	EQUIPMENT; ATSC (NCRCC); NCRCC; ADAPT FAA position 1 failed at 1333, restarted and working at 1334. Concept Solutions Helpdesk notified.
1335	3-9 19 T-3-0, 11-10
1336	NORDO; ATSC (FAA HQ DEN); ZJX; N373RS; FA50; AZOMYNN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. Communications re-established at 1339.
1345	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1348	COD; ATSC (FAA HQ DEN); ZTL; JIA564; CRJ2; BTRCLT New Destination: GSP; Fuel.
1403	COD; ATSC (FAA HQ DEN); ZAN; ASA7082; B734; ANCJUN New Destination: SEA; Weather.
1408	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); BOS; AAL1897; B752; BOSDFW; Aircraft returned to departure gate due to sick passenger.
1413	ERGIO MURIO DIR LA C
1414	TOI-US ADIZ,TOI; ATSC (CONR/AOC); (77 (28 (BORGE))
1415	
1429	COD: ATSC (FAA HQ DEN); ZKC; GJS3681; CRJ7; ORD. SAT New Destination: STL; Mechanical.
1440	EMERGENCY; ATSC (FAA HQ DEN); SAT; BEAD2; T38; RNDRND; Generator failure. Aircraft landed at 1444.
1500	CONFERENCES: ATSC (CONR/AOC); CFACC test unsuccessful.
1512	CONFERENCES; ATSC (N/NC); TACOPS for potential launch.
1525	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZME; AAL1854; MD83; ORD. TPA New Destination:
1530	BNA; Sick passenger. CONFERENCES; ATSC (CONR/AOC); CFACC test successful.
	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); I90; UAL1423; B739; MNMGIAH; Sick passenger.
1547	EINIEMOENO 1- INIEDIOAE, ATOO (1 AA FIG DEIN), 180, OAE1423, D738, MINIMOATI, OION PASSETIGET.

Page 2



Element:	Created by:	Created on: 04/10/2013 0428Z	Checked by:
ALL	CWard,		CU

Log:	
Time (ປີ	(C) Remarks
1559	EMERGENCY; ATSC (FAA HQ DEN); SDF; SWA781; B733; MDWSDF; Flap problem. Aircraft landed at 1554.
1600	BG 42 U.S.C. 1144p
1601	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Received coordination for a military exercise commencing in the NCR. 1705: Klaxon for the exercise.
1618	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Received PD packages from PCT for DCA-1, incident occurred on 4/6/2013 and DCA-1, incident occurred on 4/5/2013.
1641	TOI-US ADIZ,TOI; ATSC (CONR/AOC); PROBLEM CONTROL CONT
1651	EMERGENCY, COD; ATSC (FAA HQ DEN); MCI; N10DH; BE9T; MKCBAZ New Destination: MKC; Fire warning indication. Aircraft landed at 1653.
1657	COD; ATSC (FAA HQ DEN); LAS; DAL1479; A320; MEM. LAS New Destination: PSP; Weather.
1700	ADMN; ATSC (FAA HQ DEN); DR on HQE/HQW. WCLC.
1700	ADMIN; ATSC (CONR/AOC); LB on.
1711	NORDO; ATSC (NCRCC); ZAU; EGF4124; E145; ORDCVG; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1713.
1721	Pr; 40 U.S.C. 114/g
	RYLWY MRAN, 110-19
1730	NORDO ATSC (FAA HQ DEN); F11; AWE1585; A321; PHLMCO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1733.
1731	NORDO; ATSC (FAA HQ DEN); ZDV; N61VC; BE40; OAKPNC; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. At 1735 requested status, no change, OMIC reviewing voice tape recordings. Communications re-established with ZKC at 1800, PIC issued BRASHER to contact ZDV OMIC for possible MOR Action.
1732	NORDO; ATSC (FAA HQ DEN); ZJX; N738UR; C172; IXAPNS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1740.
1733	Berger Wicker, 11: 10
1739	ADMIN; ATSC (NCRCC); UL off duty.
1739	NORDO; ATSC (FAA HQ DEN); ZDC; SWG671; B737; MUSCCYYZ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1745.
1743	Bry 40 U.S.C. 114 C
1749	NORDO; ATSC (FAA HQ DEN); ZDV; N80SN; C56X; CICSLN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1756.
1759	NORDO; ATSC (FAA HQ DEN); ZJX; N82818; PA34; LA48PCM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1808.
1800	ADMIN; ATSC (NCRCC); VP on duty.
1800	ADMIN; ATSC (FAA HQ DEN); RS/RV on HQW; WCLC.
1809	COD; ATSC (FAA HQ DEN); ZAN; CFS216; AT72; SIT. KKTN New Destination: JNU; Weather.

Page 3



Element:	Created by:	Created on:	Checked by:
ALL	CWard,	04/10/2013 0428Z	CU

Log:	
Time (UTC)	Remarks
1810	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDC; DAL781; MD88; LGAATL New Destination: IAD
1812	Passenger medical emergency. NORDO; ATSC (FAA HQ DEN); ZME; HOUND91; CVSVPS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1815.
1815	ADMIN; ATSC (NCRCC); WCLC.
1815	COD; ATSC (FAA HQ DEN); ZID; SWA142; B737; AUSEWR New Destination: BWI; Company dispatch request.
1839	EMERGENCY ; ATSC (FAA HQ DEN); N90; GJS6189; STLLGA; Asymmetrical flap configurations. Aircraft landed at 1842.
1843	821 No. (1874)
1851	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZDC; JBU1272; A320; FLLLGA New Destination: RDU; Passenger medical emergency.
1852	(7 -), E-0,(c)
	Tour proje
1853	NORDO; ATSC (FAA HQ DEN); ZDC; N800JR; EA50; MYRVGC; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available, aircraft transitioned into ZNY airspace OMIC advised. At 1905 requested status, no change. Communications re-
1909	established at 1910. COD: ATSC (FAA HQ DEN): ZKC: ASQ6070: E45X; DENSDF New Destination: MCI: Weather.
1909	COD; ATSC (FAA HQ DEN); ZAN; ERR8080; B190; ANCFAI New Destination: SSC; Weather.
1917	NORDO; ATSC (FAA HQ DEN); ZNY; N4558J; P28A; CDNUNV; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1920.
1933	NORDO; ATSC (FAA HQ DEN); ZME; RCH745; C17; BIF. CHS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1944.
1937	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOA; QXE377; DH8D; PDXSJC; PAX medical issue.
2006 2011	COD; ATSC (FAA HQ DEN); ZAB; GLA25F; B190; FMNSOW New Destination: PHX; Unreliable NDB at
2013	previous destination (SOW). NORDO; ATSC (FAA HQ DEN); ZDC; CJA771; B738; MDPPCYYZ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. 2014 ADW on battle stations. Communications re-established at 2022; ADW standing down.
2014	Err (1.0.8.0. 1152)
2023	EMERGENCY, COD, MECHANICAL; ATSC (FAA HQ DEN); ZBW; SWA749; B737; BOS BNA New Destination BWI; Rapid descent to 10,000 feet; pressurization problem. 2029 ZBW advised ACFT no longer emergency, will divert to BWI.
2030	ADMIN; ATSC (N/NC); MT on. Briefed by XS. WCLC.
2040	NORDO; ATSC (FAA HQ DEN); ZAB; XAEFL; H25B; GJTMMTO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 2048.
2053	COD: ATSC (FAA HQ DEN); ZTL; VNR196; P180; CEUMCO New Destination: PIE; Logistics.
2101	
	Fig. 4a 9.25.5. 43.5c

Page 4



Date: 04/09/2013

Element: ALL

Created by: CWard,

Created on: 04/10/2013 0428Z Checked by: CU

Log:	
Time (UTC)	Remarks
2101 2114	COD; ATSC (FAA HQ DEN); ZAB; GRYHK40; E2; NZYFOE New Destination: NZY; Mechanical issue. NORDO; ATSC (FAA HQ DEN); ZDC; N404TL; VELO; OGS14A; Aircraft reported on course, at assigned
2114	altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 2120.
2115	Braige Public Hillary
	Big on the entire gr
	Eng. (1. 1994) (1. 114 2) Reg. (1. 114) (1. 114) (2)
2115	TE 2
2118	COD; ATSC (FAA HQ DEN); AZO; FLG3667; CRJ2; DTWGRR New Destination: AZO; Weather.
2136	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZTL; SWA3849; B738; MDWRSW New Destination: BHM; Passenger medical emergency.
2138	EMERGENCY- MEDICAL, COD; ATŚC (FAA HQ DEN); ZJX; JBU277; A320; FLLSFO New Destination: MCO; Two flight attendants reportedly violently ill, ambulance standing by. Aircraft landed at 2220.
2145 2145	COD; ATSC (FAA HQ DEN); ZDV; SKW595M; CRJ2; DENBIS New Destination: DEN; Door open indication.
2146	7 <u>E</u> 17 (A) (B) V (C) (T) (T) (T) (T) (T) (T) (T) (T) (T) (T
2153	ATC FACILITY; ATSC (FAA HQ DEN); RAP; RAP Tower advised they are ATC-0 due to staffing/weather(blizzard conditions).
2200	
2200 2207	COD; ATSC (FAA HQ DEN); ZHU; LXJ519; CL30; MSYADS New Destination: MSY; Company request.
2213	EMERGENCY; ATSC (FAA HQ DEN); SHAD21; HAWK; NMMNMM; 7700 mode 2 observed north of Meridian WADS, ZME investigating. ZME advised engine issue. Aircraft landed at 2216.
2219	NORDO; ATSC (FAA HQ DEN); ZDC; BATON54; C130; MDTMDT; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2220.
2224	COD; ATSC (FAA HQ DEN); ZFW; EJA396; C680; DALRIL New Destination: EGE; Weather.
2229	COD; ATSC (FAA HQ DEN); ZJX; EJA625; C56X; AGSBHM New Destination: FLL; Company request. NORDO; ATSC (FAA HQ DEN); ZTL; AMX002; B763; LEMDMMMX; Aircraft reported on course, at assigned
2247	altitude. Attempting contact on Guard and with Company. 2302 NORDO 0+15; ZTL investigating. ZHU attempting contact via air to air on last known frequency. 2307 HQ DEN contacted AMX OPS. Communications re-established at 2310.
2251	COD; ATSC (FAA HQ DEN); ZOB; EJA125; BE40; TTNPKB New Destination: HVN; Company request.
2304	September 11 fer
2327	EMERGENCY, COD; ATSC (FAA HQ DEN); F11; UAL1737; B739; MCOCLE New Destination: MCO; Bird strike and overweight landing. Aircraft landed at 2323.
2328	EMERGENCY ; ATSC (FAA HQ DEN); ROC; N490JC; BE40; RDUROC; Landing gear issue. Aircraft landed at 2324.
2328	Propries. Here

Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552




Date: 04/09/2013

Element: Created by: Created on: Checked by: CWard, 04/10/2013 0428Z CU

Log:	
Time (UTC	Remarks
2333	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZKC; ZKC authorized to suspend change of destination
2340	reporting for AOR until 0200 due to weather. 0144 Extended until 0300. NORDO; ATSC (FAA HQ DEN); ZOA; N92884; PA46; MRYSLC; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2341.
2352	COD; ATSC (FAA HQ DEN); ZTL; EJA577; C56X; RYYAPF New Destination: PDX; Company request.
2356	NORDO,SIF; ATSC (FAA HQ DEN); ZAN; CHH496; A332; SEAZBAA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. Established communications with ACFT at 0059.
04/10/2013	
0001	Style May 1181c
0002	EMERGENCY ; ATSC (FAA HQ DEN); M98; G23884; H60; STPSTP; Cracked windshield. Aircraft landed at 0110.
8000	
0011	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ELM; AWI4075; CRJ2; PHLELM; PAX medical problem.
0033	NORDO; ATSC (FAA HQ DEN); ZAN; KAL036; B77W; ATLRKSI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0037.
0035	COD; ATSC (FAA HQ DEN); ZFW; EGF2984; E135; DFWCSG New Destination: DFW; Mechanical issue.
0037	COD; ATSC (FAA HQ DEN); IAH; EJA688; C56X; HOUSGR New Destination: HOU; Company request.
0049	COD; ATSC (FAA HQ DEN); ZFW; EMD21; BE9L; 1F0OKC New Destination: PWA; New destination (PWA) closer to hospital.
0100	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off.
0114	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; UAL1295; B738; IAHOKC; PAX medical issue (chest pains).
0128	LASER; ATSC (FAA HQ DEN); N90; GJS6218; CRJ7; LGARDU; 0052 ACFT reported cockpit illuminated by green LASER, at 3,000 feet, 8 W of LGA, northeastbound from left side. No injuries reported.
0140	COD; ATSC (FAA HQ DEN); ROC; AWI3895; CRJ2; BOS. BUF New Destination: ROC; Weather.
0147	COD; ATSC (FAA HQ DEN); ZAN; WAV760; PA31; FAI. TAL New Destination: FAI; Weather.
0200	ADMIN; ATSC (NCRCC); MX on duty. WCLC at 0215.
0200	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC.
0201	LASER; ATSC (FAA HQ DEN); PIT; WIG7465; C208; UNVPIT; Green laser, from left, illuminated cockpit at 6,000 feet, 11 miles E Pittsburgh. ACFT W bound, no injuries reported.
0204	LASER; ATSC (FAA HQ DEN); CAK; FLG4056; CRJ2; DTW. CAK; Green laser, from left, illuminated cockpit at
0211	4,000 feet, 1 mile W Akron, OH. ACFT SE bound, no injuries reported. EMERGENCY,COD; ATSC (FAA HQ DEN); STL; LOF9500; E145; STLMEZ New Destination: STL; Landing
0040	gear would not retract. Aircraft landed at 0207.
0218	NORDO, ATSC (FAA HQ DEN); ZJX; SWG645; B738; MUHGCYUL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0226.
0300	ADMIN; ATSC (NCRCC); VP off duty.
0317	COD; ATSC (FAA HQ DEN); ZMP; ASQ1355; E45X; DENORD New Destination: DLH; WX.
0318	LASÉR; ATSC (FAA HQ DÉN); VNY; FIRE3; Green laser, from right, illuminated helicopter at 1,300 feet, 3 miles SW Van Nuys. Helo N bound, no injuries reported.
0330	CONFERENCES; ATSC (NCRCC); NCRCC; CFACC Preamble for FALCON VIRGO 13-07a.
0333	COD; ATSC (FAA HQ DEN); ZAB; NVT613; PC12; IWASOW New Destination: IWA; WX.
0336	LASER; ATSC (FAA HQ DEN); DAY; TRS89; B712; ATLDAY; Green laser, from left, illuminated cabin at 3,000 feet, 10 miles E Dayton. ACFT NW bound, no injuries reported.

Page 6

FOR OFFICIAL USE ONLY



Log:		
Time (UTC) Remarks		
0339	29, definate line	
0344	NCR-COORDINATION; ATSC (NCRCC); NCRCC; COSMK41,42 airborne from ACY. GUARD DOG ATCAA active FL210-FL250.	
0359	ADMIN; ATSC (FAA HQ DEN); COB.	

Page 7

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552




Date: 04/10/2013

Element:	Created by:	Created on:	Checked by:
ALL	JFerrell,	04/11/2013 0405Z	JF

Security Event Statistics:				
Begins Million (C. 1) Begins Million (C. 1)	TOI: 1 TOI-US ADIZ: 1	NORDO: 21	COD: 50	
EMERGENCY: 15 EMERGENCY- MEDICAL: 11	TOT GO NOIL.	89, 49 U.S.C. 1141r.	LASER: 4	


Log:	
Time (U1	C) Remarks
04/10/20	13
0400	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC. CFPL: RAP ATC Zero; (ATC Zero canceled at 2015/DR).
0400	ADMIN; ÁTSC (NCRCC); NCRCC; MX on duty. CFPL: NASA Goddard LASER operations UFN, WCLC.
0400	NCR-COORDINATION, PAGED; ATSC (NCRCC); NCRCC; CFPL: 0330: CFACC Preamble for FALCON VIRGO 13-07a. 0345: COSMK41,42 airborne from ACY,GUARDDOG ATCAA active FL210-FL250. 0400: Falcon Virgo Exercise 13-07a commenced. 0418: VUL1 terminated, no issues. 0431: VUL2 commenced. 0450: VUL 2 terminated, no issues. 0504: VUL 3 commenced. 0517: COSMK41,42 RTB ACY. 0521: VUL 3 terminated, no issues. 0530: GUARDDOG ATCAA inactive. 0540: VUL 4 commenced. 0555: VUL 4 terminated, no issues. ENDEX at 0556.
0400	ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC.
0403	LASER; ATSC (FAA HQ DEN); MEM; FDX82; B752; MMQTMEM; Green laser, direction not reported, illuminated cockpit at 8,000 feet, 7 miles SW Memphis. ACFT N bound, no injuries reported.
0431	LASER; ATSC (FAA HQ DEN); N90; DAL2098; MD88; MIALGA; Green laser, direction not reported, illuminated cockpit (3 times) at 3,000 feet, 7 miles N La Guardia ARPT. ACFT SE bound, no injuries reported.
0438	COD; ATSC (FAA HQ DEN); ZTL; USC110; C208; CLT. LCK New Destination: CLT; Company request.
0517	EMERGENCY ; ATSC (FAA HQ DEN); ABI; EGF9808; E145; ABIABI; Faulty nose gear indicator. ACFT is a maintenance flight flying under EGR9808. Aircraft landed at 0525.
0546	LASER; ATSC (FAA HQ DEN); SAN; SWA3867; B737; HOUSAN; Green laser, from directly below the ACFT, struck at 2,200 feet, while on 7 mile final approach for RY27. No injuries reported.
0550	ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN.
0625	EQUIPMENT; ATSC (NCRCC); NCRCC; PCT performed successful cold start of RACD.
0831	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); HCF; OAE110; B762; LAS. PHNL; Sick PAX.
0842	COD; ATSC (FAA HQ DEN); ZKC; LBQ640; E50P; OKCIXD New Destination: MKC; WX.
0842	COD; ATSC (FAA HQ DEN); ZKC; LBQ652; E50P; DPAIXD New Destination: MKC; WX.
0849	COD; ATSC (FAA HQ DEN); ZMA; NKS632; A319; MDSTFLL New Destination: PBI; Fort Lauderdale closed.
0952	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); HCF; HAL8; A332; PHNLLAS New Destination: PHNL; Sick PAX.
1000	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1100: WCLC.
1000	ADMIN; ATSC (NCRCC); UL on duty. At 1015: WCLC.
1000	ADMIN'S ATSC (FAA HQ DEN); GR on HQE/HQW. WCLC.
1000	ADMIN; ATSC (FAA HQ DEN); CU off.
1055	EMERGENCY; ATSC (FAA HQ DEN); SCT; PAC214; B744; RJAALAX; Hydraulic failure. Aircraft landed at 1054.
1130	ADMIN; ATSC (CONR/AOC); BD on.

Page 1



Log:	18 4. v
Time (UTC	Remarks
1131	NORDO; ATSC (FAA HQ DEN); ZDC; AWE1254; A321; TPAPHL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Aircraft will fly over Capitol SFRA in approximately 10 minutes. 1142 HQ DEN contacted US Airways for tail number and SÖB count. Company operations attempting contact on ACARS, ARINC and all other means. HQ DEN requested FSS broadcast over NAVIADs. 250 JUNE 250
1145	ADMIN; ATSC (CONR/AOC); WCLC.
1200	ADMIN; ATSC (N/NC); KN on. Briefed by HQ. WCLC.
1204	89/ 59 Maket, 114 m
	89 (1994) (1994)
1211	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); BOS; JBU892; A320; MDSDBOS; Tower received call from Massport, of passenger medical emergency on board. ZBW was advised by HQ DEN.
1218	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAU; ZAU/ZID/C90 authorized to suspend change of destination reporting for AOR until 1800 due to weather. 1800 ZAU/ZID/C90 extended until 2000.
1243	COD, MECHANICAL; ATSC (NCRCC); PCT; UCA011; DH8B; IADCRW New Destination: IAD; Mechanical issue, non emergency.
1245	CONFERENCES; ATSC (N/NC); TACOPS conference complete. VIP movements, practice scrambles and monitoring foreign activity discussed.
1250	COD; ATŠC (FĀA HQ DĒN); ZBW; WIG1062; BE99; MHTRUT New Destination: BTV; Weather.
1316	
1319	TOI-US ADIZ,TOI; ATSC (CONR/AOC);
	ACABA A A
	19 9 400
1330	7 (Las. 19 & 5)
1336	
1330	
1343	EQUIPMENT; ATSC (FAA HQ DEN); HQ DEN position 1 main computer froze, required full system restart. System took 17 minutes to reboot.
1349	COD: ATSC (FAA HQ DEN); ZAB; SKW5547; CRJ2; ONTDEN New Destination: ONT; Mechanical.
1351	NORDO; ATSC (FAA HQ DEN); ZDV; PAC242; B744; CVGHNL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1355.
1404	837 48 MW.C. 1110.
1406	NORDO; ATSC (FAA HQ DEN); ZLC; AAR246; B744; ORDPDX; Aircraft reported on course, at assigned attitude. Attempting contact on Guard and with Company. Communications re-established at 1411.
1407	COD; ATSC (FAA HQ DEN); ZME; SFH533; EA50; PDK. JLN New Destination: SGF; Weather.
1417	COD; ATSC (FAA HQ DEN); ZTL; ASQ5441; CRJ2; ATLSHV New Destination: ATL; Mechanical.
1441	NORDO; ATSC (FAA HQ DEN); SAV; N111SN; P32R; VRB. CAE; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1445.
1451	EMERGENCY; ATSC (FAA HQ DEN); GSB; EAGLE11; F15; GSBGSB; Hung gun. Aircraft landed at 1458.
1454	NORDO; ATSC (FAA HQ DEN); ZAB; N800GM; C650; CCRDFW; Aircraft reported on course, at assigned

Page 2



Log:	
Time (ປ	rc)Remarks
145 9 1500	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1454. CONFERENCES; ATSC (CONR/AOC); CFACC test successful. ADMIN; ATSC (FAA HQ DEN); DR on HQE. WCLC.
1510 1510	COD; ATSC (FAA HQ DEN); ZOA; SWA370; B737; SMFPHX New Destination: LAS; Mechanical. NORDO; ATSC (FAA HQ DEN); ZLA; CGPDZ; HXB; 5AZ3IDA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. At 1529 requested status, no change ZLC attempting additional Guard calls and aircraft relay on previously assigned frequencies. Communications re-established at 1533.
1512	NORDO; ATSC (FAA HQ DEN); TPA; N612PZ; BE36; LNAPNS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1516.
1515	Strate United Strate
1518	EMERGENCY,COD; ATSC (FAA HQ DEN); ZAU; AAL459; B737; ORDMMUN New Destination: ORD; Lightning strike. Aircraft landed at 1538.
1527	VIP; ATSC (NCRCC); ADW; B737; ADWMDW; 1527 VIP departed ADW en route MDW.
1538	stransferinger
	Beg (9 756 111 p) Reject 755 114 p)
1547	NCR-COORDINATION, EQUIPMENT; ATSC (NCRCC); N5215E, C172, approved to enter SFRA with inoperative MODEC portion of transponder.
1601	CONFERENCES; ATSC (N/NC); TACOPS conference for foreign activity developing.
1607	NORDO; ATSC (FAA HQ DEN); ZKC; N278HN; C56X; HUTIAD; Aircraft reported on course, at assigned altitude, NORDO since 1555. Attempting contact on Guard. No satellite phone available. 1624 ZKC reported attempting contact via air to air and previous frequencies. At 1623 ZKC OMIC reported no change in status, reattempted Guard and GA Desk, attempting aircraft relay on previous frequencies. Communications reestablished at 1635.
1609	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ELM; ELM authorized to suspend change of destination reporting for AOR until 2000 due to WX.
1613	COD; ATSC (FAA HQ DEN); ZHU; SWA23; B733; ELP. DAL New Destination: AUS; Weather.
1617	200 (A. M. A.
1629 1636	COD; ATSC (FAA HQ DEN); S56; SKW4522; CRJ2; SLCGPI New Destination: SLC; Mechanical. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; NKS511; A319; DTWLAS; Two passengers with medical emergencies. ZMP and NKS Corporate reported illnesses are unrelated, aircraft will continue to original destination.
1641	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZHU; ZHU/ZFW authorized to suspend change of destination reporting for Dallas area airports until 2000 due to weather.
1654	VIP; ATSC (N/NC); Report July 2015 10 10 10 10 10 10 10 10 10 10 10 10 10
1700	ADMIN; ATSC (CONR/AOC); LB on.
1700	av, q+ 0.810. 114.E.
1705	COD; ATSC (FAA HQ DEN); ZOB; LOF5280; E145; IAD. CLE New Destination: IAD; Mechanical.
1706	NORDO; ATSC (FAA HQ DEN); ZAN; PAC237; B748; CVGRKSI; Aircraft is NORDO in Russian Territorial airspace. ZAN is assisted Russian ATC with communications efforts. Aircraft is west bound away from US airspace.
1721	NORDO; ATSC (FAA HQ DEN); ZAB; TRS539; B737; ATLLAX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1727.

Page 3



Element: Created by: Created on: Checked by: JFerrell, 04/11/2013 0405Z JF

Log:	
Time (UTC	Remarks
1721	NORDO; ATSC (FAA HQ DEN); ZAB; AAL1365; MD83; ORDPHX; Aircraft reported on course, at assigned
Ì	altitude. Attempting contact on Guard and with Company. Communications re-established at 1728.
1746	COD; ATSC (FAA HQ DEN); ZAN; PEN501; SF34; ANCDUT New Destination: CDB; Weather.
1747	NORDO; ATSC (FAA HQ DEN); N90; N19GR; B350; MFDCDW; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications
	re-established at 1750.
1800	ADMIN; ATSC (NCRCC); UL off duty.
1800	ADMIN; ATSC (FAA HQ DEN); RS/RV on HQE; WCLC.
1800	ADMIN; ATSC (NCRCC); VP on duty.
1815	ADMIN; ATSC (NCRCC); WCLC.
1815	ADMIN; ATSC (NCRCC); NCRCC; SH off.
1815	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZAB; SWA571; B733; LAXHOU New Destination:
	PHX; Passenger medical emergency.
1820	COD; ATSC (FAA HQ DEN); ZME; FLG3860; CRJ2; CLEDTW New Destination: FNT; Weather.
1844	COD; ATSC (FAA HQ DEN); ZMP; JOSA842; LJ35; COSBDL New Destination: GRB; Fuel.
1900	Bey 32 (0.8.2), 11 (4)
1902	Sq. D. Malet. Malet
1913	NORDO; ATSC (FAA HQ DEN); ZDV; AVA246; A319; SKBO. IAD; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. 1914 ADW Battle Stations. Communications re-
	established at 1918; ADW Standing Down.
1921	COD; ATSC (FAA HQ DEN); ZAN; ERR121; DH8A; FAIGBH New Destination: FAI; Weather.
1942	NORDO; ATSC (FAA HQ DEN); N90; N6600L; BE36; BEDLYH; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. 1957 NORDO 0+15 HQ DEN contacted
	FSOC and relayed contact information to N90 TRACON. 2002 HQ DEN contacted WRI Approach to get
	frequency; WRI advised the ACFT had switched to ACY Approach and then to came over to their frequency.
	Communications re-established at 2005.
1950	NORDO; ATSC (FAA HQ DEN); ZHU; N696CM; MU2; CWFDMN; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2002.
1951	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZKC; ASQ4455; E145; IAHICT; PAX medical issue.
2002	EMERGENCY; ATSC (FAA HQ DEN); ZMP; N92SL; BE17; GRIDEN; ZMP OMIC reported having received
1	two "MADAY" calls on subject aircraft in vicinity of Omaha. ZDV and ZKC OMIC's both advised of aircraft
	reports of receiving the MADAY call on 121.5. FSS data indicated negative VFR flight plan on file, negative
	contact information. UPDATE: At 2014 ZMP OMIC reported aircraft departed Grand Island, NE; VFR enroute to
	Denver, CO. UPDATE: At 2023 ZDV OMIC advised of receiving reports from aircraft indicating possible location
	approximately 30NM east of ONL VOR. CLOSEOUT: At 2120 ZMP OMIC reported aircraft landed safely at
	Broken Bow, NE. (BBW).
2006	NORDO; ATSC (FAA HQ DEN); MEI; N258SC; PA32; TLHRNV; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and previous frequencies. No satellite phone available, aircraft
	transitioned into ZME airspace. Communications re-established at 2008.
2008	COD; ATSC (FAA HQ DEN); ZKC; ASQ6189; E145; JAXORD New Destination: STL; Fuel.
2010	NORDO; ATSC (FAA HQ DEN); ZHU; SIS214; C750; SDLOPF; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications
	re-established at 2019.
2011	COD; ATSC (FAA HQ DEN); CMH; UCA822; DH8D; CLECMH New Destination: CLE; Nose gear issue.
2015	ATC FACILITY; ATSC (FAA HQ DEN); RAP; RAP back to normal operations (back from ATC-0; CFPL).
2025	COD; ATSC (FAA HQ DEN); SAT; SKW428L; CRJ2; SAT. DEN New Destination: SAT; Mechanical.
2027	ADMIN; ATSC (N/NC); MT on. Briefed by KN. WCLC.
2030	EMERGENCY-MEDICAL,COD; ATSC (FAA HQ DEN); ZMP; SWA822; B737; MDWLAS New Destination:

Page 4



Element:	Created by:	Created on:	Checked by:
ALL * 185	JFerrell,	04/11/2013 0405Z	JF

<u> </u>	
Time (UTC)	Remarks
	MCO; Sick PAX.
E .	COD; ATSC (FAA HQ DEN); ZDV; RPA3874; DH8D; DEN. FSD New Destination; DEN; Weather.
	COD; ATSC (FAA HQ DEN); ZHU; SKW590T; CRJ7; IAH.,DTW New Destination; MCI; Fuel.
	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; SWA1451; B737; MCOOKC New Destination: TPA: PAX medical issue.
2102	NORDO; ATSC (FAA HQ DEN); ZME; TWY717; CL30; TEBDAL; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 2118.
	COD; ATSC (FAA HQ DEN); ZJX; EJA681; C56X; HOU. LAL New Destination: SRQ; Airshow in progress.
	COD; ATSC (FAA HQ DEN); ZME; ASQ4914; CL30; ATLFSM New Destination: LIT; Weather.
2118	EMERGENCY ; ATSC (FAA HQ DEN); ZKC; SWA2791; B735; SATSTL; Pressurization issue. Aircraft landed at 2144.
2122	EMERGENCY ; ATSC (FAA HQ DEN); ZFW; MSTNG03; F16; NFWNFW; Equipment issue. Aircraft landed at 2137.
2135	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZME; ZME authorized to suspend change of destination reporting for AOR until 0200 due to WX. 0012 LIT added. 0142 ZME extended until 0359.
2138	SIF; ATSC (FAA HQ DEN); ZBW; CES588; A346; JFKZSPD; HQ DEN approved small deviation for weather.
2141	EMERGENCY, COD; ATSC (FAA HQ DEN); ZME; AAL1198; MD82; DFWRIC New Destination: BNA; Unreliable airspeed indicator. Aircraft landed at 2158.
2143	NORDO: ATSC (FAA HQ DEN); ZFW; N417PC; WW24; LGB.,CPT; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2148.
2148	CONFERENCES; ATSC (N/NC); ONEC test successful.
2148	CONFERENCES; ATSC (CONR/AOC); CFACC test successful.
2149	EMERGENCY ; ATSC (FAA HQ DEN); N2576T; PA46; GADOZW; Observed 7700 squawk on N2576T. ZOB advised ACFT was emergency with engine out. 2159 ZOB advised ACFT started the engine and is no longer emergency.
2211	COD; ATSC (FAA HQ DEN); ZSE; BOE371; B738; MWH. BFI New Destination; PAE; Pilot request.
2214	COD: ATSC (FAA HQ DEN); ZNY; PDT4629; DH8A; PHLERI New Destination: PHL; Weather.
2225	COD; ATSC (FAA HQ DEN); ZID; PRY08; PC12; LEX. CYO New Destination; LEX; Company request.
2229	NORDO; ATSC (FAA HQ DEN); ZJX; JBU277; A320; FLL. AUS; Aircraft reported on course, at assigned
2223	altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications reestablished at 2234.
2230	COD; ATSC (FAA HQ DEN); ZID; RCH697; C130; CYYTLRF New Destination: HOP; Change in mission
0000	requirements.
2233	COD; ATSC (FAA HQ DEN); ZHU; AWE157; A320; SANPHL New Destination: CLT; Fuel.
2234	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZNY; ZNY/N90 authorized to suspend change of
2005	destination reporting for NYC AOR until 0200 due to WX. 0142 Extended until 0359.
2235	COD; ATSC (FAA HQ DEN); ZAU; SKW5472; CRJ2; ORDSGF New Destination: ORD; Weather.
2235	VIP; ATSC (N/NC); 2016 10 3.0. THE CONTROL ; 2235 VIP departed MDW enroute to ADW. 0021 arrived ADW.
2246	COD; ATSC (FAA HQ DEN); ZDC; FSR103; LJ45; TEBORF New Destination: CMI; Company request.
2256	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZBW; ZBW/PHL authorized to suspend change of destination reporting for AOR until 0200 due to weather. 0142 Extended until 0359.
2258	EMERGENCY ; ATŠC (FAA HQ DEN); ZBW; FDX555; MD11; MEMBOS; Auto-pilot issue. Aircraft landed at 2315.
2300	ADMIN; ATSC (FAA HQ DEN); RS/RV on HQE/HQW.
2300	COD; ATSC (FAA HQ DEN); ZOB; SKW5193; CRJ7; CYYZIAH New Destination: ORD; Toilet problem.
2300	ADMIN; ATSC (FAA HQ DEN); DR off.
2302	COD: ATSC (FAA HQ DEN); ZSE; QXE118; DH8D; SEACYYC New Destination: SEA; Company request.

Page 5



Date: 04/10/2013

Element: Created by: Created on: Checked by: JFerrell, 04/11/2013 0405Z JF

Log:	
Time (UTC)	Remarks
2312 2339 2352 2352	COD; ATSC (FAA HQ DEN); A90; UAL1611; B738; BOSEWR New Destination: BOS; Weather. COD; ATSC (FAA HQ DEN); ZMP; EJA699; C56X; MSPAPA New Destination: OMA; Company request. COD; ATSC (FAA HQ DEN); ZAN; DAL173; B744; JFKRJAA New Destination: ANC; Electrical problem.
2354	EMERGENCY, COD; ATSC (FAA HQ DEN); ZOB; ASQ5216; CRJ7; MCILGA New Destination: JST; Electrical/navigation problem. 0004 ZOB advised ACFT diverting to PIT. Aircraft landed at 0015.
04/11/2013	
8000	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDV; SKW4565; CRJ7; OKCSLC New Destination: DEN; Sick PAX.
0011	VIP,PAGED; ATSC (NCRCC); Explain 9.56.5. 144.49
0016 0036 0050	COD; ATSC (FAA HQ DEN); ZOB; CHQ5078; E145; HPN. ORD New Destination: FNT; Company request. COD; ATSC (FAA HQ DEN); ZMP; UAL730; A320; SNA. ORD New Destination: DSM; Fuel. EMERGENCY; ATSC (FAA HQ DEN); SCT; ASA458; B738; SEALAX; Flap issue. Aircraft landed at 0049.
0053	EMERGENCY; ATSC (FAA HQ DEN); ZNY; VIR9M; A333; EGLLJFK New Destination: BDL; Fuel issue. Aircraft landed at 0053.
0100 0101	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off. EMERGENCY ; ATSC (FAA HQ DEN); ZKC; EGF2907; E135; DFWCVG; Air speed indicator issue. Aircraft landed at 0132.
0115	54 59 4.C.C. 115 59
	Proposition of the
0116	EMERGENCY- MEDICAL,COD; ATSC (NCRCC); PCT; POE728; DH8D; IADCYTZ New Destination: IAD; PAX medical emergency.
0123	COD; ATSC (FAA HQ DEN); ZMP; EGF4597; CRJ7; MSPLGA New Destination: MSP; Traffic volume at LGA.
0129	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZID; ZID authorized to suspend change of destination reporting for AQR until 0359 due to weather
0131	COD; ATSC (FAA HQ DEN); ZDV; GLA60N; B190; DENMCK New Destination: LBF; Company request.
0146	COD; ATSC (FAA HQ DEN); ZOB; FLG3833; CRJ2; CVGPIT New Destination: CVG; Weather.
0200	ADMIN; ATSC (NCRCC); VP off duty.
0200	ADMIN; ATSC (FAA HQ DEN); JF on HQE/HQW. WCLC.
0200 0211	ADMIN; ATSC (NCRCC); MX on duty. WCLC at 0215. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); IAH; IAH authorized to suspend change of destination
0213	reporting for AOR until 0359 due to thunderstorms. EMERGENCY; ATSC (FAA HQ DEN); ZDV; TETON38; C130; CYSCYS; Number 1 engine OTS. Aircraft landed at 0223.
0228	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDC; AWE30; A320; LAXPHL; Male PAX passed out.
0244	Ser. 43 T.S.C. 116-92
0252	NORDO; ATSC (FAA HQ DEN); ZBW; POE145; DH8D; CYTZEWR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0253.
0319	Regular Malaca (1904) Regular Malaca (1904)
0336	LASER; ATSC (FAA HQ DEN); SJC; N650MC; PC12; SNA. SJC; Cockpit was illuminated by green laser on left side at 3,300 feet while on 8 mile final to RWY 30L. No injuries reported.

Page 6

FOR OFFICIAL USE ONLY

FAA Air Traffic Organization NAS Daily Events Log			Date : 04/10/2013	
Element: Created by: JFerrell,		Created on: 04/11/2013 04	05Z Checked JF	by:
Log:				
Time (UTC	Remarks			
0359	ADMIN; ATSC (FAA HQ DEN); COB.			

Page 7

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/11/2013


Element:	Created by:	Created on:	Checked by:
ALL	JFerrell,	04/12/2013 0402Z	JF

Security Event Statistics:				
EMERGENCY: 14	TOI: 1 TOI-US ADIZ: 1	AIRPORT: 1 NORDO: 20	COD: 58 LASER: 7	
EMERGENCY- MEDICAL 13	:	Bt; 40 7.8.d. 11142		

Log:	
Time (UTC	Remarks
04/11/2013	
0400	ADMIN; ATSC (N/NC); MT on. CFPL; None. WCLC.
0400	ADMIN; ATSC (NCRCC); MX on duty. CFPL: NASA Goddard LASER operations UFN. WCLC.
0400	ADMIN; ATSC (FAA HQ DEN); JF on HQW/HQE, WCLC. CFPL: Disturbance, Level 2- UAL1556. 0555 CLOSEOUT: Deemed customer service, PAX allowed to continue.
0427	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLA; AAL1775; B738; ORDSNA New Destination: LAS; PAX ill.
0431	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZSE; ASA7; B738; EWRSEA; PAX ill.
0434	COD; ATSC (FAA HQ DEN); ZNY; UAL62; B752; EWRLEMD New Destination: EWR; Mechanical.
0439	COD; ATSC (FAA HQ DEN); ZTL; USC141; LJ35; CLTSTL New Destination: TYS; Company request.
0441	LASER; ATSC (FAA HQ DEN); SAT; ASH2847; CRJ2; PHXSAT; Cockpit was illuminated by green laser from the right side while heading SE at 11,000 feet 10 miles W of SAT. No injuries reported.
0448	LASER; ATSC (FAA HQ DEN); SDF; UPS1303; MD11; ATLSDF; Cockpit was illuminated by green laser from the left side while heading S at 3,000 feet 15 miles NNW of SDF. No injuries reported.
0453	LASER; ATSC (FAA HQ DEN); I90; NDU603; PA28; VFRVFR; Cockpit was illuminated by green laser from the back side of the aircraft while heading NW at 6,000 feet 10 miles WNW of IAH. No injuries reported.
0459	NORDO; ATSC (FAA HQ DEN); ZME; FDX1290; A306; RNOMEM; Aircraft reported on course, at assigned altitude, Attempting contact on Guard and with Company. Communications re-established at 0500.
0500	EQUIPMENT; ATSC (NCRCC); PCT; BWI ASR OFM. RTS 0820.
0518	92) 12 July 12 11 12 12
0530	EQUIPMENT; ATSC (NCRCC); PCT performed successful cold start of RACD.
0550	ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN.
0619	COD; ATSC (FAA HQ DEN); ZTL; RAX81; BE10; FTY. BWI New Destination: RIC; Fuel.
0646	LASER; ATSC (FAA HQ DÉN); PHX; AWÉ1556; A321; PHXCLT; Cockpit was illuminated by green laser from the left side while heading E at 11,000 feet 20 miles SE of PHX. No injuries reported.
0800	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDV; AAL2013; MD82; ORDLAX; PAX ill.
0941	84; 43 U.S.C. 111 1 84; 43 U.S.C. Hart
1000	ADMIN; ATSC (NCRCC); NCRCC; MX Off.
1000	ADMIN; ATSC (FAA HQ DEN); GR on HQE/HQW. WCLC.
1000	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1100: WCLC.

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552




Element: Created by: Created on: Checked by: JFerrell, 04/12/2013 0402Z JF

Log:	
Time (U	TC) Remarks
1018	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZOB; ZOB/ZID/ZME/ZTL/ZHU/ZJX/CAE/BTR/MSY authorized to suspend change of destination reporting for AOR until 1800 due to weather. Extended until 0200, except BTR/RV.
1032	LASER; ATSC (FAA HQ DEN); P50; UPS856; B752; RFDPHX; Cockpit was illuminated by green laser from the right side while heading SW at 9,000 feet 10 miles NE of PHX. No injuries reported.
1058	COD; ATSC (FAA HQ DEN); CVG; EGF2711; E145; CVGDFW New Destination: CVG; Mechanical.
1130	ADMIN; ATSC (CONR/AOC); BD and PM on. WCLC.
1137	COD; ATSC (FAA HQ DEN); ZID; CHQ5034; E135; SDFORD New Destination: SDF; Lightning strike, no damage.
1142	COD; ATSC (FAA HQ DEN); MIA; WMA121; C208; FXEMYAN New Destination: MYAK; Company flied wrong destination.
1143	NCR-COORDINATION; ATSC (NCRCC); NCRCC; BAYFLIGHT 1: C172, N739CN will depart FDK this morning and fly on the east side of the SFRA down toward ORF. BAYFLIGHT will return on east side of SFRA and land FDK approximately 2000.
1146	178 og (\$1.00)
1200	ADMIN; ATSC (N/NC); KN on. Briefed by HQ. WCLC.
1221	EMERGENCY; ATSC (FAA HQ DEN); ZME; AAL471; MD82; RICDFW; Electrical problem. 1247 Aircraft resolved problem, emergency cancelled.
1233	Bay as Tus c. 114 m
1300	CONFERENCES; ATSC (N/NC); TACOPS conference complete. VIP status and foreign activity discussed.
1303	20, 40 July 116 m
1316 1319	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); FAY; ASQ5127; CRJ2; ATLFAY; Sick passenger. COD,EQUIPMENT; ATSC (NCRCC); ZNY; C102; GLF5; DCABGR New Destination: DCA; COD: Equipment
1328	issue. NORDO; ATSC (FAA HQ DEN); FAY; N607SR; SR22; W03DNL; Aircraft reported on course, at assigned attitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1338.
1347	29 se that is the se
1359	COD: ATSC (FAA HQ DEN): ZMA: FIV699; C680: BCT. DAL New Destination: MCO: Mechanical.
1412	COD: ATSC (FAA HQ DEN); NCT: FDX1490; A310; MEM. RNO New Destination: SMF; Weather.
1417	NORDO; ATSC (FAA HQ DEN); ZAU; N744RV; PA46; ORD. FAM; Aircraft reported on course, at assigned attitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1427.
1441	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZHU; UAL735; A320; MIAIAH; Sick passenger.
1444	
1453	COD; ATSC (FAA HQ DEN); ZTL; AAY9886; MD83; TYSPIE New Destination: SFB; Company request.
1454	COD; ATSC (FAA HQ DEN); SBA; AMF1942; SW4; BUR. SBP New Destination: SMX; Weather.
1526	COD; ATSC (FAA HQ DEN); ZDV; VNR156; P180; SDL. RIL New Destination: GJT; Company request.
1545	INTEL; ATSC (NCRCC); NCRCC; Spent time tracking down Intel briefing per AJR management request. Document located and AJR management notified of its classification and location.
1545	23; 40 TURC BESS
1557	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZLC; SWA270; B737; MDWSEA New Destination: BIL; Electrical fumes in cabin. Aircraft landed at 1606.
1600	ADMIN; ATSC (FAA HQ DEN); DR on HQE, WCLC.
1600	ADIVIN, A 130 (FAA NO DEN), DA ON NO NOCE, WOLC.

Page 2



Element:	Created by:	Created on:	Checked by:
ALL	JFerrell,	04/12/2013 0402Z	JF



Page 3



Element:Created by:Created on:Checked by:ALLJFerrell,04/12/2013 0402ZJF

Log:		_
Time (UTC	Remarks	-
1921	COD; ATSC (FAA HQ DEN); ZAB; PKW629; SW4; YIP. ELP New Destination: AMA; Physiological issue.	-
1929	CONFERENCES; ATSC (N/NC); TACOPS for foreign activity.	
1931	NORDO; ATSC (FAA HQ DEN); HTS; N9190R; NAVI; CKBFFT; Aircraft reported on course, at assigned	
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1941.	
1933	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZBW; CJA661; B738; MMUNCYQM New Destination: BOS; Passenger medical emergency.	:
1935	NORDO; ATSC (FAA HQ DEN); ZJX; EJA628; C56X; CHSPBI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1940.	
1935	NORDO; ATSC (FAA HQ DEN); ZME; N304EM; CL30; IAHAGS; Aircraft reported on course, at assigned	
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1939.	
1940	NORDO; ATSC (FAA HQ DEN); ZMA; AWE1033; B752; TJSJCLT; Aircraft reported on course, at assigned	
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1953.	
1945	COD; ATSC (FAA HQ DEN); ZTL; DAL844; MD83; ATLOMA New Destination: ATL; Mechanical issue.	
1954	COD; ATSC (FAA HQ DEN); ZDC; SWA51; B733; BWIMSY New Destination: BWI; Mechanical.	
2000	ADMIN; ATSC (FAA HQ DEN); RS/RV on HQE/HQW.	
2001	OTHER; ATSC (FAA HQ DEN); ZAB; ZAB exempt from change of destination reporting until 0200 for	
	Scottsdale (SDL)/until runway reopened. ZAB advised Scottsdale RY reopened.	
2010	COD; ATSC (FAA HQ DEN); ZHU; EGF3438; E145; DFWGPT New Destination: MSP; Fuel.	
2019	NORDO; ATSC (FAA HQ DEN); ZME; AJI483; FA20; YIPHKS; Aircraft reported on course, at assigned	
	altitude. Attempting contact on Guard and with Company. 2022 ZME advised to spoke to AJI ops to send	
	message to ACFT. Communications re-established at 2028.	
2025	COD; ATSC (FAA HQ DEN); ZNY; EJA878; H25B; IADBOS New Destination: BED; Company request.	
2027	COD; ATSC (FAA HQ DEN); ZMA; SWA364; B737; PBI. PHL New Destination: MCO; Flap problem/fuel.	
2028	ADMIN; ATSC (N/NC); MT on. Briefed by KN. WCLC.	
2038	COD; ATSC (FAA HQ DEN); ZOB; INDY61; K35R; COSSWF New Destination: GUS; Mission change.	
2052	EMERGENCY; ATSC (FAA HQ DEN); BLURR02; F22; PAMVAD; Fuel issue. Aircraft landed at 2106.	
2053	COD; ATSC (FAA HQ DEN); ZID; FLG3795; CRJ2; ATLFWA New Destination: IND; Weather.	
2104	COD; ATSC (FAA HQ DEN); ZAU; SWA2051; B737; PITMDW New Destination: IND; Weather.	
2108	COD; ATSC (FAA HQ DEN); ZAU; EJA306; C680; RSTGYY New Destination: VPZ; PAX request.	
2112	EMERGENCY; ATSC (FAA HQ DEN); VVSD123; F18; NHKNKT; Observed 7700 code inbound to NKT; contacted Navy Oceana. Equipment Issue. Aircraft landed at 2115.	
2114	COD; ATSC (FAA HQ DEN); ZTL; ROGUE33; C130; WRBHIF New Destination: WRB; Lost radar.	
2118	NORDO; ATSC (FAA HQ DEN); ZLA; AAR204; B772; RKSILAX; Aircraft reported on course, at assigned	
2122	altitude. Attempting contact on Guard and with Company. Communications re-established at 2119.	
22	NORDO; ATSC (FAA HQ DEN); ZMP; N701MK; SR22; FAR. MDW; Aircraft reported on course, at assigned	
2123	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2127.	
2130	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDV; FFT135; A319; DFWDEN; Sick PAX.	
2130	ADMIN; ATSC (CONR/AOC); CFACC test successful.	
2134	COD; ATSC (FAA HQ DEN); ZMC; EJA659; C56X; IADDFW New Destination: LIT; Fuel.	
2 134	NORDO; ATSC (FAA HQ DEN); ZKC; UAL1451; B737; AUS. EWR; Aircraft reported on course, at assigned	
2148	altitude. Attempting contact on Guard and with Company. Communications re-established at 2139.	
2149	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; CJA995; B738; MHROCYUL; Sick PAX.	
143	NORDO; ATSC (FAA HQ DEN); ZJX; MJI44; FA10; MMUNPMP; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and NBAA desk. No satellite phone available. Communications reestablished at 2153.	
2150		
2 150	NORDO; ATSC (FAA HQ DEN); ZJX; N5550CE; FA50; AWMOPF; Aircraft reported on course, at assigned	
2156	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2154. COD; ATSC (FAA HQ DEN); ZAU; FDX542; B752; MEM. GFK New Destination: MEM; Company request.	

Page 4



Element: ALL	Created by: JFerrell.	Created on: 04/12/2013 0402Z	Checked by:
	or circui,	04/12/2013 04022	JF

Log:	
Time (UTC)Remarks
2156	EMERGENCY; ATSC (FAA HQ DEN); ZLC; SKW1357; E120; DENSLC; Smoke in cockpit. Aircraft landed at
2158	2205. EMERGENCY,COD; ATSC (FAA HQ DEN); N90; GJS6285; CRJ7; LGACLT New Destination: LGA; Flight control issues. Aircraft landed at 2200.
2201	COD; ATSC (FAA HQ DEN); ZHU; FDY2407; PA31; VCTIAH New Destination: VCT; Landing gear issue.
2221	
2221	COD; ATSC (FAA HQ DEN); ZMA; YV1740; BE20; TPAFXE New Destination: TPA; Weather. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZHU; UAL1087; B739; SMFIAH; Sick PAX.
2233	CONFERENCES; ATSC (N/NC); ONEC test successful.
2238	So to the pro-
2230	2 g 49 (1.3.5) 111 ps
	Est Vallett, Udar
2245	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); F11; TRS148; B737; TJSJMCO; Sick PAX.
2247	NORDO; ATSC (FAA HQ DEN); ZOA; AAL432; B737; SFODFW; Aircraft reported on course, at assigned attitude. Attempting contact on Guard and with Company. Communications re-established at 2300.
2254	COD; ATSC (FAA HQ DEN); PHL; RPA4908; DH8D; DCAEWR New Destination: PHL; WX.
2258	COD; ATSC (FAA HQ DEN); ZTL; GTW2325; B350; AIKHUF New Destination: GSO; Maintenance issue.
	2303 ZTL advised ACFT returning to original destination (HUF). 2310 ZTL advised ACFT going to GSO now.
2259	COD; ATSC (FAA HQ DEN); ZTL; ASQ5013; CRJ2; PHFATL New Destination: CSG; Fuel.
2302	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; CFG188; B763; EDDFMUVR; Sick PAX.
2305	COD; ATSC (FAA HQ DEN); ZOA; EJA998; C750; EKOVNY New Destination: LAX; Company request.
2311	COD; ATSC (FAA HQ DEN); ZHU; ASQ4629; E145; IAHLIT New Destination: IAH; Pressurization problem.
2327	NORDO,FAM-ONBRD; ATSC (FAA HQ DEN); ZBW; DAL228; B763; CVGLFPG; Aircraft reported on course,
	at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2329.
2328	COD; ATSC (FAA HQ DEN); ZOA; EJA894; H25B; CECBUR New Destination: SFO; Company request.
2336	EMERGENCY, COD; ATSC (FAA HQ DEN); ZTL; AAL683; MD83; CLTDFW New Destination: CLT; Smoke in
İ	cabin. Aircraft landed at 2343.
2347	COD; ATSC (FAA HQ DEN); ZTL; JZA624; CRJ9; ATLCYYZ New Destination: ATL; Equipment issue.
04/12/2013	
0013	COD; ATSC (FAA HQ DEN); ZLA; AAY188; MD83; IWABZN New Destination: LAS; Instrument problem.
0018	EQUIPMENT; ATSC (FAA HQ DEN); ADAPT not tracking; NCRCC monitoring for HQ DEN; contacted ADAPT
	help desk and reported outage. 0047 Help desk advised there is a power outage in the telco unit that feeds
İ	ADAPT in the HQ building and they are getting C3 personnel to investigate further. 0119 C3 advised this was a
	scheduled outage linked to fire alarm testing for the building until 0230; declined option to move to design center
	since return to service is scheduled for 0230. 0232 ADAPT RTS.
0023	NORDO; ATSC (FAA HQ DEN); ZAB; SKW224Y; CRJ2; PHXBFL; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 0023.
0028	COD; ATSC (FAA HQ DEN); ZID; CNS13; PC12; MQY. YIP New Destination: ARB; Company request.
0044	NORDO; ATSC (FAA HQ DEN); ZAU; ASH3792; CRJ7; ORDCLT; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications re-
	established at 0045.
0057	NORDO; ATSC (FAA HQ DEN); ZDC; VRD127; A320; PHLLAX; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications re-
0400	established at 0101.
0100	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off.
0101	COD; ATSC (FAA HQ DEN); ZID; AWI3641; LEXCLT New Destination: TRI; Weather/fuel.
0103	MECHANICAL; ATSC (FAA HQ DEN); ZTL; ASQ4926; CRJ2; XNAATL; Lightning strike.
0104	EMERGENCY ; ATSC (FAA HQ DEN); ZTL; ASQ5482; CRJ2; CRWATL; Hydraulic issue. Aircraft landed at
1	0125.

Page 5



Date: 04/11/2013

Element: Created by: Created on: Checked by: JFerrell, 04/12/2013 0402Z JF

Log:	
Time (UTC)	Remarks
0110	COD; ATSC (FAA HQ DEN); ZBW; EJA693; C56X; PYM. HPN New Destination: BOS; Company request.
0117	COD; ATSC (FAA HQ DEN); ZAN; NAC70; B732; ANCDLG New Destination: ANC; Mechanical issue.
0119	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZTL; ZTL/ZJX authorized to suspend change of
	destination reporting for AOR until 0359 due to line severe thunderstorms.
0124	Brando Marce, 110-1
	335 N.S. 3371 33831
04.40	SIL OF THE MEAN HELD
0140	COD; ATSC (FAA HQ DEN); ZMP; MRA603; C208; APN. LAN New Destination: ASW; Company request.
0145	0141 ZMP advised ACFT now going back to LAN. EMERGENCY; ATSC (FAA HQ DEN); ZMP; SKW4724; CRJ2; MSPATW; Mechanical issue. Aircraft landed
0 145	at 0145.
0200	ADMIN; ATSC (FAA HQ DEN); JF on HQE/HQW/NCRCC. WCLC.
0200	ADMIN: ATSC (FAA HQ DEN): RS/RV off.
0201	EQUIPMENT; ATSC (FAA HQ DEN); NORAD is monitoring ADAPT due to HQ DEN outage. 0232 HQ DEN
	resumes monitoring of country.
0207	EMERGENCY; ATŠC (FAA HQ DEN); ZSE; GRUDA22; A6; NUWNUW; Pressure problem. Aircraft landed at
	0237.
0207	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZJX; AAL1787; B738; JFKTPA; PAX ill.
0236	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAU; ZAU authorized to suspend change of destination
	reporting for Chicago Metro Area until 0359 due to WX/ thunderstorms.
0253	COD; ATSC (FAA HQ DEN); ZID; FDX1362; B722; ROAMEM New Destination: GSP; Company request.
0259	AIRPORT; ATSC (FAA HQ DEN); ORD; Runway and Taxiway lighting failure on north side of Chicago (ORD)
	airport. Only one runway available for arrivals and one for departures. Ground delay program in effect. HQ DEN
0305	confirmed ATCSCC was aware of lighting problem. COD; ATSC (FAA HQ DEN); ZTL; UPS3367; A306; PNSTYS New Destination: PNS; Maintenance.
0305	ADMIN: ATSC (NCRCC); VP off duty.
0325	LASER; ATSC (FAA HQ DEN); PHX; AWE665; A319; SNAPHX; Cockpit was illuminated by green laser on left
0020	side white heading NW at 7,000 feet 5 miles SE of PHX. No injuries reported. PHX PD notified at 602-273-3311.
0327	LASER; ATSC (FAA HQ DEN); C90; SWA3160; B737; PIT. MDW; Cockpit was illuminated by green laser on
	left side while heading 310 at 600 feet on final to runway 31C. No injuries reported.
0335	NORDO; ATSC (FAA HQ DEN); ZJX; WJA1166; B737; CYYZMCO; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. HQ DEN gave phone number to ZJX.
	Communications re-established at 0341.
0348	EMERGENCY, COD; ATSC (FAA HQ DEN); ZFW; FLX491; C210; HOUADS New Destination: CRS; Engine
L	problem. Aircraft landed at 0358.
0354	COD; ATSC (FAA HQ DEN); ZMP; FDX1393; B752; GFKMEM New Destination: MKE; Company request.
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 6



Date: 04/12/2013

	ALL Created JFerrell,	by: Created on: 04/13/2013 04042	Checked by: Z JF
--	-----------------------	----------------------------------	-------------------

Security Event Statistics: TOI: 1 TOI-US ADIZ: 1 EMERGENCY- MEDICAL: NORDO: 23 MOR: 2

Log:		
Time (UTC	Remarks	
04/12/2013		
0400	ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC.	
0400	ADMIN; ATSC (FAA HQ DEN); JF on HQW/HQE/NCRCC. WCLC. CFPL: NASA Goddard LASER operations UFN.	
0416	LASER; ATSC (FAA HQ DEN); DEN; SWA2969; B737; MKEDEN; Cockpit was illuminated by green laser on the left side while heading W at 1,100 feet 10 miles W of DEN. No injuries reported.	
0459	LASER; ATSC (FAA HQ DEN); PDX; UAL595; B752; SFOPDX; Cockpit was illuminated by green laser on right side while heading W at 1,200 feet 4 miles E of PDX. No injuries reported.	
0504	LASER; ATSC (FAA HQ DEN); SCT; N388S; C182; VFRVFR; Cockpit was illuminated on left side while heading W at 4,000 feet 8 miles E of Chino. No injuries reported.	
0550	ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN.	
0654	NORDO; ATSC (FAA HQ DEN); ZTL; USC1910; LJ35; LCKFMY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. HQ DEN provided ZTL with company phone number. Communications re-established at 0658.	
0831	99 38 0020 1114 1 89 3 4 90 1	
	Regular status. 184 as	
0945	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZOA; UAL200; B772; HNLLAX New Destination: SFO PAX ill.	
1000	ADMIN; ATSC (NCRCC); NCRCC; MK on. NCRCC decombined from HQ DEN. WCLC. NASA Goddard LASER operations ongoing.	
1000	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1100: WCLC.	
1000	ADMIN; ATSC (FAA HQ DEN); GR on HQE/HQW. WCLC. NCRCC briefed and resuming normal operations.	
1025	EQUIPMENT; ATSC (NCRCC); NCRCC; NCRCC ADAPT OTS, left a message for the help desk. 1205: ADAPT RTS.	
1028	EQUIPMENT; ATSC (FAA HQ DEN); NCRCC ADAPT OTS. HQ DEN monitoring SFRA. RTS 1206, normal operations.	
1037	COD; ATSC (FAA HQ DEN); BDL; UPS2114; B752; JFKBDL New Destination: PHL; Company request.	
1040	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDC; ZDC/ZNY/ZBW/ZOB/ZJX/N90/PCT/BTV/A90	
1043	authorized to suspend change of destination reporting for AOR until 1800 due to weather. EMERGENCY , COD; ATSC (FAA HQ DEN); ZAB; N855SA; GLF3; LYHCMA New Destination: AMA; Engine fire. Aircraft landed at 1059.	
1045	NORDO; ATSC (FAA HQ DEN); CPZ5731; E170; BISMSP; Aircraft reported on course, at assigned altitude,	

Page 1



Date: 04/12/2013

Element: Created by: Created on: O4/13/2013 0404Z JF

Log:	
Time (UTC)	Remarks
	squawking 7600. ZMP notified and investigating. 1046 ZMP reported aircraft having transmitter problems, can receive but not transmit, is responding to instructions via transponder ident. Communications re-established at 1051.
1048	NCR-COORDINATION; ATSC (NCRCC); PCT; DCA230016, CNS50, PC12, inbound IAD is deviating for a thunderstorm over the airport, deviation may require transition of the FRZ on the western edge.
1130	ADMIN: ATSC (CONR/AOC); BD and PM on, ADAPT has no tracks. Help desk notified.
1146	ADMIN; ATSC (CONR/AOC); WCLC. ADAPT RTS.
1200	ADMIN; ATSC (N/NC); N/NC; VM on, briefed by HQ. WCLC, ADAPT OTS.
1204	NORDO,MOR,PAGED; ATSC (FAA HQ DEN); ZID; MWT139; BE9L; MKTRIC; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 1224 HQ DEN contacted company to attempt messaging to pilot. ZID has reviewed tapes and attempted air to air and previous frequencies. 1234 aircraft NORDO + 30 minutes, aircraft is approaching normal descent point. 1238 aircraft observed identing. 1249 aircraft + 45 minutes. 1250 HQ DEN contacted FBO at RIC, they are expecting arrival of aircraft and will transmit to aircraft to relay ATC frequency. Communications re-established at 1252. Pilot issued Brasher warning, ZID filed MOR. Aircraft NORDO for 48 minutes.
1207	EMERGENCY, COD; ATSC (FAA HQ DEN); BTV; EJA726; GALX; BTVMMU New Destination: BTV; Smoke in cockpit. Aircraft landed at 1122.
1208	EQUIPMENT; ATSC (N/NC); N/NC; ADAPT RTS.
1208	COD; ATSC (NCRCC); NCRCC; SWA215; B738; BDLBWI New Destination: ORF; COD: WX, Cells over BWI
1216 1241	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZME; DAL1971; A319; MSNATL; Sick passenger.
	Ber 35 7.8 110 re
	39, or 3,877, 127 (
1242	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZKC; AAL2324; MD83; DFWORD New Destination: STL; Sick passenger.
1300	F1. Stock passedings.
1302	CONFERENCES; ATSC (N/NC); N/NC; TACOPS Conference complete.
1303	COD; ATSC (FAA HQ DEN); A90; JIA519; CRJ2; MHT. DCA New Destination: MHT; Mechanical.
1306	COD; ATSC (FAA HQ DEN); N90; CHQ6045; E145; LGA. CLE New Destination: LGA; Mechanical.
1319	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOA; DAL1152; B752; HNLSFO; Sick passenger.
1345	ADMIN; ATSC (FAA HQ DEN); JV/RV on HQE/HQW. GR on HQC.
1350	NOTAM; SOSC (FAA HQ); FDC NOTAM 3/1614 published for VIP movement to Wilmington, Delaware from
	1304121945-1304122100. Spans = 18,571.
1417	NORDO, MOR; ATSC (FAA HQ DEN); ZOB; N316GC; BE20; GAI140; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1428 Contacted FSOC to transmit to instruct PIC to change the ZOB frequency 124.4 using IHD (Seven Springs, PA). 1436 FSOC advised they transmitted


Page 2



Element:	Created by:	Created on:	Checked by:
ALL	JFerrell,	04/13/2013 0404Z	JF

Log:	
Time (UTC	Remarks
	using Morgantown, PA. 1423 NORDO 0+15 Used contact info to call landline for PIC; no answer. 1430 NORDO 0+22 ZDC advised they received ACFT NORDO from PCT; PCT checking tapes. Communications reestablished at 1448; ZDC will read brasher/file MOR.
1423	COD; ATSC (FAA HQ DEN); ZOB; PRY03; C208; ERIBUF New Destination: CLE; Weather.
1444	COD; ATSC (FAA HQ DEN); M98; PAT901; SH33; FFTIRK New Destination: LNK; Pilot request.
1454	NORDO; ATSC (FAA HQ DEN); ZHU; N449LC; AC90; IXDCRP; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1503.
1500	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful.
1501	NORDO; ATSC (FAA HQ DEN); ZHU; C6001; H60; MOBMOB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1505.
1506	NORDO; ATSC (FAA HQ DEN); ZHU; N203A; GLF5; GOOYIAH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. 1510 HQ DEN attempted on listed satellite phone; no answer. Communications re-established at 1518.
1510	COD; ATSC (FAA HQ DEN); ZME; MOON71; BE40; GTRLIT New Destination: CBM; Company request.
1520	
1530	COD; ATSC (FAA HQ DEN); N90; ASQ4409; E145; EWRRIC New Destination: EWR; Pressurization problem.
1533	EMERGENCY ; ATSC (FAA HQ DEN); ZBW; PACK11; K35R; PSMPSM; Pressurization problem. Aircraft landed at 1605.
1537	EMERGENCY , COD; ATSC (FAA HQ DEN); ZFW; AAL712; B752; DFWLGA New Destination: DFW; Right engine ots. Aircraft landed at 1555.
1545	CONR-COORDINATION; ATSC (CONR/AOC); Called ILG ATCT and PHL approach to ensure they were aware of FDC NOTAM 3/3614 at Wilmington, DE 4/12/2013 1945-2100.
1549	COD; ATSC (FAA HQ DEN); ZBW; EJM202; C680; TEB. BOS New Destination: SWF; Indicator light.
1550	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLA; AAL1193; B752; DFW. SNA; PAX medical problem.
1554	CONFERENCES; ATSC (N/NC); N/NC; ONEC Test successful.
1557	EMERGENCY , COD; ATSC (FAA HQ DEN); ZLA; AAL1342; B738; LAXRDU New Destination: LAX; Pressurization problem/overweight. Aircraft landed at 1608.
1559	NORDO; ATSC (FAA HQ DEN); ZJX; N53LE; BE36; ZPHAIK; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1602.
1610	COD: ATSC (FAA HQ DEN); ZAB; TWY21; C25B; LAS. DAL New Destination: AFW; Pilot request.
1620	ADMIN: ATSC (FAA HQ DEN); RV on HQW, GR on HQE.
1622	TOI-US ADIZ, TOI; ATSC (CONR/AOC); EADS; N60078; BE76; MYBSFXE; EADS Unknown, Fort Lauderdale (FLL)110037, 1230 code, heading 310 degrees, indicating 900 feet and 140 knots. 1625 EADS identified track as N60078, BE76, South Bimini (MYBS) to Fort Lauderdale Executive (FXE). Track was on assigned code entire time. NFA.
1625	EMERGENCY; ATSC (FAA HQ DEN); ZBW; SNOOP56; C130; EGUNBGR; Engine problem. Aircraft landed at 1653.
1633	COD; ATSC (FAA HQ DEN); ZME; MWT44; BE20; LALLJF New Destination: MWA; Fuel.
1655	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Received coordination for a military exercise commencing in the NCR. 1800: Klaxon for the exercise.
1700	ADMIN; ATSC (CONR/AOC); LB on.
1703	ADMIN; ATSC (FAA HQ DEN); RV on HQE/HQW, GR on HQC.
1713	COD; ATSC (FAA HQ DEN); ZJX; EJA389; C680; SFBBNA New Destination: PBI; Company request.
1715	EMERGENCY; ATSC (FAA HQ DEN); ZSE; WANG2; F16; LMTLMT; Engine problem. Aircraft landed at 1720.
1716	COD; ATSC (FAA HQ DEN); ZME; PAT986; BE20; DAALIT New Destination: MEM; Mission change.
1719	COD; ATSC (FAA HQ DEN); ZAB; PKW643; SW3; YIPAMA New Destination: ELP; Company request.
1725	EMERGENCY, COD; ATSC (FAA HQ DEN); FDY2455; PA31; HGR. IAD New Destination: HGR; Observed

Page 3



Log:	
Time (∪	TC) Remarks
	7700 code 12 NE of HGR, contact ZDC; confirmed ZDC initiated emergency for ACFT for weather related
	problems. ACFT returning to HGR. ACFT landed at 1732.
1729	EMERGENCY; ATSC (FAA HQ DEN); ABQ; DUDLEY4; A10; DMADMA; Oxygen system problems. Aircraft
4700	landed at 1755. EMERGENCY ; ATSC (FAA HQ DEN); SHV; TUFF76; B52; BADBAD; Anti skid malfunction. Aircraft landed at
1729	
1735	1725. EMERGENCY,COD; ATSC (FAA HQ DEN); ZBW; AWE2127; E190; BOSLGA New Destination: BOS;
1735	Mechanical problem, 1753 A90 advised ACFT declared emergency due to flap control problem. ACFT landed
	at 1801.
1738	COD; ATSC (FAA HQ DEN); ILG; ASQ4994; CRJ2; ATLOAJ New Destination: ILG; Weather.
1740	EMERGENCY; ATSC (FAA HQ DEN); ZAU; AAL153; MD83; MCOORD; Gear control issue. Aircraft landed at
1740	1746.
1752	EMERGENCY; ATSC (NCRCC); PCT; CHQ6030; E145; LGACAE New Destination: BWI; EMRG: Aircraft
	landed at 1805.
1800	ADMIN; ATSC (FAA HQ DEN); CW on HQE. WCLC.
1800	ADMIN; ATSC (NCRCC); NCRCC; MK off.
1800	ADMIN; ATSC (NCRCC); NCRCC; SH off.
1800	ADMIN; ATSC (NCRCC); VP on duty.
1808	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDC/ZNY/ZBW/ZJX authorized to suspend change of
	destination reporting for AOR until 0200 due to weather.
1815	NORDO; ATSC (FAA HQ DEN); ZDC; N92TC; MU2; CAEPHF; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1817.
1815	ADMIN; ATSC (NCRCC); WCLC.
1830	ADMIN; SOSC (FAA HQ); MS on SOSC2, briefed by YZ.
1840	NORDO; ATSC (FAA HQ DEN); ZKC; N633SR; SR22; BVOSMD; Aircraft reported on course, at assigned
4040	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1857.
1843	COD; ATSC (FAA HQ DEN); M98; SKW4519; CRJ2; MSPBIS New Destination: MSP; De-icing equipment
1040	malfunction. COD; ATSC (FAA HQ DEN); EGF3327; E135; TYSDFW New Destination: LIT; Pressurization problem.
1848 1850	SUSPICIOUS ACTIVITY; ATSC (FAA HQ DEN); ZKC; DAL1755; B752; ATLLAX; ZKC advised they were
1000	concerned with ACFT operation (missed turn/wrong turn) by the PIC; they also notified ZAB. 1853 HQ DEN
	contacted DAL dispatch to query the crew about their actions/condition; advised ZKC/ZAB of call. 1901 DAL
	dispatch advised they spoke with PIC and it was deemed pilot/controller misunderstanding; all is well cockpit
	secure: advised ZKC/ZAB. No further action.
1852	NORDO; ATSC (FAA HQ DEN); ZHU; ASH2609; CRJ9; CLTSAT; Aircraft reported on course, at assigned
1.002	altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications re-
	established at 1853.
1904	COD; ATSC (FAA HQ DEN); ZBW; EJA290; F2TH; TEBLEB New Destination: MHT; Braking action poor.
1929	NORDO; ATSC (FAA HQ DEN); ZNY; CJA991; B738; MMCZ. CYUL; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1941.
1931	NORDO, PAGED; ATSC (FAA HQ DEN); ZID; N31KH; LJ31; JVLMCO; Aircraft reported on course, at
	assigned altitude. Attempting contact on Guard. No satellite phone available. 1946 ZID advised tape review
	indicated freq change was issued, with a good readback, at 1910. Aircraft NORDO 0+36. 1955 ZTL contacted
	home base FBO in Beloit, WI and they are researching contact info. Communications re-established at 2002.
	NORDO 0+52. MOR filed by ZTL.
1937	NORDO; ATSC (FAA HQ DEN); EADS; N15500; PA28; IGX35A; 7600 code observed 10S CLT; ZTL
10.10	investigating. Communications re-established at 1939.
1940	NORDO, FFDO-ONBRD; ATSC (FAA HQ DEN); ZTL; JBU953; E190; BOSMCO; Aircraft reported on course,

Page 4



Element:	Created by:	Created on:	Checked by:
ALL	JFerrell,	04/13/2013 0404Z	JF

Log:	
Time (UTC)	Remarks
1942 1945	at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1942. COD; ATSC (FAA HQ DEN); ZMP; BJS611; LJ45; PLNOMA New Destination: ORD; Company request. NOTAM-VIP, TFR, PAGED, VIP; ATSC (CONR/AOC); FDC NOTAM 3/1614 for VIP movement to Wilmington, DE in effect. TFR around train station and not associated with the airport (ILG). 2100 TFR expired. TOI Summary: 0 TOI, 0 MOR, 0 Unable to Identify.
1946	COD; ATSC (FAA HQ DEN); ZDC; RSP654; C525; BOSHOU New Destination: BNA; Fuel.
2004	NORDO; ATSC (FAA HQ DEN); ZFW; EGF3287; E135; DFWSAF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2010.
2012	EQUIPMENT; ATŠC (CONR/AOC); CONR ADAPT Work Station A10 is permanently OTS. ADAPT Support will ship a replacement computer.
2015	ADMIN; ATSC (N/NC); KN on. Briefed by VM. WCLC.
2016	
	973 (24 M.S.V.) 1551r
2030	
	87: 49 M.B.C. 310 FF
	84; 40 N.A.C. 114 s
2031	NORDO; ATSC (FAA HQ DEN); ZLC; OPT322; E55P; TULSUN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications reestablished at 2034.
2043	NORDO; ATSC (FAA HQ DEN); ZBW; ASA12; B739; SEABOS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2044.
2044	COD; ATSC (FAA HQ DEN); ZMP; EJM250; C25B; HIO. RST New Destination: MKE; Company request.
2048	COD; ATSC (FAA HQ DEN); CHS; BKA715; LJ35; ORF. CHS New Destination: CAE; Weather.
2104	EMERGENCY ,AIRPORT; ATSC (FAA HQ DEN); SMO; N153NL; BE95; VFRSMO; Gear collapsed while landing at 2102. Single RY Closed; ATCSCC notified. No information available in reference to PIC/PAX. 2148 SMO reported 2 PAX, no injuries, and minor damage./CW.
2110	Sivio reported 2 FAX, no injunes, and minor damage/2000.
	OF.
2110	NORDO; ATSC (FAA HQ DEN); ZOA; N375DT; BE40; SFOLAS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2113.
2117	COD; ATSC (FAA HQ DEN); ZAB; AMF2145; BE99; SLC. DFW New Destination: AMA; Company request.
2118	EMERGENCY; ATSC (FAA HQ DEN); ZHU; MT732; T34P; NGP. NGP; Minimum fuel. Aircraft landed at 2110.
2121	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZLA; ZLA exempt from change of destination reporting for
2135	SMO (Santa Monica, CA) until 0200 or runway reopens. 2150 Runway re-opened; ACSCC advised. NORDO; ATSC (FAA HQ DEN); ZLC; N970SF; F900; IADOAK; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2144.
2140	EMERGENCY- MEDICAL; ATSC (FAA HO DEN); D10; AAL1344; MD83; AUSDFW; PAX medical.
2142	EMERGENCY ; ATSC (FAA HQ DEN); ZTL; AWE1581; A321; PHLCLT; Hydraulic problem. Aircraft landed at 2118.
2145	ADMIN; ATSC (FAA HQ DEN); CW on HQE/HQW. RV off. NORDO; ATSC (FAA HQ DEN); ZAB; N4131C; P28R; RYNFFZ; Aircraft reported on course, at assigned
2203	NONDO, A 130 (FAA ING DEN), ZAB, N41310, FZON, KTNFFZ, Aliciali reported on course, at assigned

Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	JFerrell,	04/13/2013 0404Z	JF

Log:	
Time (UTC)	Remarks
2206	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2212. EMERGENCY ,AIRPORT; ATSC (FAA HQ DEN); FNT; ASQ5017; CRJ9; ATLFNT; Nose wheel issue; aircraft may need tow off runway. Aircraft landed at 2212.
2208	NORDO; ATSC (FAA HQ DEN); ZJX; AAL1533; B752; BOSMIA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2213.
2213	COD; ATSC (FAA HQ DEN); ZAB; FAO9000; MD83; IWAMIA New Destination: IWA; Minor mechanical,
2225	EMERGENCY, COD; ATSC (FAA HQ DEN); ZTL; AAL1883; MD83; ATLDFW New Destination: ATL; Smoke in cockpit. Aircraft landed at 2237.
2227	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLA; DAL1402; B763; ATLLAS; 57yo female PAX with low blood pressure.
2324	COD; ATSC (FAA HQ DEN); ZAB; SBE823; C25A; MALCH New Destination: ADS; Company request.
2330	COD; ATSC (FAA HQ DEN); RST; BMJ33; BE65; CPS. BJI New Destination: ANE; PAX request.
2332	NORDO; ATSC (FAA HQ DEN); ZFW; SKW4966; CRJ7; CMHIAH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2346.
2333	COD; ATSC (FAA HQ DEN); ZME; PWA4501; CL60; ALNRZR New Destination: CHA; PAX request.
2342	CONFERENCES; ATSC (N/NC); TACOPS conference for foreign activity.
2349	ATC FACILITY; ATSC (NCRCC); ZHU; Austin ATCT declared ATC Alert due to Automation trigger - ARTS outage and VSCS problems. ATC alert terminated at 2352.
2358	COD; ATSC (NCRCC); PCT; CNS313; PC12; HPNFME New Destination: IAD; Company request.
04/13/2013	cos, mos (nemos), con constant me me source of company request.
0002	COD; ATSC (NCRCC); WRI; CNS214; PC12; JGGBLM New Destination: TEB; Weather Divert.
0010	COD; ATSC (NCRCC); ZJX; AAY9404; MD83; TOLSFB New Destination: IAG; Company request.
0100	ADMIN: ATSC (CONR/AOC); CONR combined with NORAD, LB off.
0108	ATC FACILITY; ATSC (FAA HQ DEN); YNG; YNG TRACON declared ATC Alert at 0055 due to an automation trigger; ATCSCC advised.
0153	COD; ATSC (FAA HQ DEN); ZAU; RCH440; C172; NYLBGR New Destination: WRI; Minor mechanical.
0200	ADMIN; ATSC (FAA HQ DEN); JF on HQE/HQW/NCRCC. WCLC.
0208	LASER; ATSC (FAA HQ DEN); MSY; N4622P; C152; VFRVFR; Cockpit was illuminated by green laser while heading E at 2,000 feet 25 miles W of MSY. No injuries reported.
0215	ADMIN; ATSC (NCRCC); VP off duty.
0215	ADMIN: ATSC (FAA HQ DEN); CW off.
0225	EMERGENCY; ATSC (FAA HQ DEN); DFW; NKS903; A320; ORDDFW; Flap problem. Aircraft landed at 0231.
0248	COD; ATSC (FAA HQ DEN); ZBW; FDX1254; B752; PWMBTV New Destination: MEM; Company request.
0259	ADMIN: SOSC (FAA HQ): MS off, SOSC closed. TH on call.
0306	COD; ATSC (FAA HQ DEN); ZDV; FDX540; DC10; MEMSJC New Destination: OAK; Company request.
0307	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZLA; AAL1617; B738; ORDLAX New Destination: LAS: Female PAX seizure.
0314	LASER; ATSC (FAA HQ DEN); ZKC; KAP609; C402; TBNSTL; FTZ reports that cockpit was illuminated by green laser on right side while heading W at 4,000 feet 25 miles WSW of FTZ. No injuries reported.
0325	LASER; ATSC (FAA HQ DEN); MSY; EGF3398; E135; LCHDFW; Aircraft was illuminated by laser while heading NE at 1,000 feet 3 miles SW of Lake Charles Airport. No injuries reported.
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 6




Date: 04/13/2013

Element: Created by: Created on: Checked by: JFerrell, 04/14/2013 0405Z JF

Log:	
Time (UTC	Remarks
04/13/2013	
0400	ADMIN; ATSC (FAA HQ DEN); JF on HQW/HQE/NCRCC. WCLC. CFPL:None.
0400	ADMIN; ATSC (N/NC); KN on. CFPL: None. WCLC.
0420	LASER; ATSC (FAA HQ DEN); NCT; AMF282; PA31; RNOSAC; Cockpit was illuminated by blue laser from left side while heading SE at 5,000 feet 10 miles W of SAC. No injuries reported
	The same meaning SE at 3,000 feet to filles W of SAC. No injuries reported
0427	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOA; SWA2074; B737; PDXRNO; Male PAX passed out.
0446	LASER; ATSC (FAA HQ DEN); PDX; QXE574A; DH8D; OAKPDX; Cockpit was illuminated by green laser
	from behind while heading W at 2,500 feet 10 miles E of PDX. No injuries reported.
0506	ing go the course
0300	8-y a- M.S. 1, 140 to
	25: 0 - 107:07. 3165m
0510	LASER; ATSC (FAA HQ DEN); FAT; SKW3490; CRJ7; SEAFAT; Cockpit was illuminated by green laser on
	right side while heading SE at 8,400 feet 15 miles NW of Fresno. No injuries reported.
0550	ADMIN; ATSC (N/NC); KN off. Combined with HQ DEN.
0609	LASER; ATSC (FAA HQ DEN); HNL; HAL196; B712; HNLOGG; Aircraft was illuminated by green laser while
	heading SSE at 2,000 feet 3 miles NNE of Lahina, Maui. No injuries reported.
1000	ADMIN; ATSC (NCRCC); NCRCC; MK on. NCRCC decombined from HQ DEN.
1000	ADMIN; ATSC (FAA HQ DEN); GR on HQE/HQW. WCLC.
1018	ADMIN; ATSC (NCRCC); NCRCC; WCLC.
1019 1130	ADMIN; ATSC (NCRCC); NCRCC; MK off. ADMIN; ATSC (CONR/AOC); PM on.
1134	ADMIN; ATSC (CONR/AOC); WCLC.
1139	NORDO; ATSC (FAA HQ DEN); SWG551; B738; CYQBMMUN; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1143.
1200	ADMIN; ATSC (N/NC); XS on, briefed by GR.
1226	NORDO; ATSC (FAA HQ DEN); LBB; CTL8; AC50; LBBELP; Aircraft reported on course, at assigned altitude.
	Attempting contact on Guard and with Company. Communications re-established at 1230.
1246	CONFERENCES; ATSC (N/NC); TACOPS complete including VIP locations, LRA, and potential foreign launches. WCLC.
1255	EMERGENCY, COD; ATSC (FAA HQ DEN); ZBW; AWE2025; E190; BOSDCA New Destination: BOS; Flap
1233	problem. Aircraft landed at 1312.
1303	EMERGENCY, COD; ATSC (FAA HQ DEN); A90; JBU909; A320; BOSMYNN New Destination: BOS; Open
	door indication. Aircraft landed 1325.
1306	3 7: 40 U.S.C. 11(1)
1220	
1329	TO THUS.C. He re

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on: 04/14/2013 0405Z	Checked by:
ALL	JFerrell,		JF

Log:		
Time (UTC)	Remarks	
1333	COD; ATSC (FAA HQ DEN); ZDV; LYM710; PA31; DEN. SNY New Destination: STK; Weather.	
1347	No. 12 Marie: 113 cm	
	Por 40 Caral Mari	
1348	89 30 0.8.0. 114.50	
1350	84 17 Tex. 112 ar	
1355	LASER OPERATION; ATSC (NCRCC); NASA; NASA Goddard Space Flight Center conducting LASER	
1000	operations. Operations terminated at 0055.	
1400	ADMIN; SOSC (FAA HQ); MS on SOSC2, SOSC open.	
1400	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1500: WCLC.	
1405	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZID; ASQ4904; CRJ9; SATDTW; Sick passenger.	
1412	ADMIN; ATSC (FAA HQ DEN); CW on HQE/HQW.	
1413	NORDO; ATSC (FAA HQ DEN); ZDC; N47EG; F900; SCHPBI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. HQ DEN contacted aircraft via satellite phone, relayed correct frequency. Communications re-established at 1415.	
1416	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMP; ZMP authorized to suspend change of destination reporting for AOR until 2000 due to weather.	
1420	NORDO; ATSC (FAA HQ DEN); ZBW; MNINE; BE58; BGRGSO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1435 NORDO 0+15. FSOC attempting comm over ALB VORTAC/ZBW freg 123.75. Communications re-established at 1436.	
1424	COD, ATSC (FAA HQ DEN); M98; ASQ5019; CRJ7; MSP. BNA New Destination: MSP; Minor mechanical.	
1427	COD; ATSC (FAA HQ DEN); ZFW; EGF3439; E145; DFWFSM New Destination: DFW; Minor mechanical.	
1432	33; 44 8.3.2. Hara	
1433	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); D21; ASQ4904; CRJ9; SATDTW; Female PAX with possible heart attack; nurse attending.	
1438	NCR-COORDINATION,PAGED; ATSC (NCRCC);	
1442	NORDO; ATSC (FAA HQ DEN); ZAU; RAX220; LJ35; SBPPTK; Aircraft reported 10N of course, at assigned	
1442	altitude. Attempting contact on Guard and with Company. Communications re-established at 1450.	
1452	EMERGENCY; ATSC (FAA HQ DEN); CHS; JILL41; C130; POBCLT; #3 engine out. Aircraft landed at 1503.	
1454	EMERGENCY- MEDICAL; ATSC (NCRCC); PCT; N65497; C172; VKXLKU; EMRG Passenger: Aircraft landed at 1450. Passenger in distress. EMTs called to meet aircraft.	
1455	NORDO, NOTIFICATION-LATE, MOR, PAGED; ATSC (FAA HQ DEN); ZME; SWA1747; B737; FLLMCI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 1457 ADAPT showed aircraft crossed into ZME airspace at 1430; aircraft NORDO 30+ minutes. Communications reestablished at 1502. ZTL researching tapes. 1511 MOR filed by ZME. 1537 ZTL advised aircraft lost between sectors at 1427; MOR filed by ZTL. (NORDO 0+35).	
1500	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful.	
1502	BO 48 TAKE NAME	
1503	CONFERENCES; ATSC (N/NC); ONEC test successful.	
1533	COD; ATSC (FAA HQ DEN); ZMA; AAL580; B738; TULMIA New Destination: RSW; Weather.	
1534	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMA; ZMA authorized to suspend change of destination reporting for MIA until 1800 due to weather/T. Extended until 2200.	
1540	NOTAM,VIP; SOSC (FAA HQ); FDC NOTAM 3/1817 published for VIP movement to Wilmington, DE. from 1304151045-1304151200, 3 NMR SFC-3,000 AGL. Spans:18,651.	
1540	34 24 7.8 C. Harr	
	B4: 44 0.517. 144.67	

Page 2



Element: Created by: Created on: O4/14/2013 0405Z Checked by: JF

Log:	
Time (UTC)	Remarks
1542	Box 49 M. Son. Livea
1549	EMERGENCY,COD; ATSC (FAA HQ DEN); ZOB; TRS282; B712; DTWATL New Destination: DTW; Engine out. Aircraft landed at 1601.
1552	NORDO,COD; ATSC (FAA HQ DEN); N44734; P28A; LQKINT New Destination: SVH; 7600 code observed 30NW CLT. Aircraft in CLT airspace but they never had comm; 45NM from destination. 1608 ZTL advised aircraft landed at SVH with alternator failure.
1557	COD; ATSC (NCRCC); NCT; SKW5503; E120; SFO. MRY New Destination; SFO; Weather at MRY.
1605	COD; ATSC (NCRCC); NCRCC; N54240; BL8; FMEVFR New Destination: FME; Transponder failed on
	departure, returning to FME.
1625	Bry w 1 (2), Not. 113 (2)
1647 1648	COD; ATSC (FAA HQ DEN); ZMA; JV834; B737; NQXSAV New Destination: NIP; Fuel. COD,PAGED,SUSPICIOUS ACTIVITY; ATSC (FAA HQ DEN); ZJX; SWA1656; B733; TPAMKE New Destination: TPA; Minor mechanical for a cargo pressure problem. 1706 TPA advised they were notified by Airport Authority of a possible stowaway in the wheel well. Aircraft landed at 1708. TSOC advised. 1716 TPA ATCT advised runway swept with negative findings. CLOSEOUT: 1751 LEO's and TSA swept aircraft and found that luggage had come loose and was rattling around in the cargo hold and was believed to be the source of the knocking; no stowaway.
1656	COD; ATSC (FAA HQ DEN); ZMP; SKW4828; CRJ2; MSPGFK New Destination: MSP; Minor mechanical.
1659	EMERGENCY; ATSC (FAA HQ DEN); ZMP; GORDO14; B742; MLEOFF; Flap issue. Aircraft landed at 1734.
1700	COD; ATSC (FAA HQ DEN); ZME; IDAHO17; C208; BNASHV New Destination: ACT; Fuel stop not required.
1701	Bkg 19 7.8.0. 114 s
1706	COD; ATSC (FAA HQ DEN); ZSE; QXE216; DH8D; SEAPUW New Destination: SEA; Minor mechanical.
1711	EMERGENCY; ATSC (FAA HQ DEN); ZOB; N203VS; LJ25; IAGIAG; Engine malfunction. Aircraft landed at 1718.
1727	COD; ATSC (FAA HQ DEN); D21; FLG3851; CRJ2; DTWCYOW New Destination: DTW; Minor mechanical.
1728	
1758	
1800	ADMIN; ATSC (FAA HQ DEN); CU on HQW, WCLC.
1800	ADMIN; ATSC (NCRCC); UL on duty. At 1815: WCLC.
1802	COD; ATSC (FAA HQ DEN); D10; EGF3446; E145; DFW. VPS New Destination: DFW; Minor mechanical.
1807	EMERGENCY ; ATSC (FAA HQ DEN); ZAB; SKW409A; CRJ2; PHXLAX New Destination: PHX; Warning light for an overheating engine. Aircraft landed at 1817.
1813	TOI-US ADIZ, TOI; ATSC (CONR/AOC); EADS; N3582Y; C182; MYBSFXE; EADS Unknown, Fort Lauderdale
	(FLL)105031, 1236 code, heading 315 degrees, indicating 2700 feet and 170 knots. 1815 EADS identified track
	as N3582Y, C182, South Bimini (MYBS) to Fort Lauderdale Executive (FXE). Track was on assigned code.
	NFA.
1838	COD; ATSC (FAA HQ DEN); ZMP; FLG3610; CRJ2; CWADTW New Destination: CWA; No de-icing
	equipment. 1838 COD to DTW.
1845	NORDO; ATSC (FAA HQ DEN); ZDC; CHQ5132; E145; AVLLGA; Aircraft reported on course, at assigned
	altitude. Attempting coritact on Guard and with Company. Communications re-established at 1846.
1846	Big in United States
1907	SIF; ATSC (FAA HQ DEN); ZMA; ORB9948; B772; MMUNULLI; Deviated off approved routing for WX,
1015	returning ASAP. FINE DCENCY: ATSC (FAA HO DEN): BOS: IRLI1226: E100: BDLL BOS: Brake issue. Aircraft landed at 1010.
1915	EMERGENCY; ATSC (FAA HQ DEN); BOS; JBU1226; E190; RDU. BOS; Brake issue. Aircraft landed at 1910. NORDO; ATSC (FAA HQ DEN); ZMA; TSO999; B744; UUWWMIA; Aircraft reported on course, at assigned
1928	altitude. Attempting contact on Guard and with Company. Communications re-established at 1929.
1930	ADMIN; ATSC (CONR/AOC); CONR combined to NORAD. PM off.

Page 3

FAA Air Traffic NAS Daily Ever				Date: 04/13/2013
Element: ALL	Created by: JFerrell,	Created on: 04/14/2013 0405Z	Checked by: JF	

Log:	
Time (UTC)	Remarks
1944	EMERGENCY,COD; ATSC (FAA HQ DEN); ZMA; LN160AJ; LJ60; ORFPBI New Destination: MLB; Aft
	baggage door open. Aircraft landed at 1953.
2014	EMERGENCY- MEDICAL, ATSC (FAA HQ DEN); ZOB; EGF3801; CRJ7; PHLORD; Male PAX with heart
0000	palpitations; physician attending.
2029	101, 17 Million, 116 fre
2030	
2036	
	BA 10 M A 2 M A 17 A 17 A 17 A 17 A 17 A 17 A 17 A
2044	ADMIN; ATSC (N/NC); KN on. Briefed by XS. WCLC.
2045	COD; ATSC (FAA HQ DEN); ZHU; LXJ437; LJ45; DWHAPF New Destination: ATL; Company request,
2100	ATC FACILITY, PAGED: ATSC (FAA HQ DEN): ZLA; Burbank ATCT evacuated due to possible fire, 2103
	Burbank ATC Zero, building on fire, 2118 Burbank ATCT resumed normal operations.
2109	3.5 to 0.8.0. 136 p.
2114	37, 37 3.5
2118	SUSPICIOUS ACTIVITY, MOR; ATSC (FAA HQ DEN); FTW; N117RW; MO20; FWSCPT; Aircraft twice
	violated both FTW and AFW airspace. FTW requesting assistance in identifying the violator. ADAPT shows
	departure point Fort Worth-Spinks (FWS). 2140 Aircraft landed Cleburne Muni (CPT) and identified by AMOC.
	PIC instructed to contact FTW; MOR filed.
2136	COD; ATSC (FAA HQ DEN); CMH; FLG3857; CRJ2; DAY. DTW New Destination: DAY; Minor mechanical.
2138	COD; ATSC (FAA HQ DEN); A90; DAL1723; A320; BOSDTW New Destination: BOS; Minor mechanical.
2145	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAN; ZAN authorized to suspend change of destination
	reporting for AOR until 0200 due to weather.
2200	ADMIN; ATSC (NCRCC); NCRCC; SH off.
2200	ADMIN; ATSC (FAA HQ DEN); CW off; CU on HQE/HQW.
2201	CONFERENCES; ATSC (N/NC); CFACC test successful.
2202	CONFERENCES; ATSC (N/NC); ONEC test successful.
2218	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDV; SWA920; B737; DEN. TPA New Destination: DEN; Sick PAX.
2224	COD; ATSC (FAA HQ DEN); ZDC; SKW6643; BE40; AlkFRG New Destination: BLM; PAX request.
2227	COD; ATSC (FAA HQ DEN); ZHU; ASQ4185; E45X; MYNNIAH New Destination: LFT; Lavatory issue.
2243	EMERGENCY- MEDICAL: ATSC (FAA HQ DEN): ZLA: ASA704: B734: CYVR. LAX: Sick PAX.
2311	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZBW; UAL918; B772; IADEGLL New Destination:
	BOS; Emergency declared, nature unknown. 2314 Emergency is Sick PAX.
2317	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ŽMA; AAL2191; B738; TJSJMIA New Destination:
	MYNN; Sick PAX. 2320 COD to MYNN.
2321	ALNOT; ATSC (FAA HQ DEN); WOC; N75602; C172; ETNETNG; VFR ACFT 6,500 feet, last known position
	25 miles SE Eastland, TX. 0035 ALNOT cancelled.
2326	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); BGR; AWI3830; CRJ2; PHLBGR; Sick PAX.
2333	COD; ATSC (FAA HQ DEN); GSP; CAP3993; C172; ANDCAE New Destination: AND; Alternator issue.
2342	CONFERENCES; ATSC (N/NC); TACOPS conference for foreign activity.
04/14/2013	
8000	COD; ATSC (FAA HQ DEN); ZTL; ASQ5159; CRJ7; ATLEYW New Destination: ATL; Maintenance issue.
0016	COD; ATSC (FAA HQ DEN); ZAN; AER43; B190; ANCJNU New Destination: SIT; Company request.
0018	EMERGENCY, COD; ATSC (FAA HQ DEN); N90; JBU378; A320; FLLLGA New Destination: JFK; Gear will not
1	come down. Aircraft landed at 0036, ACFT was able to lower the landing gear, towed off RY due to steering
0020	ISSUE. COD: ATSC (EAA HO DEN): 7DV: CLASSO: P100: DEN, CDP New Postination, DEN, Circuit has also increased.
0028	COD; ATSC (FAA HQ DEN); ZDV; GLA320; B190; DENCDR New Destination: DEN; Circuit breaker issue.

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/13/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 JFerrell,
 04/14/2013 0405Z
 JF

Log:	
Time (UT	Remarks
0035	LASER; ATSC (FAA HQ DEN); ROA; N459JA; C172; Green laser, from the right side, illuminated cockpit at 4,000 feet, 8 miles NNW Lynchberg ARPT. ACFT E bound, no injuries reported.
0104	EMERGENCY,COD; ATSC (NCRCC); ZSU; AAL1995; B752; MIATBPB New Destination: TJSJ; A series of warning lights. Aircraft landed at 0137.
0200	ADMIN; ATSC (FAA HQ DEN); CU off.
0200	ADMIN; ATSC (FAA HQ DEN); JF on HQE/HQW/NCRCC, WGLC.
0204	COD; ATSC (FAA HQ DEN); ZMP; GLA30; B190; PIRCYS New Destination: PIR; Pilot request.
0215	ADMIN; ATSC (NCRCC); UL off duty. Combined with HQ DEN.
0238	EMERGENCY, COD; ATSC (FAA HQ DEN); ZFW; AAL1136; MD82; DFWDTW New Destination: DFW; Smoke in cockpit. Aircraft landed at 0242.
0304	Exp. 3 - Magazin 344 M
0320	LASER; ATSC (FAA HQ DEN); C90; AWE958; A320; PHLORD; Cockpit was illuminated by green laser on right side while heading W at 2,500 feet 8 miles E or ORD. No injuries reported.
0320	LASER; ATSC (FAA HQ DEN); PCT; CHQ9812; E145; EWRBWI; Cockpit was illuminated by green laser while heading SW at 4,000 feet 22 miles NE of BWI. No injuries reported.
0328	OTHER; ATSC (FAA HQ DEN); DTW; DAL248; B772; DTWEHAM; Aircraft ran off taxilane (non-movement area) and into mud and got stuck; aircraft was taxing to active runway for departure. PAXs were deplaned on taxilane.
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 5



ed by: Created on: Checked by:
ell, 04/15/2013 0404Z JF
1

		***************************************	4.7.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4
Security Event Statistics:			
2 (g. 4) (F.4) (f. 12)	TOI: 2	AIRPORT: 1	음식을 되는 선생님들이 발표되었다.
EMERGENCY: 15	TOI-EQUIPMENT: 1 TOI-US ADIZ: 1	NORDO: 21	COD: 44
EMERGENCY- MEDICAL:	TOI-05 ADIZ. T		LASER: 5
12			MOR: 2

Log:	
Time (UTC	Remarks
04/14/2013	
0400	ADMIN; ATSC (N/NC); KN on. CFPL: None. WCLC.
0400	ADMIN; ATSC (FAA HQ DEN); JF on HQW/HQE/NCRCC. WCLC. CFPL: Disturbance, JBU521, 0413
	CLOSEOUT: Deemed customer service.
0407	LASER; ATSC (FAA HQ DEN); HOU; SWA2024; B737; DENHOU; Cockpit was illuminated by green laser on the right side at 1,500 feet while on a five mile final to RWY 4. No injuries reported.
	ATTICO (EAA HO DEAN) TOOO ACASEA BYON COO DAN O SINI AS A SINI AS
0416	OTHER; ATSC (FAA HQ DEN); TSOC; ASA854; B738; OGGSAN; Suspicious substance was discovered in
	lavatory. Area is secure. Cockpit is secure. 1997 and 1998 HQ DEN called SAN ATCT to coordinate. Aircraft landed at 0726, 0822 CLOSEOUT: Substance was discovered to be Splenda (sweetener).
0433	COD; ATSC (FAA HQ DEN); ZDV; DAL2187; A319; MSPRAP New Destination: MSP; Fog.
0 4 33 0531	EMERGENCY; ATSC (FAA HQ DEN); ZNY; JBU990; A320; FLLJFK; Brake light indicator on. Aircraft landed
0001	at 0554.
0550	ADMIN; ATSC (N/NC); KN off. Combined with HQ DEN.
0616	LASER; ATSC (FAA HQ DEN); NCT; CHP21; C206; VFRVFR; Cockpit was illuminated by blue laser from
	underneath at 3,000 feet 6 miles N of McClellan Airfield. Pilot reported vision impairment. Suspect was located
	and is in custody.
0716	LASER; ATSC (FAA HQ DEN); TUS; AIR1; R44; VFR. VFR; Cockpit was illuminated by green laser at 3,000
	feet 5 miles N of TUS, while orbiting. No injuries reported.
0844	NORDO; ATSC (FAA HQ DEN); ZAU; TAI589; A320; ORDMGGT; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0845.
1000	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. WCLC.
1000	ADMIN; ATSC (PAA NG DEN), DR ON NGE/NGW. WOLG. ADMIN; ATSC (NCRCC); NCRCC; SH on. 1100: WCLC.
1121	Abmin, Arab (Nonco), Nonco, orron. Troc. Wells.
1121	839 (13.00) (3.13) (4.14)
1130	ADMIN; ATSC (CONR/AOC); PM on.
1146	COD; ATSC (FAA HQ DEN); ZJX; NAO901; B763; NKTMIA New Destination: TPA; Company request.
1200	ADMIN; ATSC (N/NC); XS on, briefed by DR.
1209	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZJX; ZJX authorized to suspend change of destination
	reporting for AOR until 1800 due to WX.
1230	NORAD-COORDINATION; ATSC (NCRCC); NCRCC; MIG 21: N1165, procession of the state of
1040	approximately 1400 for about 30 minutes. CONFERENCES, ADMIN; ATSC (N/NC); TACOPS complete including VIP locations, LRA, and potential foreign
1240	launches. WCLC.
1323	COD; ATSC (FAA HQ DEN); NCT; SWA218; B737; RNODEN New Destination: RNO; Mechanical.
1335	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1351	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZTL; AWE1034; A321; ORDCLT; Passenger medical
	emergency.

Page 1



Date: 04/14/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 JFerrell,
 04/15/2013 0404Z
 JF

Log:	
Time (∪	TC) Remarks
1358	EMERGENCY,COD; ATSC (FAA HQ DEN); ZDV; SKW2981; CRJ7; DSMPHX New Destination: COS; Aileron
İ	system malfunction. Aircraft landed at 1432.
1400	ADMIN; ATSC (FAA HQ DEN); CW on HQE.
1400	ADMIN; SOSC (FAA HQ); MS on SOSC2, SOSC open.
1403	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Military exercise in NCR starting at 11AM.
1409	
1412	
1441	Beg 1 (1918-0) 113-12
1445	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLC; DAL978; B738; SANSLC; Passenger medical emergency.
1450	NOTAM; SOSC (FAA HQ); FDC NOTAM 3/1881 published for VIP movement to Baltimore, MD, from 1304162145-1304170045, 3 NMR- 3,000 FT AGL. Spans:19.836.
1457	NORDO; ATSC (FAA HQ DEN); ZAB; N225EE; GLF5; LGBSAT; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and previous frequencies. No satellite phone available, Communications
1	re-established at 1415.
1500	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful.
1514	Bar AM Bullett Bar a
	£-5 C+ D.W.C. 11:13
1539	COD; ATSC (FAA HQ DEN); ZAB; OPT733; C750; PDK. RNO New Destination: STS; Intermediate fuel stop not
	required.
1543	COD; ATSC (NCRCC); NCRCC; RPA3332; E145; DCAPWM New Destination: IAD; Mechanical issue.
1546	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZME; VALOR42; TEX2; AFWL!T New Destination: LRF; Pressurization system failure. Aircraft landed at 1615.
1557	COD; ATSC (FAA HQ DEN); ZDV; SKW6379; DH8D; HDNDEN New Destination: COS; Unable to hold.
1605	TOI-EQUIPMENT, TOI; ATSC (NCRCC); EADS; DCA266030, N6382S, C182, in communication with HEFT, electrical problem and a failed transponder. BKJK RWY Alert at 1605. Flight landed HEF at 1610, BKJK stood down. NFA.
1608	NORDO; ATSC (FAA HQ DEN); ZME; N1592W; BE33; SMDPOF; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications
	re-established at 1620.
1619	Exp. Co. Musica, 1990s. Exp. Co. Musica, 1990s.
1620	EMERGENCY,COD; ATSC (FAA HQ DEN); YNG; CFCAH; BE36; MKJSERI New Destination: GKJ; Rough
	running engine. Aircraft landed at 1625.
1623	88, 39 th.g. t. 111-11
1624	82) 42 U.S.C. 11-12
1604	COD; ATSC (FAA HQ DEN); ZDV; FFT259; A318; RAP. DEN New Destination: COS; Unable to hold.
1624	
1627	COD; ATSC (FAA HQ DEN); ZMP; SKW4830; CRJ2; MSPISN New Destination: MSP; Weather.
1635	COD; ATSC (FAA HQ DEN); ZMP, SKW4630, CRJ2, MSP.:TSN New Destination: MSP, Weather.
1638	EMERGENCY, COD; ATSC (FAA HQ DEN); ZLA; N914CE; H25B; MSPSEE New Destination: PSP; Starboard
1640	engine failure. Aircraft landed at 1652.
1644	36-34-7-34-6-11-12-
1650	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDV; ZDV authorized to suspend change of destination
1050	reporting for DEN AOR until 2000 due to WX and holding.
1656	NORDO, MOR, PAGED; ATSC (FAA HQ DEN); ZNY; N40HP; PA46; AVLBED; Aircraft reported on course, at

Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	JFerrell,	04/15/2013 0404Z	JF

Log:	
Time (U	rc) Remarks
1657	assigned altitude. Attempting contact on Guard. No satellite phone available. 1711 NORDO 0+15. 1716 FSOC attempting contact over HTO VORTAC/ZBW freq 124.85. 1720 Aircraft appears to be off course; however, ZBW believes aircraft is flying previous filed route and possibly was not issued the amended route in the NAS; ZDC is reviewing tapes. FSOC attempting comm over HFD VORTAC. 1726 NORDO 0+30. 1730 Aircraft past normal descent point. FSOC advised DUATS showed 2 POB and fuel 6+30. Aircraft departed at 1435; fuel exhaustion 2105. ZDC advised aircraft NORDO since 1645. Communications re-established at 1743. PIC will be read Brasher Warning and contact ZNY after landing. MOR filed by ZBW, ZNY, and ZDC. (NORDO 0+58). EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZTL; DAL2154; B752; LAXATL; Non-specific PAX medical.
1701	Aircraft landed at XXXX. ATC FACILITY; ATSC (FAA HQ DEN); ZHU; ZHU ATC ALERT due to Automation Trigger. ERAM Channels A and B are asynchronous. 0347 HQ DEN called ZHU for update; normal OPS at 1806.
1729	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZTL; TRS268; B712; DCAATL New Destination: CLT; Passenger medical emergency.
1749	NORDO; ATSC (FAA HQ DEN); ZOB; N811RA; LJ60; ROCIAD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1750.
1749	NORDO; ATSC (FAA HQ DEN); ZME; USC243; SUSFTY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1758.
1750 1758 1759	COD; ATSC (FAA HQ DEN); ZAU; ROPER93; C130; SKFHOP New Destination: MSN; Weather. COD; ATSC (FAA HQ DEN); ZMP; FLG3610; CRJ2; DTWCWA New Destination: LSE; Weather.
1800 1800 1800	ADMIN; ATSC (FAA HQ DEN); DR off. ADMIN; ATSC (NCRCC); NCRCC; SH off. ADMIN; ATSC (FAA HQ DEN); CU on HQW, WCLC. ADMIN; ATSC (FAA HQ DEN); CU on HQW, WCLC.
1800 1800 1804	COD; ATSC (FAA HQ DEN); ZAU; ROPER92; C130; SKFHOP New Destination: MSN; WX. ADMIN; ATSC (NCRCC); UL on duty. At 1815: WCLC. COD; ATSC (FAA HQ DEN); S56; SKW4680; CRJ2; SLCEUG New Destination: SLC; Gear issue.
1805	SIF; ATSC (FAA HQ DEN); ZJX; CUB190; A319; MUHGCYYZ; Taken off approved routing for WX, returning at ATL.
1805 1807	COD; ATSC (FAA HQ DEN); ZMP; FLG3738; CRJ2; MSPCWA New Destination: MSP; WX. NORDO; ATSC (FAA HQ DEN); ZFW; N2991T; M200; 85TERFI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1809.
1814	COD; ATSC (FAA HQ DEN); ZOB; OPT325; E55P; FTYBTV New Destination: ORF; Company request. 1820 Destination changed back to BTV.
1815 1817	COD; ATSC (FAA HQ DEN); ZDC; EJA108; BE40; PGVPDK New Destination: ILM; Minor mechanical. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80/ZTL/ZJX authorized to suspend change of destination reporting for AOR until 0400 due to weather/T.
1833	COD; ATSC (FAA HQ DEN); ZMP; ASQ5819; E145; ORDFAR New Destination: ORD; Back-up instrumentation issue.
1834	NORDO; ATSC (FAA HQ DEN); ZDV; DAL1787; A320; MSPSAN; Aircraft reported on course, at assigned altitude, NORDO since 1827. Attempting contact on Guard and with Company. Communications re-established at 1835.
1837	EMERGENCY, COD; ATSC (FAA HQ DEN); ZID; DAL1612; DC95; ATLORD New Destination: ATL; Navigation equipment issue. Aircraft landed at 1912.
1840	TOI-US ADIZ, TOI; ATSC (CONR/AOC); EADS; N8586Y; PA30; LALCPC; EADS Unknown, CHS #1, Charleston CHS150044, 1205 code, heading 035 degrees, indicating 9,500 feet and 175 knots. Track just popped up and EADS reports no one has been assigned 1205 code since early this morning. DoD is contemplating scrambling on track. 1855 Track crossed inner ADIZ and changed to a 1200 code. ZJX, Sealord

Page 3



 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 JFerrell,
 04/15/2013 0404Z
 JF

Log:	
Time (UTC)	Remarks
	and JAX approach have been queried with negative results. 1910 Track began descent over Myrtle Beach (MYR). MYR approach reports no contact, but will assist in tracking. 1930 CONR transferred responsibility of track to NORAD. (XS)1926 faded over Columbus County, NC (CPC). Only recording at FBO. 1933, AMOC ID as N8586Y. Pilot interviewed and had activated DVFR through FSS, NFA.
1849	NORDO; ATSC (FAA HQ DEN); CMH; N2544R; C182; LUKIKW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1851 FSOC attempting contact over DQN VOR/CMH freq 118.42. 1904 NORDO 0+15. Communications re-established at 1910.
1857	NORDO,MOR; ATSC (FAA HQ DEN); ZFW; N996F; BE36; CHDGKY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1904, PIC issued Brasher warning, will contact ZFW for possible MOR. 1907 D10 report ACFT still NORDO. Communications re-established at 1913.
1900	NORDO; ATSC (FAA HQ DEN); ZNY; KEY11; H25B; AGCHPN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1902.
1901	COD; ATSC (FAA HQ DEN); ZAN; ERR734; B190; FAIGAL New Destination: FAI; WX.
1909	at to this. Here.
1930	ADMIN; ATSC (CONR/AOC); CONR combined to NORAD. PM off.
1930	NORDO; ATSC (FAA HQ DEN); A90; EJA697; C56X; PVDBED; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1934.
1939	NORDO; ATSC (FAA HQ DEN); TUL; N612PZ; BE36; COSLIT; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1950.
2004	NORDO; ATSC (FAA HQ DEN); ZDC; N70XL; C56X; RUQPWM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2005.
2008	COD; ATSC (FAA HQ DEN); ZDC; EJM525; PRM1; IADUKF New Destination: INT; PAX request.
2008	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZID; AAY680; MD83; SFBMLI New Destination: OWB; Sick PAX.
2025	NORDO,FFDO-ONBRD; ATSC (FAA HQ DEN); ZAB; AAL1390; MD82; ONTDFW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2034.
2046	EMERGENCY; ATSC (FAA HQ DEN); E10; CFLMK; CL60; LASBUR; Blown tire. Aircraft landed at 2045.
2048	COD; ATSC (FAA HQ DEN); ZID; VNR167; P180; IADGBD New Destination: STL; WX.
2048	COD; ATSC (FAA HQ DEN); ZOB; EJA944; C750; TEB. LBF New Destination: SLN; PAX request.
2049	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; AAL1146; B738; MMCZDFW; Sick PAX.
2054	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOA; HAL15; A332; SANHNL; Sick PAX.
2101	D19 U3 9U3 P1 414 B
2102	
2102	gar qe Muducu 114 izo
	Buy 4 - Multiple 104 and
	8 (3) 10 (3) 4 (4)
2103	Land Carlotte Standard
2104	EMERGENCY; ATSC (FAA HQ DEN); EADS; RCH975; C5; ETADCEF; 7600 code observed 35NW BGR; ZBW advised aircraft has a pressurization problem. Aircraft landed at 2152.
2104	COD; ATSC (FAA HQ DEN); ZDV; EJA372; C680; APC. ASE New Destination: RIL; High winds.
	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. Briefed by XS.
2111	COD; ATSC (N/NC), N/NC, DH off N/NC/CONR. Briefed by XS. COD; ATSC (FAA HQ DEN); ZHU; EJA806; C560; AUSAIK New Destination: SAT; Company request.
2120 2127	EMERGENCY; ATSC (FAA HQ DEN); ZJX; DAL428; B752; TJSJATL; Smell in cockpit; loss of cabin pressure

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	JFerrell,	04/15/2013 0404Z	JF

Log:	
Time (UTC)	Remarks
	Aircraft descending to 10,000'. Aircraft landed at 2213.
2135	ADMIN; ATSC (NCRCC); NCRCC; MK off.
2141	COD; ATSC (FAA HQ DEN); ZMP; GLA237; B190; MSPPIR New Destination: MSP; Pressurization problem.
2155	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDV; SWA2329; B737; BWILAS New Destination: DEN; Sick PAX.
2200	ADMIN; ATSC (FAA HQ DEN); CW off; CU on HQE/HQW.
2203	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZHU; UAL481; A320; MMSDIAH; Sick PAX.
2211	COD; ATSC (FAA HQ DEN); ZJX; WJM13; GLF4; LWBFXE New Destination: BCT; Company request.
2226	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; JBU369; A320; LGAPBI; Sick PAX.
2236	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZSE; ASA659; B737; PHX., PDX; Sick PAX.
2238	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZMA; EJA706; GALX; MAIAGS New Destination: PBI; Pressurization issue. Aircraft landed at 2233.
2246	COD; ATSC (FAA HQ DEN); ZLC; ASQ6179; E45X; DEN. ISN New Destination: RAP; WX.
2246	NORDO; ATSC (FAA HQ DEN); ZNY; UAL1165; B753; EWRLAX; Aircraft reported on course, at assigned
2240	altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications reestablished at 2247.
2248	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); F11; F11/ZMA authorized to suspend change of destination reporting for AOR until 0200 due to WX.
2251	EMERGENCY, COD; ATSC (FAA HQ DEN); ZMA; N131AJ; LJ35; TJSJILM New Destination: TJSJ; Electrical
	issue. Aircraft landed at 2320.
2259	ADMIN; SOSC (FAA HQ); MS off, SOSC closed. YZ on call.
2301	COD; ATSC (FAA HQ DEN); ZMA; TRS284; B712; MKEMCO New Destination: TPA; WX.
2303	COD; ATSC (FAA HQ DEN); ZJX; EJA227; F2TH; BTRPBI New Destination: AGS; Company request.
2321	NORDO; ATSC (FAA HQ DEN); ZMA; N819LX; H25B; MFEMIA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2330.
2343	EMERGENCY, NOTIFICATION-LATE, PAGED; ATSC (FAA HQ DEN); CLT; ASH2658; CRJ9; MYRCLT; At 2255 ACFT experienced a nose wheel problem, veered off the RY in the vicinity of taxi way Bravo, at this time
	no injuries reported, buses are deplaning ACFT via stairs, RY23 closed. Aircraft landed at 2255. 0109 CLOSEOUT: RY23 re-opened, no injuries reported.
04/15/2013	occosed in Miles to opened, no injunes reported.
0002	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; SWA130; B738; SEAMDW; Sick PAX.
0014	COD; ATSC (FAA HQ DEN); ZLA; RSP039; E50P; LASSNA New Destination: VNY; Brake issue. 0021 COD to LGB, emergency declared. ACFT landed 0046.
0022	COD; ATSC (FAA HQ DEN); ZOA; SKW831X; CRJ7; SFOMMH New Destination: SAN: WX.
0022	EMERGENCY; ATSC (FAA HQ DEN); CAK; N3512B; BE35; LUK. TSO; Emergency declared 0010, Variable
0036.	pitch propeller. Aircraft landed at 0020. COD; ATSC (NCRCC); ZTL; JZA628; CRJ2; ATLCYYZ New Destination: ATL; Pressure problem, non
0043	emergency. NORDO; ATSC (FAA HQ DEN); ZHU; XAPTR; GLF4; MMTOGSP; Aircraft reported on course, at assigned
0048	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0049. NORDO; ATSC (FAA HQ DEN); ZDV; AWE52; A319; MSP. PHX; Aircraft reported on course, at assigned
0055	altitude. Attempting contact on Guard and with Company. Communications re-established at 0052. LASER; ATSC (FAA HQ DEN); PHL; N675QS; C56X; MYAMTEB; Green laser, 1 O'Clock position, illuminated
0000	cockpit at 11,000 feet, 10 miles W Yardley. ACFT NE bound, no injuries reported.
0102	COD; ATSC (FAA HQ DEN); ZOB; ASQ4662; E45X; CLEBDL New Destination; CLE; Bird strike.
0104	EMERGENCY; ATSC (FAA HQ DEN); E10; 7700 observed on ADAPT 15 miles SSE Victorville, CA (VCV) ARPT. 0118 Aircraft rolled to a 1200 squawk 4 miles ENE Ontario ARPT.

Page 5



Element:	Created by:	Created on:	Checked by:
ALL	JFerrell,	04/15/2013 0404Z	JF

Log:	
Time (UTC	Remarks
0134	COD; ATSC (FAA HQ DEN); ZLC; N577AC; LJ35; BFISDL New Destination: SLC; Fuel leak. Landed without incident.
0200	ADMIN; ATSC (FAA HQ DEN); CU off.
0200	ADMIN: ATSC (FAA HQ DEN); JF on HQE/HQW, WCLC.
0200	ADMIN; ATSC (NCRCC); VP on duty.
0215	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAN; ZAN authorized to suspend change of destination reporting for AOR until 0359 due to WX.
0215	ADMIN; ATSC (NCRCC); UL off duty.
0215	ADMIN; ATSC (NCRCC); WCLC.
0219	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMA; ZMA authorized to suspend change of destination reporting for AOR until 0359 due to WX.
0250	EMERGENCY , COD; ATSC (NCRCC); PCT; RPA3294; E170; DCASYR New Destination: DCA; Landing gear sensor failure. Aircraft landed at 0306.
0252	ATC FACILITY; ATSC (FAA HQ DEN); ZID; HTS ATC-0 due to loss of ARTS. VFR Tower only, ZID assumes airspace. No impact to NAS.
0254	NORDO; ATSC (FAA HQ DEN); ZME; N511WK; E50P; MOBCGI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0312.
0258	NORDO; ATSC (FAA HQ DEN); ZLC; SWQ767; B762; BFI. ORD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0327.
0325	LASER; ATSC (NCRCC); DCA; DAL1438; MD90; ATLDCA; DCA ATCT reported a green laser, 10 miles N/NE, struck aircraft while on final approach RWY19, 3000 feet, front end multiple times but did not illuminated cockpit, no reported injuries.
0330	OTHER; ATSC (NCRCC); WADS; WADS assumed air sovereignty of NCR until 0530.
0341	COD; ATSC (FAA HQ DEN); ZHU; ASQ4616; E45X; IAHMMLO New Destination; IAH; Airport is now closed.
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 6

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/16/2013 0423Z	RS

Security Event Statistics:			
g 3 9 10 10 11 11 11 11 11 11 11 11 11 11 11	TOI: 2	AIRPORT: 3	B3; 49 U.S.J. Lieff)
(j 49 U.S.". 114(r)	TOI-PA: 1	NORDO: 18	COD: 55
EMERGENCY: 15	TOI-PA-P-56A: 1 TOI-US ADIZ: 1	B3; 49 U.S.C. 114:1:	LASER: 3
EMERGENCY- MEDICAL: 13			MOR: 1
10			

Log:			
Time (UTC)	Remarks		
04/15/2013			
0400	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. CFPL: None.		
0400	ADMIN,OTHER; ATSC (NCRCC); VP on duty. CFPL: WADS assumed air sovereignty of NCR until 0530. WCLC.		
0400	ADMIN; ATSC (FAA HQ DEN); JF on HQW/HQE. WCLC. CFPL: None.		
0401	COD; ATSC (FAA HQ DEN); ZBW; UAL924; B772; IADEGLL New Destination: IAD; Lavatory problems. HQ DEN called UAL OPS to verify and it was confirmed.		
0422	LASER; ATSC (FAA HQ DEN); BFL; N3103Q; BE35; VFRVFR; Aircraft was illuminated by green laser while heading N at 4,000 feet 4 miles SE of BFL. No injuries reported.		
0423	COD; ATSC (FAA HQ DEN); E10; SKW324X; E120; LAXIYK New Destination: LAX; WX.		
0441	AIRPORT, OTHER; ATSC (FAA HQ DEN); LAS; Security breach at A and B Gates. Details unknown. TSOC investigating. No impact. 0442 TSOC reports it was a prohibited item. 0456 Operations normal. No impact.		
0510	EMERGENCY, COD; ATSC (FAA HQ DEN); HNL; UAL751; B752; SFOKOA New Destination: KNL; Number 2 engine OTS. Aircraft landed at 0739.		
0545	ADMIN; ATSC (N/NC); N/NC; DH off. Combined to HQ.		
0710	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLC; UAL421; A320; EWRSFO; PAX ill.		
0729	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDV; AWE1660; A320; PDX.:CLT New Destination: DEN; PAX ill.		
0743	LASER; ATSC (FAA HQ DEN); HNL; HAL555; B712; OGGHNL; Cockpit was illuminated by green laser while heading N at 1,000 feet 5 miles S of HNL. Laser from left side. No injuries reported.		
0912	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; JZA931; CRJ2; CYQMCYFC; Female PAX unconscious.		
1000	ADMIN; ATSC (NCRCC); VP off duty.		
1000	ADMIN; ATSC (FAA HQ DEN); RV on HQW, DR on HQE; WCLC.		
1000	ADMIN; ATSC (NCRCC); NCRCC; MK on.		
1003	ADMIN; ATSC (NCRCC); NCRCC; WCLC.		
1121	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZJX; ZJX/MSY authorized to suspend change of destination reporting for AOR until 1600 due to low ceilings/weather. 1215 ZME added.		
1123	destination reporting for AOR until 1600 due to low ceilings/weather. 1215 Ziviz added.		
	En la Yang katar		
1130	ADMIN; ATSC (CONR/AOC); PM on.		
1137	ADMIN; ATSC (CONR/AOC); WCLC.		
1154	COD; ATSC (FAA HQ DEN); ZSE; DAL2223; B752; ANCSLC New Destination: LAS; Anti-ice system malfunction.		
1158	COD; ATSC (FAA HQ DEN); ZME; EJA839; C560; STLSTL New Destination: CHA; Weather.		

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	BSagler,	04/16/2013 0423Z	RS

Log:	.og:			
Time (UTC)	Remarks			
1200	ADMIN; ATSC (N/NC); XS on, briefed by DR.			
1205	COD; ATSC (FAA HQ DEN); ZME; IRO8579; C208; MKECMX New Destination: SAW; Weather.			
1240	NORDO; ATSC (FAA HQ DEN); ZAU; N61DN; BE20; FQDPWK; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1255 NORDO 0+15 contacted ZID to check tapes for last good frequency. Communications re-established at 1258.			
1242	EMERGENCY, COD; ATSC (FAA HQ DEN); ZJX; DAL1526; MD88; MCOLGA New Destination: MCO;			
1244	Starboard engine failure. Aircraft landed at 1256. CONFERENCES, ADMIN; ATSC (N/NC); TACOPS complete including VIP locations, LRA, foreign launches,			
4046	and weather diverts. WCLC. NORDO; ATSC (FAA HQ DEN); ZDC; N2242Y; SR22; ?SFQ; Aircraft reported on course, at assigned altitude			
1246	Attempting contact on Guard and previous frequencies. No satellite phone available. Communications reestablished at 1255.			
1255	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Received coordination for a military exercise commencing in the NCR. 1334: Klaxon for the exercise.			
1302	EMERGENCY ,COD; ATSC (FAA HQ DEN); MCI; SWA127; B737; MCIHOU New Destination: MCI; Starboard engine malfunction. Aircraft landed at 1305.			
1311	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; NKS951; A319; FLLMDPP; Passenger medical emergency.			
1320	EMERGENCY; ATSC (FAA HQ DEN); ZNY; N1361S; COZY; GSHN38; Rough running engine. Aircraft landed at 1332.			
1320	COD; ATSC (FAA HQ DEN); LFT; ASQ4105; E135; LFT. LFT New Destination: IAH; Weather.			
1335	COD; ATSC (FAA HQ DEN); ZMP; TSS27; BE40; ATW. EVV New Destination: ATW; Weather.			
1337	COD; ATSC (FAA HQ DEN); ZTL; FIV571; C56X; DNLSGR New Destination; AUS; Company request.			
1345	The state of the s			
1351	NORDO; ATSC (FAA HQ DEN); ZMP; N252CR; M20T; MICFSD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1401.			
1351	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZAU; DAL833; B738; DTWSAT New Destination: ORD; Sick PAX.			
1354	NORDO; ATSC (FAA HQ DEN); C90; N925TK; P180; PWKHUF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1356.			
1400	ADMIN; ATSC (NČRCC); MX on duty.			
1401	COD; ATSC (FAA HQ DEN); ZOA; SKW1352; CRJ2; EUGPSP New Destination: FAT; Company request.			
1407	WAIVER-REVIEW; ATSC (NCRCC); NCRCC; Reviewed and concurred on waiver 2013-PIC7-104771, 2013-PIC7-104772, 2013-PIC7-104773, 2013-PIC7-104774, and 2013-PIC7-104881.			
1409	NORDO; ATSC (NCRCC); ZDC; N898TS; F900; BNAFDK; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications re-established at 1410.			
1412	EMERGENCY; ATSC (FAA HQ DEN); ZFW; KENT27; T38; SPSSPS; Engine overheat indication. Aircraft landed at 1424.			
1412	COD; ATSC (FAA HQ DEN); ZDC; FIV606; C680; HPNCRG New Destination: IAD; Mechanical.			
1426	COD; ATSC (FAA HQ DEN); CHS; ASQ4625; E145; EWRCHS New Destination; CAE; Weather.			
1438	Rey (*) QL(1/2) (#86/e)			
1443	8 (2 3 3 3 d.d.c. 113 g)			
1447	COD; ATSC (FAA HQ DEN); I90; UAL1487; B738; IAHMHLM New Destination: IAH; Airspeed indicator inoperative.			

Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:Created by:Created on:Checked by:ALLBSadler,04/16/2013 0423ZRS

Log:	Log:				
Time (U	TC)Remarks				
1508 1527 1530 1535	COD; ATSC (FAA HQ DEN); ZID; PJC32; C56X; CAKHOU New Destination: DAL; Company request. COD; ATSC (FAA HQ DEN); ZME; ASQ5970; E45X; DSMDEN New Destination: MCI; Fuel. CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful. CONFERENCES; ATSC (CONR/AOC); NEC test successful.				
1542 1547	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZFW; SWA1067; B737; HOULAS New Destination:				
1549 1559	MAF; Sick PAX. COD; ATSC (FAA HQ DEN); ZLA; RSP518; E50P; LGBPSP New Destination: VNY; Fuel. EMERGENCY,COD; ATSC (FAA HQ DEN); ZMA; NOJ70; H25B; PBICYYZ New Destination: PBI; Rear compartment overheat. Aircraft landed at 1609.				
1600 1600 1604 1606 1608	ADMIN; ATSC (FAA HQ DEN); DR off. ADMIN; ATSC (FAA HQ DEN); RV on HQE/HQW. COD; ATSC (FAA HQ DEN); ZHU; DICEY34; TEX2; CLLDYS New Destination: LAW; Mission delay. COD; ATSC (FAA HQ DEN); ZDV; SKW5524; CRJ7; DENASE New Destination: DEN; Weather. TOI-US ADIZ,TOI; ATSC (CONR/AOC); EADS; CGTKY; SR22; MYBSFPR; EADS Unknown/TOI FLL#1, Fort Lauderdale (FLL) 095035, 1200 code, heading 305 degrees, indicating 2,800 feet and 155 knots. Track appears to have departed South Bimini. 1619 Track changed to 0274 code and is flying parallel to the coastline at 700				
1609	hord feet. NORDO; ATSC (FAA HQ DEN); ZJX; JBU569; A320; BOSFLL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1612.				
1624	attitude. Attempting contact on Guard and with Company. Communications re-established at 1612.				
1635 1647 1651	COD; ATSC (FAA HQ DEN); ZAN; WRF9FW; PA31; FAIKAL New Destination: GAL; Company request. NORDO; ATSC (FAA HQ DEN); ZHU; N9265M; M20P; EYQ?; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1655 NORDO 0+15 contacted I90 to verify last transmission (reference ACFT climb). Communications re-established at 1700. EMERGENCY, COD; ATSC (FAA HQ DEN); ZHU; ASQ45678; E145; IAHMOB New Destination: IAH; #1 Engine ots. Aircraft landed at 1713.				
1656	Br; 19 U.S.F. 114 19				
1700 1701	NCR-COORDINATION; ATSC (NCRCC); ZDC; LN551MF, LJ55, HOU to ILG requested lifeguard priority to enter the FRZ. Authorized to enter FRZ to remain clear of the seven mile ring. USSS and PCT advised. COD; ATSC (FAA HQ DEN); ZFW; EJA387; C680; DALAPA New Destination: CMH; Company request.				
1708 1715	WAIVER-REVIEW; ATSC (NCRCC); NCRCC; FLC; Reviewed and concurred on waiver 2013-GOV-104878.				
1718 1723 1734	COD; ATSC (FAA HQ DEN); ZDV; SKW329T; CRJ7; DENASP New Destination: DEN; Weather. COD; ATSC (FAA HQ DEN); ZMP; AJA966; C750; MDWSTP New Destination: MSP; Passenger request. COD; ATSC (FAA HQ DEN); ZAB; AWE797; A320; PHLLAX New Destination: PHX; Unusual smell in cockpit.				
1737 1742	ADMIN; ATSC (N/NC); N/NC; DH on. Briefed by XS. EMERGENCY ,COD; ATSC (FAA HQ DEN); ZHU; N30PC; LJ45; GPTPDK New Destination: GPT; Engine fire; extinguished. Aircraft landed at 1755.				
1750	NORDO; ATSC (FAA HQ DEN); ZMP; DAL2219; A319; LGAMSP; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications reestablished at 1757.				
1752 1800	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; EGF3848; CRJ7; ORDSAT; Sick PAX. ADMIN; ATSC (NCRCC); NCRCC; MK off.				


Page 3



Date: 04/15/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 BSadler,
 04/16/2013 0423Z
 RS



Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/15/2013

Element: Created by: Created on: Checked by: RS

ALL BSadler, 04/16/2013 0423Z RS

Log: Time (UTC) Remarks 2017 2020 COD; ATSC (NCRCC); ZHU; XAGPR; CL30; MMTO. BED New Destination: MMTO; Company request. 2026 NCR-COORDINATION; ATSC (NCRCC); USSS Authorized TRP3 and TRP5 in P40 for a medivac. 2028 COD: ATSC (FAA HQ DEN); ZHU; AAL9616; B763; BFM, DFW New Destination: BFM; Maintenance issue. 2033 EMERGENCY; ATSC (FAA HQ DEN); ZMP; UAL662; A319; SFO..MSP; Something burning in back of ACFT, 2034 flight crew think they have it extinguish, requested CFR. Aircraft landed at 2051. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZBW; ZBW authorized to suspend change of destination 2038 reporting for AOR until 2400 due to Boston Marathon BOMBing. COD; ATSC (FAA HQ DEN); F11; SIL3986; SF34; MCO..PNS New Destination: MCO; Navigational issue. 2042 TFR; ATSC (FAA HQ DEN); SOSC; ZBW 3/2050 91137.a1 due to Boston bombing. 2045 EMERGENCY; ATSC (FAA HQ DEN); ZDV; KNOLL11; C130; COS..COS; Number 3 engine issue. Aircraft 2047 landed at 2103. NORDO, NOTIFICATION-NONE; ATSC (FAA HQ DEN); ZHU; N510BA; C510; SHV..SGR; Aircraft reported on 2051 course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications reestablished at 2051 NORDO, FFDO-ONBRD; ATSC (FAA HQ DEN); ZOB; CHQ6124; E145; DTW..PHL; Aircraft reported on course, 2102 at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2106. AIRPORT; ATSC (FAA HQ DEN); TSOC; At PHX SWA Cargo facility, item alarmed for TATP. Facility on 2120 airport property 7 miles from terminal. EOD responding. CLOSEOUT: 2159 EOD responded and cleared item; no impact to operations. 2124 CONFERENCES; ATSC (CONR/AOC); CFACC test successful. 2130 2130 NORDO: ATSC (FAA HQ DEN); ZMP; KSU11; C172; SLN..K62; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2132. COD; ATSC (FAA HQ DEN); GEG; CFS779; C208; GEG. YKM New Destination: GEG; Mechanical issue. 2131 NORDO: ATSC (FAA HQ DEN); ZMP; N114SN; ASTR; OMA..PDK; Aircraft reported on course, at assigned 2132 altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2138. COD; ATSC (FAA HQ DEN); ZMP; GLA34K; E120; DIK..DEN New Destination: ISN; Minor mechanical. 2132 2134 COD: ATSC (FAA HQ DEN); ZAN; ERR4GV; B190; SCC..AQT New Destination: BRW; WX. SIF; ATSC (FAA HQ DEN); ZBW; CES588; A346; JFK. ZSPD; Taken off approved routing for traffic, returning 2136 ASAP. 2140 NORDO; ATSC (FAA HQ DEN); ZNY; PDT4166; DH8A; PHL..SYR; Aircraft reported on course, at assigned 2158 altitude. Attempting contact on Guard and with Company. Communications re-established at 2203. 2200 ADMIN: ATSC (NCRCC); MX off duty EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; EGF2912; E135; MMMM..DFW; Sick PAX. 2202 EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZAB; AAL399; B738; DFW..SFO New Destination: 2209 ABQ: Elderly male PAX with no pulse. COD; ATSC (FAA HQ DEN); ZTL; SKQ505; PA31; BUY..BHM New Destination: HKY; Fuel. 2209 WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMA; ZMA authorized to suspend change of destination 2210 reporting for AOR until 2400 due to WX. 2223 ADMIN; ATSC (N/NC); MT on, Briefed by DH, WCLC. NORDO; ATSC (FAA HQ DEN); ZMP; N371VP; C510; OMA. PWK; Aircraft reported on course, at assigned 2233 altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2248. COD; ATSC (FAA HQ DEN); ZFW; ASQ4422; E145; MAF..IAH New Destination: MAF; Maintenance issue. 2233

Page 5



Date: 04/15/2013

Element: Created by: Created on: Checked by: RS


ALL BSadler, 04/16/2013 0423Z RS

Log:	
Time (UTC)	Remarks
2249	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDV; ZDV authorized to suspend change of destination
	reporting for AOR until 0200 due to WX.
2318	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MSP; CPZ5698; E170; CYWGMSP; Sick PAX.
2348	COD; ATSC (FAA HQ DEN); SUN; SKW7405; E120; SLCSUN New Destination: TWF; Weather.
2357	ATC FACILITY, PAGED; ATSC (FAA HQ DEN); ZBW; Boston Logan (BOS) lost all runway lighting. 2358 Lights back on RY4L. 0000 All airport lighting RTS.
04/16/2013	
0009	33; 57 (337, 114.0)
	BAY 19 DUALET 211 NA
ſ	8-2-3-3-0-5-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
0031	EMERGENCY; ATSC (FAA HQ DEN); ZMA; EGF3493; E145; CLTMIA; Fuel emergency declared by ZMA,
0031	PIC unable to take any vectors. Aircraft landed at 0045.
0035	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; AAL2289; B752; BOS. DFW; Sick PAX.
0059	EMINOLINO I - WEDICAL, A 100 (I AA 110 DEN), 21 VV, AALEEDS, D/ 32, DOSDI VV, SICK FAA.
0059	
0100	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off.
0104	NORDO; ATSC (FAA HQ DEN); ZAB; N593ER; DA42; PRCNYL; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0127.
0133	COD; ATSC (FAA HQ DEN); ZDV; CYO915; LJ55; MMSDEGE New Destination: ABQ; Company request to satisfy customs.
0133	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; CPZ5778; E170; MSP., MDW; Sick PAX.
0140	EMERGENCY; ATSC (FAA HQ DEN); N90; EGF4604; CRJ7; RDULGA; Hydraulics issue, PIC advised N90 while on final approach. Aircraft landed at 0140.
0157	COD; ATSC (FAA HQ DEN); ZTL; DAL2022; A319; ATLROA New Destination: CLT; ACFT reposition.
-	
0200	ADMIN; ATSC (FAA HO DEN); CU off.
0200	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW.
0200	ADMIN; ATSC (NCRCC); VP on duty.
0206	NOTAM; SOSC (FAA HQ); FDC NOTAM 3/2075 & 3/2076 published for VIP movement to Wilmington, DE. from 1304170015-1304170130 & 1304171245-1304171400, 3 NMR, SFC - 2,999 FT AGL. Spans:18,657.
0207	COD; ATSC (FAA HQ DEN); ZJX; MRA688; C208; ARW. CHS New Destination: CAE; Company request.
0214	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZMP; SWA1967; B737; MKEDEN New Destination: OMA; Sick flight deck officer. 2016 ZMP advised crew member feels much better; ACFT continuing on to DEN.
0215	ADMIN; ATSC (NCRCC); UL off duty.
0215	ADMIN; ATSC (FAA HQ DEN); CW off.
0215	ADMIN; ATSC (NCRCC); WCLC.
0213	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDV; ZDV authorized to suspend change of destination
0231	reporting for DEN Metro Area until 0359 due to low visibility and ceilings.
0247	COD; ATSC (FAA HQ DEN); A80; DAL1711; MD90; ATLDFW New Destination: ATL; Landing gear issue.
0255	COD; ATSC (FAA HO DEN); ZSE; ASA852; B737; LIHSEA New Destination: PDX; WX.
0256	COD; ATSC (FAA HQ DEN); ZFW; EMD21; BE9L; MLCEBG New Destination: MFE; Closer to hospital.
0337	NORDO; ATSC (FAA HQ DEN); ZBW; N18WA; WW24; ASHHSI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. NORDO 0+15; ZBW investigating. 0357 ZBW advised ACFT read back frequency change to ZOB; ZOB advised ACFT entering Canadian airspace,
1	Toronto Sector. ZOB will advise CZY of previous two known ZBW frequencies.

Page 6

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

FOR OFFICIAL USE ONLY



Log:	Log:		
Time (UTC)	Remarks		
0353	LASER; ATSC (FAA HQ DEN); ZTL; CTL67; AC50; BUYPDX; 0338, south of Jefferson, GA, at 6,000 feet, heading west; left side of cockpit illuminated by a green LASER. No injuries reported;		
0358 0359	ADMIN; SOSC (FAA HQ); MS off, SOSC closed. YZ on call. ADMIN; ATSC (FAA HQ DEN); COB.		

Page 7

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

	FOR O	FFICIAL USE ONLY	
	raffic Organization Events Log		
Element: ALL	Created by: BSadler,	Created on: 04/17/2013 0436Z	Checked by RS
Security Event Statis	stics:		
Br, 40 0.0.0.	,£	AIRPORT: 2	COD: 43
EMERGENCY: 11	E	NORDO: 18	LASER: 12
EMERGENCY- MEDI 16	CAL:	B() 00 0.8.0. 114(a)	MOR: 3
Log:			
Time (UTC) Remarks			
04/16/2013			
0400 0400			
2			
0400			
0400	DUJECTO MUNT ATOOJEMA	HO DENI ZDV - db - d- d	

WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDV; ZDV authorized to suspend change of destination 0401 reporting for DEN Metro Area until 0600 due to blizzard conditions. LASER; ATSC (FAA HQ DEN); P50; SKW2988; CRJ1; BUR..PHX; 0346, 8 miles northeast of PHX, at 6,000 0414 feet, heading 090 degrees; left side of cockpit illuminated by a green LASER. No injuries reported; LASER: ATSC (FAA HQ DEN): P50: AWE469; A320; LAS..PHX; 0346, 8 miles northeast of PHX, at 6,000 feet, 0416 heading 090 degrees; left side of cockpit illuminated by a green LASER. No injuries reported LASER: ATSC (FAA HQ DEN): P50: SWA2435: B737: BUR, PHX: 0346, 8 miles northeast of PHX, at 6,000 0418 feet, heading 090 degrees; left side of cockpit illuminated by a green LASER. No injuries reported 0419 LASER; ATSC (FAA HQ DEN); P50; N590ER; DA42; PRC..TUS; 0346, 8 miles northeast of PHX, at 6,000 feet, heading 090 degrees; left side of cockpit illuminated by a green LASER. No injuries reported: LASER; ATSC (FAA HQ DEN); PDX; QXE55; DH8D; SEA..PDX; 0407, 8 miles west of PDX, at 2,600 feet, 0427 heading east; left side of cockpit illuminated by a green LASER. No injuries reported COD; ATSC (FAA HQ DEN); ZID; ABX36; B762; ROW..CVG New Destination: STL; Company request. 0447 COD; ATSC (FAA HQ DEN); ZKC; AWE152; A319; PHX..STL New Destination: IND; WX. 0453 0454 LASER; ATSC (FAA HQ DEN); C6592; S65C; VFR..MTC; 0032, 15 Apr, MTC TRACON reported: 8 miles northeast of MTC, at 2,300 feet, heading 010 degrees; left side of cockpit illuminated by a green LASER from camp fire near golf course. No injuries reported; LASER; ATSC (FAA HQ DEN); TUS; N590ER; DA42; PRC. TUS; 0430, 6 miles northwest of TUS, at 4,500 0457 feet, heading east; left side of cockpit illuminated by a green LASER. No injuries reported; Tucson PD notified via ATC frequencies and PD ACFT vectored to location by ATC. 0550 0600 EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); CRP; EGF9305; E135; DFW..BRO; Sick PAX. 0610 0807

Page 1

Date: 04/16/2013

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/16/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 BSadler,
 04/17/2013 0436Z
 RS


Log:	
Time (UT	Remarks
1000	ADMIN; ATSC (NCRCC); VP off duty.
1000	ADMIN; ATSC (FAA HQ DEN); DR on HQW. WCLC.
1015	ADMIN; ATSC (FAA HQ DEN); RS off.
1021	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1021	COD; ATSC (FAA HQ DEN); ZME; USC191; PA31; SUSADS New Destination: FSM; Fuel.
1022	ADMIN; ATSC (NCRCC); NCRCC; WCLC.
1023	ATC FACILITY; ATSC (FAA HQ DEN); ZLA; Las Vegas TRACON ATC-ALERT due to SURVEILLANCE TRIGGER. 1322 Normal Ops.
1112 1114	COD; ATSC (FAA HQ DEN); ZNY; ASQ4535; E45X; EWRMSP New Destination: EWR; Mechanical.
1116	COD; ATSC (FAA HQ DEN); ZDC; OPT803; H25B; TEB. OCF New Destination; TEB; Maintenance.
1130	ADMIN, EQUIPMENT; ATSC (CONR/AOC); BD on. WCLC, ADAPT CONWSA10 OTS.
1136	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); DTW; FLG3775; CRJ2; GSPDTW; PAX medical issue.
1139	30 to Color Hood
1100	
	307 FM M.B. N. 116 Tr
	971 M.K.M. 31144-
	Erg de Matin. Hans
1200	27) 47 M.B. N. 181 f
1200	COD; ATSC (FAA HQ DEN); ZKC; LOF3517; E145; STLPIT New Destination: STL; Oxygen mask defective.
1200	ADMIN; ATSC (N/NC); XS on, briefed by DR.
1203	COD; ATSC (FAA HQ DEN); ZLC; GLA31K; E120; ISNDIK New Destination: ISN; Mechanical.
1223	COD; ATSC (FAA HQ DEN); ZFW; EJA803; C560; SATSAF New Destination: SAT; Mechanical.
1227	COD; ATSC (FAA HQ DEN); ZTL; ASQ6032; E145; CHSORD New Destination: TYS; Mechanical.
1232	NORDO; ATSC (FAA HQ DEN); ZTL; N8VF; F900; GSOMMCU; Aircraft reported on course, at assigned attitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1247.
1240	LASER; ATSC (FAA HQ DEN); SCT; ABX1920; B763; LAXSFO; Cockpit illuminated by a green laser at 2,000
1240	feet 1NM West LAX, southwest bound. Laser from left side. No injuries reported.
	reet Trivi West LAX, Southwest bound. Laser from left side. No injuries reported.
1243	COD; ATSC (FAA HQ DEN); ZKC; AWE949; A319; MCICLT New Destination: MCI; Mechanical.
1248	NORDO; ATSC (FAA HQ DEN); ZNY; JBU1329; E190; BOS.:BWI; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1251.
1250	En. 32 Marc. His a
	34 D 755 1649
1251	CONFERENCES, ADMIN; ATSC (N/NC); TACOPS complete including VIP locations and movements with
	TFRs, BOS TFR, ZAN airspace protection, foreign launches, LRA, Amalgam Arrow Exercise, and multiple
	practice scrambles. WCLC.
1323	COD; ATSC (FAA HQ DEN); ZID; PAT783; BE20; DEC. IND New Destination: DEC; Maintenance problem.
1327	NORDO; ATSC (FAA HQ DEN); ZNY; N601LS; CRJ1; TEB. CMH; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications
1220	re-established at 1328.
1330	Ety 94 M.S.C. 11 Max
I	50, 40 U.S.C. 4150

Page 2



 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 BSadler,
 04/17/2013 0436Z
 RS



Page 3

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/16/2013

Element: Created by: Created on: Checked by: RS

ALL BSadler, 04/17/2013 0436Z RS

Log:	
Time (UTC)	Remarks
1545	26 43 T.M.C. 1374
1548	27: 10 (3.0. N. 184.3)
1553	NORDO; ATSC (FAA HQ DEN); ZHU; GLF54; GLF6; SAVSAV; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1558.
1553	873 (20 908 of 143) c
1555	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDC; TRS484; B712; RSWPHL; PAX medical emergency.
1558	
1600	89 to 9.5.0. 110 m
1626	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLA; DAL284; B77L; RJAALAX; Passenger medical emergency.
1643	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAB; SWA1323; B737; SEAABQ; PAX medical emergency.
1647	NORDO; ATSC (FAA HQ DEN); ZDC; HRF4SH; PC12; BOSOAJ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1700 HQ DEN requested ZBW check tapes to verify communications transfer and last assigned frequency. 1705 NORDO 0+17 HQ DEN contacted ZDC to check recordings/frequency transfer. Communications re-established at 1707.
1652	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAN; ZAN authorized to suspend change of destination reporting for AOR until 1800 due to weather.
1700	ADMIN; ATSC (CONR/AOC); LB on.
1705	NORDO; ATSC (FAA HQ DEN); ZJX; TRS595; B712; MDWFLL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1711.
1712	TOI-NCR FRZ,MOR,PAGED,TOI; ATSC (NCRCC); NCRCC; VVHX562; H60; NHKNHK; DCA-2, Late Notification: 1530: entered the FRZ on the DCA160015, aircraft continued over DCA and exited the FRZ to the east, pilot failed to accomplish proper coordination as required by NOTAM 0/8326. PCT will file MOR
1715	
1732	27 (0 Total) 116 (0
11.02	
1746	EMERGENCY ; ATSC (FAA HQ DEN); ZME; ARROW41; C130; LRFLRF; Inboard port-side engine failure. Aircraft landed at 1804.
1800	ADMIN; ATSC (FAA HQ DEN); CU on HQW, WCLC.
1800	ADMIN; ATSC (FAA HQ DEN); CW on HQE.
1800	ADMIN; ATSC (NCRCC); NCRCC; UL on duty. At 1815: WCLC.
1800	ADMIN; ATSC (FAA HQ DEN); DR off.
1800	ADMIN; ATSC (NCRCC); NCRCC; MK off.
1800	ADMIN; ATSC (FAA HQ DEN); RV off.
1801	OTHER,PAGED; ATSC (FAA HQ DEN); Late entry: At 1709 at the request of AAL Corporate, the ATCSCC placed a Ground Stop on AAL flights. At 1715 the ground stop extended to EGF flights at DFW/LGA/ORD only. 1814 The Ground Stop is due to an internal computer outage. Ground Stop will extend until 1930 for EGF and 2100 for AAL. 1825 HQ DEN contacted AAL Corporate Security and was advised that IT is attempting to determine the cause of the failure; unknown at this time
	24) 1° deline. 10 10
	Big 10 (48.0) 13211
	Profits Cont. (1986)

Page 4



Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/17/2013 0436Z	RS

Log:	
Time (UTC)	Remarks
1814	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZAB; AWE267; A319; DFWPHX New Destination:
10.4	ELP; Sick PAX.
1817	EMERGENCY ; ATSC (FAA HQ DEN); ORH; N171WT; R44; BEDORH; At 1732 helicopter rotor became entangled with a plastic bag, put down at a local high school 2 to 3 miles E of the ORH. Aircraft landed at 1732. 2014 HQ DEN called Worcester ATCT, no injuries, PIC cleared debris and departed.
1833	NORDO; ATSC (FAA HQ DEN); EADS; N7495J; PA28; HFYHUF; 7600 code observed 10SE HUF; ID confirmed by ZID, destination HUF. HUF ATCT advised aircraft landed at 1842.
1839	COD; ATSC (FAA HQ DEN); ZDV; SKW5589; CRJ2; DENPSP New Destination: DEN; Oil pressure indicator issue.
1845	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZMA; DAL488; B738; MDSDJFK New Destination: MDSD; Non-specific PAX medical.
1852	NORDO; ATSC (FAA HQ DEN); ZDC; N758AZ; M7; IGXSHD; Aircraft reported on course, at assigned altitude. Primary only; possible alternator failure. Attempting contact on Guard. No satellite phone available. Communications re-established at 1856; PIC confirmed alternator problem and cancelled IFR.
1855	NORDO; ATSC (FAA HQ DEN); ZAU; N101HZ; F2TH; TULTEB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1902.
1857	COD; ATSC (FAA HQ DEN); ZLC; DAL1365; A319; MSPBZN New Destination: GEG; Company request.
1859	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAN; ZAN authorized to suspend change of destination reporting for AOR until 2400 due to WX.
1901	Proporting for AON until 2400 due to VVA.
1301	g y 4 - 8.8.e. 1113
1906	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZAU; N425QS; GLF4; BOSOAK New Destination: DSM; Crew or PAX not known. 1912 HQ DEN called DSM APCH, young PAX is ill. Aircraft landed at 1921.
1907	COD; ATSC (FAA HQ DEN); ZHU; EJA587; C56X; HOUOMA New Destination: DFW; Company request.
1916	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZNY; UAL1292; B739; DENEWR; Unconscious female PAX.
1920	COD; ATSC (FAA HQ DEN); ZKC; EJA739; GALX; ARRSAT New Destination: CMH; Company request.
1929	COD: ATSC (FAA HQ DEN); ERI; LJY889; C550; CYYB. ERI New Destination; BUF; Weather.
1929	COD; ATSC (FAA HQ DEN); ZHU; ASQ2598; CRJ2; BRODFW New Destination: SAT; Computer problem with American airlines.
1940	NORDO; ATSC (FAA HQ DEN); ZAU; N566KA; BE30; DAYSUX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1950 HQ DEN asked for update, NORDO. Communications re-established at 1959.
1941	EMERGENCY; ATSC (FAA HQ DEN); ZSE; VVGK801; P3; NUWNUW; Engine fire. Aircraft landed at 2012.
1947	MECHANICAL, NOTIFICATION-NONE; ATSC (FAA HQ DEN); DAL1826; MD90; ATLFLL; After landing, while taxiing to the gate PIC reported engine fire warning light, one fire bottle deployed, ARFF responded, no fire found. ACFT taxied to the gate.
1950	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZME; ASQ5189; CRJ2; XNAATL; Sick PAX.
1953	COD; ATSC (FAA HQ DEN); A80; ASQ5056; CRJ7; ATLFAY New Destination: ATL; Gear issue.
1954	B-y 19 3-S-(), 14 (4)
1958	EMERGENCY ,COD; ATSC (FAA HQ DEN); I90; UAL532; A320; IAHLGA New Destination: IAH; Emergency declared at 1928, Speed indicator light. Aircraft landed at 1937.
2011	OTHER; ATSC (FAA HQ DEN); TSOC; JBU618; E190; PBIHPN; PAX arrested for lewd behavior (indecent
2014	exposure). TOI-NCR SFRA,MOR,PAGED,TOI; ATSC (NCRCC); EADS SR22; YNGHEF; DCA-3: DCA273/26,

Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/16/2013

Element: Created by: Created on: Checked by: RS

ALL BSadler, 04/17/2013 0436Z RS

Log:	
Time (UTC)	Remarks
2029 2030	1200 Code, heading 160 degrees, indicating 1,500 feet and 171 knots. Aircraft appears to have departed YNG, 2015: HEF verified in communications and PIC returned to previously assigned discrete beacon code, Policy Picture (PCT OM upon landing. PCT will be filing a MOR. MECHANICAL; ATSC (FAA HQ DEN); MSY; RIVER51; F18; NBGNBG; Minimum fuel. ADMIN; SOSC (FAA HQ); MS on SOSC1, briefed by KF. MECHANICAL; ATSC (FAA HQ DEN); ZME; ASH2674; CRJ9; OMACLT; Minor mechanical; unable RVSM.
2041	Bay in Mark College
2043 2052 2102 2115 2115	EXERCISE EXERCISE CONFERENCES; ATSC (N/NC); ONEC pre-amble for Amalgam Arrow. ADMIN; ATSC (N/NC); MT on. Briefed by XS. WCLC. COD; ATSC (FAA HQ DEN); ZDV; GLA84D; B190; DENDDC New Destination: DEN; Pressurization problem. OTHER; ATSC (FAA HQ DEN); TSOC; JBU39; A320; LGAPBI; On 4/15/2013 one 9mm round discovered on ACFT by cleaning crew, TSA investigating. TFR; ATSC (FAA HQ DEN); FDC NOTAM 3/2491 issued at the request of the FBI for BOS UFN. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZHU; UAE211; B77W; OMDBIAH; Sick child PAX.
2121	.73; g (p) kan
2123	EMERGENCY; ATSC (FAA HQ DEN); ZFW; FATE11; T38; SPSSPS; Engine number 2 issue. Aircraft landed at 2127. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZTL; DAL442; MD88; MKJSATL; Sick PAX.
2134 2137	VIP,PAGED; ATSC (NCRCC); NCRCC; 2137 VIP departed WH via motorcade en route Union Station, taking train to Baltimore Penn Station. 2236 VIP arrived Baltimore Penn Station, departed for University of Baltimore.
2145	NOTAM, PAGED, VIP; ATSC (NCRCC); NCRCC; FDC NOTAM 3/1881 AREA A for VIP movement to Baltimore, MD in effect but not enforced due to the location of the VIP. 2215 FDC NOTAM 3/1881 enforced. 0010 TFR no
2149	NORDO; ATSC (FAA HQ DEN); ZMP; OPT330; E55P; RILBIV; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2157.
2200 2213	ADMIN; ATSC (NČRCC); NCRCC; MX off duty. EMERGENCY ,COD; ATSC (FAA HQ DEN); ZTL; ASQ5103; CRJ2; ATLJAN New Destination: ATL; Gear issue. Aircraft landed at 2242.
2213 2218	COD; ATSC (FAA HQ DEN); ZFW; EMD21; BE9L; 4O4PWA New Destination: OKC; Hospital is closer. NORDO; ATSC (FAA HQ DEN); ZLC; KLM602; B744; LAXEHAM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2220, HQ DEN not notified until we call ZLC at 2229.
2251	NORDO; ATSC (FAA HQ DEN); ZMA; N464JB; P46T; CHSFLL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2301.
2258	NORDO; ATSC (FAA HQ DEN); ZOA; N207NX; PC12; FATEUG; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2306.
2303	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; ACA985; A319; MKJPCYYZ; 12yo child with allergic reaction.
2327	NORDO; ATSC (FAA HQ DEN); ZKC; N690JK; AC90; 1A9IND; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2333. EMERGENCY ,COD; ATSC (FAA HQ DEN); P50; N316EN; MU2; DVTNYL New Destination: DVT; Right

Page 6



Date: 04/16/2013

Element:Created by:Created on:Checked by:ALLBSadler,04/17/2013 0436ZRS

Log:	
Time (UTC	Remarks
	engine out. Aircraft landed at 2339.
2357	NORDO; ATSC (FAA HQ DEN); ZOB; N941CE; H25B; PTK. TEB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2358.
04/17/2013	
0001	COD; ATSC (FAA HQ DEN); ZOB; DAL1005; A319; CLTDTW New Destination: CLE; Fuel due to holding.
0015	NOTAM-VIP, PAGED, VIP; ATSC (CONR/AOC); FDC NOTAM 3/2075 for VIP movement to Wilmington, DE area in effect, no airport associated with this movement. 0130 TFR expired. TOI Summary: 0 TOI, 0 PD, 0 MOR, 0
20.40	Unable to Identify.
0040	COD; ATSC (FAA HQ DEN); ZLA; AMF1941; SW4; SBPBUR New Destination: ONT; Customer request.
0052	COD; ATSC (FAA HQ DEN); ZHU; UAL1695; B762; IAHLAX New Destination: IAH; Minor mechanical. 0110 airspeed indicator issue./CU.
0053	EMERGENCY ; ATSC (FAA HQ DEN); POB; PACKR30; C130; POBPOB; Hydraulic failure. Aircraft landed at 0156.
0100	ADMIN: ATSC (CONR/AOC): CONR combined with NORAD, LB off.
0104	EMERGENCY, COD; ATSC (FAA HQ DEN); ZAB; HAWK93; B1; DYSCVS New Destination: DYS; Smoke in
0400	cockpit. Aircraft landed at 0113.
0108	COD; ATSC (FAA HQ DEN); ZTL; ASQ5368; CRJ2; ATLDAL New Destination: ATL; Equipment issue.
0138	LASER; ATSC (FAA HQ DEN); METRO PD4; Green laser, from 200 17th Street just W of Turnpike, illuminated cockpit at 500 feet, 4 miles NE Homestead ARB. No injuries reported. Cutler Ridge PD notified on frequency.
	Suspects apprehended.
0138	EMERGENCY ; ATSC (FAA HQ DEN); HCF; STEEK22; F22; HNLHNL; Air cooling system issue. Aircraft landed at 0139.
0200	ADMIN; ATSC (FAA HQ DEN); CU off.
0200	ADMIN; ATSC (NCRCC); VP on duty.
0200	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW.
0215	ADMIN; ATSC (NCRCC); WCLC.
0215	ADMIN; ATSC (NCRCC); WOLC: ADMIN; ATSC (FAA HQ DEN); CW off.
0215	COD; ATSC (FAA HQ DEN); CW oii. COD; ATSC (FAA HQ DEN); ZMP; JBU637; A320; BOSSLC New Destination: SFO; No fuel stop.
0238	LASER; ATSC (FAA HQ DEN); MKE; FRG1543; BE99; CWAMKE; 0121, 17 miles north northwest of MKE, at 5,000 feet, heading 160 degrees; cockpit illuminated by a green LASER (no bearing provided). No injuries
0238	reported; LASER; ATSC (FAA HQ DEN); MKE; FRG1543; BE99; CWAMKE; 0121, 17 miles north northwest of MKE, at 5,000 feet, heading 160 degrees; cockpit illuminated by a green LASER (no bearing provided). No injuries
0242	reported; LASER; ATSC (FAA HQ DEN); N90; DAL504; A319; ATLEWR; 0120, 3.5 miles west of Princeton, at 6,000 feet, heading 060 degrees; cockpit illuminated by a green LASER (no bearing provided). No injuries reported;
0309	COD; ATSC (FAA HQ DEN); ZOA; SKW613Y; CRJ7; SFO. LAX New Destination: SFO; Engine vibration issue.
0309	COD; ATSC (FAA HQ DEN); ZID; JBU254; A319; CLTDAY New Destination: CLT; Equipment issue.
0330	
	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); L30; SWA587; B737; MSYLAS; Sick PAX. ACFT went around on first attempt due to warning light in cockpit; returned to field and landed at 0310.
0332	COD; ATSC (FAA HQ DEN); ZAB; SWA3518; B737; LASMSY New Destination: DFW; Bleed air issue.
0358	ADMIN; SOSC (FAA HQ); MS off, SOSC closed. YZ on call.
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 7



Date: 04/17/2013

Element: Created by: Created on: Checked by: BSadler, 04/18/2013 0411Z RS

Security Event Statistics:

EMERGENCY: 19
EMERGENCY- MEDICAL: 10

TOI: 3
TOI-US ADIZ: 1

NORDO: 12

BY 10 10 10 10

LASER: 14

MOR: 3

Log:	
Time (UTC)	Remarks
04/17/2013	
0400	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW; WCLC. CFPL: NOTAM ZBW 3/2491 TFR 91.137(a)(2).
0400	ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC.
0400	ADMIN; ATSC (NCRCC); VP on duty. CFPL: none. WCLC.
0432	COD; ATSC (FAA HQ DEN); ZHU; EGF2822; E135; DFW. LCH New Destination: AEX; WX.
0435	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZID; ZID authorized to suspend change of destination
0.400	reporting for AOR until 0700 due to widespread thunderstorms.
0439 0520	COD; ATSC (FAA HQ DEN); ZLC; SKW4637; CRJ9; MSPBOZ New Destination: BIL; WX. LASER; ATSC (FAA HQ DEN); ABQ; SKW4615; CRJ9; SLCABQ; 0500, 12 miles east northeast of ABQ, at
0520	9,000 feet, heading east; ACFT observed a green LASER (no bearing provided). No injuries reported;
0526	COD; ATSC (FAA HQ DEN); ZBW; AAL120; B752; JFKLFPG New Destination: JFK; Maintenance checklist
	issue.
0529	COD; ATSC (FAA HQ DEN); ZHU; MRA224; C208; LBBEDC New Destination: AUS; Company request.
0550	ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN.
0611	NORDO; ATSC (FAA HQ DEN); ZLA; AWE431; A320; LAS. PHL; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 0611.
0638	COD; ATSC (NCRCC); PCT; AAL2100; B738; MIADCA New Destination: IAD; Unable to land DCA RWY33.
0734 0820	COD; ATSC (FAA HQ DEN); CVG; AMF723; SW4; MEMCVG New Destination: SDF; WX. LASER; ATSC (FAA HQ DEN); S46; UAL1102; B738; SFOSEA; 0515, 3 miles south southeast of SEA, at 700
0620	feet, heading 340 degrees; left side of ACFT illuminated by a green LASER. No injuries reported;
0823	LASER; ATSC (FAA HQ DEN); N66215; C172; VFRCMA; 0245, NDT ATCT reported 4 to 5 miles south of CMA, at 4,000 feet, heading 070 degrees; cockpit illuminated by a green LASER from 1 to 2 miles north of CMA just south of Spanish Hills housing development. No injuries reported;
0828	LASER; ATSC (FAA HQ DEN); ZSU; JBU747; A320; MCOTJSJ; 0336, 40 miles northwest of TJSJ, at 7,000 feet, heading southeast; right side of cockpit illuminated by a green LASER. No injuries reported
0831	LASER; ATSC (FAA HQ DEN); P50; N967DS; DA40; VFRMSC; 0422, 5 miles east of MSC, at 2,500 feet, heading east; ACFT illuminated by a green LASER (no bearing provided). No injuries reported
0954	COD; ATSC (FAA HQ DEN); ZFW; EMD1; BE9L; ICT. 4O4 New Destination; HHW; AWOS issue.
1000	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. WCLC.
1000	ADMIN; ATSC (NCRCC); VP off duty.
1000	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1100: WCLC.
1015	EMERGENCY, COD; ATSC (FAA HQ DEN); ZTL; ASQ5862; E45X; TYS.:IAD New Destination: TYS; Cabin pressurization failure. Aircraft landed at 1030.

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/18/2013 0411Z	RS

Log:	
Time (UTC)	Remarks
1024	712:
1055	COD; ATSC (FAA HQ DEN); ZID; FLG4317; CRJ2; INDRDU New Destination: IND; Mechanical.
1116	200 J. ATOC (LAATIQ DEN), 210, LEGISTI, GROZ, IND.:RDO New Destination: IND, Mechanical.
1130	ADMIN; ATSC (CONR/AOC); BD on.
1145	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZJX; ZJX authorized to suspend change of destination
1140	reporting for AOR until 1600 due to WX.
1145	EMERGENCY, COD, MECHANICAL; ATSC (FAA HQ DEN); ZDC; JBU272; A320; FLLLGA New Destination: JFK; Cabin pressurization system failure. 1157: ZDC reports aircraft now landing at JFK where maintenance
4000	facility is. Aircraft landed at 1245.
1200 1205	ADMIN; ATSC (N/NC); KN on. Briefed by HQ. WCLC. ATC FACILITY; ATSC (FAA HQ DEN); MFE; MFE reports ATC ALERT due to power trigger. Battery back failure anticipated in 30 minutes. When ATC ZERO declared, airspace will revert to Corpus APCH. UPDATE: at 1312 MFE OMIC reported ATC-ZERO cancelled, facility remains on ATC-ALERT. 1605 ATC alert cancelled/RV.
1212	Eq. 1 - 3.5.5 114.56
1233	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; AAL675; B752; MIADFW New Destination: SHV; Sick passenger.
1241	EMERGENCY, COD; ATSC (FAA HQ DEN); ZNY; JIA357; CRJ2; ALBDCA New Destination: PHL; Smoke in cockpit. Aircraft landed at 1249. Aircraft stopped on runway, passengers deplaned via stairs and bussed to
1245	terminal. ATCSCC initiated brief restriction to arrivals, then lifted restriction when runway re-opened. NOTAM-VIP; ATSC (CONR/AOC); FDC NOTAM 3/2076 for VIP movement from Wilmington, DE in effect. Train
1248	station, no air travel associated with this movement. 1400 TFR expired status, movements and practice scrambles discussed.
1255	COD; ATSC (FAA HQ DEN); ZNY; FDX872; DC10; MHT. MEM New Destination: IAD; Company request.
1310	EMERGENCY; ATSC (FAA HQ DEN); ZLA; AWE47; B752; LIHPHX; Lost thrust in port-side engine. Aircraft landed at 1321.
1320	NORDO; ATSC (FAA HQ DEN); ZAU; AWE657; A320; PHLSFO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1324.
1330	PRACTICE SCRAMBLE; ATSC (CONR/AOC); EADS; LUCKY01; F15; HSTHST; Fighters airbome at 1343.
1334	NORDO; ATSC (FAA HQ DEN); ZID; N563M; C560; INDCMH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1337.
1335	EMERGENCY; ATSC (FAA HQ DEN); N90; EGF4581; CRJ2; CLTLGA; Spoiler malfunction. Aircraft landed at 1346.
1353	
1400	्रमण्ड स्व अ.इ.ट. अवस्था
1400	ADMIN; ATSC (NCRCC); UL on duty. At 1415: WCLC.
1400	88, 45 Dec. 0, 424445
1408	NORDO; ATSC (FAA HQ DEN); ZJX; N666TM; EA50; SATCRG; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1414.
1412	CONR-COORDINATION; ATSC (CONR/AOC); Coordinated the cancellation of the Lawrence DOD airspace with ZKC.
1449	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZDV; ZDV authorized to suspend change of destination reporting for AOR until 2000 due to weather.
1456	NCR-COORDINATION; ATSC (NCRCC); N/NC; UAV activity in progress, indoor facility in Chantilly, Contact

Page 2

FAA Air Traffic Organization NAS Daily Events Log			Date: 04/17/2013	
Element:	Created by:	Created on:	Checked by:	
ALL	BSadler,	04/18/2013 0411Z	RS	

Log:	
Time (UTC	Remarks
1500 1501 1528	information: Mark at 571-239-2240. Operations terminated at 1630. ADMIN; ATSC (FAA HQ DEN); RV on HQW. CONFERENCES; ATSC (CONR/AOC); CFACC test successful. EMERGENCY,COD; ATSC (FAA HQ DEN); ZKC; DAL833; A320; DTWSAN New Destination: OKC; Unfamiliar odor in aft cabin, emergency due to overweight landing. Aircraft landed at 1559.
1530	39 (19.5) (3.1)
1534 1535 1540 1551 1602	CONFERENCES; ATSC (N/NC); ONEC test successful. COD; ATSC (FAA HQ DEN); ZJX; CNS185; PC12; BCTTET New Destination: ISO; Company request. COD; ATSC (FAA HQ DEN); ZKC; KAP93; C402; STLCGI New Destination: MWA; Pilot request. COD; ATSC (FAA HQ DEN); ZLC; CPT333; C208; RKSCPR New Destination: RKS; Maintenance issue. EMERGENCY; ATSC (FAA HQ DEN); ZME; JODY15; C130; GLFLRF; Starboard engine failure. Aircraft landed at 1622.
1608	201 at 1022.
1616	245 CH. 308.00 110 CH
1627 1627	COD; ATSC (FAA HQ DEN); ZAU; EJA884; H25B; TEBSAN New Destination: OMA; Fuel. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZKC; ZKC/MCI authorized to suspend change of destination reporting for AOR until 2200 for weather.
1631	destination reporting for AOR until 2200 for weather. NORDO; ATSC (FAA HQ DEN); ZBW; LN35NK; LJ35; CYHZFPR; NORDO 0+10 Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. 1636 NORDO 0+15 HQ DEN contacted CZM to verify communication transfer/frequency. Communications reestablished at 1640.
1632	CONR-COORDINATION; ATSC (CONR/AOC); Coordination completed with ZBW and A90 for DOD contingency airspace on April 18, 2013 in regard to VIP movement to Boston.
1638 1644	COD; ATSĆ (FAA HQ DEN); ZOB; OPT480; BE40; TEBSBN New Destination: OMA; Fuel. EMERGENCY ; ATSC (FAA HQ DEN); ZDC; RCH9023; C5; SSCMRB; Outer starboard engine failure. Aircraft landed at 1727.
1645 1651	COD; ATSC (FAA HQ DEN); ZLA; LXJ526; CL30; LASMTJ New Destination: GUC; Weather. TOI; ATSC (NCRCC); NCRCC; C177; JYOSNC; DCA325029; JYO Maneuvering Area:
1658	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOB; UAL1041; B738; LASIAD; Passenger medical emergency.
1700 1700 1700 1701	ADMIN; ATSC (CONR/AOC); LB on. 29; 30; 30; 31; 31; 32; COD; ATSC (FAA HQ DEN); ZNY; EJA913; C750; MDWTEB New Destination: ITH; Company request.
1708 1711 1716	COD; ATSC (FAA HQ DEN); ZAU; TCF3447; E170; CYEGORD New Destination: MSN; Weather.
1718 1720	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); MKE; MKE authorized to suspend change of destination

Page 3



Date: 04/17/2013

Element: Created by: Created on: Checked by: BSadler, 04/18/2013 0411Z RS

Log:	
Time (UTC)	Remarks
	reporting for AOR due to weather until 2200.
1721	29, 40 0,857, 11070
1729	NCR-COORDINATION; ATSC (NCRCC); NCRCC; P-56B access for NH aircraft coordinated with DCA ATCT.
1729	VIP; ATSC (NCRCC); NCRCC; Movement times coordinated by NH control for tomorrows VIP movement.
1730	ADMIN; SOSC (FAA HQ); MS on SOSC2, briefed by YZ.
1733	TOI; ATSC (NCRCC); EADS; C172; ANPVFR; DCA090025; 23 feet; TOI: EADS reports a 1200 code at the DCA090025 attitude 023 heading east. FAA NCRCC shows the 1200 as and instructed PCT to have pilot return to discrete code. PCT reports they are in ATC communication with and and will have pilot call PCT to discuss event. PCT also talking to controller about incident event is not labeled at this time.
	than a minute. 1200 code was deemed inadvertent, aircraft in communications with ATC the entire time, PIC briefed on proper transponder procedures in SFRA. NFA.
1743	EMERGENCY; ATSC (FAA HQ DEN); ZFW; DICEY24; TEX2; ABISPS; Rough running engine. Aircraft landed at 1750.
1749	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAU; ZAU authorized to suspend change of destination reporting for ORD AOR until 2200 due to WX. 1829 ZOB added until 2200/RV. 2153 ZAU extended until 2400./CU.
1751	BACACTORIA
	## (2,75%) 11:20°
1758	COD; ATSC (FAA HQ DEN); ZKC; UAL664; A320; SNAORD New Destination; STL; Fuel.
1800	ADMÍN; ATSČ (FAA HQ DÉN); CÚ on HQE, WCLC.
1800	ADMIN; ATSC (NCRCC); NCRCC; SH off.
1800	ADMIN; ATSC (NCRCC); NCRCC; MX on duty. WCLC.
1800	ADMIN; ATSC (FAA HQ DEN); DR off.
1821	COD; ATSC (FAA HQ DEN); ZLA; RSP895; E50P; SLCSMO New Destination: SNA; Company request.
1840	Regris (M.C. 114) e
1842	9 (9 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P. 10 P.
1847	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); C90; C90 authorized to suspend change of destination reporting for AOR until 2400 due to WX.
1906	EMERGENCY; ATSC (FAA HQ DEN); ZMP; ASQ6006; E45X; PIADEN; Looking for a VFR ARPT, Air speed indicator not functioning, 1913 HQ DEN ensured ZDV was informed. Aircraft landed at 2000.
1907	COD: ATSC (FAA HQ DEN): ATL: VNR187: P180: 07FA. AVL New Destination: TRI; WX.
1913	EMERGENCY: ATSC (FAA HQ DEN); ZLA; PINON71; U2; BAB. BAB; Flap problem. Aircraft landed at 1932.
1922	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDV; DAL1651; A320; MSPLAX New Destination: SLC: PAX medical emergency.
1936	Per production district
	$E(p,q)\in \mathbb{N}, \text{for} \in \mathbb{N}$
	34) of 1554, 114 a
	Begins to the state of the stat

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:Created by:Created on:Checked by:ALLBSadler,04/18/2013 0411ZRS

Log:	
Time (UTC)	Remarks
1942	COD; ATSC (FAA HQ DEN); ZMA; SIL4020; SF34; MYAMMCO New Destination: PBI; Overheated battery.
1957	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZME; AAL1968; B738; MUNORD New Destination: MEM; PAX medical emergency.
2007	COD: ATSC (FAA HQ DEN); ZKC; AAL2098; B738; SNA .ORD New Destination; STL; WX.
2008	COD; ATSC (FAA HQ DEN); ZKC; VNR183; P180; MHKLAS New Destination: MKC; Company request.
2018	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZFW; VRD334; A320; LAXFLL New Destination: DFW; PAX medical emergency.
2023	EMERGENCY ,COD,NORDO; ATSC (FAA HQ DEN); WADS; N13HL; C421; HNDCMA New Destination: WJF; WADS/HQ DEN observed 7600 sqawk 15 NE VCV; contacted ZLA and was advised ACFT was talking to ATC
	but had radio problems. Aircraft descended to VFR altitude 11,500 ft but quickly returned to assigned altitude and is maintaining flight plan course, Attempting contact on Guard. No satellite phone available. Communications re-established at 2033 via cell phone; declared emergency going to WJF. ACFT landed at
	2048.
2032	NOTAM,VIP; SOSC (FAA HQ); FDC NOTAM 3/2802 published for VIP movement to Boston, MA. from 1304181315-1304181900, 10/30 NMR SFC-17,999 MSL. Spans:13,851.
2033	SIF; ATSC (FAA HQ DEN); ZMP; ABW301; B744; UUEEORD; Taken off approved routing for WX, returning ASAP.
2036	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZHU; N920CS; SR22; SGRPDK; Sick PAX. 2038 emergency cancelled.
2044	ADMIN; ATSC (N/NC); MT on. Briefed by KN. WCLC.
2047	COD; ATSC (FAA HQ DEN); ZME; PAT382; BE20; DTOMYR New Destination: AVL; No float in oxygen tank.
2049	COD; ATSC (FAA HQ DEN); ZSE; QXE272; DH8D; SEAGP! New Destination: SEA; Mechanical issue.
2052	NORDO; ATSC (FAA HQ DEN); ZAB; N995S; P46T; PHX81XA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2104.
2056	EMERGENCY ,COD; ATSC (FAA HQ DEN); F11; ASQ4235; E145; MCOIAH New Destination: MCO; Fuel leak. Aircraft landed at 2053.
2103	EMERGENCY ; ATSC (FAA HQ DEN); I90; N421PK; C421; AMAIWS New Destination: SGR; Right engine out. Aircraft landed at 2138.
2112	COD; ATSC (FAA HQ DEN); ZFW; EGF2916; E145; DFWMHK New Destination: DFW; Weather.
2118	NORDO; ATSC (FAA HQ DEN); ZSE; N6851T; C441; SBA. UAO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2118.
2120	NORDO,MOR,PAGED; ATSC (FAA HQ DEN); ZDV; SKW365K; CRJ2; DENPSP; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 2136 HQ DEN requested update, NORDO. 2142 HQ DEN called SKW Dispatch, they will send ACARS for frequency 118.22. 2150 NORDO 0+30 contacted ZDV; still no contact and advised ZLA. 2155 ZLA advised they were able to establish communications on 132.85; advised to read Brasher statement and contact ZDV for MOR.
2128	NORDO; ATSC (FAA HQ DEN); HUF; N9518Y; BE50; OSU3DW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2142.
2131	EMERGENCY ; ATSC (FAA HQ DEN); HNL; N51M; P51; HNLHNL; Bolt loose on elevator. Aircraft landed at 2131.
2139	COD; ATSC (FAA HQ DEN); ZME; AAL1759; MD82; PBIORD New Destination: MEM; Ground stop at O'Hare.
2153	NORDO; ATSC (FAA HQ DEN); ZKC; N729JM; LJ45; MDWAMA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 2000 HQ DEN asked FSOC to broadcast over SGF, frequency 118.12. Communications re-established at 2202.
2155	SIF; ATSC (FAA HQ DEN); ZBW; CCA982; B772; JFK. ZBAA; Turned off approved routing for traffic, returning ASAP.
2156 2200	COD; ATSC (FAA HQ DEN); C90; EJA655; C56X; SATUGN New Destination: ENW; Missed approached. ADMIN; ATSC (NCRCC); UL off duty.

Page 5



Date: 04/17/2013

Element: Created by: Created on: Checked by: ALL BSadler, 04/18/2013 0411Z RS

Log:	
Time (UTC	Remarks
2224	COD; ATSC (FAA HQ DEN); ZDV; EJA719; GALX; CPROKC New Destination: CPR; Gear issue.
2232	EMERGENCY, COD; ATSC (FAA HQ DEN); ZAB; AWE224; A319; PHX. BOX New Destination: PHX; Hydraulic
2239	problem. Aircraft landed at 2300. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZOB; ZOB authorized to suspend change of destination reporting for AOR until 2400 due to weather. 0013 extended until 0200.
2255	se actual that
	84 Sa NAC 118 1
	84, 19 (M.K. 114)
2300	ADMIN; ATSC (FAA HQ DEN); RV off.
2321	COD; ATSC (FAA HQ DEN); ZAB; FIV556; C56X; GUPSTE New Destination: ELP; Blowing dust.
2331	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ATL; SWA1516; B737; SDFATL; Sick FA. Aircraft landed at 2320.
2336	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; AWE719; A320; PHLMIA; Sick PAX.
2337	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZDC; YANKE37; LJ35; SSCBDL New Destination: NHK; Electrical issue. 2341 COD to SBY. 2342 COD to ADW. Aircraft landed at 0002.
2343	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZKC; ZKC authorized to suspend change of destination reporting for AOR until 0200 due to WX.
2348	
2350	
2000	. 38; 38 M.S.C. (13):
2355	TFR,MOR; ATSC (FAA HQ DEN); LGA; N7825Z; C150; Airspace violator of the New York Yankee's TFR about 2325. Brasher warning read to PIC, PIC will contact LGA ATCT for possible MOR.
04/18/2013	
8000	AIRPORT; ATSC (NCRCC); NCRCC; ADW RWY 1L closed, no runways available. Runway reopened 0015.
0010	EMERGENCY ; ATSC (FAA HQ DEN); ZSE; YUKON1; F15; LMTLMT; Flight control issue. Aircraft landed at 0013.
0017	COD; ATSC (FAA HQ DEN); ZHU; TTX3536; SH36; DTOMMIO New Destination: LRD; Fuel.
0023	COD; ATSC (FAA HQ DEN); MIA; EJM166; GL5T; MQSOPF New Destination: MIA; PAX request.
0039	LASER; ATSC (FAA HQ DEN); JFK; AAL1831; B738; BOSJFK; Green laser observed at 1,100 feet, 5 miles NE JFK. ACFT SW bound, no injuries reported
0041	COD; ATSC (NCRCC); ZAB; AAL414; MD83; DEN. DFW New Destination: ABI; Due to fuel.
0045	COD; ATSC (NCRCC); BLU72; PA31; PDKBMG New Destination: 2R2; Weather.
0100	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off.
0103	TFR, MOR; ATSC (FAA HQ DEN); LGA; N426LP; C172; Airspace violator of the New York Yankee's TFR about 0052, Brasher warning read to PIC, PIC will contact LGA ATCT for possible MOR.
0106	COD; ATSC (FAA HQ DEN); ZDV; LYM234A; SW4; LBFDEN New Destination: SNY; Company request.
0111	COD; ATSC (FAA HQ DEN); ZFW; SKW8503; CRJ2; PSPOKC New Destination: IAH; WX.
0113	COD; ATSC (FAA HQ DEN); ZDC; JBU396; A320; MCOLGA New Destination: JFK; Mechanical issue.
0118	89 68 U.S. C. (1730)
	BQ 45 BLCC 116 45
	Registration (Ages)
0128	COD; ATSC (FAA HQ DEN); ZFW; AAL1024; MD82; DFWOKC New Destination: DFW; WX.

Page 6



Element: Created by: Created on: Checked by: RS
ALL BSadler, 04/18/2013 0411Z RS

Log:	_og:		
Time (UTC)	Remarks		
0130	COD; ATSC (FAA HQ DEN); ZFW; SWA247; B737; BWIOKC New Destination: DAL; WX.		
0140	COD; ATSC (FAA HQ DEN); ZOA; HAL449; A332; HNLRJBB New Destination: HNL; Degraded navigational issue.		
0150	EMERGENCY,COD; ATSC (FAA HQ DEN); ZNY; JBU396; A320; MCOLGA New Destination: JFK; Brake issue. Aircraft landed at 0201.		
0200	ADMIN; ATSC (NCRCC); VP on duty.		
0200	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW.		
0200	ADMIN; ATSC (FAA HQ DEN); CU off.		
0206	COD; ATSC (FAA HQ DEN); ZHU; SWA3134; B733; HOU. TPA New Destination: HOU; Equipment issue.		
0207	COD; ATSC (FAA HQ DEN); N90; EJA930; C750; LGAIAD New Destination: HPN; Company request.		
0208	COD; ATSC (FAA HQ DEN); ZOB; GJS6279; CRJ7; LGAOMA New Destination: STL; De-ice equipment issue.		
0209	LASER; ATSC (FAA HQ DEN); DAB; N493ER; C172; VFRDAB; 0053, 3.5 miles east of DAB, at 2,500 feet, heading north; ACFT observed a green LASER of the right at the intersection of Intercoastal Speedway Blvd. 92 and the beach. No injuries reported;		
0214	COD; ATSC (FAA HQ DEN); ZMP; GLA178; B190; MSPHON New Destination: PIR; Maintenance issue.		
0214			
0215	MECHANICAL; ATSC (FAA HQ DEN); ZBW; FDX1908; B752; SYREWR; Transponder issue. ADMIN: ATSC (NCRCC); WCLC.		
0215			
0215	LASER; ATSC (NCRCC); ZDC; ASQ4209; E145; BNAEWR; 0215, ARD235013, 12,000 feet, heading east;		
0219	Green laser, right side, no reported injuries LASER; ATSC (FAA HQ DEN); PHL; BAD141; MU2; TEBPHL; 0050, 12 miles northeast of PHL, at 4,000 feet, heading southeast; ACFT observed green LASER off right side 2 miles. No injuries reported;		
0225	LASER; ATSC (NCRCC); ZDC; UAL721; B752; IAHEWR; 0225, ARD235013, 12,000 feet, heading Northeast; Green laser, right side, no reported injuries,		
0230	LASER; ATSC (NCRCC); ZDC; UAL1069; B737; SKBOEWR; 0230, ARD235013, 12,000 feet, heading Northeast; Green laser, right side, no reported injuries,		
0235	LASER; ATSC (NCRCC); DCA; HH65; ADWADW; 0235, DCA060009, at 1,000 feet, heading south; Green laser, left side, 1 injury to crewmember (mechanic) reported.		
0258	COD; ATSC (FAA HQ DEN); ZDV; SKW865L; CRJ7; DEN. ASE New Destination: GJT; WX.		
0259	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOA; DAL1149; B753; LAX., HNL; Sick PAX.		
0300	COD; ATSC (FAA HQ DEN); ZMP; BMJ43; BE65; BJIROX New Destination: BJI; WX.		
0313	NORDO; ATSC (FAA HQ DEN); MEI; N125LC; SR22; PPQBFM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0330.		
0318	TFR,NOTAM; ATSC (FAA HQ DEN); ZFW; ZFW 3/2873 91.137(a)(1) 3/3000 for Waco, TX plant explosion.		
0310	COD; ATSC (FAA HQ DEN); BUF; ASH3730; CRJ7; BUFORD New Destination: BUF; Pressurization issue.		
0347	LASER; ATSC (FAA HQ DEN); CAK; JIA262; CRJ7; CLTCAK; 0138, 6 miles north of CAK, at 5,000 feet, heading north; ACFT observed a green LASER from 1 o'clock. No injuries reported;		
0351	LASER; ATSC (FAA HQ DEN); AVP; UCA3587; DH8C; EWRAVP; 0115, 11 miles northeast of MPO, at 5,000 feet, heading west; ACFT observed green LASER (no bearing provided). No injuries reported;		
0353	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZKC; UAL1439; B738; IADLAX New Destination: STL; Sick PAX.		
0359	ADMIN; ATSC (FAA HQ DEN); COB.		

Page 7

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/18/2013

Element: ALL

Created by: BSadler.

Created on: 04/19/2013 04027 Checked by: RS

Security Event Statistics:

EMERGENCY: 14 EMERGENCY- MEDICAL:

TOI: 3 TOI-TFR: 1 TOI-US ADIZ: 1 AIRPORT: 1 NORDO: 17

COD: 40 LASER: 12

MOR: 2

Log:

Time (UTC) Remarks

04/18/2013

0400

ADMIN: ATSC (NCRCC); VP on duty, CFPL: none, WCLC. 0400

ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW; WCLC. CFPL: ZBW 3/2491 TFR 91.137(a)(2) for BOS:

ZFW 3/2837 TFR 91.137(a)(1) for ACT.

0400 ADMIN; ATSC (N/NC); MT on, CFPL; None, WCLC,

COD; ATSC (FAA HQ DEN); ZMA; AAL221; B752; MIA., SBRF New Destination; MIA; Temperature sensor 0403

issue

0404 WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZKC; ZKC authorized to suspend change of destination reporting for AOR until 0700 due to widespread thunderstorms. 0449 OKC and ZAU added.

ADMIN: ATSC (N/NC): MT off. Combined with HQ DEN. 0550

OTHER; ATSC (FAA HQ DEN); ZAN; R26298; H60; FBK..BIG; ACFT advised ZAN they had approval to land at 0738 BIG; advisory circular states no ACFT to land at BIG if ATCT closed. ZAN advised PIC ATCT closed and unable to issue clearance. ACFT cancelled IFR and appeared to continue to BIG

EQUIPMENT; ATSC (FAA HQ DEN); WOC; Lotus Notes E-mail appears to intermittant; big delay times in mail 0745

delivery, 0200 RTS

0747 EQUIPMENT; ATSC (FAA HQ DEN); ETMS at HQ DEN position 2 OTS; contacted help desk who advised system appears to be working normally. Help desk rebooted system without effect. 0755 Help Desk advised will work issue; probably will not be resolved until morning, 0023 RTS.

LASER; ATSC (FAA HQ DEN); ZDC; UAL721; A320; IAH. EWR; 0225, 18 Apr, 13 miles southwest of ARD, at 0823 12,000 feet, heading northeast; right side of ACFT illuminated by a green LASER. No injuries reported;

LASER; ATSC (FAA HQ DEN); ZDC; ASQ4209; E145; BNA..EWR; 0225, 18 Apr., 13 miles southwest of ARD. 0826 at 12,000 feet, heading northeast; right side of ACFT illuminated by a green LASER. No injuries reported;

LASER; ATSC (FAA HQ DEN); ZDC; UAL1060; B738; MCO..EWR; 0230, 18 Apr, 13 miles southwest of ARD, at 12,000 feet, heading northeast; right side of ACFT illuminated by a green LASER. No injuries reported;

0834

0830

LASER: ATSC (FAA HQ DEN); SCT; AAL181; B762; JFK..LAX; 0352, 18 Apr. 6 miles southwest of POM, at 0842 7,000 feet, heading west; right side of ACFT illuminated by a green LASER. No injuries reported:

LASER; ATSC (FAA HQ DEN); SCT; SWA2084; B737; OAK. SNA; 0306, 18 Apr., 10 miles east northeast of 0845 SLI, at 3,000 feet, heading east; left side of ACFT illuminated by a green LASER. No injuries reported;

COD; ATSC (FAA HQ DEN); ZKC; FDX1750; MD11; IND..LAX New Destination: IND; Maintenance issue 0849

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



ر يا يوم الحيل دم ي

FAA Air Traffic Organization NAS Daily Events Log

Date: 04/18/2013

Element: Created by: Created on: Checked by: BSadler, 04/19/2013 0402Z RS

Log:	
Time (UTC	Remarks
0856	NORDO,FFDO-ONBRD; ATSC (FAA HQ DEN); ZOA; AAL2237; MD83; DFWSMF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0903.
0907 0922	COD; ATSC (FAA HQ DEN); ZTL; LBQ870; BE58; LZUROA New Destination: LYH; WX. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZFW; ZFW authorized to suspend change of destination
0924	reporting for AOR until 1200 due to thunderstorms. NORDO; ATSC (FAA HQ DEN); ZAU; FDX1536; A310; MEMGRR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0926.
0926	50, 15 p.s.e. 11 m
0929 1000 1000	COD; ATSC (FAA HQ DEN); ZAU; LBQ652; E50P; DPAIXD New Destination: MCI; WX. ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. WCLC. ADMIN; ATSC (NCRCC); SH on. 1100: WCLC.
1000 1016	ADMIN; ATSC (NCRCC); VP off duty.
1025 1036 1043	NCR-COORDINATION; ATSC (NCRCC); NCRCC; VIP movements confirmed for this mornings VIP movement. ATC FACILITY; ATSC (NCRCC); NCRCC; FAA HQ DEN reports DAA ATCT DEN telephone is out of service. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZOB; ZOB authorized to suspend change of destination reporting for AOT until 1600 due to WX.
1102 1130	NCR-COORDINATION; ATSC (NCRCC); NCRCC; VIP movement coordinated again for later this morning. ADMIN; ATSC (CONR/AOC); PM on.
1133	ATC FACILITY; ATSC (FAA HQ DEN); D21; D21 ATC ALERT due to surveillance trigger, negative impact to operations, 1204 Cancel ATC ALERT, operations normal.
1138 1141	ADMIN; ATSC (CONR/AOC); WCLC. OTHER; ATSC (NCRCC); C6591; YNWN?; USCG NCRCC reports a SAR (C6591) mission in north east of SFRA beginning 1215Z. 1330: Aircraft observed departing the area.
1141	EMERGENCY , COD; ATSC (FAA HQ DEN); F11; N352XR; LJ60; MCOIAD New Destination: MCO; Smoke in the cockpit. Aircraft landed at 1143.
1145 1200	ADMIN; ATSC (N/NC); KN on. Briefed by HQ. WCLC.
1215	CONFERENCES; ATSC (CONR/AOC); CFACC preamble conference conducted for FDC NOTAM 3/2802 VIP TFR Boston, MA.
1215 1240	ADMIN; ATSC (FAA HQ DEN); DR on HQT. JV on HQW/HQE. WCLC. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAU; ZAU authorized to suspend change of destination reporting for ORD AOR until 1800 due to WX.
1243	South Distriction
	\$47 (2.71,8.12, 111, 1)
	50) 16 T.B.C. 1110c
1254	30 of California (1) a
1257	NORDO; ATSC (FAA HQ DEN); ZDV; RPA4924; DH8D; MCI. DEN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1305.

Page 2



Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/19/2013 0402Z	RS

coordinated DoD commit intentions for TFR with ZBW, BOS TRACON, and USSS. NOTAM-VIP,TFR,PAGED,VIP, ATSC (FAA HQ DEN); FDC NOTAM 3/2802 AREA A and B for VIP movement to Boston, MA in effect, enforced at 1350. arrival delays: 1 @ +15, and 9 departure delays: 5 @ +15, 4 @ +30. TOI Summary. 1 TOI, 1 MOR Action. COD; ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEBF45 New Destination: PBI; Company request. COD; ATSC (FAA HQ DEN); ZDC; AWE1678; A319; TPA. DCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUY. BHC; Alroraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRABWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: MEM; Fuel. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: MEM; Fuel. EMERGENCY; ATSC (RORCC); PCT; N432HF; B430; JRABWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: MEM; Fuel. EMERGENCY; ATSC (RORCC); PCT; N432HF; B430; JRABWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: MEM; Fuel. EMERGENCY; ATSC (NCRCC); PCT; N491; B494; B599; BIE. GRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land	Log:	
coordinated DoD commit intentions for TFR with ZBW, BOS TRACON, and USSS. NOTAM-VIP,TFR,PAGED,VIP, ATSC (FAA HQ DEN); FDC NOTAM 3/2802 AREA A and B for VIP movement to Boston, MA in effect, enforced at 1350. Summary: 1 TOI, 1 MOR Action. COD: ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEB.F45 New Destination: PBI; Company request. COD: ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEB.F45 New Destination: PBI; Company request. COD: ATSC (FAA HQ DEN); ZDC; AWE1678, A319; TPA. DCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUY. BHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment lissues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRA. BWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E146; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E146; STLIAH New Destination: MEM; Fuel. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E146; STLIAH New Destination: MEM; Fuel. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E146; STLIAH New Destination: CAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E146; STLIAH New Destination: CAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E146; STLIAH New Destination: CAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. AW3335 is approved to land DCA. IAD ATCT notified that AW33835 is allowed to land DCA. No call per NOTAM 0/8326 cwas made to the NCRCC. TSA NCRCC is investigating. 1446; TSA reports AW3335 is approved to land DCA. IAD ATCT notified that AW33835 is allowed to land DCA. TOI-USA pDIZ.TOI; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. AW3335 is approved to land DCA. IA	Time (UTC)	Remarks
NOTAM-VIP,TFR,PAGED,VIP, ATSC (FAA HQ DEN); FDC NOTAM 3/2802 AREA A and B for VIP movement to Boston, MA in effect, enforced at 1350. arrival delays: 1 @ +15, and 9 departure delays: 5 @ +15, 4 @ +30. TOI Summary: 1 TOI, 1 MOR Action. COD; ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEB.F45 New Destination: MSP; Mechanical. COD; ATSC (FAA HQ DEN); ZDC; AWE1678, A319; TPA. DCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); ZDC; AWE1678, A319; TPA. DCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); ZFW; HA130W; P28A; BUY, BHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRA. BWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; B145; STLIAH New Destination: MEM; Fuel. EMERGENCY- MEDICAL, ATSC (CONRAOC); ADAPT CONWSA10 RTS. OTHER, ATSC (NCRCC); IAD; AWI9335; CRJ2; IAD. DCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating 1445: TSA reports AWI3835 is approved to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. NORDO; ATSC (FAA HQ DEN); CRCR OF AWI3835; BA1041 (140 Nnots.	1300	
to Boston, MA in effect, enforced at 1350. Summary: 1 TOI, 1 MOR Action. COD, ATSC (FAA HQ DEN); ZJX, BJS; LJ40; TEB.F45 New Destination: PBI; Company request. COD, ATSC (FAA HQ DEN); ZJX, BJS; LJ40; TEB.F45 New Destination: PBI; Company request. COD, ATSC (FAA HQ DEN); ZDC; AWE1678, A319; TPA. DCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUY. BHC, Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY, ATSC (NCRCC); PCT; N432HF; B430; ARA, BWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD, ATSC (FAA HQ DEN); ZBY; LD5029; E145; STL. IAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZBY; LD5029; E145; STL. IAH New Destination: MEM; Fuel. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DHBC; ALB, EWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; ADAPT CONWSA10 RTS OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IAD, DCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOHUS ADIZ, TOI; ATSC (CONR/AOC); BAST, B407; MYAF, FLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 137 arck on 1240 code and identified B407; ABC (CONR/AOC); B407; B407; MYAF, FLL; EADS Unknown Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNN. EQY; Aircraft reported on course, at assigned altitude, Attempting contact on Guard. No saallellie phone available. Communications re-established at 1500.	1301	223 10 11.56 11.56
arrival delays: 1 @ +15, and 9 departure delays: 5 @ +15, 4 @ +30. TOI Summary: 1 TOI, 1 MOR Action. COD: ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEB. F45 New Destination: PBI; Company request. COD: ATSC (FAA HQ DEN); ZMP; GLA244; B190; MSPHMS New Destination: MSP, Mechanical. COD: ATSC (FAA HQ DEN); ZDC: AWE1678; A319; TPA. DCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (CNCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUY. BHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRA. BWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW: LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZMF; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. EMERGENCY- MEDICAL, ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALB. EWR; Sick passenger COD; ATSC (FAA HQ DEN); ZMF; AAL1045; B738; CYULDFW New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ, TOI; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. 1439 B407; departed Andros Town Bahamas to Fort Lauderdale (FLL) PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNN.EQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNN.EQY; Aircraft reported on course.	1315	1.5.4.140.0
arrival delays: 1 @ +15, and 9 departure delays: 5 @ +15, 4 @ +30. TOI Summary: 1 TOI, 1 MOR Action. COD: ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEBF45 New Destination: PBI; Company request. COD: ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEBF45 New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUYBHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRABWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STL.IAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZME; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. EMERGENCY: MEDICAL, ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIE. GRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. EMERGENCY: MEDICAL, ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIE. GRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. TOI-US ADIZ, TOI; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. TOI-US ADIZ, TOI; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. TOI-US ADIZ, TOI; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. AW/J8835 is approved to land DCA. IAD ATCT notified that AW/J3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AW/J3835 is approved to land DCA. IAD ATCT notified that AW/J3835 is allowed to land DCA. IAD ATCT notified that AW/J3835 is allowed to land DCA. IAD ATCT notified that AW/J3835 is allowed to land DCA. IAD ATCT notified that AW/J3835 is allowed to land DCA. IAD ATCT notified that AW/J383	·	34, 4, M. G. G. 4, 3, 4
arrival delays: 1 @ +15, and 9 departure delays: 5 @ +15, 4 @ +30. TOI Summary: 1 TOI, 1 MOR Action. COD; ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEB.,F45 New Destination: PBI; Company request. COD; ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEB.,F45 New Destination: MSP, Mechanical. COD, ATSC (FAA HQ DEN); ZDC; AWE1678; A319; TPA.,DCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUY.,BHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRA.,BWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STL.,IAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STL.,IAH New Destination: MEM; Fuel. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STL.,IAH New Destination: MEM; Fuel. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALB.,EWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMF; AMF1694; BE99; BIE.,GRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IAD.,DCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. 1439 TOI-US ADIZ,TOI; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. 1440 TOI-US ADIZ,TOI; ATSC (CONR/AOC); BAPT TO notified that AWI3835 is allowed to land DCA. 1441 TOI-US ADIZ,TOI; ATSC (CONR/AOC); BAPT TO NOTIFICAL TO TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE ADIC TOTE A		\$49 q (M.A.) 11 c q
COD; ATSC (FAA HQ DEN); ZJX; BJS; LJ40; TEB.F45 New Destination: PBI; Company request. COD; ATSC (FAA HQ DEN); ZMP; GLA244; B190; MSPHMS New Destination: MSP; Mechanical. COD; ATSC (FAA HQ DEN); ZDC; AWE1678; A319; TPADCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUY; BHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRA. BW; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZMP; AAL1045; B738; CYUL. DFW New Destination: MEM; Fuel. EMERGENCY; MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ, TOI; ATSC (CONR/AOC); B407; MYAF.FLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified by 1843 B407, departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude, Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT.		arrival delays: 1 @ +15, and 9 departure delays: 5 @ +15, 4 @ +30. TOI
1332 COD; ATSC (FAA HQ DEN); ZMP; GLA244; B190; MSP. HMS New Destination: MSP; Mechanical. 1348 COD; ATSC (FAA HQ DEN); ZDC; AWE1678; A319; TPA. DCA New Destination: RIC; Volume. Holding. 1348 WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. 1351 NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUY. BHC; Aircraft reported on course, at assigned allitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. 1352 EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRA. BWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. 1354 COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STL. IAH New Destination: OKC; Fuel. 1359 COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STL. IAH New Destination: MEM; Fuel. 1401 EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DHBC; ALB. EWR; Sick passenger. 1402 COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIE. GRI New Destination: EAR; Company request. 1403 EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DHBC; ALB. EWR; Sick passenger. 1404 COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIE. GRI New Destination: EAR; Company request. 1405 EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. 1406 OTHER; ATSC (NCRCC); IAD; AWI3835; CRJz; IAD. DCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. 1409 TOI-US ADIZ,TOI; ATSC (CONR/AOC); EARD; B407; MYAF. FLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified EARD B407; Adeparted Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. 1446 NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNN. EQY; Aircraft reported on course, at assigned altitude. Attempting c	1319	
 COD; ATSC (FAA HQ DEN); ZDC; AWE1678; A319; TPADCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUYBHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRABWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZME; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. EMERGENCY: MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ, TOI; ATSC (CONR/AOC); ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ, TOI; ATSC (CONR/AOC); BAOT; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified B407, departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT. 	1319	
 COD; ATSC (FAA HQ DEN); ZDC; AWE1678; A319; TPADCA New Destination: RIC; Volume. Holding. WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUYBHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRABWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZME; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. EMERGENCY: MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ, TOI; ATSC (CONR/AOC); ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ, TOI; ATSC (CONR/AOC); BAOT; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified B407, departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT. 		897 (2.28)
WEATHER DIVERTS-MULT; ATSC (NCRCC); PCT; PCT authorized to suspend change of destination reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUYBHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRABWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZME; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ, TOI; ATSC (CONR/AOC) (CONR/AOC	1	
reporting for NCRCC until 1500 due to weather and runway changes. NORDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUYBHC; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRABWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZME; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ,TOI; ATSC (CONR/AOC); STATE (CONR/AOC); B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified B407; Apparted Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT.	1	
 NÖRDO; ATSC (FAA HQ DEN); FAY; N4130W; P28A; BUYBHČ; Aircraft reported on course, at assigned altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRABWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZME; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ,TOI; ATSC (CONR/AOC); ATSC (GNR/AOC); B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified B407; departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT. 	1340	
altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407. EMERGENCY; ATSC (NCRCC); PCT; N432HF; B430; JRA. BWI; EMRG due to low fuel and holding at BWI. Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZME; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ, TOI; ATSC (CONR/AOC); State; B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified B407; departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT.	1351	
Now given straight in APCH to BWI. Aircraft landed at 1359. COD; ATSC (FAA HQ DEN); ZFW; LOF5029; E145; STLIAH New Destination: OKC; Fuel. COD; ATSC (FAA HQ DEN); ZME; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. BEMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ,TOI; ATSC (CONR/AOC) ADAPT CONWSA10 RTS. 1439 TOI-US ADIZ,TOI; ATSC (CONR/AOC) ADAPT CONWSA10 RTS. 1440 NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT.		altitude. Loss of communications caused by FAA equipment issues. Communications re-established at 1407.
COD; ATSC (FAA HQ DEN); ZME; AAL1045; B738; CYULDFW New Destination: MEM; Fuel. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ,TOI; ATSC (CONR/AOC) Series; B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT.	Į.	
 EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ,TOI; ATSC (CONR/AOC) B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified B407, departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT. 		
 EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UCA3585; DH8C; ALBEWR; Sick passenger. COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ,TOI; ATSC (CONR/AOC) B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified B407, departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT. 	1	
 COD; ATSC (FAA HQ DEN); ZMP; AMF1694; BE99; BIEGRI New Destination: EAR; Company request. EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ,TOI; ATSC (CONR/AOC) and B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified and B407, departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT. 	1 1	
 EQUIPMENT; ATSC (CONR/AOC); ADAPT CONWSA10 RTS. OTHER; ATSC (NCRCC); IAD; AWI3835; CRJ2; IADDCA; IAD ATCT queried if AWI3835 is allowed to land DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. TOI-US ADIZ,TOI; ATSC (CONR/AOC) 15 10 10 10 10 10 10 10 10 10 10 10 10 10	1	
DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports AWI3835 is approved to land DCA. IAD ATCT notified that AWI3835 is allowed to land DCA. 1439 TOI-US ADIZ,TOI; ATSC (CONR/AOC) 1840 185; B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified 1840 1840. B407, departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and transponder worked. NFA. NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT.	1	
TOI-US ADIZ, TOI; ATSC (CONR/AOC) 18 18 18; B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified 18 18 18 18 18 18 18 18 18 18 18 18 18	1433	DCA. No call per NOTAM 0/8326 was made to the NCRCC. TSA NCRCC is investigating. 1445: TSA reports
1446 NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1500. ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT.	1439	TOI-US ADIZ, TOI; ATSC (CONR/AOC) B. (1998); B407; MYAFFLL; EADS Unknown Fort Lauderdale(FLL) 110038, primary only, heading 250 degrees, indicating 6,000 feet, 140 knots. 1433 Track on 1240 code and identified B. (1998); B407, departed Andros Town Bahamas to Fort Lauderdale (FLL). PIC recycled and
1500 ADMIN; ATSC (FAA HQ DEN); DR/RV on HQT.	1446	NORDO; ATSC (FAA HQ DEN); CHS; N33849; P28R; LNNEQY; Aircraft reported on course, at assigned
	1500	47

Page 3



Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/19/2013 0402Z	RS

Log:	
Time (UTC) Remarks
4-4-	Region Policy (1994)
1515 1519	NORDO; ATSC (FAA HQ DEN); ZTL; N658CF; CL60; SHVTTN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. At 1527 aircraft transitioned into ZDC airspace. Communications re-established at 1530.
1521	COD; ATSC (FAA HQ DEN); ZME; AAL1174; MD83; TPA. ORD New Destination: MCI; Fuel.
1530	COD; ATSC (FAA HQ DEN); ZMP; FLG4184; CRJ2; DTWMSP New Destination: DTW; Weather.
1533	COD; ATSC (FAA HQ DEN); ZTL; AAL1097; MD82; LGADFW New Destination: MSY; Fuel.
1537	TOI; ATSC (NCRCC); EADS EADS identified a TOI at the DCA210010 leading 075 speed 130.
1541	CONFERENCES; ATSC (N/NC); ONEC test successful.
1608	EMERGENCY, COD; ATSC (FAA HQ DEN); ZMP; CHQ6123; E145; DTWTVC New Destination: FNT; Minimum fuel. Aircraft landed at 1645.
1612	26. 4 (J.S.C. 11) C
1631	COD; ATSC (FAA HQ DEN); ZAB; UAL6155; B737; IAHSAN New Destination: PHX; Fuel.
1633	TOI-TFR,MOR,PAGED,TOI,VIP; ATSC (FAA HQ DEN); Boston TOI #1: BOS190/029, 1200 Code, heading 050 degrees, indicating 2,700AGL, and 130 knots. Aircraft appears to have departed 1N2, 1640 ACFT appears to
	have landed at K28 (Cranland, MA); A90 contacting FBO for information.
1640	EMERGENCY ; ATSC (FAA HQ DEN); SAT; CREEP2; T38; RNDRND; Fuel sensor failure. Aircraft landed at 1644.
1645	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZOB; ZOB authorized to suspend change of destination reporting for AOR until 2100 due to weather. Extended to 2359.
1653	EMERGENCY, COD, MECHANICAL, PAGED; ATSC (FAA HQ DEN); D21; SCX266; B737; DCA. LAN New Destination: DTW; Aircraft experienced flight control problems and had a rough landing at LAN, but went around and is diverting to DTW. The aircraft may have scrapped his wing and is currently not experiencing flight control problems. Aircraft landed at 1700 without incident.
1710	COD,MECHANICAL; ATSC (FAA HQ DEN); ZID; SWA495; B737; BWISTL New Destination: BNA; Mechanical.
1722	EMERGENCY, COD; ATSC (FAA HQ DEN); ZKC; N32PE; LJ35; 36UMQY New Destination: BNA; Engine out. Aircraft landed at 1759.
1723	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); I90; I90 authorized to suspend change of destination reporting for AOR until 2359 due to WX.
1731	NORDQ; ATSC (FAA HQ DEN); ZJX; DAL1762; B752; LAXJFK; Aircraft reported on course, at assigned
''	altitude. Attempting contact on Guard and with Company. Communications re-established at 1733.
1732	COD; ATSC (FAA HQ DEN); PDT4328; DH8D; CHACLT New Destination: CHA; Mechanical.
1734	84; A. T.B.C. 34; P.
1	
1739	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMP; ZMP authorized to suspend change of destination
	reporting for AOR until 2300 due to weather. Extended to 0359.
1800	ADMIN; ATSC (NCRCC); NCRCC; MX on duty. WCLC at 1815.
1800	ADMIN; ATSC (FAA HO DEN); JV/RV on HQT, JF on HQE/HGW, WCLC.
1800 1809	ADMIN; ATSC (FAA HQ DEN); DR off. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; SWA569; B737; ROCTPA; Female PAX ill.
1812	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); DTW; DTW authorized to suspend change of destination
.5 .2	reporting for AOR until 2359 due to WX.

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/19/2013 0402Z	RS

Log:	
Time (UT	Remarks
1815	ADMIN; ATSC (NCRCC); NCRCC; SH off.
1819	B+; 40 D.W.C. 110 14
1821	80: 40 T.S.C. 11c10
1846	EMERGENCY, COD; ATSC (FAA HQ DEN); ZDC; EGF4083; E145; RICORD New Destination: PIT; Requested immediate descent to 12,000 feet due to rapid decompression. Aircraft landed at 1912.
1853	EMERGENCY, COD; ATSC (FAA HQ DEN); SLC; SKW130J; B190; SLCSAN New Destination: SLC; Smoke in cockpit. Aircraft landed at 1854.
1900	NORDO; ATSC (FAA HQ DEN); ZHU; N115TT; B350; MEIDTS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1902.
1906	EMERGENCY, COD; ATSC (FAA HQ DEN); ZNY; AWI3577; CRJ2; LGAPIT New Destination: HAR; Engine light indicator. Aircraft landed at 1924.
1907	8 (c) (d) (d) (d) (d) (d) (d)
1015	Signer Main. The id
1915 1920	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZME; ZME authorized to suspend change of destination
1921	reporting for AOR until 2359 due to WX. EMERGENCY ,OTHER,PAGED; ATSC (FAA HQ DEN); CLT; VFR aircraft landed in trees. Callsign unknown.
1921	type believed to be SR22. Fire and Rescue on scene. Pilot okay. 2035 HQ DEN called CLT for callsign and type- N76688, C140.
1923	EMERGENCY, COD; ATSC (FAA HQ DEN); ZDV; RSP323; E50P; BISSDL New Destination: IWA; Hydraulic issue affecting brakes. Aircraft landed at 2004.
1926	COD; ATSC (FAA HQ DEN); ZAU; AAL374; MD83; PHXORD New Destination: MSN; Weather.
1930	ADMIN; ATSC (CONR/AOC); CONR combined to NORAD. PM off.
1942	EMERGENCY, NOTIFICATION-LATE; ATSC (FAA HQ DEN); LEX; N157CC; C310; VFRLEX; Nose gear collapsed on landing. Aircraft landed at 1938.
1948	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAU; ZAU, C90 authorized to suspend change of destination reporting for AOR until 2359 due to WX.
1951	ADMIN; ATSC (FAA HQ DEN); RV on HQW.
1956	COD; ATSC (FAA HQ DEN); ZFW; EMD21; BE9L; PWAMLC New Destination: RUE; Company request.
2000	COD; ATSC (FAA HQ DEN); ZME; MDS212; C208; AXVNQA New Destination: AWM; Fuel.
2008	99 (+ 7.8.C. 1101)
2009	Big 19 tonet. List
2034	NORDO; ATSC (FAA HQ DEN); ZKC; ASQ417T; E45X; IAHOMA; Aircraft reported on course, at assigned
2040	altitude. Attempting contact on Guard and with Company. Communications re-established at 2050. EXERCISE EXERCISE EXERCISE CONFERENCES; ATSC (N/NC); ONEC for exercise Amalgam Arrow.
2040	ADMIN; ATSC (N/NC); MT on. Briefed by KN. WCLC.
2047	COD; ATSC (FAA HQ DEN); ZLA; RATS41; K35R; RIVPMD New Destination: RIV; Mechanical issue.
2056	EMERGENCY- MEDICAL; ATSC (NCRCC); PCT; FLG3411; CRJ2; CVGDCA; Sick pax.
2101	SIF; ATSC (FAA HQ DEN); ZME; ABW401; B744; UUEEORD; Route Change around weather; will return to
2115	assigned course when able. COD; ATSC (FAA HQ DEN); ZOA; UAL1074; B739; SFOSAN New Destination: SFO; Crew maximum
2118	allowable hours issue. COD; ATSC (FAA HQ DEN); ZKC; EJM826; F2TH; MEM. MSP New Destination: STC; Company request.
12110	COD, 71130 (1787 119 DEIT), 2110, Editio20, 12111, INCINITION DOSIGNATION, 010, Company request.

Page 5



Element: Created by: Created on: Checked by: BSadler, 04/19/2013 0402Z RS

Log:	
Time (UTC)	Remarks
2141	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAB; AWE338; A319; PHXMMSD New Destination: TUS; PAX medical emergency.
2153	NORDO; ATSC (FAA HQ DEN); ZAU; ASQ4945; CRJ7; DTWOMA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2201.
2159	NORDO; ATSC (FAA HQ DEN); ZLA; GRZLY21; MQ1; ?VCV; HQ DEN observed 7600 squawk 10 NM NE of Santa Barbara at 19,000 ft; contacted ZLA to investigate. ACFT originated in R2508 and is a UAV; pilot contacted ZLA to advise them it has lost its link. ACFT s executing pre-programmed event to return to range complex R2508. ACFT appears to be on course, at assigned altitude. Communications established at 2218; ACFT entered R2508.
2208	COD; ATSC (FAA HQ DEN); ZJX; EJA895; H25B; TPAMKC New Destination; TPA; Equipment problem.
2224	COD; ATSC (FAA HQ DEN); ZMP; FTH444; C650; PWKFNL New Destination: BJC; Company request.
2235	NORDO, MOR, PAGED; ATSC (FAA HQ DEN); ZKC; N690FS; BE55; POFODX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 2305, 0+30 minutes. Communications re-established at 2311. ZKC to file MOR.
2235	EMERGENCY , COD; ATSC (FAA HQ DEN); ZAU; ASQ6186; E45X; DENPIT New Destination: ORD; Smoke in cockpit. Aircraft landed at 2251.
2237	NORDO; ATSC (FAA HQ DEN); ZOA; N9663; BE36; SQLPSP; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2245.
2245	NORDO; ATSC (FAA HQ DEN); ZKC; FDX906; MD11; MEM. SAN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2250.
2300	ADMIN; ATSC (FAA HQ DEN); RV off.
2306	WAIVER-MD3; ATSC (NCRCC); NCRCC; N9234H; C172; BCTVKX; MD3 requirements verified.
2317	COD; ATSC (FAA HQ DEN); ZKC; UAL357; A320; IADSLC New Destination: SEA; Has enough fuel (didn't have to deviate much due to WX).
2321	[84] [49] [6,84]. [114].
2332	NORDO; ATSC (FAA HQ DEN); ZOA; N800MM; SW3; VGTEUG; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2345.
2343	NORDO; ATSC (FAA HQ DEN); ZHU; N715SY; B737; MROCMSP; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2350.
2349	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; UAL1299; B738; SFOEWR; Flight Attendant, no reason given. HQ DEN called UAL to inquire. 2357 UAL called back and said Flight Attendant (male) has sweaty palms and blurred vision. Aircraft landed at 0007.
04/19/2013	onder, painte due plante de la constant de la const
0010	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); MKE; MKE authorized to suspend change of destination reporting for AOR until 0359 due to WX.
0013	WAIVER-REVIEW; ATSC (NCRCC); NCRCC; BSK279; Reviewed and concurred on waiver 2013-GOV-104989.
0023	EQUIPMENT; ATSC (FAA HQ DEN); TSD at position 2 RTS. Position 3 power adaptor OTS, TSD not working.
0043	Total groves
	TOWN NO.
	NEW AND ADDRESS OF THE SECOND
	7 (M) k (v) d)
0110	LASER; ATSC (FAA HQ DEN); HTS; HNET7; R44; VFRVFR; Cockpit was illuminated by red laser from beneath while heading NNE at 2,500 feet 4 miles SE of HTS. No injuries reported.

Page 6



Date: 04/18/2013

Element: Created by: Created on: Checked by: RS

ALL BSadler, 04/19/2013 0402Z RS

_og:			
Time (U	C) Remarks		
0138	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; AAL1115; B752; MIA., LAX New Destination: TPA PAX ill.		
0200	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW.		
0200	EL 10 MEST 114-11		
0214	COD; ATSC (FAA HQ DEN); SBN; FLG3888; CRJ2; DTWMDW New Destination; DTW; WX.		
0215	ADMIN; ATSC (NCRCC); MX off duty.		
0215	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW/NCRCC.		
0215	ADMIN; ATSC (NCRCC); NCRCC combined to HQ DEN.		
0216	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZME/ZID authorized to suspend change of destination		
0210	reporting for AOR until 0359 due to line of thunderstorms.		
0223	COD; ATSC (FAA HQ DEN); ZLA; EJA677; C56X; SAN. LAS New Destination: SBA; Company request.		
224	COD; ATSC (FAA HQ DEN); ZTL; ASQ4912; CRJ2; ATL. LFT New Destination: ATL; Fuel light issue.		
306	COD; ATSC (FAA HQ DEN); ZOA; AMF282; PA31; RNO. SAC New Destination: RNO; Company request.		
0307	LASER; ATSC (FAA HQ DEN); ZBW; JBU488; A320; TPABOS; 0246, 1 mile northeast of BOS, at 3,000 feet heading southwest; ACFT illuminated by a green LASER from beneath. No injuries reported;		
0309	LASER; ATSC (FAA HQ DEN); ZBW; UAL6505; B738; IAHBOS; 0246, 1 mile northeast of BOS, at 3,000 fee heading southwest; ACFT illuminated by a green LASER from beneath. No injuries reported;		
310	LASER; ATSC (FAA HQ DEN); I90; UAL6098; B738; DENIAH; 0250, 13 miles northeast of IAH, at 2,000 feet no heading provided; left side of ACFT illuminated by a green LASER. No injuries reported;		
0312	LASER; ATSC (FAA HQ DEN); I90; SKW5188; CRJ2; OKCIAH; 0250, 13 miles northeast of IAH, at 2,000 fee no heading provided; left side of ACFT illuminated by a green LASER. No injuries reported;		
0314	NORDO; ATSC (FAA HQ DEN); ZMA; DAL47; B763; DTWSBGR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 0328 NORDO 0+15; ACFT is in ZSU airpace about depart NAS on course and altitude. Communications re-established at 0339.		
0317	LASER; ATSC (FAA HQ DEN); ELP; SWA2130; B737; ELPSAT; 0303, 10 miles southeast of ELP, at 10-13,000 feet, heading east; right side of ACFT illuminated by a green LASER. No injuries reported;		
320	LASER; ATSC (FAA HQ DEN); ELP; N9LM; B06; VFRELP; 0255, 7 miles northwest of ELP, at 5,000 feet, heading east; left side of ACFT illuminated by a green LASER. Co-pilot reported eyes hurting;		
0332	OTHER, PAGED; ATSC (FAA HQ DEN); NC4 reported: 7.0 Earthquake, Russia (160 miles ENE of Kuril'sk) in the Pacific Ocean occurred at 0321. No reports of damage or injuries; No tsunami warning or watches issued.		
0338	EMERGENCY, COD; ATSC (FAA HQ DEN); PHL; AWI3789; CRJ2; PHL. DCA New Destination: PHL; Trim issue. Aircraft landed at 0309.		
0359	ADMIN; ATSC (FAA HQ DEN); COB.		

Page 7



Date: 04/19/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 BSadler,
 04/20/2013 0420Z
 RS

Security Event Statistics:

TOI: 3

EMERGENCY: 18

EMERGENCY- MEDICAL:

TOI-US ADIZ: 3

NORDO: 16

LASER: 7

Log:	.og:		
Time (UTC)	Remarks		
04/19/2013			
0400	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW/NCRCC; WCLC. CFPL: ZBW 3/2491 TFR 91.137(a)(2) for BOS; ZFW 3/2837 TFR 91.137(a)(1) for ACT; HQ DEN 3 ETMS OTS; TSD RTS 2342.		
0400	ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC.		
0407	LASER; ATSC (FAA HQ DEN); DAB; N4653L; C152; VFREVB; 0338, 3 miles northwest of EVB, at 3,500, heading south; cockpit illuminated by a green LASER from ahead. No injuries reported;		
0413	OTHER; ATSC (FAA HQ DEN); RE: Earthquake reported by NC4 in Russia, intensity change to 7.2 and location has been updated to 155 miles ENE of Kuril'ski; no other changes.		
0424	COD; ATSC (FAA HQ DEN); ZBW; GJS6253; CRJ7; LGABTV New Destination: ALB; Wind.		
0425	COD; ATSC (FAA HQ DEN); ZBW; JBU128; E190; JFKBTV New Destination: BOS; Wind.		
0427	COD; ATSC (FAA HQ DEN); ZBW; ASQ5720; CRJ2; IADBTV New Destination: BOS; Wind.		
0428	COD; ATSC (FAA HQ DEN); ZDV; FDX1385; B752; CPR. AFW New Destination: ICT; Company request.		
0428	COD; ATSC (FAA HQ DEN); BTV; AWE1714; E190; PHLBTV New Destination: ALB; Wind.		
0445	NORDO; ATSC (FAA HQ DEN); ZMP; ASA23; B739; ORDSEA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0448.		
0501	Proceedings (Committee of the Committee		
0519	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZBW; DAL10; B764; ATLEGLL New Destination: BOS; Hydraulic issue. 0618 ZBW advised ACFT holding to burn fuel. Aircraft landed at 0641.		
0524	COD; ATSC (FAA HQ DEN); ZBW; GPD72; PC12; ORDOXC New Destination: BDL; WX.		
0529	COD; ATSC (FAA HQ DEN); ZHU; ASQ4492; E145; IAHBTR New Destination: IAH; Wind.		
0550 0556	ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLC; FFT837A; A320; DENSEA; Sick PAX.		
0601	AIRPORT, PAGED; ATSC (FAA HQ DEN); SFO; 0600 SFO advised of small fire outside terminal 3 at SFO; it caused fire alarms to go off in adjacent terminal and caused terminal to evacuate. CFR is on scene; TSOC advised. 0602 SFO advised fire is contained in a dumpster. CLOSEOUT: 0615 TSOC advised evacuation lasted 3 minutes; terminal repopulating.		
0604	LASER; ATSC (FAA HQ DEN); OAK; JBU91; A320; JFKOAK; 0501, 9 miles east of OAK, at 2,400 feet, heading west; ACFT illuminated by a green LASER. PIC reported slight headache;		
0633	LASER; ATSC (FAA HQ DEN); NCT; QXE189; DH8D; SJCRNO; 0618, 6 miles east of SJC, at 9,000 feet, heading northeast; right side of ACFT illuminated by a green LASER. No injuries reported;		
0637	EMERGENCY; ATSC (FAA HQ DEN); I90; UAL715; A320; LASIAH; Instrument issue. Aircraft landed at XXXX.		

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/20/2013 0420Z	RS

Log:	
Time (UTC	Remarks
0651	7 (4 b) 5 %
	17.101.24.24.
	This charge
0716	COD; ATSC (FAA HQ DEN); ZNY; CPZ5754; E170; JFK. LGA New Destination: BUF; Company request; ACFT
	positioning.
0804	NORDO; ATSC (FAA HQ DEN); ZLA; CFLMK; CL60; BURTEB; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0806.
0952	ADMIN; ATSC (FAA HQ DEN); RV on HQE/HQW; WCLC.
1000	ADMIN; ATSC (FAA HQ DEN); RS off.
1000	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1100: WCLC.
1017	NCR-COORDINATION; ATSC (NCRCC); FBI; FBI coordinated movement about the NCR.
1100	EMERGENCY, PAGED; ATSC (FAA HQ DEN); TSOC; DAL1170; B738; LAXCMH; TSOC advised at 1047
	ACFT skidded off runway 28R at CMH, fire and rescue responding, RY28R closed, PAX being deplaned using
	mobile stairs, injury status unknown at this time, media on scene. 1100 HQ DEN contacting CMH tower for
	details. 1110 CMH tower confirmed they are taking PAX off plane and RY28R is closed; they do not know status
	of injuries of this time; will get on DEN to report as soon as possible. 1113 CMH Tower advised that the ACFT did not actually skid off the runway; landed long, then tried to turn around in the overrun and maneuvered into a
	position the ACFT could not get out of without assistance. No injuries reported.
1110	NORDO; ATSC (FAA HQ DEN); ZOB; EGF4570; E135; DTWLGA; Aircraft reported on course, at assigned
1110	altitude. Attempting contact on Guard and with Company. Communications re-established at 1115.
1129	COD; ATSC (FAA HQ DEN); ZTL; GLF15; G280; SAVIMT New Destination: SAW; Weather.
1130	ADMIN; ATSC (CONR/AOC); PM and BD on.
1138	NORDO; ATSC (FAA HQ DEN); ZAU; N181PC; PAY2; CID. OSH; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications re-
	established at 1140.
1142	ADMIN; ATSC (CONR/AOC); WCLC.
1145	ADMIN; ATSC (FAA HQ DEN); GR on HQE.
1200	ADMIN; ATSC (N/NC); KB on. Briefed by HQ. WCLC.
1213	NORDO; ATSC (FAA HQ DEN); ZAU; EGF2999; E145; GRRDFW; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1221.
1228	COD; ATSC (FAA HQ DEN); K90; KAP33; C402; EWBACK New Destination: EWB; Weather.
1238	
1202	COD; ATSC (FAA HQ DEN); ZMP; SKW124T; CRJ2; MKEDLH New Destination: MSP; Weather.
1303 1312	COD; ATSC (FAA HQ DEN); ZMP; SRW 1241; CRJ2; MRE. DLH New Destination: MSP; Weather. CONFERENCES; ATSC (N/NC); TACOPS conference complete. VIP status, movements and possible
1312	domestic launch and FBI movements discussed.
1313	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMP; ZMP authorized to suspend change of destination
1313	reporting for AOR until 1800 due to weather.
1325	Tepotang for AON until Todo due to weather.
.025	
1345	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOA; DAL1152; B752; HNLSFO; PAX medical emergency.
	, , , , , , , , , , , , , , , , , , , ,

Page 2



Element:	Created by:	Created on:	Checked by:
ALL	BSadler,	04/20/2013 0420Z	RS

Log:	
Time (UTC)	Remarks
1400	ADMIN; ATSC (NCRCC); MX on duty.
1408	NOTAM, VIP; SOSC (FAA HQ); FDC NOTAM 3/3213 published for VIP movement to Wilmington, Delaware from 1304192300-1304200015. Spans = 18,747.
1414	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZAB; AAL1832; B737; LASMIA New Destination: PHX; PAX medical emergency.
1417	COD; ATSC (FAA HQ DEN); ZAU; SCX341; B738; MSPMCO New Destination: MSP; Company request. 1444 ZAU reported aircraft resolved problem, continuing on to original destination.
1428	NORDO; ATSC (FAA HQ DEN); ZMA; LN405GJ; LJ35; PXEMHLM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1431.
1455	EMERGENCY, COD; ATSC (FAA HQ DEN); ZTL; EGF3501; E145; ATLMIA New Destination: CLT; Unspecified mechanical failure. Aircraft landed at 1532.
1500	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful.
1501	CONFERENCES; ATSC (N/NC); ONEC test successful.
1507	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZNY; AWE1071; B752; PHLTJSJ New Destination: PHL; Sick passenger.
1518	NORDO, FAM-ONBRD; ATSC (FAA HQ DEN); ZDC; JBU503; A320; EWRFLL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1522.
1534	EMERGENCY, COD; ATSC (FAA HQ DEN); JAX; JBU611; E190; JFK. TPA New Destination: JAX; Nosegear problem. Aircraft landed at 1528.
1534	EMERGENCY,COD; ATSC (FAA HQ DEN); ZBW; ASH2751; CRJ9; ALBCLT New Destination: ALB; Pressurization problem. Aircraft landed at 1551.
1550	COD; ATSC (FAA HQ DEN); ZAU; EJA947; C750; MCOGYY New Destination: VPZ; Weather.
1556	77 (g. e. 5)() -(5)(g. d. 6)() -(5)(g. d. 6)()
1558	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAN; ZAN authorized to suspend change of destination reporting for AOR until 2200 due to weather.
1609	COD; ATSC (FAA HQ DEN); ZFW; SKW6437; CRJ7; IAHCYYZ New Destination: IAH; Fuel imbalance.
1612	COD; ATSC (FAA HQ DEN); ZBW; EJA397; C680; BED. HPN New Destination: TEB; Company request.
1624	7 (1) 20(4)(2) - 7 (4) (4) (4) - 7 (4) (4) (4) - 7 (4) (4) (4)
1632	COD; ATSC (FAA HQ DEN); ZBW; EJA658; C56X; BOSPWK New Destination: ORD; Fuel stop.
1644	WAIVER-COORDINATION; ATSC (NCRCC); NCRCC; BSK; B734; MUGMADW; Coordinated GOV waivered aircraft landing ADW with PCT OM.
1647	COD; ATSC (FAA HQ DEN); ZTL; XSR605; E50P; MKCAUG New Destination: JZI; PAX request.
1654	EMERGENCY ; ATSC (FAA HQ DEN); ZDV; REDI12; F16; BKFBKF; Engine instrument problem. Aircraft landed at 1717.
1700	ADMIN; ATSC (CONR/AOC); LB on.
1712	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; SWA1795; B738; PHXMDW; Sick passenger.
1728	EMERGENCY,COD; ATSC (FAA HQ DEN); ZMA; ASQ4302; E45X; MIACLE New Destination: MIĀ; High engine temperature. Aircraft landed at 1742.

Page 3



Element: Created by: Created on: Checked by: RS

Log:	
Time (UTC)	Remarks
1753	EMERGENCY,COD; ATSC (FAA HQ DEN); ZDC; AAL1767; MD83; RICDFW New Destination: RIC; Fumes in
	cockpit. Aircraft landed at 1800.
1756	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZTL; DAL28; MD88; MEMATL; Sick passenger.
1800	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1800	ADMIN; ATSC (FAA HQ DEN); JF on HQW. WCLC.
1800	ADMIN; ATSC (NCRCC); NCRCC; \$H off.
1800	ADMIN; ATSC (FAA HO DEN); CW on HQC.
1808 1814	COD; ATSC (FAA HQ DEN); ZFW; EJA657; C56X; HOUF44 New Destination: TYR; Winds. EMERGENCY ; ATSC (FAA HQ DEN); JAX; VVLT621; P3; NIPNIP; Engine out. Aircraft landed at 1816.
1830	ADMIN; ATSC (NCRCC); NCRCC; WCLC.
1833	TOI-US ADIZ, TOI; ATSC (CONR/AOC); EADS; EADS; C402; MYBSFLL; EADS Unknown Ft Lauderdale
1033	(FLL) 121032, 1200 code, heading 286 degrees, indicating 2,300 feet, 167 knots. Appears to have departed South Bimini (MYBS) and heading towards FLL.
1834	EMERGENCY; ATSC (FAA HQ DEN); L30; SKW5467; E120; PSPLAS; Smoke in cockpit. Aircraft landed at
1840	1838. COD: ATSC (FAA HQ DEN); ZID: PRY03; C208; CEU. DAY New Destination; AXV: PAX request.
1847	COD; ATSC (FAA HQ DEN); A80; ASQ5102; CRJ2; ATLMGM New Destination: ATL; Mechanical.
1850	NORDO; ATSC (FAA HQ DEN); ZFW; AAL1629; MD83; DFWSJC; Aircraft reported on course, at assigned
1000	altitude. Attempting contact on Guard and with Company. Communications re-established at 1853.
1851	COD: ATSC (FAA HQ DEN): PHL: EJA615: C56X: FMYPHL New Destination: PNE: Weather.
1857	ATC FACILITY, PAGED; ATSC (FAA HQ DEN); CHS; CHS ATCT on ATC Alert due to radar outage. Facility
	does not have maintenance technicians on duty today, advised TechOps is not staffed on Friday, Saturday and Sunday and they are unable to call in overtime due to the furlough / sequester. Facility on CENRAP plus through the weekend. ATCSCC advised. 1945 HQ DEN called CHS to verify Alert. The facility misidentified itself on the DEN, it was CHA. And CHA is no longer ATC Alert. HQ DEN coordinated with ATCSCC to verify that they had correct information.
1903	COD; ATSC (FAA HQ DEN); A90; EJA700; GALX; ALB. BED New Destination: TTN; Company request.
1906	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZJX; ZJX/ZTL/PHL authorized to suspend change of destination reporting for AOR until 0359 due to weather.
1912	COD: ATSC (FAA HQ DEN); ZID: EGF4346; E145; ORD. CLT New Destination: TYS: Weather.
1918	EMERGENCY: ATSC (FAA HQ DEN): C90; UAL1715; B738; IAHORD; Flaps problem. Aircraft landed at 1943.
1923	EMERGENCY , COD; ATSC (FAA HQ DEN); ZJX; AAY854; MD83; PITSBN New Destination: PIE; Vibration in door. Emergency declared at 1932 with TPA. Aircraft landed at 1939.
1926	
	7 (q. pro c)
1930	ADMIN; ATSC (FAA HQ DEN); GR off; CW on HQE.
1935	Committee Commit
1943	AIRPORT; ATSC (FAA HQ DEN); TSOC; PHL BAW Cargo facility, item alarmed; facility located 1 mile from
	terminal. No evacuations. TSA/LEOs on scene. 2015 Facility was evacuated and EOD responded. EOD
	cleared the facility at 2005; no impact.
2011	COD; ATSC (FAA HQ DEN); ZJX; AMF702Q; SW4; OPFALB New Destination: BED; Company request.
2042	COD; ATSC (FAA HQ DEN); ZNY; AAL404; B752; TISTJFK New Destination: EWR; Unable to continuing holding.
2044	COD; ATSC (FAA HQ DEN); MYR; AWE1058; A319; MBPVCLT New Destination: CHS; Weather.
2045	ADMIN; ATSC (N/NC); N/NC; DH on. Briefed by XS.
2047	COD; ATSC (FAA HQ DEN); ZJX; NUS944; C56X; PWKMIA New Destination: OPF; Company request.

Page 4



Element:	Created by:	Created on: 04/20/2013 0420Z	Checked by:
ALL	BSadler,		RS
	` ·		

Log:	
Time (UTC)	Remarks
2052	COD; ATSC (FAA HQ DEN); ZNY; JBU1015; A320; BOSJFK New Destination: BOS; Unable to continue
	holding.
2113	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZBW; ZBW authorized to suspend change of destination
	reporting for AOR until 0359 due to WX.
2113	COD; ATSC (FAA HQ DEN); ZMP; DAL19; B752; DTWLAX New Destination: MSP; Minor mechanical.
2115	COD; ATSC (FAA HQ DEN); ZHU; PAIN12; BE40; DWHOKC New Destination: END; Mission requirement.
2115	TFR; ATSC (FAA HQ DEN); FDC NOTAM 3/3504 for TFR at New Bedford, MA is in effect. FDC NOTAM
	3/3504 canceled at 2236. HQ DEN coordinated times with K90, ZBW, and PVD- who coordinated with New Bedford (EWB) ATCT.
2123	NORDO; ATSĆ (FAA HQ DEN); ZAB; ASH2827; CRJ2; SAT. PHX; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 2126.
2125	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZNY; ZNY/ZDC authorized to suspend change of
	destination reporting for AOR until 0359 due to weather.
2130	CONFERENCES; ATSC (CONR/AOC); CFACC test successful.
2136	EMERGENCY, OTHER, PAGED; ATSC (FAA HQ DEN); TSOC; N111BK; C210; VKXJGG; TSOC reports that
	N111BK, C210, crashed while on final to JGG. One fatality; no one else on board. Pilot was a retired Air Force
	general, HQ DEN called PHF to ask about crash and they were unaware of it. 2138 HQ DEN called ORF and
2442	aircraft was IFR but canceled when he saw airport (JGG) and did approach VFR. NORDO: ATSC (FAA HQ DEN); A90; FLG3344; CRJ9; BOS. BOS; Aircraft reported on course, at assigned
2142	altitude. Attempting contact on Guard and with Company. Communications re-established at 2143.
2157	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAU; AAL408; MD83; TUSORD; Male PAX passed out.
2158	NORDO; ATSC (FAA HQ DEN); ZAB; SWA756; B737; SANELP; Aircraft reported on course, at assigned
2.30	altitude. Attempting contact on Guard and with Company. Communications re-established at 2159.
2200	ADMIN; ATSC (NCRCC); MX off duty.
2201	COD; ATSC (FAA HQ DEN); SUS; MWT894; AEST; MMLBTA New Destination: MML; Company request.
2220	NOTAM-VIP, TFR, PAGED, VIP; ATSC (CONR/AOC); FDC NOTAM 3/3212 for VIP movement to Wilmington, DE
2225	area cancelled. The Book of the Copy and the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy are cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy area cancelled. The Book of the Copy are cancelled. The Copy are cancelled. The Copy are cancelled. The Copy are cancelled. The Copy are cancelled. The Copy are cancelled. The Copy are cancelled are cancelled. The Copy are cancelled are cancelled a
2225	problem.
2237	COD: ATSC (NCRCC); PCT; FLG3692; CRJ2; DTWRIC New Destination: ROA; Weather.
2245	EQUIPMENT: ATSC (CONR/AOC); CONR called SkyWatch Helpdesk POC. Unable to edit entries.
2254	COD; ATSC (FAA HQ DEN); MDT; ASQ5108; CRJ2; ATLMDT New Destination: ABE; Weather.
2304	EMERGENCY, NOTIFICATION-NONE; ATSC (FAA HQ DEN); SJU; AMF6902; B190; TNCATJSJ; Aircraft
	landed at 2251 after declaring EMERG for gear issue.
2304	EMERGENCY,NOTIFICATION-NONE; ATSC (FAA HQ DEN); SJU; KAP4831; C402; TJSJTKPN New
	Destination: TJSJ; Aircraft landed at 2129 after declaring EMERG for non-specific mechanical issue.
2305	COD; ATSC (FAA HQ DEN); PCT; AWI3746; CRJ2; SDFDCA New Destination: LYH; Weather.
2307	TOI-US ADIZ, TOI; ATSC (N/NC); WADS; 2307 WADS declared a primary track off the Corpus Christi (CRP)
1	112115 heading 335 degrees, 365 knots, as unknown
2200	NORDO ATCO (EAA HO DEN): 70M: ACHOCES: CR IO: CLT. ALIC: Aircraft reported on course of conicad
2308	NORDO; ATSC (FAA HQ DEN); ZFW; ASH2653; CRJ9; CLTAUS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2325.
2310	COD; ATSC (FAA HQ DEN); ZFW; EJA678; C56X; ATLAMA New Destination: OKC; Pressure problem.
2310	ATC FACILITY; ATSC (NCRCC); ADW; ADWT is ATC Zero due to a tornado warning, tower evacuated. 2345:
2324	Normal operations.
2334	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMP; DAL1043; B738; JFKSEA; PAX unconscious.
2344	NORDO; ATSC (FAA HQ DEN); ZOA; N288G; C525; SLCDVO; Aircraft reported on course, at assigned
,	, , , , , , , , , , , , , , , , , , , ,

Page 5



Date: 04/19/2013


Element:	Created by:	Created on: '	Checked by:
ALL	BSadler,	04/20/2013 0420Z	RS

Log:	
Time (UTC)	Remarks
<u> </u>	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2346.
2348	177 (A) (B) Q(A)
	(* 'a 1,15 c)
04/20/2013	
0024	NORDO; ATSC (FAA HQ DEN); ZAB; N924S; F900; FAT. DAL; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0042.
0059	770 a hex(x)
0100	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off.
0100 0117	EMERGENCY, COD; ATSC (FAA HQ DEN); ZAN; VTS980; DC93; ANC., OTZ New Destination; ANC;
0,11	Equipment problem. Aircraft landed at 0208.
0121	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZOB; ZOB authorized to suspend change of destination
	reporting for AOR until 0359 due to WX.
0142	OTHER; ATSC (N/NC); 6.6 earthquake in Southern China. Highest magnitude of 4 consecutive quakes.
0200	Significant damage. ADMIN: ATSC (NCRCC); NCRCC; MK off.
0200	ADMIN; ATSC (NCRCC), NCRCC, MR 611. ADMIN; ATSC (FAA HQ DEN); R\$ on HQE/HQW/NCRCC.
0215	ADMIN; ATSC (NCRCC); NCRCC combined with HQ DEN.
0215	ADMIN; ATSC (FAA HQ DEN); CW off.
0228	COD; ATSC (FAA HQ DEN); ZOB; EJA654P; C56X; MDWPIT New Destination: IAD; Company request.
0235	LASER; ATSC (FAA HQ DEN); M98; SWA2969; B737; DENMSP; 0211, 3 miles north of FCM, at 11,000 feet,
	heading northeast; right side of ACFT illuminated by a green LASER. No injuries reported;
0239	EMERGENCY, COD; ATSC (FAA HQ DEN); ZBW; AAL69; B763; MIA., LFPG New Destination: BOS; Over
0239	water equipment issue. Emergency status due to weight. Aircraft landed at 0310.
0243	COD; ATSC (FAA HQ DEN); ZME; FDX1362; B722; ROAMEM New Destination: SBN; Company request.
0257	LASER; ATSC (FAA HQ DEN); I90; N2201T; P32R; VFRGLS; 0245, over GLS, at 2,400 feet, heading west;
	cockpit illuminated by multiple green LASERs. No injuries reported;
0000	LASER: ATSC (FAA HQ DEN): 190; ASQ3263; CRJ2; IAH. LCH; 0223, over Baytown, TX, at 10,000 feet,
0303	heading east; right side of ACFT illuminated by a green LASER. No injuries reported:
	ricading east, right side of Aof 1 indiminated by a green brocks. No injuries reported,
0307	NORDO; ATSC (FAA HQ DEN); ZNY; UAL1744; B737; IAH. LGA; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 0307.
0324	COD; ATSC (FAA HQ DEN); ZDC; CHQ6119; E145; SDF. LGA New Destination: JFK; Gate issue at LGA.
0330	COD; ATSC (FAA HQ DEN); ZDC; CPZ5812; E170; DFW. LGA New Destination: JFK; Gate issue at LGA.
0336 0337	COD; ATSC (N/NC); N90; SWA2343; B737; BWIISP New Destination: BWI; Windshear and minimum fuel. NORDO; ATSC (N/NC); ZJX; N209EA; EA50; OPFGSO; Aircraft reported on course, at assigned altitude.
0337	Attempting contact on Guard and with Company. No satellite phone available. Communications re-established
	at 0350.
0350	LASER; ATSC (FAA HQ DEN); I90; CGVMP; H25B; CYEG. IAH; 0327, 22 miles north northwest of IAH, at
	6,000 feet, heading southeast; cockpit illuminated by a flashing blue LASER (no bearing provided). No injuries
0250	reported;
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 6

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

FOR OFFICIAL USE ONLY



Page 7

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

THE STATE OF THE S

Date: 04/20/2013

Element:	Created by:	Created on:	Checked by:
ALL	RDavis,	04/21/2013 0445Z	DR

Security Event Statistics:			
EMERGENCY: 14 EMERGENCY- MEDICAL: 9	AIRPORT: 1 DIVERT: 1 NORDO: 22	COD: 27 LASER: 9 MOR: 1	

Log:	
Time (UTC	Remarks
04/20/2013	
0400	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW/NCRCC; WCLC. CFPL: NOTAMs ZBW 3/3268 and ZBW 3/3485 for BOS.
0400	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. CFPL: None.
0403	LASER; ATSC (FAA HQ DEN); TPA; NKS631; A319; DTWTPA; 0346, 10 miles north of TPA, at 3,000 feet, heading south; left side of ACFT illuminated by a red LASER. No injuries reported;
0409	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZNY; ZNY/ZJX/ZBW authorized to suspend change of destination reporting for AOR until 0700 due to widespread line of thunderstorms.
0412	NORDO; ATSC (FAA HQ DEN); NKS126; A319; FLLMYR; 7600 Code observed on short final to MYR; ACFT appears to have landed at 0413. ZJX investigating; MYR airspace combined to ZJX. 0426 ZJX advised ACFT landed at 0413 safely; no issue other than lost communication with ZJX.
0418	LASER; ATSC (FAA HQ DEN); MFE; N819LX; H25B; TEBMFE; 0400, 2 miles northwest of MFE, at 1,000 feet, heading southeast; left front of cockpit illuminated by multiple green LASERs. No injuries reported;
0427	LASER; ATSC (FAA HQ DEN); SAT; ARCARE1; EC35; VFRSAT; 0407, 4 miles northwest of SKF, at 1,200 feet, heading southwest; right side of ACFT illuminated by a green LASER. No injuries reported;
0436	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); NCT; SWA3695; B737; ONTSMF; Injured FA. Aircraft landed at 0445.
0509	LASER; ATSC (FAA HQ DEN); NCT; SWA1367; B737; MDWOAK; 0427, 26 miles east of OAK, at 8,000 feet, heading southwest; right side of ACFT illuminated by a green LASER. No injuries reported; The state of the state o
0525	LASER; ATSC (FAA HQ DEN); MSY; UAL679; B752; ORDMSY; 0450, 7 miles southwest of MSY, at 2,000 feet, heading east southeast; cockpit illuminated by a green LASER from below. No injuries reported;
0545	ADMIN: ATSC (N/NC): N/NC: DH off. Combined to HQ.
0620	EMERGENCY; ATSC (FAA HQ DEN); ZAN; N204JS; BE20; ANCSIT; Landing gear issue. Aircraft landed at 0625.
0621	COD; ATSC (FAA HQ DEN); ZOB; GCT26; GLF4; BGR. LFT New Destination: HOU; PAX request.
0629	NORDO; ATSC (FAA HQ DEN); ZAU; SUB33; B190; CVGOMA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 0644 NORDO 0+15; ZAU advised able to contact SUB OPS who are attempting to contact crew. Communications re-established at 0646.
0746	COD; ATSC (FAA HQ DEN); ZJX; UAL6852; B752; MIAORD New Destination: IAD; Company request; ACFT positioning.
0933	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; NKS972; A320; IWADFW; Sick PAX.
1000	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1100: WCLC.
1000	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE/HQT, WCLC.
1005	LASER; ATSC (FAA HQ DEN); ZID; CHQ3030; E145; SDFCLT; Green laser, from ahead, illuminated cockpit at FL200, 30 miles SW Lexington. ACFT S bound, no injuries reported.

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/20/2013

Element: Created by: Created on: Checked by: DR

Log:	
Time (UTC)	Remarks
1014	89- 44- 0.165- HG (4)
1103	EMERGENCY- MEDICAŁ, COD; ATSC (FAA HQ DEN); ZDC; TRS345; B737; LGAATL New Destination: BWI; Sick PAX.
1106	EMERGENCY- MEDICAL; ATSC (NCRCC); PCT; TRS345; B737; LGAATL New Destination: BWI; Aircraft landed at 1119.
1130	ADMN; ATSC (CONR/AOC); PM on.
1133	ADMIN: ATSC (CONR/AOC); WOLC.
1146	WAIVER-MD3; ATSC (NCRCC); NCRCC; N91PV; CH7A; VFRCGS; MD3 requirements verified. ADAPT did
1140	not have proper remarks and AFSS verified.
4455	
1155	COD; ATSC (FAA HQ DEN); ZNY; HPN5; EA50; OWDTHV New Destination: AVP; Fuel.
1155	The state of the s
1200	ADMIN: ATSC (N/NC); KN on. Briefed by HQ. WCLC.
1218	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZME; DAL941; B752; MCIATL; Sick PAX.
1228	COD; ATSC (FAA HQ DEN); ZMA; EJA306; C680; APFGSO New Destination: HXD; Company request.
1250	COD; ATSC (FAA HQ DEN); ZOB; PAT965; BE20; CON. FTK New Destination: PKB; Fuel.
1253	CONFERENCES; ATSC (N/NC); TACOPS conference complete. VIP status, movements and scheduled domestic launch discussed.
1255	MECHANICAL; ATSC (FAA HQ DEN); ZDC; UAL229; A319; IAD. SAN; Pressurization issue.
1302	COD; ATSC (FAA HQ DEN); ZMP; NDU69; C172; GFKDLH New Destination: GPZ; Training.
1302	COD: ATSC (FAA HQ DEN); ZMA; EJA812; C560; OCFSUA New Destination; PBI; Company request.
1306	NORDO; ATSC (FAA HQ DEN); N90; RSP723; C525; HPNITH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1309.
1306	887 - 43 (C.S. N. 1174)
4000	altitude. Attempting contact on Guard and with Company. Communications re-established at 1322.
1326 1334	COD; ATSC (FAA HQ DEN); ZDV; LYM114; SW4; DEN. RIW New Destination: RWL; Company request.
	To a Mark
1349	EMERGENCY,COD; ATSC (FAA HQ DEN); ORF; FLG4434; CRJ2; ORFBOS New Destination: ORF; Bleed
	air malfunction. Aircraft landed at 1348.
1359	NORDO; ATSC (NCRCC); CMH; N6857W; P28A; I62LOU; NORDO for 5 minutes. Aircraft reported on
	course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-
	established at 1403.
1400	ADMIN; ATSC (NCRCC); UL on duty. At 1415: WCLC.
1410	NORDO, MOR, PAGED; ATSC (FAA HQ DEN); ZME; N4135Q; PA32; TRIOLV; Aircraft reported on course, at
1410	assigned altitude. Attempting contact on Guard. No satellite phone available. 1422 HQ DEN requested update, NORDO. 1440 NORDO 0+30. 1441 ZME stated they never talked with ACFT and will have ZTL check tapes.
	Communications re-established at 1447,
1433	NORDO; ATSC (FAA HQ DEN); ZNY; TRS167; B737; BOSBWI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1435.

Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/20/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RDavis,
 04/21/2013 0445Z
 DR

Log:	
Time (U	TC)Remarks
1435	AIRPORT; ATSC (NCRCC); DCA; DCA tower reports RWY 01 closed due to a blown tire, PCT working on getting another RWY for arrivals. PCT authorized to suspend change of destination reporting for DCA until 1530. 1447; RWY 01 reopened. Two reported diverts, AWI3952 to BWI and, no reportable arrival or departure delays.
1442	DIVERT ; ATSC (FAA HQ DEN); PCT (ORFDCA New Destination: IAD; Disabled ACFT on RY at DCA.
1500	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful.
1501	CONFERENCES; ATSC (N/NC); ONEC test successful.
1508	COD; ATSC (FAA HQ DEN); ZAU; OPT429; BE40; OSU. LNK New Destination: BJC; No fuel stop required.
1515	COD; ATSC (FAA HQ DEN); ZTL; SKQ35; PC12; BHMBUY New Destination: GSO; Burlington, NC closed.
1533	EMERGENCY; ATSC (FAA HQ DEN); ZME; AUSTIN1; T38; GTRGTR; Pressurization issue. Aircraft landed a 1602.
1540	EMERGENCY,COD; ATSC (FAA HQ DEN); PVD; 100 DH8A; EWBBOS New Destination: EWB; Equipment malfunction. Aircraft landed at 1539.
1600	NCR-COORDINATION; ATSC (NCRCC); PCT; N82593, P28R, code 4654, departing FME for FDK escorting N50240, a Bellanca 8KCAB, inoperative transponder, EADS notified.
1600	ADMIN; ATSC (N/NC); XS on, briefed by KN.
1604	NORDO; ATSC (FAA HQ DEN); ZLA; N333UP; AC90; HIO. UDD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1604.
1623	
1624	W for IFP until 1900 due to fatal accident on RY at Bullhead City, AZ (IFP).
1627	WAIVER-REVIEW; ATSC (NCRCC); NCRCC; Reviewed and concurred on waiver 2013-GOV-104822-J.
1632	COD; ATSC (FAA HQ DEN); D10; EGF2904; E135; DFW. CID New Destination: DFW; Baggage door open.
1633	NORDO; ATSC (FAA HQ DEN); MSP; N8291E; C172; FCM. FCM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1642.
1635	NORDO; ATSC (FAA HQ DEN); ZID; [15, 15, 15]; TUPHEF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 1641: Contacted PIC through SAT phone and instructed to contact ZID on 124.57. Communications re-established at 1643.
1645	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZJX; ZJX authorized to suspend change of destination reporting for AOR until 2000 due to WX.
1650	Big an Conn. He m
1655	NORDO; ATSC (FAA HQ DEN); ZFW; AMX686; B737; MMMXORD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. 1656 HQ DEN contacted Company, frequency 124.92. 1702 HQ DEN requested update for ZME, NORDO. 1706 HQ DEN asked FSOC to broadcast over LiT. Communications reestablished at 1707.
1659	COD: ATSC (FAA HQ DEN); RSW; EJA820; C560; HKY. RSW New Destination: APF; WX.
1702	NORDO; ATSC (FAA HQ DEN); FAY; N606JS; PA31; MRHRUQ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1710 HQ DEN called CLT APCH for update
1703	they are checking. Communications re-established at 1712. NORDO; ATSC (FAA HQ DEN); ZDC; LOF3332; E145; IADMDT; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1707.
1724	COD; ATSC (FAA HQ DEN); ZAN; VTS980; DC93; ANCOTZ New Destination: OME; Low visibility.
1734 1741	EMERGENCY, COD; ATSC (FAA HQ DEN); ZDC; AWI3978; CRJ2; DCACLT New Destination: GSO; Cracket windshield. 1747 COD back to CLT. Aircraft landed at 1810.
1800	VIP; ATSC (NCRCC); NCRCC; Market and the second sec
1800	ADMIN; ATSC (FAA HQ DEN); CW on HQE. WCLC.

Page 3



Element:	Created by:	Created on:	Checked by:
ALL	RDavis,	04/21/2013 0445Z	DR

Log:	
Time (UTC)	Remarks
1800	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1800	ADMIN; SOSC (FAA HQ); MS on SOSC1, briefed by TH.
1802	7 and show or
	The Company of the Co
	COD; ATSC (FAA HQ DEN); ZMA; JIA243; CRJ7; CLTMYGF New Destination: MLB; Company misfile.
	ADMIN; ATSC (FAA HQ DEN); JF on HQW. WCLC.
	ADMIN; ATSC (FAA HQ DEN); CU off.
	EMERGENCY ; ATSC (FAA HQ DEN); ZFW; EGF2975; E145; JAN. DFW; Pressurization issue. Aircraft landed at 1818.
	ADMIN; ATSC (NCRCC); NCRCC; WCLC.
	EMERGENCY, NOTIFICATION-LATE; ATSC (FAA HQ DEN); BOS; AAL1456; B752; MIABOS; Flaps. Aircraft landed at 1809.
1839	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZMA; N111NM; PA46; EYWUIN New Destination: TNT; Engine OTS. Aircraft landed at 1902.
1846	NORDO; ATSC (FAA HQ DEN); ZNY; PDT4521; DH8A; PHLUNV; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1851.
1850	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMP; CPZ5691; E170; DFWMSP; Male PAX passed out.
1901	NORDO; ATSC (FAA HQ DEN); ZMA; N85WT; C650; TFFFPBI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1916 NORDO 0+15. Communications reestablished at 1919.
1915	89 SETUSET 131 IN
	Beg on March, 118-15
1919	NORDO; ATSC (FAA HQ DEN); ZSE; AAL493; B738; DFWSEA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1822.
1930	ADMIN; ATSC (CONR/AOC); CONR combined to NORAD. PM off.
1940	NORDO; ATSC (FAA HQ DEN); ZMA; CMP478; B738; MPTOMCO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1945.
1952	NORDO; ATSC (FAA HQ DEN); ZMP; N7485Y; PA31; BTAVFR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1954.
2002	NORDO; ATSC (FAA HQ DEN); ZAB; SKW229P; CRJ2; PHXDRO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2009.
2030	EMERGENCY; ATSC (FAA HQ DEN); ZAB; N787AK; PA18; VFRFFZ; VFR aircraft did emergency landing short of field due to running out of fuel. No injuries reported. Aircraft landed at 2029.
2031	LASER OPERATION; ATSC (NCRCC); NASA; NASA Goddard Space Flight Center conducting laser operations until 0600Z.
2039	NORDO; ATSC (FAA HQ DEN); ZFW; DCM4082; LJ45; FYVBTR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2040.
2049	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZOB; TCF3498; E170; BUFIAD New Destination: BUF; Male PAX having a seizure.
2100	Page 24 (1950 to 1944 a)
	Because that the second
	Bry da Misiro, Duciar

Page 4

FAA Air Traffic NAS Daily Eve			······································		Date: 04/20/2013
Element: ALL	Created by: RDavis,	Created on: 04/21/2013 044	-5Z	Checked by: DR	7,311,5

Log:	
Time (UTC)	Remarks
	3/2 (2 U.F.C. 1() are
2101	NORDO; ATSC (FAA HQ DEN); ZID; ASQ4649; E145; ATLCLE; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2106.
2104	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMA; ZMA authorized to suspend change of destination reporting for AOR until 0000 due to weather/T.
2106	EQUIPMENT, PAGED; ATSC (FAA HQ DEN); HQ DEN ADAPT OTS; no other locations affected. 2125 Outage elevated by Concept Solutions as FTI problem. 2230 ADAPT RTS.
2108	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); MIA; MIA authorized to suspend change of destination
2114	reporting for AOR until 0359 due to WX. MECHANICAL; ATSC (FAA HQ DEN); BNA; SWA2202; B737; BNAMDW; Something was observed flapping on an aircraft believed to be SWA2202; PIC, Dispatch, and facilities along route notified. Aircraft landed at 2141.
2126	NORDO; ATSC (FAA HQ DEN); ZTL; TRS572; B712; MCODTW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2132.
2129	CONFERENCES; ATSC (N/NC); CONR; CFACC conference test successful.
2131	CONFERENCES; ATSC (N/NC); ONEC test successful.
2134	COD; ATSC (FAA HQ DEN); ZLA; OPT854; H25B; PSPSJC New Destination: TUS; Company request.
2145	COD; ATSC (FAA HQ DEN); ZBW; VNR140; P180; PWMAVL New Destination: CHO; Pilot request.
2147	EMERGENCY; ATSC (FAA HQ DEN); ZDV; SWQ2334; B734; SUSDEN; Cracked windshield. Aircraft landed at 2214.
2200	ADMIN: ATSC (NCRCC): UL off duty.
2215	ADMIN: ATSC (N/NC); N/NC; DH on N/NC/CONR. Briefed by XS.
2236	EMERGENCY, COD; ATSC (FAA HQ DEN); C90; SWA2187; B737; CLTMDW New Destination: ORD; Right gear problem. Aircraft landed at 2250.
2246	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAB; SKW5618; CRJ7; AUSABQ; Female PAX with panic
2338	attack. EMERGENCY; ATSC (FAA HQ DEN); ZMA; CWC426; MD11; SCELMIA; Hydraulic failure; will need tow off runway and impact operations, ATCSCC advised. Aircraft landed at 0011. No impact to operations, aircraft taxied off of runway, ATCSCC advised.
04/21/2013	
0013	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; AAL582; B738; DFWFLL; Female PAX ill.
0015	COD; ATSC (FAA HQ DEN); DFW; ASQ2576; CRJ2; DFWHOU New Destination: DFW; Air conditioning problem.
0039	EMERGENCY ; ATSC (FAA HQ DEN); PCT; JBU1152; E190; FLLRIC; Slat indicator light. Aircraft landed at 0042.
0100	88, 49 U.S.M. 111 G
0111	NOTAM, VIP; SOSC (FAA HQ); FDC NOTAM 3/3632 published for VIP movement to Wilmington, DE. from 1304221215-1304221330, 3NMR, SFC-2999 AGL. Spans:18,672.
0134	EMERGENCY, COD; ATSC (FAA HQ DEN); ZBW; AWE734; A332; PHLEGCC New Destination: BOS; Minor mechanical. EMERG declared at 0144 for #2 engine oil pressure. Aircraft landed at 0202.
0141	COD; ATSC (FAA HQ DEN); DEN; SKW735R; CRJ2; DEN. HLN New Destination: DEN; Probe heat issue.

Page 5

FOR OFFICIAL USE ONLY



Date: 04/20/2013

Element:	Created by:	Created on:	Checked by:
ALL	RDavis,	04/21/2013 0445Z	DR

Log:	_og:		
Time (UT	C) Remarks		
0200	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. WCLC.		
0205	ADMIN; ATSC (NCRCC); NCRCC; NCRCC combined with HQ DEN.		
0212	ADMIN; ATSC (FAA HQ DEN); CW off.		
0214	LASER; ATSC (FAA HQ DEN); M98; DAL1712; MD90; TPA. MSP; Heading northeast bound illuminated by		
	green laser in cockpit from right side at 8,000 feet 5 NE MSP. No injuries reported.		
0215	ADMIN; ATSC (NCRCC); NCRCC; MK off.		
0218	COD; ATSC (FAA HQ DEN); ZAB; UAL274; A320; LAXMMMX New Destination: TUS; Mechanical.		
0259	ADMIN; SOSC (FAA HQ); MS off, SOSC closed. MS on call.		
0355	LASER; ATSC (FAA HQ DEN); CHA; N38198; BE55; 7A8. CHA; Cockpit illuminated by a green laser from the		
	left side while westbound at 1,700 feet 4 SE CHA. No injuries reported.		
0356	LASER; ATSC (FAA HQ DEN); LAS; SWA1257; B737; DENLAS; Cockpit illuminated by a green laser from the		
	right side while e bound at 8,000 feet 5NM S LAS. No injuries reported.		
0359	ADMIN; ATSC (FAA HQ DEN); COB.		

Page 6



Date: 04/21/2013

Element: Created by: Created on: Checked by: ALL RDavis, 04/22/2013 0413Z DR

Security Event Statistics:				
34, 45 0,870 11	TOI: 3	AIRPORT: 3	COD: 31	
EMERGENCY: 9	TOI-NCR SFRA: 2	NORDO: 17	LASER: 9	
EMERGENCY- MEDICAL:			MOR: 2	

Log:	
Time (UTC	Remarks
04/21/2013	
0400	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW/NCRCC; WCLC. CFPL: NASA Goddard Space Flight Center conducting laser operations until 0600, (terminated at 0535); NOTAMs ZBW 3/3268 and ZBW 3/3485 for BOS.
0400	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. CFPL: None.
0545	ADMIN; ATSC (N/NC); N/NC; DH off. Combined to HQ.
0554	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); HCF; ASA893; B739; SEAHNL; Passenger medical emergency.
0650	NORDO; ATSC (FAA HQ DEN); ZAB; VRD130; A320; LAXPHL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0654.
0656	ATC FACILITY; ATSC (FAA HQ DEN); MKE; MKE ATC-ALERT due to staffing trigger. CLOSEOUT: ATC-ALERT cancelled at 0847.
0719	LASER; ATSC (FAA HQ DEN); L30; NKS817; A319; DFWLAS; Aircraft illuminated by a green laser left side a 7,000 feet while westbound 20NM east LAS. No injuries reported
0721	LASER; ATSC (FAA HQ DEN); D01; EAGLE1; UH60; VFRDEN; Aircraft illuminated by green laser at 6,500 feet 5NM W/SW DVV. No injuries reported.
0733	LASER; ATSC (FAA HQ DEN); HCF; MKU102; AT72; OGGHNL; ACFT illuminated by a green laser, eastbound, from right side at 1,500 feet 5NM W HNL. No injuries reported.
0735	LASER; ATSC (FAA HQ DEN); N235AM; EC35; VFRVFR; (Event reported by Fort Drumm ATCT). Cockpit illuminated by a green laser from beneath while eastbound at 1,200 feet over Watertown. No injuries reported.
0740	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZOA; WOODN81; DC10; PGUARODN New Destination: PGUA; Low fuel emergency, aircraft associated with SLIP31 flight, Aircraft landed at 0858.
0742	EMERGENCY, COD; ATSC (FAA HQ DEN); ZOA; SLIP31; F18; PGUARODN New Destination: PGUA; Low fuel emergency, aircraft associated with WOODN81 flight, Aircraft landed at 0858.
0807	CONFERENCES; ATSC (FAA HQ DEN); N/NC; NEC for White Sands event, negative impact to the NAS.
0918	De se the view
1000	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC.
1000	ADMIN; ATSC (FAA HQ DEN); DR off.
1000	ADMIN; ATSC (NCRCC); UL on duty. WCLC. De-combined from HQ DEN.
1005	ADMIN; ATSC (FAA HQ DEN); GR on HQW.
1130	ADMIN; ATSC (CONR/AOC); PM on.
1134	ADMIN; ATSC (CONR/AOC); WCLC.

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/21/2013

Element: Created by: Created on: Checked by: ALL RDavis, 04/22/2013 0413Z DR

Log:	
Time (UTC)	Remarks
1200	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Bayflight1 active, low level helicopter on the eastern portion
	of the SFRA. Operations terminated at 2115
1207	COD; ATSC (FAA HQ DEN); A90; AMF707; SW4; BEDCVG New Destination: BED; Company request.
1209	NOTAM,TFR,PAGED; ATSC (FAA HQ DEN); BOS; FDC NOTAM 3/3485 cancelled. All NOTAMs in Boston area associated with security event are cancelled.
1230	ADMIN; ATSC (N/NC); XS on, briefed by GR.
1248	COD; ATSC (FAA HQ DEN); ZFW; EGF2702; E145; DFWLIT New Destination; DFW; Mechanical.
1300	COD; ATSC (FAA HQ DEN); D10; EGF2702; E145; DFW. LIT New Destination: DFW; Oxygen problem.
1306	EMERGENCY- MEDICAL: ATSC (NCRCC): PCT: RPA3228: E170: CHS. DCA: PAX medical.
1314	CONFERENCES, ADMIN; ATSC (N/NC); TACOPS complete including VIP locations, domestic launch, foreign
	launches, and reentry. WCLC.
1326	COD; ATSC (FAA HQ DEN); ZJX; VNR106; P180; SSIATL New Destination: FTY; Company request.
1330	ADMIN; SOSC (FAA HQ); MS on SOSC1, SOSC open.
1339	TOI-NCR SFRA,MOR,PAGED,TOI; ATSC (NCRCC); EADS; N136RW; SR22; CJRJYO; DCA-1: DCA283/29, 1227 Code, heading 010 degrees, indicating 900 feet and 121 knots. Aircraft appears to have departed CJR.
1419	NORDO; ATSC (FAA HQ DEN); ZFW; N324GM; MU2; HSD. SOW; Aircraft reported on course, at assigned
1415	altitude. Attempting contact on Guard, No satellite phone available. Communications re-established at 1427.
1446	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMP; DAL756; B752; MSP., LAS; Sick passenger, 1507 ZMP
1440	
4440	reported passenger has recovered, emergency cancelled.
1449	COD; ATSC (FAA HQ DEN); S56; DAL1857; A320; SLCSEA New Destination: SLC; Mechanical.
1456	NORDO; ATSC (NCRCC); ZDC; LOF3411; E145; STLIAD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company, ADW placed on RWY alert. Communications re-established at 1459, ADW standing down.
1458	
1503	COD; ATSC (FAA HQ DEN); ZHU; ASQ4650; E45X; IAHTUS New Destination: ELP; Mechanical.
	· · · · · · · · · · · · · · · · · · ·
1503	Project (bask)
	. 157 (12 J. 1709
1504	CONFERENCES; ATSC (CONR/AOC); CFACC conference test successful.
1513	CONTENENDED, MICO (CONTENDED, OF MOC CONTENENDE COST SUBSCISSION.
1515	
1313	
1519	NORDO; ATSC (FAA HQ DEN); ZSE; CES583; A346; ZSPDLAX; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1521.
1520	NORDO; ATSC (FAA HQ DEN); ZJX; N2114P; PA23; OCF. HKY; VFR Aircraft reported off course, descending
1320	towards 138 (1747) and 1747 (1747) towards 138 (174
	approximately 7 miles SW Hatch, 900 feet, 86 knots.
4500	
1536	NORDO; ATSC (FAA HQ DEN); ACT; N9847R; BE35; DUCSGR; Aircraft reported on course, at assigned
l. -	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1549.
1549	SIF; ATSC (FAA HQ DEN); ZJX; AFL154; A332; UUEEMMUN; Command center issued route for WX.
1551	NORDO; ATSC (FAA HQ DEN); ZDC; N21PD; PA46; MYR4G4; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1601 HQ DEN asked for update, NORDO. Communications re-established at 1612.
1005	
1605	75 (4. (b) 6-(c)

Page 2



Date: 04/21/2013

Element: ALL Created by: RDavis, Created on: 04/22/2013 0413Z

Checked by: DR

Log:	
Time (UTC)	Remarks
	O what
1623	NOTAM, VIP; SOSC (FAA HQ); FDC NOTAM 3/3688 published for VIP movement to New York, NY. from 1304231645-1304240230, 1 NMR/3 NMR - 3000 FT AGL. Spans:16,484.
1649	NORDO; ATSC (FAA HQ DEN); ZJX; AFR636; B77W; LFPGIAH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1631.
1650	NORDO; ATSC (FAA HQ DEN); ZSE; JAL62; B77W; RJAALAX; Aircraft reported on course, at assigned attitude. Attempting contact on Guard and with Company. Communications re-established at 1652.
1700	COD; ATSC (FAA HQ DEN); ZMP; SKW124T; CRJ2; MKEDLH New Destination: MSP; Company request.
1714	CONFERENCES; ATSC (N/NC); ONEC test successful.
1718 1722	COD; ATSC (FAA HQ DEN); ZMA; NGF1CG; BE58; PIEPNS New Destination: JKA; PAX request. TOI-NCR SFRA,MOR,PAGED,TOI; ATSC (NCRCC); EADS; N6830L; C310; FDKLNS; DCA-2: DCA354/28, 1200 Code, heading 100 degrees, indicating 4,900 feet and 121 knots, Section 100 Aircraft
	appears to have departed FDK.
	84 6 CSC 10 G
	(7) a. 1 a. 5
	8-1-49 (BAC) 1-319-3
	CT CAT TE VICE
	Still Address the or
1746	ADMIN; ATSC (FAA HQ DEN); JF on HQE/HQW. WCLC.
1756	NORDO; ATSC (FAA HQ DEN); PVD; N1455R; C182; MMU. BID; Aircraft reported on course, at assigned
1800	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1800. ADMIN; ATSC (FAA HQ DEN); CW on HQE.
1800	ADMIN; ATSC (FAA HQ DEN); CU off.
1800	ADMIN; ATSC (PAR HQ DEN), CO 011. ADMIN; ATSC (NCRCC); NCRCC; MK on.
1805	ADMIN, A 130 (NORCO), NORCO, MR OII.
1000	
	$(T_{i}, \chi_{i}, Y_{i}, \chi_{i})$
İ	
1808	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZNY; UAE201; A388; OMDB. JFK; PAX in labor.
1815	ADMIN; ATSC (NCRCC); UL off duty
1824	ADMIN; ATSC (NCRCC); NCRCC; WCLC.
1825	COD; ATSC (FAA HQ DEN); ZMP; ASP547; C56X; CYHMCYWG New Destination: CYEG; Fuel stop not
	re
	B42 (4) Th.M.C. (14) (4)
1831	COD; ATSC (FAA HQ DEN); ZNY; BJS442; LJ45; SOP. LEB New Destination: TEB; PAX request.
1838	COD; ATSC (FAA HQ DEN); ZME; MRA1516; C208; TBRDTN New Destination: ADS; Fuel stop not required.
1840	COD; ATSC (FAA HQ DEN); N90; EJA624; C56X; BOSALB New Destination: IOW; Pilot request.
1844	NORDO; ATSC (NCRCC); PCT; SWA218; B737; DENBWI; Aircraft reported on course, at assigned altitude.
1912	Attempting contact on Guard and with Company. Communications re-established at 1845. EMERGENCY ; ATSC (FAA HQ DEN); C90; UAL1727; B752; EWRORD; Flap issue. Aircraft landed at 1922.
1912	NORDO; ATSC (FAA HQ DEN); ZMA; N370TP; C650; PBISAT; Aircraft reported on course, at assigned
1323	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1929.
1930	antitude. Attempting contact on Caulia, 140 setomic priorie available. Communications re-established at 1925.
1942	
11342	

Page 3



Date: 04/21/2013

Element: Created by: Created on: Checked by: ALL RDavis, 04/22/2013 0413Z DR

Log:	
Time (∪⁻	C) Remarks
2003	NORDO; ATSC (FAA HQ DEN); ZME; N870SC; BE9L; JKAJBR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2004.
2007 2023	COD; ATSC (FAA HQ DEN); ZLA; EJA627; C56X; IFR-P. LAS New Destination: SBA; Company request.
2020	
2028	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); N90; AAL358; MD82; ORDLGA; Female PAX iII.
2045	COD; ATSC (FAA HQ DEN); ZID; SWG9394; B738; CYQGMUSC New Destination: CYYZ; Maintenance problem.
2059 2100	COD; ATSC (FAA HQ DEN); ZDC; TCF3562; E170; CLTEWR New Destination: ABE; Due to holding at EWR.
2103	COD; ATSC (FAA HQ DEN); ZNY; AWE1972; A321; CLTEWR New Destination: PHL; Holding at EWR.
2104	COD; ATSC (FAA HQ DEN); ZNY; JBU506; A320; FLLEWR New Destination: ACY; Holding at EWR.
2104	COD; ATSC (FAA HQ DEN); ZMP; GLA195; B190; MSPIWD New Destination: MSP; NAVAID outage.
2108	$(\mathcal{T}_{T_{n},D})^{*}(\Phi_{D_{n},C})$
2112	
2118	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZJX; ZJX authorized to suspend change of destination reporting for AOR until 0359 due to WX.
2130	NORDO; ATSC (FAA HQ DEN); ZDC; N999LX; GLF4; TEBATL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2145.
2133	
2134	
2135	
2146	NORDO; ATSC (FAA HQ DEN); SZL; N4358D; PA32; AIZMLE; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2153.
2205	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZSE; ZSE authorized to suspend change of destination reporting for AOR until 0359 due to WX.
2206	76
	Control of the Contro
	(*************************************
2208	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMP; ZMP authorized to suspend change of destination reporting for AOR until 0359 due to WX.
2209	EMERGENCY; ATSC (FAA HQ DEN); ZDV; SKW5241; CRJ2; IAHCOS; Fuel. Aircraft landed at 2214.
2213	COD; ATSC (FAA HQ DEN); ZDV; RPA3866; DH8D; DEN. OKC New Destination: DEN; Minor mechanical.
2217	COD; ATSC (FAA HQ DEN); ZHU; UAL1254; B737; SAT. EWR New Destination: IAH; Minor mechanical.
2218	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZKC; ASQ4154; E45X; IAHMSP New Destination: TUL; PAX with seizure. 2224 Flight continuing on to MSP; physician attending PAX.
2230	COD; ATSC (FAA HQ DEN); P50; AAY188; MD83; IWA. BZN New Destination: IWA; Minor mechanical.
2230 2236	EMERGENCY,COD; ATSC (FAA HQ DEN); ZMA; DLH464; A346; EDDFMCO New Destination: PBI; WX at
	MCO; fuel emergency. Aircraft landed at 2237.

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security. Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	RDavis,	04/22/2013 0413Z	DR

Log:	
Time (UTC	Remarks
2310	EMERGENCY; ATSC (FAA HQ DEN); ZBW; UAL905; B763; LTBAEWR; Lost hydraulics. Aircraft landed at 2335.
2315	NORDO; ATSC (FAA HQ DEN); YNG; N919WA; PA34; FKLLNN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Aircraft entering CLE Approach airspace. Communications re-established at 2322.
2325	SIF; ATSC (FAA HQ DEN); ZOB; CUB173; A320; CYULMUCL; Turned for traffic by ZOB.
2328	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; AAL141; B772; EGLLJFK; PAX ill.
2336	LASER OPERATION; ATSC (NCRCC); NASA; NASA Goddard Space Flight Center commencing laser operations.
2352	WAIVER-MD3; ATSC (NCRCC); NCRCC; N8055W; AA1; GSOVKX; MD3 requirements verified.
2358	EMERGENCY; ATSC (FAA HQ DEN); BOS; JBU1228; E190; RDUBOS; Slat/ mechanical problem. Aircraft landed at 0014.
2358	AIRPORT; ATSC (FAA HQ DEN); VNY; Aircraft went off end of long runway; damage unknown, no injuries. Short runway available but operations impacted. ATCSCC advised. 0036 Runway re-opened; operations normal.
04/22/2013	NAME AND AND AND AND AND AND AND AND AND AND
0010	WAIVER-MD3; ATSC (NCRCC); NCRCC; N62497; C172; RICVKX; MD3 requirements verified.
0041	LASER; ATSC (FAA HQ DEN); PHL; N39NP; F900; ORLTEB; At 0030 cockpit was illuminated from the left by a blue-laser while northeast bound at 13,000', 18W Yardley; no injuries reported;
0047	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); HCF; AWE146; B752; PHXLIH; 42yo male PAX in/out of consciousness; attributed to alcohol.
0056	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZAB; AAL245; B738; DCALAX New Destination: ABQ; Female PAX with stomach issues; physician attending.
0057	COD; ATSC (FAA HQ DEN); ZID; AWE30; A320; LAXPHL New Destination: PIT; Lavatory problem.
0119	NORDO; ATSC (FAA HQ DEN); I90; N565RB; PA44; HYINEW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. FSOC attempting contact over DAS VOR/I90 freq 124.35. Communications re-established at 0124.
0129	COD; ATSC (FAA HQ DEN); OMA; AAL2032; MD83; DFWOMA New Destination: SUX; Weather.
0130	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); OMA; OMA authorized to suspend change of destination reporting for AOR until 0359 due to weather/T.
0200	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. WCLC.
0200	ADMIN; ATSC (NCRCC); NCRCC; MX on duty. WCLC at 0215.
0203	EMERGENCY; ATSC (FAA HQ DEN); C90; N17ND; GLF5; SBAMDW; Nose wheel steering malfunction. Aircraft landed at 0211.
0210	ADMIN; ATSC (FAA HQ DEN); CW off.
0210	
0215	ADMIN; ATSC (NCRCC); NCRCC; MK off.
0227	EMERGENCY , COD, EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; AAL54; B752; ORD. EGCC New Destination: BGR; Passenger medical emergency; aircraft emergency due to overweight landing. Aircraft landed at 0305.
0330	at usus. COD; ATSC (FAA HQ DEN); ZDV; SKW391V; CRJ2; DENCOD New Destination: DEN; Weather.
0230 0255	LASER; ATSC (FAA HQ DEN); \$90; N342OT; C177; VFRVFR; Cockpit illuminated by a green laser from left
0255	side while NW bound at 2,000 feet 13NM SE IAH. No injuries reported.

Page 5



Date: 04/21/2013

Element:	Created by:	Created on:	Checked by:
ALL	RDavis,	04/22/2013 0413Z	DR

Log:	Log:		
Time (UT	Remarks		
0306 0311	COD; ATSC (FAA HQ DEN); ZDV; ACA775; A319; CYULLAX New Destination: LAS; Fuel. LASER; ATSC (FAA HQ DEN); SYR; UCA4832; DH8B; IADSYR; Cockpit illuminated by a green laser from right side while NE bound at 3,500 feet 4NM SW SYR. No injuries reported.		
0314	LASER; ATSC (FAA HQ DEN); MRY; N756WV; C182; VFRVFR; Aircraft illuminated multiple times by a green laser left side at 1,000 feet while SE bound 1.5NM N MRY. No injuries reported.		
0325	LASER; ATSC (FAA HQ DEN); PBI; AAL60; B752; DFWMIA; Aircraft illuminated by a green laser from beneath while southbound at 13,000 feet 2NM N PBI. No injuries reported.		
0331 0341	OTHER; ATSC (NCRCC); NCRCC; WADS assumed air sovereignty of NCR until 0530. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); P50; AWE288; A319; SJCPHX; Passenger medical emergency.		
0359	ADMIN; ATSC (FAA HQ DEN); COB.		

Page 6



Element: Created by: Created on: Checked by: DR

Security Event Statistics:

TOI: 4
TOI-NCR SFRA: 1
TOI-US ADIZ: 2

NORDO: 12
COD: 39
LASER: 13
MOR: 3

Log:	
Time (UTC) Remarks
04/22/2013	
0400	ADMIN; ATSC (N/NC); N/NC; DH on N/NC/CONR. CFPL:None. WCLC.
0400	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. CFPL: None. WCLC.
0400	ADMIN; ATSC (NCRCC); MX on duty. CFPL: NASA Goddard Space Flight Center conducting LASER operations, WADS assumed air sovereignty of NCR until 0530. WCLC.
0405	LASER; ATSC (FAA HQ DEN); LAS; WJA1335; B737; LASCYXE; Aircraft was illuminated by a green laser right side at 6,900 feet while westbound 5NM west of LAS. No injuries reported.
0430	LASER; ATSC (FAA HQ DEN); LAS; JBU711; JFK, LAS; Cockpit illuminated by a green laser from right side while westbound at 3,000 feet 4NM E LAS. No injuries reported.
0436	LASER; ATSC (FAA HQ DEN); SAN; UAL1106; B737; EWRSAN; Cockpit illuminated by a green laser from the left side while w bound at 800 feet 1.5 e san diego. No injuries reported.
0441	COD; ATSC (FAA HQ DEN); SCT; ASA505; B738; LAXSEA New Destination: LAX; Pressurization system malfunction.
0500	EQUIPMENT; ATSC (NCRCC); NCRCC; PCT performed successful cold start of RACD.
0504	COD; ATSC (FAA HQ DEN); ZLC; QXE302; DH8D; SEABIL New Destination: GEG; Mechanical.
0515	LASER; ATSC (FAA HQ DEN); P50; N443PA; P28A; VFRVFR; Cockpit illuminated by a green laser from right side while NW bound at 3,500 feet 17NM E PHX. No injuries reported.
0515	LASER; ATSC (FAA HQ DEN); P50; AWE194; A321; MCOPHX; Cockpit illuminated by a green laser from right side while NW bound at 6,000 feet 18NM E PHX. No injuries reported
0515	LASER; ATSC (FAA HQ DEN); P50; SWA134; B737; BWIPHX; Cockpit illuminated by a green laser from left side while SW bound at 7,000 feet 20NM NE PHX. No injuries reported.
0516	LASER; ATSC (FAA HQ DEN); NCT; DAL929; A320; SLCSMF; Aircraft illuminated by a green laser from left side at 7,000 feet, westbound, 7.4NM S. Auburn, CA. No injuries reported.
0534	COD; ATSC (FAA HQ DEN); ZLC; SKW4615; CRJ9; SLCABQ New Destination: SLC; Crosswind component exceeds aircraft limitations.
0545	ADMIN; ATSC (N/NC); N/NC; DH off. Combined to HQ.
0554	NORDO; ATSC (FAA HQ DEN); ZAB; AAL427; MD82; AUSLAX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0557.
0602	COD; ATSC (FAA HQ DEN); ZLA; AWE94; A320; PHXPDX New Destination: PHX; Mechanical.
0740	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); HCF; ASA859; B739; SEAHNL; Passenger medical emergency.
0903	EMERGENCY, COD; ATSC (FAA HQ DEN); ZMP; MAZDA63; F16; BRDFAR New Destination: MSN; Avionics systems malfunction. Aircraft landed at 1042.
1000	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1100: WCLC. RELCAN is OTS. DOD NCRCC says issue being worked by IT. Expect restoration sometime later today.
1000	ADMIN; ATSC (FAA HQ DEN); DR off.
1000	ADMIN; ATSC (FAA HQ DEN); GR on HQE, CU on HQW. WCLC.

Page 1



Date: 04/22/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RDavis,
 04/23/2013 0444Z
 DR

Log:	
Time (UTC)	Remarks
1024	EMERGENCY; ATSC (FAA HQ DEN); ZUA; SLAYR12; B52; UAM. UAM; Number 4 engine shut down. Aircraft
1032	landed at 1057. LASER; ATSC (FAA HQ DEN); S56; Green laser, from the east, illuminated tower cab. No injuries reported.
1130	ADMIN; ATSC (CONR/AOC); PM and BD on.
1130	NCR-COORDINATION; ATSC (NCRCC); DCA; N5744Y begin insect spraying near P-73. 1200: N5744Y spraying activity is terminated.
1143	ADMIN; ATSC (CONR/AOC); WCLC.
1145	80 (10 Model 11) in
1157	WAIVER-MD3; ATSC (NCRCC); NCRCC; N99KE; SR22; ONZVKX; MD3 requirements verified.
1200	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZAU; UAL1212; B738; BWISFO New Destination: ORD; Sick passenger.
1215	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZNY; AWE33; A320; LAXPHL; Sick passenger.
1215	NOTAM-VIP, TFR, PAGED; ATSC (CONR/AOC); FDC NOTAM 3/3632 for VIP movement from Wilmington, DE in effect.
1225	TOI,MOR; ATSC (NCRCC); NCRCC; LJ24; NHKNHK; DCA-1: EADS called out a 1200 code at the DCA148056 speed in excess of 300 kts. NOTAM 1/1155 requires VFR aircraft within 60NM of DCA speed restricted to 230 kts or less.
1230	ADMIN; ATSC (N/NC); XS on, briefed by CU.
1252	34; 75 MS.C. 11446
1308	COD; ATSC (FAA HQ DEN); ZMP; GLA171; B190; PIR. HON New Destination: MSP; Weather.
1311	EMERGENCY; ATSC (FAA HQ DEN); ZHU; EGF3234; E135; MMLO. DFW; Possible blown tire. 1327 request
1318	CFR. Aircraft landed at 1351. NORDO; ATSC (FAA HQ DEN); ZME; N300TW; CL60; MGMOUN; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. Satellite phone available. Communications re-established at 1319.
1321	COD; ATSC (FAA HQ DEN); ZAU; EJA602; C56X; DAY. EGV New Destination: RHI; WX.
1325	COD; ATSC (FAA HQ DEN); WIS202; C310; PIRRAP New Destination: FSD; WX.
1327	COD; ATSC (FAA HQ DEN); ZNY; ASH2632; CRJ2; ABECLT New Destination: ABE; Fuel. NCR-COORDINATION; ATSC (NCRCC); DCA; N5744Y begins insect spraying. Multiple sorties for the day.
1330 1334	EMERGENCY; ATSC (NCRCC), DCA, N37441 begins insect spraying, inditiple sorties for the day.
1344	COD: ATSC (FAA HQ DEN); GLA731; B190; PIRCDR New Destination: DEN; WX.
1356	TOI-US ADIZ, TOI; ATSC (CONR/AOC); EADS; H60; ?PBI; EADS has 2 unknown tracks Fort Lauderdale(FLL) 090030, 5101 and 5103 code, heading 325 degrees, indicating 900 feet, 130 knots.
1400	ADMIN; ATSC (NCRCC); UL on duty. At 1415; WCLC.
1401	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; SWA300; B738; MCOLAS New Destination: LBB; Sick PAX.
1403	COD; ATSC (NCRCC); PCT; AVL60; C182; JYOLNS New Destination: JYO; DCA317036; NON EMRG: Aircraft returning to JYO due to engine surging.
1407	So, de Matri. Lina
1412	COD; ATSC (FAA HQ DEN); ZLA; GLA154; B190; PRCIGM New Destination: PRC; Rough running engine.
1437	EMERGENCY; ATSC (FAA HQ DEN); CHS; LIFTR37; C17; CAECAE; Equipment malfunction. Aircraft landed at 1437.
1438	COD; ATSC (FAA HQ DEN); ZMA; HI915; C550; MDPCILM New Destination: FLL; Company misfiled.

Page 2



Element: Created by: Created on: Checked by: ALL RDavis, 04/23/2013 0444Z DR

Log:	
Time (UTC)	Remarks
1440	TOI-NCR SFRA,MOR,TOI; ATSC (NCRCC); NCRCC; CJRVA42; DCA-2: DCA248029, 1200 Code, heading 113 degrees, indicating 011 feet and 081 knots. Aircraft appears to have departed CJR.
	The section of the se
1446	EMERGENCY, COD; ATSC (FAA HQ DEN); ZBW; JBU241; E190; BOSMCO New Destination: BOS; Mechanical issue, 1521 emergency declared due to loss of hydraulics. ACFT landed 1521.
1455	ATC FACILITY; ATSC (FAA HQ DÉN); ATCSCC; Peoria, IL (PIA) ATC Zero due to loss of land lines and radar services, ZAU assumed airspace, investigation ongoing. 1522 PIA ATCT operating as a VFR only Tower. 1928 NOCC advised AT&T discovered fiber cut; attempting to reroute services.(RS).
1503	NORDO; ATSC (FAA HQ DEN); ZOB; N1130J; BE9L; DTWAPN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1506.
1510	COD; ATSC (FAA HQ DEN); ABI; FSP181; C206; RBDROW New Destination: ELP; WX.
1518	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZOA; QFA7; B744; YSSYDFW New Destination: LAX; Sick PAX.
1526	EMERGENCY , COD; ATSC (FAA HQ DEN); ZFW; SCOUT19; E3TF; TIKVPS New Destination: TIK; Engine out. Aircraft landed at 1614.
1526	173 (A) (B) (B) (B) (B) (B) (B) (B) (B) (B) (B
1532 1538	WAIVER-MD3; ATSC (NCRCC); NCRCC; N316TM; SR22; JYOVKX; MD3 requirements verified.
1545	EMERGENCY; ATSC (FAA HQ DEN); LYH; N340CM; C340; CPK. LYH; Engine out. Aircraft landed at 1542.
1546	COD; ATSC (FAA HQ DEN); ZMP; OPT468; BE40; MEM. HON New Destination: ABR; Company request.
1554 1554	COD; ATSC (FAA HQ DEN); ZMP; GLA287; B190; MSP. FOD New Destination: MSP; WX. MECHANICAL; ATSC (NCRCC); PCT; N88KJ; PA31; HEF. HEF; NON EMRG: Returning to HEF with faulty
1559	alternator. 1601: Aircraft landed without further incident.
1600	R3; (; D.c.C. 224 p)
1602	70 a 16-2-00 37 -
1608	EMERGENCY, COD; ATSC (FAA HQ DEN); MSY; RIVER12; F18; NBGNBG New Destination: MSY; RIVER12 and RIVER12 emergency fuel, diverted to MSY. Aircraft landed at 1601.
1616	EMERGENCY; ATSC (FAA HQ DEN); GSB; GIRTH42; F15; GSBGSB; Engine control malfunction. Aircraft landed at 1618.
1624	EMERGENCY; ATSC (FAA HQ DEN); ZKC; REAPR32; B2; SZLSZL; Hydraulics issue. Aircraft landed at 1652.
1635	NORDO; ATSC (FAA HQ DEN); ZHU; SWA143; B737; DEN. TPA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications reestablished at 1637.

Page 3

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	RDavis,	04/23/2013 0444Z	DR

Log:	
Time (UTC	Remarks
1649	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; TUFF14; B52; BAD. BAD; Crew members having
1651	trouble with decompression. Aircraft landed at 1711.
1001	277 Pt 73.5.00 114 g
1700	ADMIN; ATSC (CONR/AOC); LB on.
1702	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOA; UAL621; A320; EWRSFO; Sick passenger.
1709	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZTL; SKW450Y; CRJ7; IAHIAD New Destination:
	MGM; Sick PAX.
1711	COD; ATSC (FAA HQ DEN); ZAU; ASQ4421; E45X; CLEMSP New Destination: CLE; Heating control issue.
1713	
1722	20/ 48 Mature 10 a
1725	NORDO; ATSC (FAA HQ DEN); ZAB; P4WIN; H25B; OPFLAS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1739 HQ DEN requested update, NORDO. 1741 HQ DEN asked FSOC to broadcast over GUP, frequency 126.92. Communications re-established at 1750.
1727	COD; ATSC (FAA HQ DEN); ZDC; UAL1627; B737; MCOEWR New Destination: SWF; Fuel. 1731 ZDC reported aircraft continuing to EWR.
1727	NORDO; ATSC (FAA HQ DEN); ZAU; RCH2552; C130; HOPLOT; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1730.
1728	NOTAM; ATSC (FAA HQ DEN); FDC NOTAM ZFW 3/3665 91.137(a)(1), 2000/2 for 7 miles W Dallas, TX in effect until further notice. 2307 SOSC advised NOTAM cancelled.
1750	ADMIN; ATSC (N/NC); N/NC; DH on. Briefed by XS.
1800	ADMIN; ATSC (FAA HQ DEN); CU off.
1800	ADMIN; ATSC (NCRCC); VP on duty.
1800	ADMIN; ATSC (NCRCC); NCRCC; SH off.
1800	NORDO, FAM-ONBRD; ATSC (FAA HQ DEN); ZME; AAL616; MD82; DFW. DCA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1810.
1800	ADMIN; ATSC (FAA HQ DEN); RS on HQE/HQW; CW on HQT.
1805	EMERGENCY ; ATSC (FAA HQ DEN); ZBW; JBU401; A900; BOSMSY; ACFT experienced severe turbulence 60 miles southwest of BOS; ACFT made an emergency descent. No injuries/no damage reported. ACFT no
1806	longer emergency status and 1819 and will continue to MSY. COD; ATSC (FAA HQ DEN); N90; ASQ4495; E45X; SAVJFK New Destination: EWR; Company reposition of ACFT.
1808	COD; ATSC (FAA HQ DEN); ZAN; PEN3298; SF34; ANCDUT New Destination: ANC; Mechanical issue.
1815	ADMIN; ATSC (NCRCC); WCLC.
1815	EMERGENCY-MEDICAL; ATSC (NCRCC); PCT; SWA3141; B737; CHSBWI; PAX medical.
1818	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZAB; FANTOM1; F4; DMADMA New Destination: HMN; Engine issue. Aircraft landed at 1842.
1819	ADMIN; ATSC (FAA HQ DEN); WCLC.
1830	EMERGENCY-MEDICAL,COD; ATSC (FAA HQ DEN); ZMA; RPN305; MD83; MIAMSLP New Destination: MIA; ACFT taxied back to gate due to sick PAX.
1832	COD; ATSC (FAA HQ DEN); ZLC; SKW7377; CRJ2; SLCBTM New Destination: HMN; WX.
1843	EMERGENCY , COD; ATSC (FAA HQ DEN); PIT; EJA658; C56X; PITMQS New Destination: PIT; Exterior door issue. Aircraft landed at 1838.
1846	COD; ATSC (FAA HQ DEN); ZMP; OPT305; E55P; ICTSDF New Destination: ICT; Mechanical issue.
1854	COD; ATSC (FAA HQ DEN); M98; EJM880; H25C; MSP, LNK New Destination: MSP; Pressurization issue.
1900	ADMIN; SOSC (FAA HQ); MS on SOSC3, Briefed by TH.

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

	FAA Air Traffic Organization NAS Daily Events Log
Surpil	NAS Daily Events Log

Element: Created by: Created on: Checked by: DR

Log:	
Time (UTC	Remarks
1900 1903	NCR-COORDINATION; ATSC (NCRCC); Military exercise activity within NCR. 1900; KLAXON received. EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDC; JBU241; E190; BOSMCO New Destination: RIC; Sick PAX.
1910 1917	ADMIN; ATSC (FAA HQ DEN); CW on HQE.
1922	NORDO; ATSC (FAA HQ DEN); ZDC; OPT448; BE40; HPNMGM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company.
1925	1926;
1935	
1939	EMERGENCY; ATSC (FAA HQ DEN); ZAU; SWA1555; B737; BWIMDW; Engine issue. Aircraft landed at 2005.
2003	EMERGENCY; ATSC (FAA HQ DEN); ZMA; CHECK64; F18; COFCOF; Fuel. Aircraft landed at 2011.
2103	E7-13 (b)999
	71,90 \$1971
2119	TOI-US ADIZ, TOI; ATSC (CONR/AOC); EADS; N926BB; PA32; VFRFPR; EADS Unknown Ft Pierce (FPR) 108041, 3704 code, heading 286 degrees, indicating 1,800 feet, 136 knots, appears to be heading towards FPR.
2130	CONFERENCES; ATSC (CONR/AOC); CFACC test successful.
2148	ADMIN; ATSC (N/NC); MT on. Briefed by DH. WCLC.
2159	NORDO; ATSC (FAA HQ DEN); ZNY; ASQ6068; E145; IADCYOW; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 2214.
2200	ADMIN; ATSC (NCRCC); UL off duty.
2215 2216	COD; ATSC (FAA HQ DEN); ZMA; UAL1164; B733; EWRFLL New Destination: PBI; Weather. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMA; ZMA authorized to suspend change of destination reporting for AOR until 0200 due to weather/T.
2229	COD; ATSC (FAA HQ DEN); ZAN; łAR802; PC12; ANCILI New Destination: 5NN; Company request.
2303	NORDO,MOR,PAGED; ATSC (FAA HQ DEN); ZAB; N54AP; LJ31; CSMCMA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 2318 NORDO 0+15; ZAB investigating. Attempting contact via air to air on last known frequency. ZAB advised crew sounded normal; ACFT requested higher due to winds; ACFT at FL470. 2331 ZAB advised attempted contact via NBAA desk. 2333 NORDO 0+30; HQ DEN conferred with WDS as to plan if ACFT continues NORDO; assets at RIV; concerns are type ACFT and altitude. Communications re-established at 2338, NORDO 0+35, ZAB will file MOR.
2331	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMP; ZMP authorized to suspend change of destination reporting for AOR until 0359 due to weather.
2338	EMERGENCY , COD; ATSC (FAA HQ DEN); ZMP; AAL461; MD82; MSPDFW New Destination: ORD; Elevator problem. Aircraft landed at 0021.
04/23/201	<u> </u>
0001	3); 48 9.83C. II749;
0009	SIF; ATSC (FAA HQ DEN); ZMP; POT4250; A124; MJKMSP; ACFT entered holding and slight re-route due to WX and delays into MSP.

Page 5


FAA Air Traffic NAS Daily Eve					Date: 04/22/2013
Element:	Created by:	Created on:	–	Checked by:	
ALL	RDavis,	04/23/2013 04	44Z	DR	

Log:	
Time (U	rc)Remarks
0010	MECHANICAL; ATSC (FAA HQ DEN); ZME; SKW5193; CRJ7; CYYZIAH; Minimum fuel.
0015	NORDO; ATSC (FAA HQ DEN); CMH; CTL15; AC50; MGYBKL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. FSOC attempting contact over MFD VORTAC/CMH freg 125.95. Communications re-established at 0020.
0027	EMERGENCY; ATSC (FAA HQ DEN); NCT; CNK769; C680; CYXDSJC; Flight control and navigation issue. Aircraft landed at 0029.
0031	NOTAM; ATSC (FAA HQ DEN); SOSC; FDC NOTAM ZNY 3/3922 91.137(a)(2) 3/3000 TFR for LEO; Longbranch, NJ UFA. 0112 SOSC advised NOTAM cancelled.
0053	LASER; ATSC (FAA HQ DEN); ZSU; SBS4619; SF34; TUPJTJSJ; 0332, 3 miles west of TJSJ, at 1000 feet, heading east; right side of ACFT illuminated by a blue LASER. No injuries reported;
0054	COD; ATSC (FAA HQ DEN); ZTL; PRY08; PC12; LZUBAK New Destination: LZU; Company request.
0055	COD; ATSC (FAA HQ DEN); ZKC; DAL2320; MD90; FLL. MSP New Destination: OMA; Fuel.
0100	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off.
0113	NORDO; ATSC (FAA HQ DEN); ZFW; AWE1767; A321; CLTLAS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0118.
0120	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZNY; DAL332; B738; TJSJJFK; PAX with diabetic complications.
0200	ADMIN; ATSC (NCRCC); VP off duty.
0200	ADMIN; ATSC (NCRCC); MX on duty. WCLC at 0215.
0200	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. WCLC.
0200	ADMIN; ATSC (FAA HQ DEN); CW off.
0200	ADMIN; ATSC (FAA HQ DEN); RS off.
0200	ATC FACILITY, PAGED; ATSC (FAA HQ DEN); JAN; JACKSON APPROACH (JAN) ATC-ZERO due to staffing trigger from 0200-0400, furlough.
0232	LASER; ATSC (FAA HQ DEN); 190; SWA8752; B737; ?HOU; Pilot reported grn laser at 7,000 feet 10 SE HOU. Acft eastbound: laser from right. No injuries reported.
0242	EMERGENCY; ATSC (FAA HQ DEN); SCT; JBU185; A320; JFKSAN; Hydraulic system malfunction. Aircraft landed at 0247.
0245	COD: ATSC (FAA HQ DEN); ZFW; ASQ4315; E45X; IAHMSP New Destination: MCI; Company request.
0258	LASÉR; ATSC (FAA HQ DÉN); C90; NKS124; A319; ?ORD; Cockpit illuminated by grn laser at 7,000 feet 10 SE ORD. Acft NW bound; laser from left. No injuries reported
0259	LASER; ATSC (FAA HQ DEN); D21; FLG3317; CRJ2; ?DTW; was illuminated by a green laser at 8,600 feet
0239	while se bound 28 n detroit metropolitan wayne county arpt. No injuries reported.
0310	LASER; ATSC (FAA HQ DEN); N90; VIR4; A343; EGLLJFK; Pilot reported grn laser at 2,400 feet 5 miles NE JFK. Acft northbound; laser direction not reported. No injuries reported.
0315	77 (a. 5) \$457
7	-7, 113 h, 5 c)
,	The Branch
	(2) (g) (g) (g)

Page 6

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

FOR OFFICIAL USE ONLY



Log:	
Time (UTC	Remarks
0348	ATC FACILITY; ATSC (FAA HQ DEN); MKE; MKE TRACON and ATCT ATC-ALERT due to staffing trigger, furlough from 0430-1100.
0358 0359	ADMIN; SOSC (FAA HQ); MS off, SOSC closed. MS on call. ADMIN: ATSC (FAA HQ DEN); COB.

Page 7

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/23/2013

Element: Created by: Created on: 04/24/2013 04	Checked by: 48Z DR
--	-----------------------

Security Event Statistics:				
EMERGENCY: 10 EMERGENCY- MEDICAL:	TOI: 3 TOI-NCR SFRA: 2 TOI-US ADIZ: 1	AIRPORT: 1 NORDO: 20	COD: 30 LASER: 5 MOR: 3	

Log:	
Time (UTC)	Remarks
04/23/2013	
0400	ADMIN; ATSC (NCRCC); MX on duty. CFPL: NASA Goddard Space Flight Center conducting LASER operations. WCLC.
0400	ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC.
0400	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. CFPL: MKE/JAN ATC-ALERT due to staffing/furlough. WCLC.
0401	EQUIPMENT; ATSC (FAA HQ DEN); EMERGIN Paging system OTS. Help Desk troubleshooting. 1205 EMERGIN in service.
0415	COD; ATSC (FAA HQ DEN); ZOB; UPS9325; B763; SDFCLE New Destination: SDF; Company request.
0426	EMERGENCY ; ATSC (FAA HQ DEN); ZAB; OPUS08; C130; ABQABQ; Inboard starboard engine failure. Aircraft landed at 0440.
0430	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; UAL686; A319; EWRPBI; Passenger medical emergency.
0433	COD; ATSC (FAA HQ DEN); ZME; FDX1311; A306; DEN. MEM New Destination: IAH; Company request.
0500	EQUIPMENT; ATSC (NCRCC); NCRCC; PCT conducted cold start of the RACD.
0509	COD; ATSC (FAA HQ DEN); OKC; ASQ204T; E45X; EWROKC New Destination: TUL; Weather.
0550	ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN.
0745	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZSE; FFT837; A320; DENSEA; Passenger medical
	emergency.
0904	(7 (x) 4) h h (0)
	25 (20 to \$2.00)
0912	NORDO, ATCO (FAA HO DEN): ZEIM: NEASED, CROSS ALIC, IRD, Aircraft constitution of the second of the
0912	NORDO; ATSC (FAA HQ DEN); ZFW; N548EB; SR22; AUSJBR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 0926.
1000	ADMIN; ATSC (NCRCC); MX off duty.
1000	ADMIN: ATSC (FAA HQ DEN); DR off.
1000	ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC.
1000	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1100: WCLC.
1013	ATC FACILITY, PAGED; ATSC (FAA HQ DEN); MKE; MKE cancels ATC Alert due to staffing trigger.
1016	25; 42 U.S.C. 115:1.
1022	EQUIPMENT, PAGED; ATSC (FAA HQ DEN); Lotus Notes appear not to be receiving messages. 1137 Lotus Notes operational.
1105	84) 1-013.0. H4.93
1118	COD; ATSC (FAA HQ DEN); SGF; LOF3372; E145; SGFORD New Destination: SGF; Pressurization issue.
1127	OTHER; ATSC (FAA HQ DEN); TSOC; PDT4179; DH8C; CHOCLT; 30 minute delay, re-screening PAX after an access control violation.

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/23/2013

Element: Created by: Created on: Checked by: ALL RDavis, 04/24/2013 0448Z DR

Log:	
Time (UTC	Remarks
1130	ADMIN; ATSC (CONR/AOC); BD on. 1148 WCLC.
1135	
1137	LASER; ATSC (FAA HQ DEN); C90; AWE1788; A321; CLTORD; At 0439 Green laser, from left side, illuminated ACFT at 7,000 feet, 4 miles W Chicago Midway ARPT. ACFT NW bound, no injuries reported.
1138	LASER; ATSC (FAA HQ DEN); P50; UAL1147; B738; IAH. PHX; At 0457 Green laser, from left side, illuminated ACFT at 8,000 feet, 15 miles E Phoenix Sky Harbor ARPT. ACFT NW bound, no injuries reported.
1138	17 31 British
1138	ATC FACILITY; ATSC (FAA HQ DEN); ATCSCC; FINAL Peoria, IL (PIA) at 0250 AT&T completed the fiber repairs, all affected radar services/land lines were restored and ATC Zero was cancelled.
1139	LASER; ATSC (FAA HQ DEN); SCT; AAL679; MD82; DFWONT; At 0619 Green laser, from right, reported at 10,000 feet, over Riverside. ACFT W bound, no injuries reported.
1200	NORDO; ATSC (FAA HQ DEN); ZKC; FFT297; A319; STLDEN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1214.
1202	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZNY; SWA538; B738; BDLBWI; Sick PAX.
1208	Bar 44 (2.4.1. 11) 45
1209	BAR COUNTRY, AND IN
1230	ADMIN; ATSC (N/NC); XS on, briefed by CU.
1244	CONFERENCES, ADMIN; ATSC (N/NC); TACOPS complete including VIP locations, VIP movement and TFR, domestic launch, foreign launches, Amalgam Arrow exercise, and ATSC team lead TELCON. WCLC.
1300	ADMIN; ATSC (FAA HQ DEN); GR on HQW.
1303 1330	COD; ATSC (FAA HQ DEN); ZAN; AER41; B190; YAKJNU New Destination: KTN; WX. ADMIN: ATSC (NCRCC): UL on duty. At 1345: WCLC.
1340	EMERGENCY; ATSC (FAA HQ DEN); SAT; EURCHRE2; T38; RNDRND; Flap malfunction. Aircraft landed at 1344.
1343	NORDO; ATSC (FAA HQ DEN); ZFW; AWE679; A321; PIT. PHX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1346.
1346	
1349	
1355	Roy All Carette Brown
1356	COD; ATSC (FAA HQ DEN); ZAN; AER145; B190; ANC. ADQ New Destination: ANC; Weather
1357	
1401 1421	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); TPA; SWA793; B737; ALBTPA; Sick passenger. EMERGENCY,COD; ATSC (FAA HQ DEN); ZBW; ASQ4440; E145; EWRCYQB New Destination: EWR; Pressurization issue. Aircraft landed at 1453.
1430	BP: 10 W/CC 114 00
1441	COD; ATSC (FAA HQ DEN); ZDV; LYM169; PA31; DENGLD New Destination: CBK; Weather.
1443	R14 13 0.2.C. 114 23
1449	EMERGENCY.COD: ATSC (FAA HQ DEN): ZID: SKW6531; CRJ7; COS. IAD New Destination: CLE; Unknown
1451	EMERGENO 1, COD, A 13C (FAA FIQ DEN), ZID, 3KW0031, CR37, CO3IAD New Destination: CLE; Unknown

Page 2



Element:	Created by:	Created on:	Checked by:
ALL	RDavis,	04/24/2013 0448Z	DR


Log:	
Time (UTC)	Remarks
1502	impact with windshield. 1458 windshield is cracked. Aircraft landed at 1513. NORDO; ATSC (FAA HQ DEN); ZMP; N23714; BE36; FARMKE; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1508.
	NORDO; ATSC (FAA HQ DEN); JAX; N8331S; P28A; SGJORD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1504.
1515	86 19 C.S.W. 1113E
1516 1522	NORDO; ATSC (FAA HQ DEN); ZDV; SWA842; B737; SANDEN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1520. NORDO; ATSC (FAA HQ DEN); ZHU; N316GC; BE20; SGRSJN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1535 HQ DEN asked ZFW for update,
	checking. Communications re-established at 1538.
1528	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); D21; ASQ4936; CRJ7; RDU. DTW; Sick PAX.
1533 1547	CONFERENCES; ATSC (CONR/AOC); CFACC test successful. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAN; ZAN authorized to suspend change of destination
	reporting for AOR until 2200 due to weather.
1549	CONFERENCES; ATSC (N/NC); ONEC test successful and Amalgam Arrow 13-3 CPX Exercise preamble.
1552	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; AAL663; AT8T; TPADFW; Sick passenger.
1600	90 OF MARK 110 B
1600	50: 00 V.C.C. 1114
1606	COD; ATSC (FAA HQ DEN); GSO; JIA528; CRJ2; CLT. ABE New Destination: CLT; Mechanical.
1615	EXERCISE EXERCISE EXERCISE OTHER; ATSC (N/NC); Amalgam Arrow 13-3 CPX Exercise.
1616	91/2 (27 Modes), 119 (2 81/2 (17 Modes), 119 (2)
1622 1624	NORDO; ATSC (FAA HQ DEN); ZHU; RPN870; B734; ATLHRL; Aircraft reported on course, at assigned
1627	altitude. Attempting contact on Guard and with Company. Communications re-established at 1629. TOI-NCR SFRA ,MOR,TOI; ATSC (NCRCC); EADS; TOI-NCR SFRA,MOR,TOI; ATSC (NCRCC); EADS (GAI). TOI appears to be in pattern at GAI, Tol. (GAI).
	EADS identified a primary target at the DCASS0020 (GAI). TO appears to be in pattern at GAI;
	77 (20 18 (3.74) 37 (3.74) (3.74) (4.74)
	TO the Brooks
1635	NORDO; ATSC (FAA HQ DEN); ZFW; FFT35; A320; ORD. MMPR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. FSS transmitting over VOR for aircraft. 1649 HQ DE asked ZFW for update, checking. Communications re-established at 1650.
1640	CONFERENCES; ATSC (N/NC); ONEC for Amalgam Arrow 13-3 CPX.
1645	NOTAM-VIP, PAGED; ATSC (CONR/AOC); FDC NOTAM 3/3688 for VIP movement to New York, NY. is in effect.
	Ben Weiter (190 m) Ven Gertreten (190 m)
	97; 1040,857; 310,10
	pogram makon tahun
	Bay de Conto. Titley

Page 3

® ₽	AA Air Traffic Organization AS Daily Events Log
------------	--

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RDavis,
 04/24/2013 0448Z
 DR



Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

FAA Air Traffic NAS Daily Eve				Date: 04/23/2013
Element:	Created by:	Created on:	Checked by:	
ALL	RDavis,	04/24/2013 0448Z	DR	

Log:	
Time (UTC)	Remarks
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2043.
2100	rine varib bire
	17 (a) (B) A (B)
	Charles (p. 476)
2109	ADMin; ATSC (N/NC); MT on, Briefed by XS, WCLC.
2114	EMERGENCY-MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; EGF3518; E145; MIA. ATL New Destination: JAX;
2115	Sick PAX.
2115 2130	ADMIN; ATSC (NCRCC); UL off duty. CONFERENCES; ATSC (CONR/AOC); CFACC test successful.
2132	CONFERENCES; ATSC (CONN/ACC); CFACC test successful.
2139	SIF; ATSC (FAA HQ DEN); ZBW; CCA982; B77W; JFK. ZBAA; Vectored off approved route for traffic; will rejoin
2 139	route once traffic is clear.
2141	COD; ATSC (FAA HQ DEN); ZJX; VNR395; P180; SRQDWA New Destination: MSY; Company request.
2143	NORDO; ATSC (FAA HQ DEN); ZJX; VHSBU; LJ60; OCF. GTU; Aircraft reported on course, at assigned
0450	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2155.
2153	NORDO, MOR; ATSC (FAA HQ DEN); E10; HITCH63; C130; PRCL52; Aircraft reported on course, at
	assigned altitude. Attempting contact on Guard. No satellite phone available. ACFT is experiencing known electrical issues. 2209 ZLA advised ACFT is primary only and appears to still have major electrical issues.
	ACFT appears to have laded at L52 at 2232; WADS concurs;
	to designati
2156	OTHER; ATSC (FAA HQ DEN); ZLA; N778JC; C551; MMLP. NYL; ZLA advised remarks section "notify
	customs". HQ DEN contacted AMOC and provided flight information.
2214	NOTAM, VIP; SOSC (FAA HQ); FDC NOTAM 3/4170 & 3/4171 published for VIP movement to Waco, TX. from
2245	1304251815-1304252100, 10/30 NMR SFC-17,999 MSL. Spans:7,779.
2215 2217	COD; ATSC (NCRCC); ZDC; ASQ5690; CRJ2; IADBNA New Destination: IAD; Company request. COD; ATSC (NCRCC); ZKC; ASQ5993; E145; BHMDEN New Destination: ICT; PIC request, Restroom
2217	Issues.
2223	EMERGENCY; ATSC (NCRCC); ZSE; N117SK; DV20; VFRRBG; Partial engine failure. Aircraft landed at
2220	2226.
2230	NORDO ATSC (FAA HQ DEN); ZFW; N730KW; E135; ABIIGM; Aircraft reported on course, at assigned
	altitude. Altempting contact on Guard. No satellite phone available. Communications re-established at 2232.
2238	TOI-US ADIZ, TOI; ATSC (CONR/AOC); EADS; CG1503; Unknown; VFRVFR; EADS Unknown Key West
	(EYW) 122065, code 0031, heading 279 degrees, indicating 2,400 feet, 266 knots, 100 miles and 100 miles are set to the contraction of the contract
	Constitution (a)
	The analysis
2252	NORDO; ATSC (FAA HQ DEN); CVG; N2DQ; BE58; OWBFWQ; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2305.
2254	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZFW; UAL1246; B738; SEAIAH; Sick PAX.
2305	NORDO; ATSC (FAA HQ DEN); CVG; N5424D; AC11; HAOOWB; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2319.
04/24/2013	
0034	NOTAM, VIP; SOSC (FAA HQ); FDC NOTAM 3/4176 published for VIP movement to Flagstaff/Sedona, AZ.

Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



2004

Date: 04/23/2013

Element: Created by: Created on: Checked by: DR

Log:	
Time (UTC)	Remarks
	from 1304261715-1304282230, 3 NMR- 3,000 FT AGL. Spans:7,738.
0041	NORDO; ATSC (FAA HQ DEN); ZMP; N401HF; GLF5; VNYEHRD; Aircraft reported on course, at assigned
0050	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0042.
0052	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); C90; UAL1564; B737; IAHORD; Sick PAX.
0100 0101	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off.
0101	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MIA; JBU15; E190; JFKFLL; Sick PAX. EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZAU; VRD127; A320; PHXLAX New Destination:
0124	ORD; Sick PAX.
0134	LASER; ATSC (FAA HQ DEN); ZOB; AWI3621; CRJ2; CLEPHL; 0056, DJB108017, at 11,000 feet, heading
	east southeast; right side of ACFT illuminated by a red LASER. No injuries reported;
	Print se
0137	COD; ATSC (FAA HQ DEN); ZAN; PEN3294; SF34; NCADUT New Destination: CDB; WX.
0138	COD; ATSC (FAA HQ DEN); ZTL; ASQ5176; CRJ9; ATLHOU New Destination: ATL; Maintenance issue.
0140	COD; ATSC (FAA HQ DEN); ZLA; UPS937; B752; FATONT New Destination: SNA; Company request.
0141	COD; ATSC (NCRCC); ZDV; LYM1647; GCKDEN New Destination: LAA; Cargo pickup.
0145	COD; ATSC (FAA HQ DEN); ZBW; UAL942; B763; ORD. LFPG New Destination: IAD; Minor mechanical issue.
0147	LASER; ATSC (FAA HQ DEN); N90; AWE2143; E190; ?EWR; Cockpit illuminated by a green laser at 3,000
	feet 8 southeast EWR while heading northeast. Laser from left side from the EWR cargo ramp. No injuries
	reported. With the bit
0156	The Control of the Co
	. Tr. 3: (£1960)
0200	ADMIN; ATSC (NCRCC); VP off duty.
0200 0200	ADMIN; ATSC (NCRCC), VP oil daty. ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. WCLC.
0200	ADMIN; ATSC (FAA HQ DEN); BY OIT TIGETIQUE. WOLC.
0200	ADMIN; ATSC (NCRCC); MX on duty. WCLC at 0215,.
0208	NORDO; ATSC (FAA HQ DEN); ZNY; AWE1714; E190; PHLBTV; Aircraft reported on course, at assigned
0200	altitude. Attempting contact on Guard and with Company. Communications re-established at 0209.
0220	COD; ATSC (FAA HQ DEN); ZLA; UP\$9806; B752; PHXSNA New Destination: ONT; Company request.
0232	54 40 9.8.C. 114 e
	5-4-43 TW/W \$100
0258	NORDO; ATSC (FAA HQ DEN); ZTL; SPK1112; BE58; GSOVLD; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established with VLD at 0317.
0302	COD; ATSC (FAA HQ DEN); ZAU; SKW5321; CRJ2; ORDDLH New Destination: ORD; Mechanical.
0316	BB Commission (1) and
1	
00.40	ENERGENCY MEDICAL COD. ATCC (FAA HO DEN); 7NV: AALOO P770; MIA ECUL Nov. Dockinstino, DDA.
0342	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZNY; AAL38; B772; MIAEGLL New Destination: BDA;
0250	Passenger medical emergency. ADMIN: COSC (FAA LIQ): MS off COSC closed, MS on coll.
0358	ADMIN; SOSC (FAA HQ); MS off, SOSC closed. MS on call.
0359	ADMIN; ATSC (FAA HQ DEN); COB.

Page 6



13

FAA Air Traffic Organization NAS Daily Events Log

Date: 04/24/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RDavis,
 04/25/2013 0453Z
 DR

Security Event Statistics:

EMERGENCY: 14 EMERGENCY- MEDICAL:

TOI: 5 TOI-NCR FRZ: 1 TOI-TFR: 4 AIRPORT: 4

COD: 45 LASER: 4

NORDO: 13

MOR: 1

Log: Time (UTC) Remarks 04/24/2013 0400 ADMIN; ATSC (NCRCC); MX on duty. CFPL: NASA Goddard Space Flight Center conducting LASER operations. WCLC. ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC 0400 ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW. CFPL: None. WCLC. 0400 LASER; ATSC (FAA HQ DEN); SCT; UAL560; A320; SFO..SNA; Cockpit illuminated by green laser emanating 0427 from right side of fuselage, altitude 2,500AGL, heading south/southwest. Approximate location was 12NM east/northeast of Los Alamitos. No injuries reported, COD; ATSC (FAA HQ DEN); ZSE; FDX582; A306; PDX..OAK New Destination: SEA; Company request. 0434 LASER; ATSC (FAA HQ DEN); EUG; SKW700V; CRJ2; ?..EUG; Cockpit illuminated by a green laser at 0448 3,500AGL, 7NM southeast EUG while heading north. Laser from left side. No injuries reported. EQUIPMENT; ATSC (NCRCC); NCRCC; PCT conducted a cold start of the RACD. 0500 0550 ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN. 0859 EMERGENCY, COD: ATSC (FAA HQ DEN); ZME: UPS1384; A306; SDF., MEM New Destination; SDF: Flight control system malfunction. Aircraft landed at 0928. COD; ATSC (FAA HQ DEN); ZID; FDX1454; B752; MEM. PVD New Destination: IAD; Mechanical. 0940 COD; ATSC (FAA HQ DEN); ZBW; WIG459A; C208; MHT. EWR New Destination: ALB; Company request. 0944 1000 ADMIN; ATSC (FAA HQ DEN); CU on HQW/HQE, WCLC. ADMIN; ATSC (FAA HQ DEN); DR off. 1000 ADMIN: ATSC (NCRCC); NCRCC; SH on. 1100: WCLC. 1000 COD; ATSC (FAA HQ DEN); ZID; ASQ6108; E45X; SDF..ORD New Destination: IND; Smell something 1024 burning. ACFT landed 1038. 1036 COD; ATSC (FAA HQ DEN); ZAU; EJA606; C56X; MDW..GRR New Destination: MDW; Avionics issue. OTHER; ATSC (NCRCC); USCG; C6040; H60; NGU. ADW; C6040 from Elizabeth City coordinated arriving 1046 ADW and flying in FRZ on helicopter routes. 1048 EMERGENCY, COD; ATSC (FAA HQ DEN); ZMA; AAL675; B752; MIA.. DFW New Destination: RSW; Something burning in cabin. Aircraft landed at 1100. 1048 NCR-COORDINATION; ATSC (NCRCC); NCRCC; VIP movement times coordinated for NCR. NCR-COORDINATION; ATSC (NCRCC); NCRCC; Military exercise commencing in NCR. 1059 1120 EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); N90; DAL1542; B738; SEA..JFK; Sick PAX. 1130 ADMIN: ATSC (CONR/AOC); BD on. WCLC 1142 COD; ATSC (CONR/AOC); CGDBS; PA31; CYKZ..VFR New Destination: CYQG; Wx. 1142 OTHER, MECHANICAL; ATSC (NCRCC); PCT; FLG3399; S223; CVG., DCA; Missed APCH to DCA due to flap 1208 issue. No EMRG declared. 1218: FLG3399 landed DCA without further incident. 1210

Page 1



Element: Created by: Created on: Checked by: ALL RDavis, 04/25/2013 0453Z DR

Log:	
Time (U	C)Remarks
1217	COD; ATSC (NCRCC); PCT; RUGBY19; V22; RIC. BGR New Destination: NYG; DCA281045; 40 feet; COD
1220	due to mechanical issue. OTHER,FFDO-ONBRD; ATSC (FAA HQ DEN); TSOC; AWE1640; A320; CLTEWR; Mechanic left their tools onboard, PAX deplaned, re-screened. 1403 CLOSEOUT: miscommunication, Mechanic had not completed assigned work.
1230	ADMIN; ATSC (N/NC); KN on. Briefed by HQ, WCLC.
1250	CONFERENCES; ATSC (N/NC); TACOPS conference complete. VIP status, movements, ZBW Fly-by, ANR activity and TFR's discussed.
1257	84) 46 P. U.C. 115 U-
1259	
1315	TFR; ATSC (NCRCC); NCRCC; (10 3 10 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	Azalea Drive, Rockville, MD 20850. 1330.
1322	ATC FACILITY; ATSC (FAA HQ DEN); FAY; Pope Field (POB), suspending arrivals due to suspicious package near the airfield. 1330 POB suspending their military departures only. 1544 POB returned to normal ops.
1330	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1333	COD; ATSC (FAA HQ DEN); BNA; AAL1346; B738; DFWBNA New Destination: HSV; WX.
1333	20: 40:00.00. 114:00 Bog (App) (0.00. 114:00
1342	COD; ATSC (FAA HQ DEN); ZAU; IRO8956; C208; IND. MSP New Destination: IND; Company request.
1348	COD; ATSC (FAA HQ DEN); ZTL; EJA728; GALX; TEB. BTR New Destination; RYY; WX.
1353	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZHU; ZHU authorized to suspend change of destination reporting for AOR until 1700 due to WX. 1646 extended until 1900.
1354	EMERGENCY, COD; ATSC (FAA HQ DEN); ZOB; N81TE; BE58; BAXZ98 New Destination: GRR; Pitot/Static system failure. At 1407 PIC cancelled emergency, COD to GRR.
1411	COD; ATSC (FAA HQ DEN); BNA; FDX1559; B752; CHSBNA New Destination: MEM; WX.
1415	\$49 GT THEORY 114 mg
1426	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZHU; AAL1442; B763; DFWMIA New Destination: MSY; Sick PAX.
1433	COD; ATSC (FAA HQ DEN); ZID; EJA830; C560; PTKLUK New Destination: CMH; Company request.
1434	Provide Miller (1997)
1435	Been de Brown of the second
1439	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZHU; SWA2376; B735; MSYHOU; Passenger medical emergency.
1445	NOTĂM-VÍP, TFR, PAGED, VIP; ATSC (CONR/AOC); FDC NOTAM 3/4110 for VIP movement to Boston, MA. is in effect.
	Disc14 7 4 2 4 14 4
	#+3-4+ Matics (14-4)
	Reg 40 Maio, 111 p

Page 2



Element: ALL	Created by: RDavis,	Created on: 04/25/2013 0453Z	Checked by: DR	
-----------------	------------------------	------------------------------	-------------------	--

Log:	
Time (UTC	Remarks
	BFF 45 CBCC, BFF 1:
	\$4, 41, 7, C.C. 114.4
	War Str. N. Str. 11 Cept
1449	NORDO; ATSC (FAA HQ DEN); GSO; N2849S; PA34; PVG0A4; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1454.
1453	ADMIN; ATSC (FAA HQ DEN); RV on HQE, WCLC.
1511	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZTL; CHQ3034; E145; SDFCLT; PAX medical emergency.
1529	Bay 44 Maged, 114.19
1533	Bry as Medica trans
1536	
1539	
1546	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZJX; JBU940; E190; MCOBOS New Destination: JAX; Oil pressure problem. Aircraft landed at 1605
1548	700 de 5.500. 110 d
1551	NCR-COORDINATION; ATSC (NCRCC); NCRCC; Received coordination for a military exercise commencing in the NCR. 1700: Klaxon for the exercise.
1615	NORDO; ATSC (FAA HQ DEN); ZJX; N90AW; BE9L; GADSFB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1622.
1627	EMERGENCY ,COD; ATSC (FAA HQ DEN); OMA; COBRA35; C135; LNKSTJ New Destination: OFF; Gear issue. Aircraft landed at 1627.
1642	EMERGENCY; ATSC (FAA HQ DEN); BUF; BISON87; C130; ADWIAG; Engine failure. Aircraft landed at 1642.
1645 1647	TOI-NCR FRZ,MOR,PAGED,TOI; ATSC (NCRCC); NCRCC H72; JPNDAA; DCA-1, Flight entered the FRZ VFR upon departure from JPN, aircraft continued over DCA and landed DAA, pilot failed to accomplish proper coordination as required by NOTAM 0/8326. Pilot will call DCAT.
1656	Programme
	(7 - a) de (8,0)
1658	COD; ATSC (FAA HQ DEN); ZJX; SWA429; B737; MDW. PHX New Destination: ATL; AC unit problem.
1700	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; AAL1078; B763; ORDMIA; Sick PAX.
1700	ADMIN; ATSC (CONR/AOC); LB on.
1705	WAIVER-MD3; ATSC (NCRCC); NCRCC; N2638J; C150; VFRW32; MD3 requirements verified.
1714	EMERGENCY; ATSC (FAA HQ DEN); ZJX; EGF3588; E145; MYEFMIA; Parking break indication. Aircraft
1717	landed at 1725. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; JBU812; A320; MDPPJFK; Sick PAX. 1718
1734	emergency medical cancelled. EMERGENCY,COD; ATSC (FAA HQ DEN); PHX; DOJ291; MD83; PHXLAS New Destination: PHX; Tail
1751	section overheating indicator. Aircraft landed at 1737. SIF; ATSC (FAA HQ DEN); ZOB; CES587; A346; ZSPDJFK; ZOB advised ACFT was taken off route for
1000	weather and now being put on preferred routing; approved.
1800	ADMIN; ATSC (FAA HQ DEN); RS on HQC.
1800	ADMIN; ATSC (NCRCC); NCRCC; SH off.
1800	ADMIN; ATSC (FAA HQ DEN); RV on HQE/HQW.
1800	ADMIN; ATSC (FAA HQ DEN); CU off.
1800	ADMIN; ATSC (NCRCC); VP on duty.

Page 3

raffic Organization Events Log

Element:	Created by:	Created on:	Checked by:
ALL	RDavis,	04/25/2013 0453Z	DR

Log:	
Time (UTC)	Remarks
1802	NORDO; ATSC (FAA HQ DEN); ZOA; VNR165; P180; LVKLAS; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1805.
1815	ADMIN; ATSC (NCRCC); WCLC.
1818	Const. B. Sono
	Transfer Biggs
4005	EMPORAL ORDER AND ATCO (FAA HO DEN), 710, 114, 264, 4220, DEN, BUIL Now Designation, IND.
1825	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZID; UAL264; A320; DEN. PHL New Destination: IND; PAX medical emergency.
1827	ADMIN; ATSC (FAA HQ DEN); WCLC.
1837	COD; ATSC (FAA HQ DEN); WOLC: COD; ATSC (FAA HQ DEN); ZOB; EJA966; C750; TEBSGR New Destination: MDW; Pilot Request.
1845	NORBO; ATSC (FAA HQ DEN); ZMP; UAL560; A320; EWRDEN; Aircraft reported on course, at assigned
1045	altitude. Attempting contact on Guard and with Company. Communications re-established at 1850; reported by
	ZAU.
1900	ADMIN; ATSC (FAA HQ DEN); RS on HQE.
1909	COD; ATSC (FAA HQ DEN); ZMP; WIS100; C310; EGVOSH New Destination: ATW; Picking up a package.
1911	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; RPA3265; E170; DCAJAX New Destination:
	CHS; Sick PAX.
1916	AIRPORT, PAGED; ATSC (FAA HQ DEN); TSOC; TSOC advised Bellingham, WA Airport (BLI) evacuated due
	to fire alarm activation at 1855Z; ATCSCC advised. 1927 TSCO advised normal operations resumed; alarm
	caused by an air flow issue.
1932	NORDO; ATSC (FAA HQ DEN); ZMA; N770JH; B350; MDPPTMP; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1933.
1954	EMERGENCY; ATSC (FAA HQ DEN); SCT; AAL1517; B738; CYYZLAX; Hydraulic failure. Aircraft landed at
	2003.
1955	EMERGENCY, NORDO; ATSC (FAA HQ DEN); ZAB; N21331; C182; AMASTK; ZAB advised they
	simultaneously lost radar/communications with ACFT and issued an ALNOT last known position TBE VOR
	150040, 2010 ACFT located and communication established, no further action required.
1959	NORDO; ATSC (FAA HQ DEN); A90; RPA3374; E170; DCAMHT; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1959.
2000	ADMIN; ATSC (FAA HQ DEN); RS on HQT; RV on HQE/HQW.
2000	NOTAM,TFR,PAGED,VIP; ATSC (FAA HQ DEN); FDC NOTAM 3/3604 for Bush Library, Dallas, Texas in
	effect.
2009	EMERGENCY, COD, PAGED; ATSC (FAA HQ DEN); ZDC; AAL1769; B763; JFKMIA New Destination: RDU;
	Smoke in the cabin/rear of aircraft. 2015 ZDC advised that crew does not know source of smoke; reported by
	PAX. Aircraft landed at 2028; PIC advised he has some package in cargo area, but not sure if that is
	the source of the smoke. Emergency services responding. 2041
2024	it was not the cause of the smoke; emergency terminated.
2021	Bey 46 N.S.C. 114.43
	- R-) - 14 D-2 14 D-4
2020	NORDO; ATSC (FAA HQ DEN); ZOB; ACA929; A320; FLLCYUL; Aircraft reported on course, at assigned
2039	altitude. Attempting contact on Guard and with Company. Communications re-established at 2041.
2042	ADMIN; ATSC (N/NC); MT on. Briefed by KN. WCLC.
2042	COD; ATSC (N/NC); MT on. Breied by KN. WCLC. COD; ATSC (FAA HQ DEN); ZSE; DAL181; A320; DTW. ZSPD New Destination: SEA; Maintenance problem.
2107	OOD, A 190 (I AA 119 DE11), ZDE, DAE101, A320, D194ZDFD New Destination. SEA, Ividintenance problem.
2111	8:0 / P 7:5: P. 113 I
- ' ' '	25) 48 (0.00) 1144 ·
	8 (y. 42) (1) B. (t. 114 (u.
i	


Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/24/2013

Element: Created by: Created on: Checked by: DR



Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552




Date: 04/24/2013

Element:	Created by:	Created on:	Checked by:
ALL	RDavis,	04/25/2013 0453Z	DR

Log:	
Time (UTC)	Remarks
2342	altitude. Attempting contact on Guard and with Company. Communications re-established at 2351. COD; ATSC (FAA HQ DEN); ZTL; DAL176; B763; ATLEIDW New Destination: ATL; Cabin temperature control issue.
04/25/2013	
0007 0007	COD; ATSC (FAA HQ DEN); ZHU; CTL9; AC50; SGRDAL New Destination: GPM; VIP TFR. TOI-TFR,PAGED,TOI,VIP; ATSC (FAA HQ DEN); Dallas, TX TOI#1: CVE339021, 1200 Code, heading 032 degrees, indicating 800 feet and 56 knots. Aircraft appears to have departed. Hidden Valley Airport
0015	TOI-TFR,PAGED,TOI,VIP; ATSC (FAA HQ DEN); Dallas, TX TOI #2: CVE285016, primary target, circling, indicating 45 knots. Aircraft popped up.
0017	79 (10 pt) (15
0018	TOI-TFR,PAGED,TOI,VIP; ATSC (FAA HQ DEN); Dallas, TX TOI #3: CVE292017, 1200 Code, heading 335 degrees, indicating 1,300 feet and 82 knots. Aircraft popped up in same vicinity Dallas TOI #2 track fade; WADS concurs.
0043	COD; ATSC (FAA HQ DEN); CKB; LBQ791; BE58; RDGHTS New Destination: CKB; Pilot request.
0050	NORDO; ATSC (FAA HQ DEN); ZDC; N453HB; HA4T; NEWTEB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. ADW RY Alert. Communications reestablished at 0056.
0059	LASER; ATSC (FAA HQ DEN); PHL; DAL2394; MD88; ATLPHL; 2309, 10 miles east of PHL, at 3,000 feet, heading north; left side of ACFT illuminated by a green LASER. No injuries reported;
0108	TOI-TFR,PAGED,TOI,VIP; ATSC (FAA HQ DEN); Dallas, TX TOI #4: CVE335023, 1200 Code, heading 179 degrees, indicating 600 feet and 64 knots. Aircraft appears to have departed Hartlee Field (3XS0).
	.71.41 (b) 4361 31. (c) (b) (c) (c)
0118	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZBW; AWI3818; CRJ2; ROCBOS New Destination: ALB; Thrust reverser issue. Aircraft landed at 0128.
0126 0152	COD; ATSC (FAA HQ DEN); N90; UCA852; DH8B; EWRBWI New Destination: EWR; Maintenance issue. NORDO; ATSC (FAA HQ DEN); ZDC; FDX1371; A310; MDTMEM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0200.
0200	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW/HQT, WCLC.
0200	ADMIN; ATSC (FAA HQ DEN); RS off; DR on HQE/HQW/HQT.
0200	ADMIN; ATSC (NCRCC); VP off duty.
0200	ADMIN; ATSC (NCRCC); MX on duty.
0209	LASER; ATSC (FAA HQ DEN); CHS; N170SD; C550; ?CHS; Cockpit illuminated by a green laser at 2,500 feet 6 NNE CHS while heading SE. Laser from right side. No injuries reported.
0222	COD: ATSC (FAA HQ DEN); ZOA; HAL449; A332; HNLRJBB New Destination: HNL; Mechanical.
0233	
0050	OOD ATOO (FAA HO DEN); 7AH, ACCCADA, FAAF, ODD MEM New Destination, ODD, Machanian
0250 0302	COD; ATSC (FAA HQ DEN); ZAU; ASQ6181; E145; ORDMEM New Destination: ORD; Mechanical. NORDO; ATSC (FAA HQ DEN); ZKC; NKS356; A319; LASORD; Aircraft reported on course, at assigned

Page 6

FOR OFFICIAL USE ONLY



Log:		
Time (UTC) Remarks		
	altitude. Attempting contact on Guard and with Company. Communications re-established at 0304.	
0321	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; VIR17; A343; EGLLEWR; Passenger medical emergency.	
0343	WAIVER-REVIEW; ATSC (NCRCC); NCRCC; Reviewed and concurred on waiver 2013-SVY7-104862.	
0359	ADMIN; ATSC (FAA HQ DEN) 201 40 200 414 (10)	
	B4; Gr. M.S.C.	

Page 7

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/25/2013

Element: Created by: Created on: Checked by: CWomack, 04/26/2013 0927Z CW

Security Event Statistics:

TOI: 9
TOI-TFR: 7
TOI-US ADIZ: 1

EMERGENCY- MEDICAL:

12


AIRPORT: 2
DIVERT: 2
LASER: 9
MOR: 4

Log:	
Time (UTC)	Remarks
04/25/2013	
0400	ADMIN; ATSC (NCRCC); MX on duty. CFPL: NASA Goddard Space Flight Center conducting LASER operations. WCLC.
0400	ADMIN; ATSC (FAA HQ DEN); DR on HQE/HQW/HQT. CFPL: FDC NOTAM 3/3591 and 3/3604 in effect for VIP movement to Dallas, TX. WCLC. FDC NOTAM NOTAM 3/3591 terminated at 1830(RS). FDC NOTAM 3/3604 terminated at 0200(RS).
0400	ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC.
0434	EQUIPMENT; ATSC (FAA HQ DEN); DEN EMERGIN and LOTUS Notes unreliable. Help Desk responding. 2146 RTS.
0445	EQUIPMENT; ATSC (NCRCC); PCT; PCT advised QPL facility shutdown until 1000Z.
0514	EMERGENCY ; ATSC (FAA HQ DEN); MEM; FDX1247; DC10; ORDMEM; Hydraulic system malfunction in starboard engine causing hydraulic fluid leakage. Aircraft landed at 0524.
0529	COD; ATSC (FAA HQ DEN); ZLC; FDX1685; A310; SEAIND New Destination: AFW; Company request.
0550	ADMIN; ATSC (N/NC); MT off. Combined with HQ DEN.
0559	COD; ATSC (FAA HQ DEN); ZNY; AAY568; B752; LAS. PDG New Destination: BDL; Weather.
0600	EQUIPMENT; ATSC (NCRCC); NCRCC; PCT conducted cold start of the RACD.
0631	LASER; ATSC (FAA HQ DEN); ZFW; N5321R; PA44; VFRVFR; Aircraft illuminated by green laser, left side, emanating from the TSTC Campus while northbound at 1,500AGL approximately 1NM south of CNW. No
0634	injuries, LASER; ATSC (FAA HQ DEN); CMH; PD557CP; MD52; VFRCMH; Cockpit illuminated by blue laser at 1,500AGL 4NM NW CMH. Acft NW bound; laser direction not reported. No injuries,
0637	LASER; ATSC (FAA HQ DEN); PHL; SWA152; B737; PHX. PHL; Cockpit illuminated by green laser at 4,000MSL 10NM NE PHL. Aircraft SE bound; laser from right. No injuries reported.
1000	ADMIN; ATSC (NCRCC); NCRCC; MK on.
1003	ADMIN; ATSC (NCRCC); NCRCC; WCLC.
1048	EMERGENCY ; ATSC (NCRCC); NCRCC; ASQ5732; CRJ2; CAEIAD; Nose gear problem. Aircraft landed at 1055
1130	ADMIN; ATSC (CONR/AOC); BD and PM on.
1144	ADMIN; ATSC (CONR/AOC); WCLC.
1145	CONR-COORDINATION; ATSC (CONR/AOC); Dallas AP and AAR asset callsigns provided to ZFW.
1200	CONR-COORDINATION; ATSC (CONR/AOC); VIP Waco movement DOD contingency airspace coordination completed with ZFW and ZHU.
1200	ADMIN; ATSC (FAA HQ DEN); JV on HQW/HQE. DR on HQT. WCLC.
1200 1216	TOI-TFR,MOR,PAGED,TOI,VIP; ATSC (FAA HQ DEN); D10; PA32; TKIDRT; Dallas, Texas TOI #1: CVE020/018, 1200 Code, heading 221 degrees, indicating 1,400 feet climbing and 104 knots. Aircraft appears

age 1



Element: Created by: Created on: Checked by: CWomack, 04/26/2013 0927Z CW



Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/25/2013

Element: Created by: Created on: Checked by: CWomack, 04/26/2013 0927Z CW

Log:	
Time (UTC)	Remarks
1603	NORDO; ATSC (FAA HQ DEN); CKB; N4115V; PA31; UNV27K; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1608.
1612	27. 40 B K 40
	7 · (2 · 1) · (2 · 2)
1623	TOI-TFR,PAGED,TOI; ATSC (FAA HQ DEN); VFRVFR; Dallas, Texas TOI #5: CVE322/15.5, primary only, heading 074 degrees, indicating 67 knots. No track of departure airport.
1637	27. 45. 11. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.
1650 1700	COD; ATSC (FAA HQ DEN); ZAB; EJA822; C560; SMOSEZ New Destination: PRC; Company request. ADMIN; ATSC (FAA HQ DEN); RV on HQE/HQW.
1700 1716	ADMIN; ATSC (CONR/AOC); LB on.
1716	8 (4 (4), 9 (5 (4), 11), 11
1736	EMERGENCY ; ATSC (FAA HQ DEN); SHV; SKULL20; B52; BADBAD; Fumes in cockpit. Aircraft landed at 1745.
1749	NORDO; ATSC (FAA HQ DEN); ZMP; N125CH; GLEX; ANCTEB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and other frequencies. Satellite phone available; HQ DEN called but no answer. Communications re-established at 1754.
1800	ADMIN; ATSC (NCRCC); NCRCC; SH on. 1900: WCLC.
1800	ADMIN; ATSC (FAA HQ DEN); RS/RV on HQT. RS on HQE/HQW.
1800	ADMIN; ATSC (NCRCC); NCRCC; MK off.
1810	NORDO; ATSC (FAA HQ DEN); ZHU; UAL740; A320; DENMSY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1811. EMERGENCY,COD; ATSC (FAA HQ DEN); MSY; DAL1392; A319; MSYJFK New Destination: MSY; Hydraulic issue. Aircraft landed at 1809.
1814	COD; ATSC (FAA HQ DEN); MSP; DAL1787; MD90; MSPSAN New Destination: MSP; Pressurization issue.
1815	NOTAM,TFR,PAGED,VIP; ATSC (FAA HQ DEN); FDC NOTAM 3/4179 and 3/4181 AREA A/B for VIP movement to Waco, TX in effect; AREA A/B not in effect due to VIP location. 1824 AREA A/B enforced. 1908 VIP landed at LZ. 1917 VIP at Event Location. 2245 TFR expired; however will continue to protect AREA A/B due to VIP location. 2256 VIP departed event location/LZ. 2305 AREA A/B no longer enforced; airport resumed normal operations. TO 2305 AREA A/B no longer enforced; airport resumed normal operations.
1818	DIVERT, PAGED; ATSC (FAA HQ DEN); ZFW; SWA1279; B733; MCIDAL New Destination: OKC; VIP TFR.
1822	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZNY, ZNY, ZBW, N90, ZDC authorized to suspend COD reported for NY Metro Area until 2200 due to airborne holding; ATSCC advised.
1830	Br 40 D.S.C. 110 C
1841	OTHER; ATSC (NCRCC); WADS; WADS has air sovereignty over NCR. 1854: EADS regains air sovereignty.
1846	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOB; AWE1222; A319; CLT. DTW; Sick PAX.
1848	NORBO; ATSC (FAA HQ DEN); ZAU; N92SL; BE17; OMALOT; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1853.
1850	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZOB; AAL366; MD83; ORDLGA New Destination: ORD; Sick PAX.
1852	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDV; AAL2293; B737; ORDLAX New Destination: DEN: Sick PAX.
1855	NORDO; ATSC (FAA HQ DEN); CGSJH; M20P; BUFIGX; Aircraft squawking 7600, continuing on course, at

Page 3



Element: Created by: Created on: Checked by: CWomack, 04/26/2013 0927Z CW

Log:	
Time (UTC)	Remarks
	assigned altitude. Attempting contact on Guard. No satellite phone available. PCT and ZDC investigating; will
1000	monitor flight, 1859 ACFT returned to normal squawk. Communications re-established at 1901. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; RPA5258; E190; ACYMHT; Sick PAX.
1900 1901	EQUIPMENT: ATSC (NCRCC); PCT; PCT SOC reports MRB ASR RTS.
1905	ADMIN; ATSC (FAA HQ DEN); WCLC.
1926	8) 74 P.S.C. 11 30
1930	ADMIN; ATSC (CONR/AOC); PM off.
1933	COD; ATSC (FAA HQ DEN); ZTL; HGE1; C441; VLDMGW New Destination: HGR; Company request.
1952	NORDO; ATSC (FAA HQ DEN); ZFW; N281V; BE35; PBFTKI; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and other frequencies. No satellite phone available. Communications reestablished at 2000.
1954	EMERGENCY; ATSC (FAA HQ DEN); ZFW; N1188V; PA31; NEW8M1; Rough Engine. Aircraft landed at
1004	2000.
2004	COD; ATSC (FAA HQ DEN); ZOB; ASQ4232; E45X; CLEBTV New Destination: CLE; Lightning strike.
2021	COD; ATSC (FAA HQ DEN); ZBW; UJT962; GLF4; LSZHTEB New Destination: HPN; Fuel. 2025 ACFT
	continuing to TEB.
2022	NORDO; ATSC (FAA HQ DEN); ZMP; UAL850; B772; ZBAAORD; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 2025.
2030	TOI-TFR,MOR,PAGED,TOI,VIP; ATSC (FAA HQ DEN); B350; TKIEDC; Waco, TX TOI #1: ACT095016, 7464 Code, heading 199 degrees, indicating 15,700 feet and 300 knots.
	ACT095016, 7464 Code, heading 199 degrees, indicating 15,700 feet and 300 knots.
2025	EQUIPMENT; ATSC (FAA HQ DEN); ADAPT print function OTS; unable to print TO! ADAPT data for VIP TFR;
2035	IT advised. 2110 IT advised issue believed to be toner supply; new toner on order since February. 0030 IT
al desirable and	advised DEN1 ADAPT printer function appears to be working; DEN2 and DEN3 remain OTS.
2043	We also the second seco
	17. x 21.3×36:
	75 (a) 1. July 1
2046	CONFERENCES; ATSC (N/NC) test successful.
2054	CONFERENCES; ATSC (CONR/AOC) test successful.
2058	EMERGENCY, COD; ATSC (FAA HQ DEN); D01; GLA42E; B190; DENEAR New Destination: DEN; Smoke in
2101	cockpit. Aircraft landed at 2048. NORDO; ATSC (FAA HQ DEN); ZAB; N365CS; B350; SDLCLL; Aircraft reported on course, at assigned
2101	altitude. Attempting contact on Guard. No satellite phone available. 2116 NORDO 0+15; ZAB advised ATCS
İ	gave ACFT wrong frequency. Communications re-established at 2121.
2103	EMERGENCY, COD; ATSC (FAA HQ DEN); ZME; ASQ5149; CRJ2; ATLXNA New Destination: ATL; #2
	Engine OTS. ACFT landed 2128.
2107	Bey (4 1968) 20 1144 if
0400	
2108	39 40 U.S.C. 111.30
2109	Bry to Music. 11. 11
1.00	- MICE AND ACTION
2114	Ear 42 May 2 124 0
	84) 49 J.H.C. 114-49
2114	NORDO; ATSC (FAA HQ DEN); ZJX; SWA3775; B737; PHXFLL; Aircraft reported on course, at assigned

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	CWomack,	04/26/2013 0927Z	CW

Log:	
Time (U	TC) Remarks
2117	altitude. Attempting contact on Guard and with Company. Communications re-established at 2118. COD; ATSC (NCRCC); ZDC; SWA1517; B737; MCOISP New Destination: BWI; ORF283013; FL380; COD due to non EMRG mechanical issue.
2118	ADMIN; ATSC (N/NC); MT on. Briefed by KN. WCLC.
2120	NORDO; ATSC (FAA HQ DEN); ZBW; FLG3812; CRJ2; PVDDTW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 2135 NORDO 0+15; ZBW investigating. Communications re-established at 2139.
2121	Bry de Dustro (bago)
2143	EMERGENCY; ATSC (FAA HQ DEN); M98; SWA320; B737; DENMSP; Possible tire issue. Aircraft landed at 2158.
2149	COD; ATSC (FAA HQ DEN); ZLA; PAT401; BE20; RNONUQ New Destination; SLI; Air work.
2153	COD; ATSC (FAA HQ DEN); ZKC; DAL567; MD90; DENATL New Destination: MCI; Flight control issue.
2157	COD; ATSC (FAA HQ DEN); SBA; IFX74; BE58; CRQSMX New Destination: BFL; Training.
2201	EMERGENCY; ATSC (FAA HQ DEN); ZMP; FFT100; A320; DEN. MSP; Tire issue. Aircraft landed at 2220.
2215	NOTAM,TFR,PAGED,VIP; ATSC (FAA HQ DEN); FDC NOTAM 3/4238 AREA A/B for VIP movement to Dallas, TX in effect; AREA A/B not enforced due to VIP location. 2310 AREA A/B enforced. 2315 AREA A/B expired; will continue to protect A/B due to VIP location.
	.7, .0, 100/-0
2233 2236	COD; ATSC (FAA HQ DEN); ZMP; ASQ4193; E45X; EWRMSP New Destination: GRB; Fuel. TOI-TFR,MOR,PAGED,TOI,VIP; ATSC (FAA HQ DEN); N74PD; C172; VFRILE; Waco, TX TOI#2: ACT071030, Primary Target, heading 224 degrees, altitude unknown, and 114 knots. No departure point
	identifiable.
2244	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLC; AAY446; MD83; LASMOT; Sick FA. Aircraft landed at 2328.
2250	NORDO; ATSC (FAA HQ DEN); ZTL; N327R; B350; PDKJQF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. ZTL advised ATCS provided wrong frequency to ACFT. Communications re-established at 2252.
2312	EMERGENCY; ATSC (FAA HQ DEN); ZSE; FENIX83; F18; NUWNUW; Engine fire light issue. Aircraft landed at 2318.
2325	EMERGENCY , COD; ATSC (FAA HQ DEN); ZBW; DLH423; A346; BOSEDDF New Destination: BOS; Smoke smell in cockpit. Aircraft landed at 0104.
2329	AIRPORT; ATSC (NCRCC); PCT; 2329: FDK runway 23 is closed due to aircraft running off end of runway. Airport is open using runway 30. No injuries reported for incident. Runway 23 being cleaned before reopening. LEO's and not FDK ATCT notified PCT of the incident. 2356 FDK Update: N163ME, C172 ran off end of runway 23 earlier. The runway is now open. No injuries reported.
2331	NORDO; ATSC (FAA HQ DEN); ZME; ASQ5385; CRJ2; DTWIAH; Aircraft reported on course, at assigned attitude. Attempting contact on Guard and with Company. Communications re-established at 2334.
2332	atritude. Attempting contact on Guard and with Company. Communications re-established at 2554.
2333	Bwg 44 Museum 119 m
2336	DIVERT, PAGED; ATSC (FAA HQ DEN); ZFW; SWA44; B735; HOU. DAL New Destination: AUS; VIP running

Page 5



Element: Created by: Created on: Checked by: CWomack, 04/26/2013 0927Z CW

Log:	
Time (UTC)	Remarks
	late, TFR expired.
2338	85 (4) M. C. (1) (4)
2340	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZME; SKW5193; CRJ7; CYYZMEM; Sick PAX.
2345	53) 12 (b.c. 114))
04/26/2013	CONTROL (FALLIC DELL) THE ADDRESS OF STATE OF THE ADDRESS OF STATE OF THE ADDRESS OF STATE OF THE ADDRESS OF TH
0001	COD; ATSC (FAA HQ DEN); ZTL; ASQ5095; CRJ2; ATLGTR New Destination: BHM; Maintenance issue.
0008	NORDO; ATSC (FAA HQ DEN); ZJX; UAL584; A320; MIADEN; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0025.
0010	ADMIN; ATSC (FAA HQ DEN); RV on HQE; RS on HQW.
0010	ADMIN, ATSC (FAA RQ DEN), RV OITTIQE, RS OITTIQW.
0021	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); LGA; DAL1435; MD88; LGA., TPA New Destination:
0023	LGA; Flight attendant medical emergency. ACFT taxied only; taxied back to gate prior to departure.
0028	EMERGENCY, COD; ATSC (FAA HQ DEN); ZOB; FLG3593; CRJ2; DTW., CIU New Destination; DTW; Steering
0020	problem. Aircraft landed at 0040.
0030	NORDO; ATSC (FAA HQ DEN); ZLC; N164S; PC12; BOL.TRM; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. 00:33 requested Flight Service to transmit to
	ACFT on MMM VOR voice and instruct ACFT to contact ZLA frequency 135.25. Communications re-
	established at 0045.
0043	COD; ATSC (FAA HQ DEN); ZOB; ASQ4202; E145; EWRSTL New Destination: CLE; Maintenance issue.
0045	EMERGENCY- MEDICAL, ATSC (FAA HQ DEN), ZOA, ASA828; B738; OGGSMF; PAX medical emergency.
0048	NORDO; ATSC (FAA HQ DEN); ZDV; CNV4745; B737; NTUNFL; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 0056.
0054	99 () J.A.C. 11 18
0050	LASER; ATSC (FAA HQ DEN); ELM; N520LR; H25C; TEB.:ELM; 0015, 13 miles southeast of ELM, at 3,300
0059	feet, heading north; right side of ACFT illuminated by a green LASER. No injuries reported;
	reet, fleading florin, right side of AOT i multimated by a green DAOLN. No injuries reported,
0100	ADMIN; ATSC (FAA HQ DEN); RV off; RS on HQE/HQW.
0100	ADMIN; ATSC (CONR/AOC); CONR combined with NORAD. LB off.
0104	3 (g. 4 ° T.), C. 115 (g.
	80g 40 00 (PC 11) 10
	BG 41 0.8.0. 110 10
	BOOK THE COUNTY TO A TO THE COUNTY TO THE CO
0107	NORDO; ATSC (FAA HQ DEN); ZAN; LN81MR; LJ35; JNU. BRW; Aircraft reported on course, at assigned
2400	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0112.
0109	LASER; ATSC (FAA HQ DEN); ZSU; JBU1736; E190; MDSDTJSJ; 0016, 26 miles west of TJSJ, at 8,000 feet,
	heading east; right side of ACFT illuminated by a green LASER. No injuries reported;
0124	COD; ATSC (FAA HQ DEN); D21; JUS205; DC93; YIPMMMY New Destination: YIP; Maintenance issue.
0134 0134	COD; ATSC (FAA HQ DEN); DAA; AAL410; B738; MIABNA New Destination: MIA; Mechanical issue.
0134	COD; ATSC (FAA HQ DEN); D01; GLA50E; E120; DEN. EAR New Destination: DEN; Maintenance issue.
0149	COD; ATSC (FAA HQ DEN); ZJX; EJA600; C56X; PHF. SAV New Destination: JZI; Company request.
0150	23, 37 (1.3.4. 114) DEN, 23X, 23X, 23X, 24X, 25X, 25X, 25X, 25X, 25X, 25X, 25X, 25
15.55	
0156	NORDO; ATSC (FAA HQ DEN); ZDV; SKW6419; CRJ2; BURDEN; Aircraft reported on course, at assigned

Page 6

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552




Date: 04/25/2013

Element: Created by: Created on: Checked by: CWomack, 04/26/2013 0927Z CW

Log:	
Time (UTC)	Remarks
0200	altitude. Attempting contact on Guard and with Company. Communications re-established at 0202. TFR,PAGED,VIP; ATSC (FAA HQ DEN); FDC NOTAM 3/3604, Dallas, TX
0200	ADMIN: ATSC (FAA HQ DEN); CW on HQE/HQW; RS off, WCLC.
0203	LASER; ATSC (FAA HQ DEN); I90; N8448G; C150; CFDLVJ; At 0144 aircraft was illuminated by a green laser while northwest bound at 1,900', 17W Houston (IAH); no injuries reported
0217	9-2-19-0.8.C. 110-25 8-3-49-0.800. 134-25
0221	COD; ATSC (NCRCC); ZHU; UPS701; B752; MSYSDF New Destination: JAN; COD company request.
0223	NORDO; ATSC (FAA HQ DEN); ZNY; CGTDO; ASTR; PHLCYHM; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0225.
0228	LASER; ATSC (FAA HQ DEN); ZJX; EGF3462; E145; MIACMH; At 0200 aircraft was illuminated twice from the left by a green laser while northbound at FL370, 5S Jacksonville Executive Airport (CRG); both pilots experienced blind spots;
0242	NORDO; ATSC (FAA HQ DEN); ZAN; CPA831; B77W; JFKVHHH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0245.
0245	ADMIN; ATSC (FAA HQ DEN); NCRCC combined with HQ DEN.
0245	ADMIN; ATSC (NCRCC); NCRCC; SH off.
0247	34; 33 (3.11. 11. a)
0248	
0248	TOI; ATSC (FAA HQ DEN); EADS; FDX1630; A306; BWIIND; DCA030022, primary only, westbound, altitude and speed unknown. Aircraft appears to have departed BWI.
0319	NORDO; ATSC (FAA HQ DEN); ZME; BAW196; B772; IADEGLL; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0322.
0325	COD; ATSC (FAA HQ DEN); ZFW; FDX1311; A306; DEN. MEM New Destination: DFW; Company request.
0333	EMERGENCY; ATSC (FAA HQ DEN); EADS; BOLT44; K35R; MCFMCF; 7700 code observed 170E ORL;
	appears to be BOLT44. ZMA did not answer when called on the DEN. 0334 ZMA did not answer when called on the commercial line; ATSC requested ZJX have ZMA come up on the DEN. 0339 ZMA came on DEN; ATSC requested that they check on the EMERG BOLT44. 0342 ZMA advised aircraft has an electrical
1	malfunction and smoke in the cockpit. Aircraft landed at 0426.
0334	LASER; ATSC (FAA HQ DEN); RDU; GJS6264; CRJ7; LGARDU; At 0236 cockpit was illuminated from the left by a green laser while heading northwest bound at 8,000', 15NNE Raleigh-Durham Airport (RDU); no injuries
	reported;
0335	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZSE; ASA33; B739; PHL. SEA; Male PAX unresponsive.
0335	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZSE; ASA585; B737; SNAPDX; Non-specific PAX medical.
0335	OTHER,PAGED; ATSC (FAA HQ DEN); Neither ZAU or ZMA would answer when called on the DEN. ATSC
	attempted to call them on commercial line, again, neither facility answered. HQ DEN ATSC requested adjacent
1	ARTCCs contact them to come up on the DEN.

Page 7

FOR OFFICIAL USE ONLY



Log: Time (UTC) Remarks	
0343	NORDO; ATSC (FAA HQ DEN); ZAN; CPA807; B77W; ORD. VHHH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0248.
0343	altitude. Attempting contact on Guard and with Company. Communications re-established at 0248. ADMIN; ATSC (FAA HQ DEN); COB.

Page 8

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

FAA Air Tra NAS Daily E	ffic Organization vents Log		Date: 04/26/2013
Element:	Created by: CWomack,	Created on: 04/27/2013 0415Z	Checked by: CW
Security Event Statistic	rol: 2	AIRPORT: 1	34 1 2 3 5 2 114 (9)

NORDO: 23

COD: 31 LASER: 9

TOI-US ADIZ: 2

EMERGENCY: 13

EMERGENCY- MEDICAL:

Log: Time (UTC) Remarks 04/26/2013 0400 ADMIN; ATSC (FAA HQ DEN); CW on HQE/HQW/NCRCC. CFPL: NASA Goddard Space Flight Center conducting LASER operations; ADAPT print function OTS, 1830 RTS (RS); I 0400 ADMIN; ATSC (N/NC); MT on. CFPL: None. WCLC. COD; ATSC (FAA HQ DEN); CHS; ASH2716; CRJ9; CLT. CHS New Destination: CLT; Weather. 0423 0424 COD; ATSC (FAA HQ DEN); CHS; DAL2366; A319; ATL..CHS New Destination: ATL; Weather. 0448 LASER; ATSC (FAA HQ DEN); SEA; ASA239; B738; SAN..SEA; At 0434 cockpit was illuminated from the right 0500 by a green laser while northbound at 3,000', 5S Seattle (SEA); no injuries reported; OTHER; ATSC (FAA HQ DEN); PCT; PCT performed successful cold start of RACD. 0515 LASER; ATSC (FAA HQ DEN); NCT; SWA3322; B737; SNA..SJC; At 0353 cockpit was illuminated from the 0517 right by a green laser while northwest bound at 11,500', 3SW Hollister, CA; no injuries reported NORDO; ATSC (FAA HQ DEN); ZDC; CTL69; AC50; BUY..IAD; Aircraft reported on course, at assigned 0527

Page 1


This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

Date: 04/26/2013


7			
Element:	Created by:	Created on:	Checked by:
ALL	CWomack,	04/27/2013 0415Z	cw

Log:	
Time (UTC)	Remarks
	altitude. Attempting contact on Guard and with Company. 0529 FSOC attempting comm over GVE VORTAC/ PCT freq 124.65. Communications re-established at 0537.
0550 0554	LASER; ATSC (FAA HQ DEN); EUG; SKW739W; CRJ2; DENEUG; At 0452 cockpit was illuminated from the left by a green laser while westbound at 4,000', 1E Eugene (EUG); no injuries reported;
0607	EMERGENCY; ATSC (FAA HQ DEN); ZNY; TAF07; C130; DOVLPLA; Problem with one of the engines; continuing on the destination. ETA 0858. Aircraft exited US airspace at 0620.
0635	NORDO; ATSC (FAA HQ DEN); ZAN; LN35CY; LJ35; BRWANC; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0636.
0641	the state of the s
0658 0837	SIF; ATSC (FAA HQ DEN); ZJX; TSO588; B744; MMUNUUWW; Deviating around weather. LASER; ATSC (FAA HQ DEN); S56; LIFEFLT41; HELO; VFRVFR; At 0818 cockpit was illuminated by a green laser while northbound at 5,100'. 10NNE SLC; no injuries reported;
1000	
1000	
1005 1009	NORDO; ATSC (FAA HQ DEN); ZMA; DAL48; B763; SBGRDTW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1009.
1015	alacade. Facempung contact on oddie and with company. Communications re-established at 1005.
1020 1024	NORDO; ATSC (FAA HQ DEN); ZMP; QXE851A; DH8D; PDXRFD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1025. LASER; ATSC (FAA HQ DEN); ZID; CHQ3030; E145; SDFCLT; Cockpit was illuminated by green laser on
	right side while heading SE at 16,500 feet 43 miles SW of LEX. No injuries reported.
1026	
1041	NORDO, MECHANICAL; ATSC (FAA HQ DEN); CLT; FLX811; C210; CLTBUY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 1045 HQ DEN called CLT and gave phone number for company dispatch. 1055 HQ DEN called ZDC, ZTL, CLT, GSO to find out status of aircraft. GSO will call back with information. Aircraft is believed to have electrical failure. Fire and Rescue is standing by at BUY for flight, Aircraft landed safely at 1123. And it was confirmed that aircraft did have complete electrical failure.
1108	NORDO; ATSC (FAA HQ DEN); ZDC; TMC435; BE40; ATLIAD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. 1115 HQ DEN called ATL ATCT for phone number. Communications re-established at 1122.
1111	
1130	
1145	COD; ATSC (FAA HQ DEN); ZKC; GEC8221; MD11; DFWEDDF New Destination: ORD; Gear problem.
1156	Dumping fuel due to overweight.
1205	76
1222	
	7F
1225	COD; ATSC (FAA HQ DEN); ILM; MTN8507; C208; ILMGSO New Destination: MQI; Company request.

Page 2



Element:Created by:Created on:Checked by:ALLCWomack,04/27/2013 0415ZCW



Page 3

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Sm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/26/2013

Element: Created by: Created on: Checked by: CWomack, 04/27/2013 0415Z CW

Log:			
Time (UTC)	Remarks		
1555			
	7½		
1558	EQUIPMENT; ATSC (FAA HQ DEN); HQ DEN ADAPT OTS. NCRCC monitoring for HQ DEN. C3 called ADAPT help. ADAPT RTS 1614.		
1623	COD; ATSC (FAA HQ DEN); ZFW; EGF2961; E145; LBBDFW New Destination: ABI; Not enough fuel to absorb metering delays.		
1625	NORDO; ATSC (FAA HQ DEN); ZTL; N916SJ; C441; GEDGPT; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1630 HQ DEN asked ZDC to review tapes to see what frequency they assigned for switch to ZTL. 1640 NORDO 0+15 HQ DEN called contact phone number for PIC; no contact. Communications re-established at 1655.		
1640	I, TE		
1642			
1648 1657	NORDO; ATSC (FAA HQ DEN); ZBW; EJA655; C56X; ACKMDW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1658. NORDO; ATSC (FAA HQ DEN); ZJX; TRS539; B712; PITFLL; Aircraft reported on course, at assigned		
1657	altitude. Attempting contact on Guard and with Company. Communications re-established at 1657.		
1700			
1703	COD; ATSC (FAA HQ DEN); PBI; SWA1573; B737; RDUFLL New Destination: PBI; Fuel.		
1715	NOTAM-VIP; ATSC (CONR/AOC); FDC NOTAM 3/4176 AREA A for VIP movement to Flagstaff, AZ in effect but not enforced due to VIP delay. 1730 Area A enforced. No Airborne holding initiated. 1734 R21 sweep complete. 1734 Arrival ramp freeze. 1744 VIP landed. 1749 VIP in chocks. 1758 VIP off airport. 1758 Normal airport operations resumed. 1758 Area A no longer enforced. No reportable arrival or departure delays. No airborne diverts. 1815 Area B in effect. 1830 Area A expired. 0130 Area C in effect. TOI Summary: 0 TOI, 0 MOR, 0 Unable to Identify.		
1741	EMERGENCY; ATSC (FAA HQ DEN); ZHU; GATOR21; T38; RNDRND; Stuck Nozzle. Aircraft landed at 1750.		
1751			
1800			
1800			
1800	E		
1823	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZDC; RCH392; C5; ETARADW New Destination: DOV; #3 Engine OTS. Aircraft landed at 1936.		
1828			
1831	2.7 PE		
1835	NORDO; ATSC (FAA HQ DEN); MFD; N812TB; PA31; MFD. LSE; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1846.		
1836	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDC; FLG4091; CRJ2; MDTCVG New Destination: IAD; Sick PAX.		
1850	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZAN; ZAN authorized to suspend change of destination reporting for Southern Peninsula until 2200 due to weather.		
1850	NORDO; ATSC (FAA HQ DEN); ZOB; N1755W; BE36; CKZY70; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. ACFT reported NORDO 0+15; ZOB attempted contact via previous frequencies, through FSS, and NAVAID voice. Communications re-established at 1852.		

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

FAA Air Traffic Organization NAS Daily Events Log					Date: 04/26/2013
Element: ALL	Created by: CWomack,	Created on: 04/27/2013 04	15Z	Checked by: CW	

Log:	
Time (UT	C) Remarks
1853	EMERGENCY; ATSC (FAA HQ DEN); ZME; EGF4325; E145; ORDLIT; Smoke smell in cockpit. Aircraft landed at 1910.
1900	COD; ATSC (FAA HQ DEN); ZKC; XSR630; E50P; PWABMG New Destination: BUF; Favorable winds; no fuel stop.
1922	NORDO; ATSC (FAA HQ DEN); LIT; N5071T; BE58; BECSRQ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1937 NORDO 0+15; ZME investigating. 1944 HQ DEN attempted contact via FSS supplied telephone; left voice message. Communications reestablished at 1950.
1930	
1936	, o
2000 2026	EMERGENCY, COD; ATSC (FAA HQ DEN); BOS; KAP311; C402; BOSRUT New Destination: BOS; Engine
2037	issue. Aircraft landed at 2019. COD; ATSC (FAA HQ DEN); ZJX; MJI33; FA10; APFJST New Destination; LNS; Passenger request.
2052	COD, A TOO (1744 N. DEN), 200, Moloo, 17410, Al 1 1.00 F NOW Destination. ENO, 1 assenger request.
2054	
2057	NORDO; ATSC (FAA HQ DEN); ZJX; CGIPX; F900; CYKFPBI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. HQ DEN attempting contact via satellite phone. Communications reestablished at 2100.
2058	COD; ATSC (FAA HQ DEN); M98; CPZ5807; E170; MSPMSN New Destination: MSP; Bird strike.
2100	
2101 2110	COD; ATSC (FAA HQ DEN); ZSU; LIA563; DH8D; TJSJTAPA New Destination: TUPJ; Passenger request. EMERGENCY,COD; ATSC (FAA HQ DEN); ZMA; HPJ352; LJ35; FXEMYNN New Destination: FXE;
2113	Maintenance problem. 2138 PIC declared emergency for hydraulic failure. ACFT landed at 2146. NORDO; ATSC (FAA HQ DEN); ZLA; N171JC; GLF4; TEBVNY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications reestablished at 2116.
2116 2119	COD; ATSC (FAA HQ DEN); ZID; EJA592; C56X; UOXBKL New Destination: TOL; PAX request. EMERGENCY ; ATSC (FAA HQ DEN); LIT; ARROW52; C130; LRFLRF; #4 Engine shutdown. Aircraft cancelled emergency at 2129.
2120 2122	COD; ATSC (FAA HQ DEN); ZID; ASH3773; CRJ7; IADMCI New Destination: PIT; Maintenance issue. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZME; ZME/ZAN authorized to suspend change of destination reporting for AOR until 0200 due to weather.
2133	2. #
2220	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZKC; TURBO71; K35R; PHXIAB New Destination: PHX; Engine issue. Aircraft landed at 2225.
2232	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); GSO; EGF2962; E145; GSODFW New Destination: GSO; Sick Passenger.
2234	COD; ATSC (FAA HQ DEN); ZMP; NDU40; C172; BJIGFK New Destination: TVF; Training.
2240	NORDO; ATSC (FAA HQ DEN); ZJX; N416MP; P32R; DBNSSI; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2243.
2300	
2300	
2327	NORDO; ATSC (FAA HQ DEN); ZSE; SWA402; B737; SEASJC; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2328.
2335	EMERGENCY, COD; ATSC (FAA HQ DEN); ZDV; N222GL; BE36; APAIXD New Destination: 1F5; Engine issue. 2337 ZDV advised ACFT overflew airport; lost RADIO and RADAR contact; ACFT in area investigating.


Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/26/2013

Element: Created by: Created on: Checked by: CWomack, 04/27/2013 0415Z CW



Page 6

FOR OFFICIAL USE ONLY



Date: 04/26/2013

ALL CWomack, 04/27/2013 0415Z CW		Element: ALL	Created by: CWomack,	Created on: 04/27/2013 0415Z	Checked by: CW
--	--	-----------------	-------------------------	------------------------------	-------------------

Log:	og:			
Time (UTC)	Remarks			
0240	COD; ATSC (FAA HQ DEN); ZAN; CFS202; AT72; ANCJNU New Destination: KTN; Weather.			
0305	LASER; ATSC (FAA HQ DEN); C90; AAL2376; MD83; DFWORD; At 0257 aircraft was illuminated by a green laser while northbound at 7,000', 12SW Chicago O'Hare (ORD); no injuries reported;			
0339	NORDO; ATSC (N/NC); ZTL; SWA446; B737; MDWMCO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0343.			
0344	COD; ATSC (N/NC); ZAN; PEN3297; SF34; DUT. AKN New Destination: ANC; No fuel stop needed.			
0352	NORDO; ATSC (FÁA HQ DEN); ZAB; UPS857; B763; PHXSDF; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0353.			
0359				

Page 7



Element:	Created by:	Created on:	Checked by:
ALL	CWomack,	04/28/2013 0516Z	CW

Log:	
Time (U	TC) Remarks
0210 0211	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZLA; UAL731; A320; LASLAX; Sick PAX. EMERGENCY,COD; ATSC (FAA HQ DEN); ZME; RCH552; C172; HOPHOP New Destination: MEM; Fuel shortage. Aircraft landed at 0232.
0215 0230	
0234	NORDO,MOR; ATSC (FAA HQ DEN); ZMA; N724JS; LJ60; SANBCT; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0243; ZMA read the Pilot the Brasher Warning and filed an MOR./CW.
0237	LASER; ATSC (FAA HQ DEN); TOL; N911PX; EC35; VFRVFR; At 0217 aircraft (PROMEDICA1) cockpit was illuminated 3 times by a green laser while southeast bound at 1,800', 3E Waterville VOR (VWV), OH; no injuries reported;
0239 0250	EMERGENCY; ATSC (FAA HQ DEN); PEG9; FA50; VNYCLE New Destination: COS; Pressurization problem; crew on oxygen. Aircraft landed at 0300.
0252	NORDO; ATSC (FAA HQ DEN); ZAN; CPA807; B77W; ORDVHHH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0257.
0253	LASER; ATSC (FAA HQ DEN); MDT; PDT4307; DH8A; PHLMDT; At 0207 cockpit was illuminated from the left by a green laser while southeast bound at 3,000′, 10N Harrisburg (MDT); no injuries reported;
0258	LASER; ATSC (FAA HQ DEN); M98; FFT108; A320; DENMSP; At 0239 cockpit was illuminated by a green laser while northeast bound at 7,000', 18W MSP; no injuries reported;
0312	NORDO; ATSC (FAA HQ DEN); ZAN; CES588; A346; JFK. ZSPD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0316.
0321	EMERGENCY , COD; ATSC (FAA HQ DEN); N90; DAL121; B764; JFKSBGR New Destination: JFK; Tire blew on takeoff; holding to burn fuel. (carried over to 4/28/13 Skywatch log).
0324	NORDO; ATSC (FAA HQ DEN); ZAN; CCA982; B77W; JFKZBAA; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0327.
0342	LASER; ATSC (FAA HQ DEN); C90; AAL1278; B738; LAXORD; At 0330 cockpit was illuminated from the right by a green laser while eastbound at 5,000', 17W O'Hare (ORD); no injuries reported
0345	LASER; ATSC (FAA HQ DEN); C90; AAL1144; B738; SNAORD; At 0337 cockpit was illuminated from the right by a green laser while eastbound at 5,000′, 10E O'Hare (ORD); no injuries reported
0349	LASER; ATSC (FAA HQ DEN); P50; SKW2980; CRJ2; SBAPHX; At 0325 cockpit was illuminated from the front by a green laser while eastbound at 7,000′, 8S Phoenix (PHX); no injuries reported
0359	

Page 6

Air Tı Daily

raffic Organization **Events** Log

Date: 04/27/2013

Checked by: Element: Created by: Created on: CWomack, 04/28/2013 0516Z CW ALL

Security Event Statistics:				
EMERGENCY: 16	ME.	AIRPORT: 1 NORDO: 20	COD: 35 LASER: 17 MOR: 2	
EMERGENCY- MEDICAL: 12			WOR. 2	

Log:	
Time (UTC)	Remarks
04/27/2013 0400	2
0400	<u>2</u>
0401	LASER; ATSC (FAA HQ DEN); LAS; AWE439; A320; PHLLAS; At 0338 cockpit was illuminated from the left by a green laser while westbound at 4,000′, 6E LAS; no injuries reported;
0405	EMERGENCY, COD; ATSC (FAA HQ DEN); SCT; SKW864A; CRJ2; LAXCOS New Destination: LAX; Gear indicator light. Aircraft landed at 0414.
0407	LASER; ATSC (FAA HQ DEN); LAS; N4119S; DA40; LASFFZ; At 0348 cockpit was illuminated from the left by a green laser while west southwest bound at 3,200', 2S Las Vegas; no injuries reported;
0416	LASER OPERATION; ATSC (FAA HQ DEN); NASA Goddard Space Flight Center conducting LASER operations. Operations complete at 0905.
0426	LASER; ATSC (FAA HQ DEN); SCT; SIS650; C560; VNYLAS; At 0350 cockpit was illuminated from the right by a green laser while northbound at 6,000', 4N Van Nuys (VNY); no injuries reported;
0428	LASER; ATSC (FAA HQ DEN); NCT; ASA834; B738; HNLSJC; At 0409 cockpit was illuminated from the left by a green laser while southeast bound at 4,500', 7S San Jose (SJC); no injuries reported;
0442	LASER; ATSC (FAA HQ DEN); MSY; RPA3253; E170; CLTMSY; At 0415 cockpit was illuminated from the right by a green laser while southbound at 2,000', 5NW New Orleans (MSY)' no injuries reported;
0444	LASER; ATSC (FAA HQ DEN); ZAB; OILER57; K35R; LTSLTS; At 0430 aircraft was illuminated in the center rear window (re-fueler position) while northbound at FL240B260, 13ENE Borger, TX; no injuries reported;
0515 0521	OTHER; ATSC (FAA HQ DEN); PCT; PCT performed successful cold start of RACD. LASER; ATSC (FAA HQ DEN); JBU419; A320; BOSLGB; JBU contacted the DEN to report the following laser event: At 0335 cockpit was illuminated 3 times from the right by a green laser while northbound at 4,000', 5E Santa Ana (SNA); First Officer experienced blurred vision. JBU official did not know which LE Agency was contacted but did state that the PIC notified ATC. As no record of the report was found, the ATSC contacted SCT who found a log entry for an MOR for a JBU419 laser event that occurred at the same time. However, SCT log entry stated that the laser was red and cockpit was illuminated from the left side while 6N SNA. The entry did not show which, if any, LE Agency was contacted but it did show that the DEN was notified. The WOC has no record of this report.
0528	LASER; ATSC (N/NC); ZSE; FLG3375; CRJ9; SLCPSC; At 0518 aircraft was illuminated in the left side

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element: Created by: Created on: Checked by: CWomack, 04/28/2013 0516Z CW

Log:	
Time (UTC)	Remarks
	cockpit while northbound at 2,500 MSL, 7SE Pasco (PSC); no injuries reported;
0545	
0545 0601	NORDO; ATSC (FAA HQ DEN); ZKC; N521PM; PAY2; SLNMTO; Aircraft reported on course, at assigned
0653	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 0603. NORDO; ATSC (FAA HQ DEN); FWA; CTL62; AC50; PWKOSU; Aircraft reported on course, at assigned altitude; now in CMH airspace. Attempting contact on Guard and with Company. Communications re-
	established at 0654.
0657	ATC FACILITY, PAGED; ATSC (FAA HQ DEN); MKE; MKE declared ATC Alert due to staffing trigger brought on by furloughs. ATCSCC advised. ATC Alert expected to be cancelled at 1000. ATC Alert cancelled at 1000. ATCSCC advised.
0659	NORDO; ATSC (FAA HQ DEN); ZDC; ASH3761; CRJ7; MCIIAD; Aircraft reported on course, descending to assigned altitude 11,000'. Attempting contact on Guard and with Company.
0716	LASER; ATSC (FAA HQ DEN); HCF; HAL224; B763; OGGOAK; At 0702 cockpit was illuminated from the left by a green laser while eastbound at 3,000′, 10W Honolulu (HNL); no injuries reported;
0802	NORDO; ATSC (FAA HQ DEN); ZLA; UAL1220; B762; LAXIAH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0804.
0807	LASER; ATSC (FAA HQ DEN); OGG; WJA1852; B738; CYVROGG; At 0703 cockpit was illuminated from the left by a green laser while northbound at 700', on 2NM final RY2 OGG; no injuries reported;
1000	
1000	
1002	
1011	
1020	
1136	NORDO,MOR,PAGED; ATSC (FAA HQ DEN); ZKC; SWG675; B738; MUVRCYVR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. HQ DEN provided company phone number to ZKC. 1156 0+30 minutes. HQ DEN asked ZKC to review tapes. 1211 0+45 minutes. Communications re-established at 1221. MOR to be filed by ZKC.
1150	TE CONTROL OF THE CON
1210	OTHER; ATSC (FAA HQ DEN); CHS; CHS reported that 3 aircraft heard ELT over DYB VOR. HQ DEN advised CHS to contact overlying TRACON and ZJX with information.
1221	EMERGENCY ,COD; ATSC (FAA HQ DEN); ZFW; AMF1722; SW4; DFWAMA New Destination: SPS; Right engine OTS. Aircraft landed at 1248.
1223	
1230	<u>.</u>
1242	COD; ATSC (FAA HQ DEN); ZMP; AMF1686; OMAOLU New Destination: ONL; WX.
1253	., 7p
1300	
1318	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; AAL1907; B738; CYULMIA; Male PAX iII.
1320	EQUIPMENT, PAGED; ATSC (FAA HQ DEN); HQ DEN on RTR ALT DEN for maintenance. 1945 HQ DEN and all Participants are on the main DEN line./CU.
1354	NORDO; ATSC (FAA HQ DEN); ZMA; N414EM; C414; SRQMTH; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1356.

Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element: Created by: Created on: Checked by: CWomack, 04/28/2013 0516Z CW

Log:	
Time (UTC)	Remarks
1417	
1417	
1441	EMERGENCY ; ATSC (FAA HQ DEN); N58LD; HIGH; VFRVFR; DCA Hub FSDO reported that N58LD took evasive action to avoid another aircraft, and hit the ground. 2 injuries, 1 of which is critical. Ohio State Police investigating. Incident occurred near Bryan, Ohio. HQ DEN notified WOC.
1505	NORDO; ATSC (FAA HQ DEN); ZDC; N299PT; C182; XSACRE; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1510.
1508	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZAB; DAL2087; B738; RDULAX New Destination: PHX; Male PAX possible stroke.
1534	NORDO; ATSC (FAA HQ DEN); ZMP; WIS500; C310; ANEANJ; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1536.
1534	NORDO; ATSC (FAA HQ DEN); ZTL; TCF3559; E170; EWRDFW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1536.
1541	
1552	COD; ATSC (FAA HQ DEN); ZTL; TRS216; B712; ATLLGA New Destination: ATL; Indicator light.
1557	COD: ATSC (NCRCC); PCT; SWA2242; B737; BNAEWR New Destination: BWI; Maintenance.
1600	T. 7E
1604	NORDO; ATSC (FAA HQ DEN); ZID; N58KT; BE58; LUKEWB; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1618.
1614	7E 7E
1626	NORDO; ATSC (FAA HQ DEN); ZTL; B8270; GLF5; SAVANC; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1634.
1658	EMERGENCY ; ATSC (FAA HQ DEN); YNG; N704YS; C150; VFRYNG; Aircraft made a forced landing 4 miles N of YNG. No injuries reported. Unknown damages to aircraft.
1711	NORDO; ATSC (FAA HQ DEN); ZJX; LMO7144; BE40; INTMWCR; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1713.
1800	
1800	
1800	
1800	
1816	EMERGENCY ,COD; ATSC (FAA HQ DEN); SAV; ASQ4415; E45X; SAVIAH New Destination: SAV; Possible fuel leak out of the right wing. Aircraft landed at 1819.
1819	EMERGENCY , COD; ATSC (FAA HQ DEN); TPA; RBY710; B734; PIEGPT New Destination: PIE; Bird strike issue. Aircraft landed at 1817.
1824	EMERGENCY , COD; ATSC (FAA HQ DEN); ZAB; DAL958; B738; LAX. BNA New Destination: PHX; Electrical failure on the right side of ACFT. Aircraft landed at 1841. 1845 emergency cancelled.
1825	COD; ATSC (FAA HQ DEN); ZDV; GLA36K; E120; DEN. DIK New Destination: CYS; Cabin door issue.
1828	EMERGENCY; ATSC (FAA HQ DEN); ZDC; BISON82; C130; POB.:POB; Burning smell in cockpit. Aircraft landed at 1840.
1852	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZME; ASQ5972; E45X; DENHSV; Sick PAX.
1905	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZMP; GJS3657; CRJ7; CIDDEN New Destination:

Page 3

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

FOR OFFICIAL USE ONLY

ration The political



Date: 04/27/2013

Element: Created by: Created on: Checked by: CWomack, 04/28/2013 0516Z CW

Log:	
Time (UTC)	Remarks
	OMA; Sick PAX.
1920 1925	COD; ATSC (FAA HQ DEN); ZDV; VNR188; P180; SWO. ASE New Destination: RIL; Company request. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); MIA; MIA authorized to suspend change of destination
1945	reporting for FLL UFA due to ACFT disabled on RY. 1936 Normal operations resumed.
1946	COD; ATSC (FAA HQ DEN); ZAB; ACA1287; E190; PHXCYYC New Destination: PHX; Electrical light issue.
1956	
1958	
2002	EMERGENCY,NOTIFICATION-LATE,COD; ATSC (FAA HQ DEN); D01; GLA183; B190; DENPIR New Destination: DEN; Engine malfunction. Aircraft landed at 2000.
2003	COD; ATSC (FAA HQ DEN); STL; KAP280; C402; STL. MWA New Destination: STL; Gear would not retract.
2007	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZME; ZME authorized to suspend change of destination reporting for AOR until 2300 due to WX.
2007	EMERGENCY, COD; ATSC (FAA HQ DEN); PBI; N414EM; C414; VNCLNA New Destination: PBI; Left engine out. Aircraft landed at 1957.
2014	EMERGENCY; ATSC (FAA HQ DEN); S56; TANKR43; P2; VFROGD; Number two engine failure. Aircraft landed at 2024.
2018	COD; ATSC (FAA HQ DEN); A11; VTS991; DC6; ANCENM New Destination: ANC; Company request.
2028	COD; ATSC (FAA HQ DEN); ZME; FIV413; C25B; BHMMKE New Destination: HSV; Unable to meet flight restrictions.
2030	TE TE
2048	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); I90; I90 authorized to suspend change of destination
2059	reporting for AOR until 0100 due to WX. EMERGENCY ,COD; ATSC (FAA HQ DEN); ZBW; DAL1701; A320; BOSATL New Destination: BDL; Aft cabin smoke. Aircraft landed at 2110.
2102	
2103	NORDO; ATSC (FAA HQ DEN); ZKC; DAL370; B752; ATLLAX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2103.
2104	NORDO; ATSC (FAA HQ DEN); ZDC; N418KC; C525; VQQPWM; Aircraft reported on course, at assigned
2111	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2119. EMERGENCY- MEDICAL, PAGED; ATSC (FAA HQ DEN); ZKC; AWE368; A319; OMAPHX; Sick Crew
	Member, PIC did not want to declare a medical emergency so ZKC declared the emergency, HQ DEN calling AWE Dispatch. 2116 AWE Dispatch report FA with diabetic symptoms. Aircraft landed at 2158.
2119	COD: ATSC (FAA HQ DEN); ZDC; VNR105; P180; RSWILG New Destination: GSO; Company request.
2123	NORDO; ATSC (FAA HQ DEN); TOL; N2880L; P28A; MIE. TOL; Aircraft reported on course, at assigned
2124	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2129.
	TF
2126	COD, MECHANICAL; ATSC (NCRCC); ZDC; ASQ5690; CRJ2; IAD. BNA New Destination: IAD; Mechanical
	issue, non emergency.

Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	CWomack,	04/28/2013 0516Z	CW

Log:	
Time (UTC)	Remarks
2137 2145	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; JBU746; A320; TJSJMCO; Sick PAX.
2 143	
2156	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZBW; JBU1294; E190; PITBOS; Sick PAX.
2200 2204	EMERGENCY; ATSC (FAA HQ DEN); TPA; N5944J; C172; BKVFPR; 7700 observed on ADAPT 13 miles SE
2204	Hernando County ARPT (BKV), HQ responding. TPA APCH reported a rough running engine and PIC may have to land in a field. 2207 Track faded. 2220 ACFT crashed, landed inverted, the three people onboard walked away. ACFT not on fire; LE on the scene.
2205	
2208	
2213 2226	COD; ATSC (NCRCC); NCT; OPT307; E55P; LASOAK New Destination: SFO; Company request. COD; ATSC (FAA HQ DEN); ZFW; EJA830; C560; BHMLBB New Destination: SEZ; Favorable winds.
2227	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZFW; ZFW authorized to suspend change of destination
,	reporting for AOR until 0100 due to WX.
2234	TF
2244	COD; ATSC (FAA HQ DEN); ZME; SWA594; B737; MDWHOU New Destination: TUL; Company request.
2253	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); CLT; AWI4089; CRJ2; PHFCLT; Sick PAX.
2256	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZHU; ZHU authorized to suspend change of destination
	reporting for IAH/HOU until 0100 due to WX.
2304	
	TE CONTRACTOR OF THE CONTRACTO
2317	COD; ATSC (FAA HQ DEN); ZAB; SWA689; B737; LAXHOU New Destination: ELP; WX.
2324	COD; ATSC (FAA HQ DEN); HUF; SKQ227; PA31; CMHSTL New Destination: HUF; WX.
2331 2331	COD; ATSC (FAA HQ DEN); ZME; SWA2364; B733; BWIHOU New Destination: LIT; Company request. COD: ATSC (FAA HQ DEN); ELP; SWA689; B737; LAXHOU New Destination: ELP; WX.
2335	COD; ATSC (FAA HQ DEN); ZAN; AER965; B190; ANCSDP New Destination: DUT; Company request.
2340	NORDO; ATSC (FAA HQ DEN); CRW; N15SP; M20T; SIF. DET; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 2347.
04/28/2013	EMERICAN MEDICAL ATCO (EAA HO DENI), 7MA, NIKO40E, ACCO, ODD, ELL, Cid. DAY
0018 0022	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; NKS425; A320; ORD. FLL; Sick PAX. COD; ATSC (FAA HQ DEN); ZKC; EJA758; GALX; MKCMDW New Destination: IND; Company request.
0022	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMP; FFT820; A320; DENMCI; Sick PAX.
0027	COD; ATSC (FAA HQ DEN); ZOA; HAL48; B763; HNLOAK New Destination: HNL; Non emergency request to
	return to Honolulu. ACFT landed 0138.
0054	LASER; ATSC (FAA HQ DEN); ACY; BOUNCER2; Green laser illuminated nose of the cockpit at 3,000 feet, 2 miles S of Sea Isle ARPT (SIF). Helicopter N bound, no injuries reported.
	miles S of Sea Isle ARPT (SIE). Helicopter N bound, no injuries reported.
0055	COD; ATSC (FAA HQ DEN); ZHU; ASQ4410; E45X; IAHMMTG New Destination: IAH; Company request.
0105	
0109	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDC; UAL1044; B738; RSW. EWR; Sick PAX.
0108 0139	COD: ATSC (FAA HQ DEN); ZHU; DAL1549; MD88; MSYHOU New Destination: IAH; WX. 0140 COD to
3100	HOU. 0144 COD to SAT due to WX.

Page 5

	FAA Air Traffic NAS Daily Eve	
Flams		0

Element:	Created by:	Created on: 04/29/2013 0405Z	Checked by:
ALL	CWomack,		CW

Security Event Statistics:				
AIRPORT: 1 COD: 39				
EMERGENCY: 12 EMERGENCY- MEDICAL: 11	*E	NORDO: 18	LASER: 2	

Log:	
Time (UTC	Remarks
04/28/2013	
0400	
0400	
0405	EMERGENCY ; ATSC (FAA HQ DEN); WADS; 7700 code observed 15WNW DMA; code not observed by HQ DEN or ZAB. 0408 AMOC observes intermittent track, low level. 0410 HQ DEN contacted TUS Approach who is observing an intermittent track also and believes the aircraft to be a helo; not in comm with ATC. TUS will attempt guard calls to aircraft. 0420 Track no longer observed.
0420	LASER OPERATION; ATSC (FAA HQ DEN); NASA Goddard Space Flight Center conducting LASER operations. Operations complete at 0916.
0432	LASER; ATSC (FAA HQ DEN); DAB; N483ER; C172; CRG. DAB; At 0405 cockpit was illuminated by a green laser while southbound at 700', 4N Daytona (DAB); no injuries reported:
0438	NORDO; ATSC (FAA HQ DEN); ZMP; JBU199; A320; JFKLAS; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 0439.
0439	LASER; ATSC (FAA HQ DEN); SCT; SWA2136; B737; SJCLAX; At 0430 cockpit was illuminated from the left by a green laser while eastbound at 5,000', 3E Santa Monica (SMO); no injuries reported;
0536	COD; ATSC (N/NC); ZAN; LN546LM; BE20; TALFAI New Destination: ANC; Company request.
0545	ADMIN; ATSC (N/NC); N/NC; DH off, Combined to HQ.
0600	OTHER; ATSC (FAA HQ DEN); PCT; PCT performed successful cold start of RACD.
0634	NORDO; ATSC (FAA HQ DEN); 7600 code observed 10SW St Augustine (SGJ); appears to have departed SGJ, southbound, climbing out of 2,000'. 0700 Aircraft still southbound at 6.500'; neither DAB or F11 have been in comm with aircraft. 0716 Aircraft appears to be descending. 0745 ZMA advised aircraft appears to be receiver only and responding by ident; however, ACID and destination is still unknown. 0840 Aircraft appears to have landed Tamiama (TMB).
0720	7E
0853	COD; ATSC (FAA HQ DEN); ZKC; NAO927; B763; BGRFOE New Destination: MCI; Weather.
0908	ATC FACILITY; ATSC (FAA HQ DEN); ZID; IND ATCT declared ATC Alert due to an automation trigger. ATC Alert cancelled at 0950.
0930	
1000	
1000	
1000	


Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/28/2013

Element: Created by: Created on: Checked by: CWomack, 04/29/2013 0405Z CW



Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

FAA Air Traffic Organization NAS Daily Events Log			Date: 04/28/2013	
Element: ALL	Created by: CWomack,	Created on: 04/29/2013 0405Z	Checked by: CW	

 COD; ATSC (FAA HQ DEN); ZHU; SWA127; B733; HOU. HRL New Destination: HOU; E COD; ATSC (FAA HQ DEN); ZSE; EJA574; C56X; ACV. LAR New Destination: FSD; No EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDV; AAL1204; B738; SJC. DFW ABQ; Female PAX with heart condition. EMERGENCY; ATSC (FAA HQ DEN); PWM; N180VW; C180; VFR. VFR; Aircraft crashed in valked away with no known injuries; LE on the scene. COD; ATSC (FAA HQ DEN); M9318V; M20T; PWA. VFR; VFR ACFT crashed in walked away with no known injuries, LE on the scene. COD; ATSC (FAA HQ DEN); MSY; SWA2288; B737; MSYBHM New Destination: MSY; DEN calling SWA Dispatch. 1744 oil quantity issue. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHLMEM; Sid WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80 authorized to suspend chareporting for AOR until 2400 due to WX. EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: TPA; NORDO; ATSC (FAA HQ DEN); ZDC; N1688; M20P; APALOU; Aircraft reported on caltitude. Attempting cont	Log:	
 COD; ATSC (FAA HQ DEN); ZHU; SWA127; B733; HOU.:HRL New Destination: HOU; E COD; ATSC (FAA HQ DEN); ZSE; EJA574; C56X; ACV.:LAR New Destination: FSD; No EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZDV; AAL1204; B738; SJC.:DFW ABQ; Fernale PAX with heart condition. EMERGENCY; ATSC (FAA HQ DEN); PWM; N180VW; C180; VFR.:VFR; Aircraft crasher No injuries reported. Damage to aircraft unknown. EMERGENCY; ATSC (FAA HQ DEN); N9318V; M20T; PWA.:VFR; VFR ACFT crashed in walked away with no known injuries, LE on the scene. COD; ATSC (FAA HQ DEN); MSY; SWA2288; B737; MSY.:BHM New Destination: MSY; DEN calling SWA Dispatch. 1744 oil quantity issue. EMERGENCY MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHL.:MEM; Sid WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80 authorized to suspend chareporting for AOR until 2400 due to WX. EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKA.:MQY New Destination engine. Aircraft landed at 1817. COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA.:LGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA.:LGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; EJA906; C750; ICT.:SUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; EJA906; C750; ICT.:SUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; B7900; ICT.:SUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; B7900; ICT.:SUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; EJA906; C750; ICT.:SUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; EJA906; C750; ICT.:SUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; B7900; DCT.:SUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; B79020; PAAE, LOU; Aircraft reported on coalititude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked XDC (COD; ATSC (FAA HQ DEN); ZMC; EJA711; GALX; DAL.:CSV New Destination: TPA; NORDO; ATSC (FAA HQ DEN); ZMC; EJA711; GALX; DAL.:CSV New Destination: TYS; WX NORDO; ATSC (FAA HQ DEN); CAE;	Time (UTC)	Remarks
COD; ATSC (FAA HQ DEN); ZSE; EJA574; C56X, ACVLAR New Destination: FSD; No EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZDV; AAL1204; B738; SJCDFW ABC; Female PAX with heart condition. EMERGENCY; ATSC (FAA HQ DEN); PWM; N180VW; C180; VFRVFR; Aircraft crasher No injuries reported. Damage to aircraft unknown. EMERGENCY; ATSC (FAA HQ DEN); PWM; N180VW; C180; VFRVFR; Aircraft crashed in walked away with no known injuries, LE on the scene. COD; ATSC (FAA HQ DEN); MSY; SWA2288; B737; MSYBHM New Destination: MSY; DEN calling SWA Dispatch. 1744 oil quantity issue. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHLMEM; Sid WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80; authorized to suspend chareporting for AOR until 2400 due to WX. EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNA. LGA New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDC; M1088; M20P; APALOU; Aircraft reported on continued to the second substitude. Attempting contact on Guard. No satellite phone available. Communications reestablished at 1855. RAMA COD; ATSC (FAA HQ DEN); ZMC; N1088; M20P; APALOU; Aircraft reported on continued to the second substitude. Attempting contact on Guard and with Company. Communications re-established LATSC (FAA HQ DEN); CAE; D		COD; ATSC (FAA HQ DEN); ZFW; EJA935; C750; HOUICT New Destination: SAT; Weather.
 EMERGENCY- MEDICAL, ÓOD; ATSC (FAA HQ DEN); ZDV; AAL1204; B738; SJCDFN ABQ; Female PAX with heart condition. EMERGENCY; ATSC (FAA HQ DEN); PWM; N180VW; C180; VFRVFR; Aircraft crasher No injuries reported. Damage to aircraft unknown. EMERGENCY; ATSC (FAA HQ DEN); N9318V; M20T; PWAVFR; VFR ACFT crashed in walked away with no known injuries, LE on the scene. COD; ATSC (FAA HQ DEN); MSY; SWA2288; B737; MSYBHM New Destination: MSY; DEN calling SWA Dispatch. 1744 oil quantity issue. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHLMEM; Sid WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80 authorized to suspend chareporting for AOR until 2400 due to WX. EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICT. SUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICT. SUN New Destination: DAL; Com Asked ZSE to verify that PIC is in compliant with ATC instructions, affirmative. NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on caltitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMC; N1068R; M20P; APALOU; Aircraft reported on caltitude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMC; EJA711; GALX; DALCSV New Destination: TPA; M COD; ATSC (FAA HQ DEN); ZMC; EJA711; GALX; DALCSV New Destination: TPA; M COD; ATSC (FAA HQ DEN); ZMC; EJA711; GALX; DALCSV New Destination: SAV; COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: DEN; CAE; SICK PAX. NORDO; ATSC (FAA HQ DE		COD; ATSC (FAA HQ DEN); ZHU; SWA127; B733; HOU. HRL New Destination: HOU; Electrical problem.
ABQ; Female PAX with heart condition. EMERGENCY; ATSC (FAA HQ DEN); PWM; N180VW; C180; VFRVFR; Aircraft crasher No injuries reported. Damage to aircraft unknown. EMERGENCY; ATSC (FAA HQ DEN); N9318V; M20T; PWAVFR; VFR ACFT crashed in walked away with no known injuries, LE on the scene. COD; ATSC (FAA HQ DEN); MSY; SWA2288; B737; MSYBHM New Destination: MSY; DEN calling SWA Dispatch. 1744 oil quantity issue. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHLMEM; Skd WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80 authorized to suspend chareporting for AOR until 2400 due to WX. EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off cou altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1855. NORDO; ATSC (FAA HQ DEN); ZMC; N1068R; M20P; APALOU; Aircraft reported on coalitude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMC; DAL134; B752; MMUNATL New Destination: TPA; NORDO; ATSC (FAA HQ DEN); ZMC; N1068R; M20P; APALOU; Aircraft reported on coalitude. Attempting contact on Guard and with Company. Communications re-established at 1855. EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZMC; CPA3432; E145; BDLORD; Aircraft reported on coalitude. Attempting contact on Guard and with Company. Communications re-established at 1855. EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJC; VRD084; A320; SFOIND; Aircraft reported on coalitude. Attempting contact on Guard and with Company. Communications re-established. COD; ATSC		COD; ATSC (FAA HQ DEN); ZSE; EJA574; C56X; ACVLAR New Destination: FSD; No fuel stop needed.
 EMERGENCY; ATSC (FAA HQ DEN); PWM; N180VW; C180; VFRVFR; Aircraft crashed No injuries reported. Damage to aircraft unknown. EMERGENCY; ATSC (FAA HQ DEN); M9318V; M20T; PWAVFR; VFR ACFT crashed in walked away with no known injuries, LE on the scene. COD: ATSC (FAA HQ DEN); MSY; SWA2288; B737; MSYBHM New Destination: MSY; DEN calling SWA Dispatch. 1744 oil quantity issue. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHLMEM; Sid WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80 authorized to suspend chareporting for AOR until 2400 due to WX. EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off coul altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1855. NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on collitude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; WX NORDO; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: SAV; CDC; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: SAV; CDC; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destinati		EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZDV; AAL1204; B738; SJCDFW New Destination: ABO: Female PAX with heart condition
EMÉRGENCÝ; ATSC (FAÁ HQ DEN); N9318V; M20T; PWAVFR; VFR ACFT crashed in walked away with no known injuries, LE on the scene. COD; ATSC (FAA HQ DEN); MSY; SWA2288; B737; MSYBHM New Destination: MSY; DEN calling SWA Dispatch. 1744 oil quantity issue. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHLMEM; Sid WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); M80; A80 authorized to suspend chareporting for AOR until 2400 due to WX. EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destination: BWI; Mei COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Mei COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Mei COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: IAH; Mei COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off could altitude. Attempting contact on Guard. No satellite phone available. Communications re-eden DEN asked ZSE to verify that PIC is in compliant with ATC instructions, affirmative. NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on coalititude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TPA; M NORDO; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TPA; M NORDO; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TPA; M NORDO; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: SAV; CMC, Sick PAX. NORDO; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CMC, Sick PAX. NORDO; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CMC, Sick PAX. NORDO; ATSC (FAA HQ DEN); ZV; VRD084; A320; SFOIND; Aircraft reported on coalititude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZV; SKW576M; CRJ7; DENASE	1724	EMERGENCY; ATSC (FAA HQ DEN); PWM; N180VW; C180; VFRVFR; Aircraft crashed 4 miles north of 0B1.
COD; ATSC (FAA HQ DEN); MSY; SWA2288; B737; MSYBHM New Destination: MSY; DEN calling SWA Dispatch. 1744 oil quantity issue. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHLMEM; Sic WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80 authorized to suspend chareporting for AOR until 2400 due to WX. EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destination: B00 and the company of the com	1733	EMERGENCY; ATSC (FAA HQ DEN); N9318V; M20T; PWAVFR; VFR ACFT crashed in a field, all PAX
DEN calling SWA Dispatch. 1744 oil quantity issue. EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHLMEM; Sid WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80 authorized to suspend chareporting for AOR until 2400 due to WX. B800 B800 B800 B800 B800 B800 B800 B8	1	
WEATHER DIVERTS-MULT; ATSC (FAA HQ DÉN); A80; A80 authorized to suspend chareporting for AOR until 2400 due to WX. B800 B800 B804 EMERGENCY,COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destinengine. Aircraft landed at 1817. COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off could altitude. Attempting contact on Guard. No satellite phone available. Communications reled DEN asked ZSE to verify that PIC is in compliant with ATC instructions, affirmative. NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on collabitude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TP4; N COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TY5; W3 NORDO; ATSC (FAA HQ DEN); ZMB; EJA711; GALX; DALCSV New Destination: TY5; W3 NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on collabitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CHS; Sick PAX. NORDO; ATSC (FAA HQ DEN); ZCE; VRD084; A320; SFOIND; Aircraft reported on collabitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on collabitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on collabitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on COLLABITUDE.		COD; ATSC (FAA HQ DEN); MSY; SWA2288; B737; MSYBHM New Destination: MSY; Reason not given, HQ DEN calling SWA Dispatch. 1744 oil quantity issue.
reporting for AOR until 2400 due to WX. 1800 1800 1800 1804 EMERGENCY,COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destin engine. Aircraft landed at 1817. 1816 COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Mei COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off cou altitude. Attempting contact on Guard. No satellite phone available. Communications re-e DEN asked ZSE to verify that PIC is in compliant with ATC instructions, affirmative. 1839 NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on condititude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. 1844 COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TPA; M COD; ATSC (FAA HQ DEN); ZMB; EJA711; GALX; DALCSV New Destination: TYS; W3 NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on condititude. Attempting contact on Guard and with Company. Communications re-established altitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CHS; Sick PAX. 1905 NORDO; ATSC (FAA HQ DEN); ZC; VRD084; A320; SFOIND; Aircraft reported on condititude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on condititude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN;	1746	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); MEM; FLG3528; CRJ9; PHLMEM; Sick PAX.
1800 1800 1800 1800 1800 1800 1804 EMERGENCY,COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destin engine. Aircraft landed at 1817. 1816 COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZHU; ASQ4149; E145; IAHSDV New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off cou altitude. Attempting contact on Guard. No satellite phone available. Communications re-e DEN asked ZSE to verify that PIC is in compliant with ATC instructions, affirmative. NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on coalititude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TPA; N COD; ATSC (FAA HQ DEN); ZMS; EJA711; GALX; DALCSV New Destination: TYS; W3 NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on altitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CEN; Sick PAX. 1903 EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. 1904 NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on coalitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on coalitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on coalitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN;		WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); A80; A80 authorized to suspend change of destination reporting for AOR until 2400 due to WX
1800 1804 1804 1806 1806 1806 1806 1806 1807 1807 1808 1809 1809 1809 1809 1809 1800 1800		
 1800 1804 EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destin engine. Aircraft landed at 1817. 1816 COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Me COD; ATSC (FAA HQ DEN); ZHU; ASQ4149; E145; IAHSDV New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off cou altitude. Attempting contact on Guard. No satellite phone available. Communications re-e DEN asked ZSE to verify that PIC is in compliant with ATC instructions, affirmative. NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on coalititude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TPA; N2 COD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; W2 NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on coalititude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; QEMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW COB; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on coalititude. Attempting contact on Guard and with Company. Communications re-established NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on coalititude. Attempting contact on Guard and with Company. Communications re-established NORDO; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN; 		- Na
 EMERGENCY, COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destin engine. Aircraft landed at 1817. COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Meta20 COD; ATSC (FAA HQ DEN); ZHU; ASQ4149; E145; IAHSDV New Destination: IAH; Meta23 COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off could altitude. Attempting contact on Guard. No satellite phone available. Communications repensed by ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on collistitude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TPA; May CoD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; Way Nordo; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on collistitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CEMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on collistitude. Attempting contact on Guard and with Company. Communications re-established NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on collistitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on collistitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN; 		
 LOD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Metalon COD; ATSC (FAA HQ DEN); ZHU; ASQ4149; E145; IAHSDV New Destination: IAH; Metalon COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: DAL; Comnormal NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off countered altitude. Attempting contact on Guard. No satellite phone available. Communications released Nordo; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on content altitude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TPA; Marcon Cod; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; Waster Cod; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; Waster Cod; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on content altitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CEMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on content and content and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on content and content and content and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN; 	1804	EMERGENCY,COD; ATSC (FAA HQ DEN); MEI; N3529A; PA31; JKAMQY New Destination: MEI; Lost right
COD; ATSC (FAA HQ DEN); ZHU; ASQ4149; E145; IAHSDV New Destination: IAH; Me COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off cou altitude. Attempting contact on Guard. No satellite phone available. Communications re-e DEN asked ZSE to verify that PIC is in compliant with ATC instructions, affirmative. NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on coaltitude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TPA; N COD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; W3 NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on coaltitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CEMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on coaltitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN;		engine. Aircraft landed at 1617. COD; ATSC (FAA HQ DEN); ZDC; SWA659; B737; BNALGA New Destination: BWI; Mechanical.
 COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICTSUN New Destination: DAL; Com NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off coul altitude. Attempting contact on Guard. No satellite phone available. Communications re-eden DEN asked ZSE to verify that PIC is in compliant with ATC instructions, affirmative. NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on condititude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TPA; N COD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; W3 NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on condititude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CEMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on condititude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN; 		COD; ATSC (FAA HQ DEN); ZHU; ASQ4149; E145; IAH. SDV New Destination: IAH; Mechanical.
 NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off coul altitude. Attempting contact on Guard. No satellite phone available. Communications re-eden DEN asked ZSE to verify that PIC is in compliant with ATC instructions, affirmative. NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on condititude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TPA; NORDO; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; W3 NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on condititude. Attempting contact on Guard and with Company. Communications re-established EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on condititude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN; 	1823	COD; ATSC (FAA HQ DEN); ZDV; EJA906; C750; ICT. SUN New Destination: DAL; Company request.
altitude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked NORDO. Communications re-established at 1855. 1844 COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TPA; M COD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; W NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on altitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CEMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. 1905 NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on collabilitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN;	1826	NORDO; ATSC (FAA HQ DEN); ZSE; N9120Y; PA46; BFIBTM; Aircraft reported off course, at assigned altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1828, HQ
 1849 COD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; WX NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on caltitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; CEMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. 1905 NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on coaltitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN; 		NORDO; ATSC (FAA HQ DEN); ZKC; N1068R; M20P; APALOU; Aircraft reported on course, at assigned altitude. Attempting contact on Guard. No satellite phone available. 1852 HQ DEN asked T75 for update, NORDO. Communications re-established at 1855.
NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on a altitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; GEMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on could altitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN;	1844	COD; ATSC (FAA HQ DEN); ZMA; DAL534; B752; MMUNATL New Destination: TPA; Mechanical.
altitude. Attempting contact on Guard and with Company. Communications re-established 1900 1900 1900 COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; GENERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. 1905 NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on countitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN;	1849	COD; ATSC (FAA HQ DEN); ZME; EJA711; GALX; DALCSV New Destination: TYS; WX.
 1900 1900 1900 1900 1901 1902 1903 1903 1904 1905 1905 1906 1906 1907 1908 1909 td><td>NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1856.</td>		NORDO; ATSC (FAA HQ DEN); ZBW; LOF3432; E145; BDLORD; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 1856.
 1900 COD; ATSC (FAA HQ DEN); CAE; DAL1478; DC95; GSOCAE New Destination: SAV; GEMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. 1905 NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on could altitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN; 		
 1903 EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEW CHS; Sick PAX. 1905 NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on coul altitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN; 		
1905 NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on could altitude. Attempting contact on Guard and with Company. Communications re-established COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DENASE New Destination: DEN;	1903	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZJX; UAL1587; B738; RSWEWR New Destination:
1909 COD; ATSC (FAA HQ DEN); ZDV; SKW576M; CRJ7; DEN. ASE New Destination: DEN;	1905	NORDO; ATSC (FAA HQ DEN); ZLC; VRD084; A320; SFOIND; Aircraft reported on course, at assigned
JIBIU NORDO; A ISO (FAA HQ DEN); ZAB; SWAT/ZI; B/35; ELPSAT; Aircraft reported on c		
	1910	
, -		altitude. Attempting contact on Guard and with Company. Communications re-established at 1917. NORDO; ATSC (FAA HQ DEN); ZTL; SWA3387; B737; JANBWI; Aircraft reported on course, at assigned
		altitude. Attempting contact on Guard and with Company. Communications re-established at 1915.
		NORDO; ATSC (FAA HQ DEN); ZAB; SWA2354; B737; ABQPHX; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. No satellite phone available. Communications reestablished at 1919.
1923 COD; ATSC (FAA HQ DEN); D01; FFT659; A319; DENSFO New Destination: DEN; Cal	1923	COD; ATSC (FAA HQ DEN); D01; FFT659; A319; DENSFO New Destination: DEN; Cargo door open.
1930	1930 I	72

Page 3

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/28/2013

Element: Created by: Created on: Checked by: CWomack, 04/29/2013 0405Z CW

Log:		
Time (UTC)	Remarks	
1937	COD; ATSC (FAA HQ DEN); ZDV; EJA384; C680; HPNASE New Destination: RIL; Crosswind component	
1950	exceeds aircraft limitations. NORDO; ATSC (FAA HQ DEN); N90; N854JA; C550; TEBMCO; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 1952.	
2000	7E- established at 1532.	
	WE	
2004	EMERGENCY- MEDICAL, PAGED; ATSC (FAA HQ DEN); ZDV; UAL1270; B738; SEADEN; Sick Crew Member. 2006 HQ DEN called D01, crew member is FA. Aircraft landed at 2013.	
2019	COD; ATSC (FAA HQ DEN); ZJX; OPT440; BE40; MSYPDK New Destination: MCN; WX.	
2019	MECHANICAL; ATSC (FAA HQ DEN); CHA; AWI3705; CRJ2; CLTCHA; Gear issue.	
2025	7F 7P	
2036	COD; ATSC (FAA HQ DEN); ZTL; VNR167; P180; CRG3J7 New Destination: HQU; WX.	
2047	EMERGENCY ; ATSC (FAA HQ DEN); C90; UAL743; B752; LASORD; Electrical smell in cockpit. Aircraft landed at 2053.	
2054	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZMA; NKS946; A319; SKCGFLL; Passenger medical emergency.	
2055	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZHU; UAL1017; B739; MMUNIAH; Sick PAX.	
2100		
2101	COD; ATSC (FAA HQ DEN); ZTL; CNS22; PC12; HPN3J7 New Destination: HQU; WX.	
2116	COD: ATSC (FAA HQ DEN); ZSE; TMC830; H25B; BVS.:STS New Destination; BFI; Mechanical issue.	
2120	OTHER; ATSC (FAA HQ DEN); ZKC; NW Fort Riley, KS (FRI) an ACFT at 1,500 feet squawking 4000, not talking to ATC, ZKC will tag the track with code 5200 and track. CLOSEOUT: Subject aircraft identified as military helicopter.	
2124	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZOB; ACA729; A319; LGACYYZ; Passenger medical emergency.	
2125	COD; ATSC (FAA HQ DEN); ZDC; RPA3419; E170; PHL. CHS New Destination: PHL; Mechanical.	
2127	EMERGENCY; ATSC (NCRCC); PCT; AAL76; B738; LAXIAD; Trim problem. Aircraft landed at 2139.	
2137	EMERGENCY- MEDICAL,COD; ATSC (FAA HQ DEN); ZSE; SWA1690; B737; SEAOAK New Destination: PDK; Passenger medical emergency.	
2143	COD; ATSC (FAA HQ DEN); ZTL; EGF4657; CRJ7; LGAATL New Destination: LGA; Mechanical.	
2144	EMERGENCY; ATSC (FAA HQ DEN); N90; XOJ722; C750; MBPVTEB; Hydraulic system failure. Aircraft landed at 2154.	
2146	COD; ATSC (FAA HQ DEN); ZDV; GLA296; E120; DEN. KRIW New Destination: KDEN; Mechanical.	
2200	2-2,2 (
2200		
2242	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZKC; SWA226; B738; PITLAS New Destination: STL;	
2245	Passenger medical emergency. COD; ATSC (FAA HQ DEN); PHL; PDT4154; DH8A; PHLERI New Destination: PHL; Anti-icing equipment failure.	
2253 2313	COD; ATSC (N/NC); ZDV; EJA718P; GALX; FRGASE New Destination: RIL; WX. EMERGENCY ; ATSC (FAA HQ DEN); MIA; AAL672; B752; TISTKMIA; Asymmetrical flap configuration.	


Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to he determined under 5 US C 552



Date: 04/28/2013

Element: Created by: Created on: Checked by: CWomack, 04/29/2013 0405Z CW



Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

	FAA NAS	
Flomont		

Date: 04/29/2013

Element:	Created by:	Created on:	Checked by:
ALL	CWomack,	04/30/2013 0506Z	CW

Security Event Statistics:				
EMERGENCY: 16	NORDO: 17	COD: 40		
EMERGENCY- MEDICAL:	TE.	LASER: 10		
6		MOR: 2		


Log:	
Time (UTC	Remarks
04/29/2013	3
0400	
0400	
0400	
0432	COD; ATSC (FAA HQ DEN); D21; PKW662; SW4; DRT. PTK New Destination: DTW; Weather.
0433	EQUIPMENT; ATSC (NCRCC); PCT; PCT SOC coordinated RACD restart. 0500: PCT RACD restart observed.
0446	
0447	COD; ATSC (FAA HQ DEN); ZME; JIA515; CRJ2; CLTJAN New Destination: BTR; Weather.
0452	LASER; ATSC (FAA HQ DEN); IWA; N29TE; C525; VFRVFR; At 0438 cockpit was illuminated from the right by a green laser while northbound at 3,800', 6S Mesa, AZ; no injuries reported;
0459	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); D21; Detroit TRACON (D21) authorized to suspend change of destination reporting for AOR until 1000 due to weather/T.
0525	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); P50; SWA630; B737; SAN. PHX; Infant with seizures.
0525	LASER; ATSC (FAA HQ DEN); SJC; SWA187; B737; PDXSJC; At 0454 aircraft was illuminated from the left by a green laser while northwest bound at 2,500', 7SE San Jose; no injuries reported;
	by a green laser while northwest bound at 2,000, 700 dail odde, no injuries reported,
0530	ATC FACILITY; ATSC (NCRCC); EADS; EADS resumes air sovereignty over NCR.
0536	LASER; ATSC (FAA HQ DEN); ZLA; SKW7397; CRJ2; SLCSJU; At 0502 cockpit was illuminated from the
	right by a green laser while southbound on final approach, 5N St George, UT (alt unkn); no injuries reported;
0542	LASER; ATSC (FAA HQ DEN); PBI; EAGLE1; S76; VFRVFR; At 0130 LE helo cockpit was illuminated from
0012	the southwest by a red laser while hovering, 1S PBI; no injuries reported
0545	
0622	SIF; ATSC (FAA HQ DEN); ZMP; CKK226; B744; ORDANC; Deviating around weather near the US/Canadian
	border.
0655	COD; ATSC (NCRCC); PCT; RCH495; C17; CHSNYG New Destination: DOV; COD: Came in after hours.
	FAA NCRCC and PCT unable to recall NYG ATC personnel to work aircraft into NYG. PCT states they are not
	authorized closed field operations into NYG. PIC elected to divert to DOV due to fuel limits.
0758	TO SEE ATOM SEA TO DEAL TO DESCRIPTION OF THE SEA AND
0823	LASER; ATSC (FAA HQ DEN); L30; AWE49; B752; LASDCA; At 0720 cockpit was illuminated from the right
	by a blue laser while ENE bound at 11,000, 10NE Las Vegas; no injuries reported;
0841	.7E
0041	
	78
1	

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security. Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

FAA Air Traffic Organization NAS Daily Events Log

Element:	Created by:	Created on:	Checked by:
ALL	CWomack,	04/30/2013 0506Z	cw



Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	CWomack,	04/30/2013 0506Z	CW

Log:	
Time (U	TC) Remarks
1440	EMERGENCY, COD; ATSC (FAA HQ DEN); ZBW; RCH321; C56X; LERTROC New Destination: CEF; Lost
	pressurization. 1446 emergency cancelled.
1443	COD; ATSC (FAA HQ DEN); ZMA; CWC405; MD11; MIASVVA New Destination: MIA; Company request.
1448	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAB; SWA251; B737; LAXABQ; Sick PAX.
1456	COD; ATSC (FAA HO DEN); N90; RPA4896; DH8D; EWRCYYZ New Destination: EWR; Pressurization issue.
1457 1459	COD; ATSC (FAA HQ DEN); ZAB; AWE254; A320; PHXPHL New Destination: PHX; Mechanical issue. COD: ATSC (FAA HQ DEN); LIT: PAT201; BE20; FSIPBF New Destination; LIT: WX.
1500	EMERGENCY; ATSC (FAA HQ DEN); D01; UAL812; A320; LASDEN; Nose wheel gear issue. Aircraft landed
	at 1500.
1502	NORDO; ATSC (FAA HQ DEN); ZFW; LXAWIN; LJ35; MMTO. RST; Aircraft reported on course, at assigned
4502	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1504.
1503 1532	COD; ATSC (FAA HQ DEN); ZJX; SWA489; B737; TPABHM New Destination: TPA; Avionics issue. NORDO; ATSC (FAA HQ DEN); ZAU; N200DA; BE20; OJCSFL; Aircraft reported on course, at assigned
1332	altitude. Attempting contact on Guard. No satellite phone available. 1534 ACFT cancelled IFR with Flight
	Service.
1545	OF The state of th
1548	EMERGENCY; ATSC (FAA HQ DEN); ZOB; EGF4477; E135; DTWLGA; Pitch trim malfunction. Aircraft
	landed at 1629.
1549	COD; ATSC (FAA HQ DEN); ZJX; ASQ4298; E145; EWRJAX New Destination: SAV; RY closure due to
1000	disabled ACFT.
1600	COD: ATSC (FAA HQ DEN); JAX; ASQ4298; E145; EWRJAX New Destination; SAV; RY closed due to oil spill
1604	from DAL1258 hydraulics failure.
1604	COD; ATSC (FAA HQ DEN); JAX; EGF4077; E145; ORDJAX New Destination; GNV; RY closed due to oil spill
1.004	from DAL1258 hydraulics failure.
1605	EMERGENCY, NOTIFICATION-NONE, AIRPORT; ATSC (FAA HQ DEN); JAX; DAL1258; B752; ATLJAX; HQ
	DEN called JAX to inquire about emergency, DAL1258 experienced a hydraulics failure. Aircraft landed at 1515.
	Emergency declared after landing and terminated at 1545. JAX closed due to oil spill on RY from DAL1258
	hydraulics issue. 1619 RY re-opened, normal operations resumed.
1616	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); D01; SKW5642; CRJ2; CPRDEN; Sick PAX.
1624	NORDO, MOR; ATSC (FAA HQ DEN); ZKC; N58BC; P46T; SLNCID; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1643; ZKC intends to file MOR.
1642	EMERGENCY, COD; ATSC (FAA HQ DEN); ZDV; RPA1557; E190; DENSAN New Destination: DEN;
1072	Pressurization issue. Aircraft landed at 1715.
1643	NORDO; ATSC (FAA HQ DEN); ZME; SWA1130; B737; ATLLAS; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and with Company. Communications re-established at 1644.
1645	COD; ATSC (FAA HQ DEN); ZMA; AWE9181; A319; MKJSCLT New Destination: PHL; Company request.
1656	NORDO; ATSC (FAA HQ DEN); ZFW; N997SS; C25A; HOUGLE; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1707.
1703	COD; ATSC (FAA HQ DEN); P50; AWE254; E190; DENPHL New Destination: DEN; Bleed air issue.
1718	NORDO, MOR; ATSC (FAA HQ DEN); ZLA; SKW5655; CRJ2; BURSFO; Aircraft reported on course, at
	assigned altitude. Attempting contact on Guard and with Company. 1730 ZLA listening to tapes; ZOA
	attempting contact on previous 2 frequencies and repeatedly through company. Communications re-established at 1734; ZOA intends to read crew Brasher warning; ZOA advised they have already filed MOR and will add
	at 1734; 20A intends to read crew Brasher warning, 20A advised they have already filed MOR and will add PIC's input when they call.
1723	PIC'S IIIput when they can.
1741	COD; ATSC (FAA HQ DEN); ZJX; VNR108; P180; BDLBCT New Destination: SAV; Fuel.
1	

Page 3


This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/29/2013

Element: ALL Created by: CWomack, Created on: 04/30/2013 0506Z

Checked by: CW




Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	CWomack,	04/30/2013 0506Z	CM



Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Element:	Created by:	Created on:	Checked by:
ALL	CWomack,	04/30/2013 0506Z	CW

Log:	og:		
Time (UTC)	Remarks		
0215	:		
0250 0300 0335	COD; ATSC (FAA HQ DEN); ZID; FDX980; MD11; MEM. IND New Destination: LCK; Company request. COD; ATSC (FAA HQ DEN); ZID; FDX2639; A306; RIC. LCK New Destination: MDT; Company request. LASER; ATSC (FAA HQ DEN); SRQ; N9NE; BL8; VFR VFR; At 0305 cockpitt was illuminated from the 11 o'clock position by a green laser while NNE bound at 500' on base leg SRQ, no injuries reported;		
0337	LASER; ATSC (FAA HQ DEN); SCT; SKW5358; E120; SBALAX; At 0308 aircraft was illuminated from the left by a green laser while eastbound at 4,000′, 5W El Monte, CA; no injuries reported;		
0341 0342	EMERGENCY ; ATSC (FAA HQ DEN); OKC; EGF3634; CRJ7; LAXOKC; Flap issue. Aircraft landed at 0353. LASER; ATSC (FAA HQ DEN); P50; AWE678; A319; PHXBOI; At 0324 cockpit was illuminated from directly below by a green laser while northbound at 7,000', 10WNW Phoenix; no injuries reported; 75		
0359			

Page 6

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director. System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

	FAA Air Traffic NAS Daily Eve	c Organization ents Log		Date 04/30/2013
Eleme ALL	ent:	Created by: RGotz,	Created on: 05/01/2013 0400Z	Checked by: RV
Securit	y Event Statistics:			
	GENCY: 9 GENCY- MEDICAL:		NORDO: 16	COD: 52 LASER: 9
Log:				
Time (U	TC) Remarks			
04/30/20)13			
0400 0400	2			
0400	2			
0409	LASER; ATSC (Fallaser while westbo	AA HQ DEN); LAS; WW ound at 5,000', 1W N ellis	W474; B736; TNXLAS; At 0330 c s AFB; no injuries reported;	cockpit was illuminated by a green
)414	COD: ATSC (FAA	HQ DEN); ZSE; SKW6	72X; CRJ7; SFOCYYC New Des	tination: GEG; Fuel.
0415	LASER; ATSC (Faright by a green la	AA HQ DÉN); NCT; SW. aser while southeast bou	A3225; B737; SJCLAX; At 0357 and at 16,000', 10SE San Jose; no 7; C750; EQYSMO New Destinat	cockpit was illuminated from the injuries reported;

EQUIPMENT; ATSC (NCRCC); PCT; PCT SOC coordinated RACD cold start at 0500. 0500: Cold start 0435 observed. 0550 EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZMA; AVA020; A332; SKBO..JFK New Destination: 0700 MIA; Non-specific PAX medical; physician attending. COD: ATSC (FAA HQ DEN); P50; UAL720; A319; PHX..EWR New Destination: PHX; Minor mechanical. 0701 NORDO, COD; ATSC (FAA HQ DEN); ZDC; PKW662; SW4; TOL...RWI New Destination: TDF; Aircraft reported 0809 on course, at assigned altitude. Attempting contact on Guard and with Company. 0640 Company Dispatch wants aircraft to change destination to TDF. Communications re-established at 0645. COD; ATSC (FAA HQ DEN); ZKC; LBQ651; E50P; IXD..LUK New Destination: CVG; Weather. 0911 COD; ATSC (FAA HQ DEN); ZTL; FDX1481; B752; MEM. MCO New Destination: TLH; Company request. 0919 COD; ATSC (FAA HQ DEN); ZID; USC140; LJ35; SUS..LCK New Destination: CMH; Runway lights OTS at 0920 LCK. WEATHER DIVERTS-MULT: ATSC (FAA HQ DEN); ZID: ZID authorized to suspend change of destination 0921 reporting for LCK until 1200 due to Runway Lights OTS. COD; ATSC (FAA HQ DEN); CAE; USC4401; BE58; ORL..CLT New Destination: RIC; Weather. 0921 COD: ATSC (FAA HQ DEN); ZID; FDX1746; B752; IND..TYS New Destination: BNA; Company request. 0926 1000 1000 1000 1000 1004

Page 1

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security. Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/30/2013

Element: Created by: Created on: Checked by: RGotz, 05/01/2013 0400Z RV

Log:		
Time (UTC)	Remarks	
1008	COD; ATSC (FAA HQ DEN); ZID; RPA3118; E170; INDCLT New Destination: IND; WX.	
1015		
1022	COD; ATSC (FAA HQ DEN); ZTL; FDX1558; B752; MEMCHS New Destination: GSP; WX.	
1047	COD: ATSC (FAA HQ DEN); ZJX; UPS1322; A306; SDFJAX New Destination: MCO; WX.	
1108	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZJX; ZJX/ZTL authorized to suspend change of	
	destination reporting for AOR until 1600 due to fog.	
1112		
–		
1113	COD; ATSC (FAA HQ DEN); LFT; UPS706; B752; SDFLFT New Destination: MSY; WX.	
1129		
1140		
1145		
1200		
1216	COD; ATSC (FAA HQ DEN); ZDC; EJA385; C680; HPNFMY New Destination: GSO; Mechanical.	
1218	COD: ATSC (FAA HQ DEN); CMH; MTN8345; C208; IND.,LCK New Destination; PKB; Weather, 1223 CMH	
	Approach reported aircraft will land LCK due to weather	
1239	COD: ATSC (FAA HQ DEN); ZNY; TMC495; BE40; TEB. OCF New Destination: ILG: Maintenance issue.	
1241	COD; ATSC (FAA HQ DEN); ZDV; LYM412; PA31; DEN. GLD New Destination; ITR; WX.	
1259	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZME; DAL303; B752; MCOSLC New Destination:	
1239	MEM: Sick PAX.	
1308		
	COD; ATSC (FAA HQ DEN); ZAB; FDX408; DC10; IAH. LAX New Destination: ABQ; Company request.	
1310	COD; ATSC (FAA HQ DEN); CHS; USC110; C208; CMHJZI New Destination: CHS; WX.	
1311	COD; ATSC (FAA HQ DEN); PDT9314; DH8C; SBYPHL New Destination: SBY; Maintenance issue. 1312	
4040	PXT advised ACFT continuing to PHL.	
1316		
1323	COD; ATSC (FAA HQ DEN); ZHU; UPS9515; B752; LRDGSO New Destination: SAT; Company request.	
1327	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); CHS; CHS/ZMA/MIA authorized to suspend change of	
	destination reporting for AOR until 1800 due to fog.	
1328	COD; ATSC (FAA HQ DEN); ZHU; ASQ4501; E135; IAHLFT New Destination: IAH; Weather.	
1344	COD; ATSC (FAA HQ DEN); ZMA; TRS44; B737; ATLMMUN New Destination: MCO; Maintenance issue.	
1400		
1402	NORDO; ATSC (FAA HQ DEN); ZKC; N303WS; CL30; LNKBWG; Aircraft reported on course, at assigned	
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1404.	
1439	COD; ATSC (FAA HQ DEN); ZAB; FDX423; A306; TUSMEM New Destination: LBB; Company request.	
1443	EMERGENCY- MEDICAL, COD; ATSC (FAA HQ DEN); ZID; SWA1903; B737; DTW. PHX New Destination:	
	STL; Sick PAX.	
1500		
1501		
1501		
1509	TE CONTRACTOR OF THE CONTRACTO	
. 500		
	76	
1518	COD; ATSC (FAA HQ DEN); S56; SKW4829; CRJ2; SLCSNA New Destination: SLC; Bird strike.	
	NORDO; ATSC (FAA HQ DEN); ZMP; N361JA; MU2; JKJYIP; Aircraft reported on course, at assigned	
1523		

Page 2

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/30/2013

Element:	Created by:	Created on:	Checked by:
ALL	RGotz,	05/01/2013 0400Z	RV

Log:	
Time (UT	Remarks
1527	EMERGENCY,COD; ATSC (FAA HQ DEN); HSV; AWI3582; CRJ2; HSVCLT New Destination: HSV; Landing
	gear issue. 1540 aircraft declared emergency. Aircraft landed 1552.
1530	NORDO; ATSC (FAA HQ DEN); ZFW; LN77HE; BE9L; HUTHOU; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1532.
1538	COD; ATSC (FAA HQ DEN); LFT; ASQ5597; CRJ2; ATLLFT New Destination: AEX; WX.
1547	NORDO; ATSC (FAA HQ DEN); ZFW; SBE607; LJ60; HOUPWA; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard and through Company. Communications re-established at 1554.
1554	EMERGENCY; ATSC (FAA HQ DEN); N90; LXJ617; LJ40; BOSTEB; Flap problem. Aircraft landed at 1600.
1556	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZDC; DAL39; B764; EGLLATL; Sick passenger.
1620	EMERGENCY, COD; ATSC (FAA HQ DEN); ZMA; NKS952; A319; MTPPRSW New Destination: MIA;
	Minimum fuel, possible fuel quantity indicator malfunction. Aircraft landed at 1633.
1623	EMERGENCY; ATSC (FAA HQ DEN); CRP; VV5G324; BE20; NGP, NGP; Unsafe gear indication. Aircraft
	landed at 1634.
1630	COD; ATSC (FAA HQ DEN); ZHU; XSR600; E50P; DZBHUM New Destination: HDC; Weather.
1648	NORDO; ATSC (FAA HQ DEN); HUF; N122SB; C310; 2A0ARR; Aircraft reported on course, at assigned
	altitude. Attempting contact on Guard. No satellite phone available. HUF advised ACFT NORDO 0+20 and
	NORDO from ZID; ZID investigating. 1654 FSOC attempting contact via DNV VOR voice; CMI attempting
	contact via previous known frequency. 1657 ZID advised ACFT switched to CMI with good read-back.
4050	Communications re-established at 1658.
1656	COD; ATSC (FAA HQ DEN); ZOB; EJA673; C56X; BDLMDW New Destination: CLE; Company request.
1656	COD; ATSC (FAA HQ DEN); ZID; FLG4193; CRJ2; LEXATL; Fuel issue.
1700	NORDO; ATSC (FAA HQ DEN); ZFW; N8421N; BE35; CXO7M3; Aircraft reported on course, at assigned
1701	altitude. Attempting contact on Guard. No satellite phone available. Communications re-established at 1702.
1701	EMERGENCY ; ATSC (FAA HQ DEN); ZHU; FIRE2; T38; RNDRND; Flight control problem. Aircraft landed at 1713.
1725	77 3.
1749	WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); ZMA; ZMA authorized to suspend change of destination
1743	reporting for AOR until 0359 due to weather.
1800	reporting to ACN until 0555 due to weather.
1800	
1800	
1800	
1813	NORDO; ATSC (FAA HQ DEN); ZKC; N645G; LJ35; LNKFTY; Aircraft reported on course, at assigned
1013	altitude. Attempting contact on Guard. No satellite phone available. 1834 HQ DEN requested update from ZME
	NORDO. 1837 HQ DEN as ZTL for frequency, 134.07 and asked FSOC to broadcast over GQO.
	Communications re-established at 1840.
1817	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZKC; SWA985; B737; LASMCI; PAX or Crew not known,
1017	ZKC checking, 1818 Sick PAX.
1823	NORDO; ATSC (FAA HQ DEN); ZJX; N197AS; BE20; LEEJQF; Aircraft reported on course, at assigned
1020	altitude. Attempting contact on Guard and FSS VOR broadcast. No satellite phone available. Communications
	re-established at 1833.
1828	COD; ATSC (FAA HQ DEN); CKB; RVJ41; BE40; CKBPIT New Destination: YNG; Company request.
1834	SIF; ATSC (FAA HQ DEN); ZMA; AFL110; A332; UUEEMIA; Routing west for WX, returning to approve
	routing afterwards.
1834	et all and wards.
	78
	T/E


Page 3

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552

Date: 04/30/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RGotz,
 05/01/2013 0400Z
 RV



Page 4

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm₂300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/30/2013

 Element:
 Created by:
 Created on:
 Checked by:

 ALL
 RGotz,
 05/01/2013 0400Z
 RV

Log:		
Time (UTC)	Remarks	
2247	NORDO; ATSC (FAA HQ DEN); ZAU; N444BG; C421; FWAIKV; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. At 2258 requested status, OMIC reported voice tape review indicates controller transferred communications to an incorrect frequency. Communications re-established at 2300.	
2306	EMERGÉNCY, COD; ATSC (FAA HQ DEN); ZNY; TCX149; A332; MMUNEGCC New Destination: BDA; Cabir fire. Aircraft landed at 2359.	
2310		
2315	COD; ATSC (FAA HQ DEN); ZFW; ASQ5391; CRJ2; SATMEM New Destination: SHV; Mechanical.	
2315	NORDO; ATSC (FAA HQ DEN); ZAU; DAL18; B763; LAXDTW; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. Communications re-established at 2315.	
2343		
2351		
05/01/2013 0004	EMERGENCY,COD; ATSC (FAA HQ DEN); A80; DAL1180; B752; ATL.:FAY New Destination: ATL; Landing	
0004	gear stuck in the down position. Aircraft landed at 2355. EMERGENCY- MEDICAL.COD; ATSC (FAA HQ DEN); ZOA; SWA358; B737; SFOLAX New Destination;	
0033	SJC; Passenger medical emergency. WEATHER DIVERTS-MULT; ATSC (FAA HQ DEN); 190; 190 authorized to suspend change of destination	
0000	reporting for AOR until 0230 due to WX.	
0038	2	
0044	NORDO; ATSC (FAA HQ DEN); ZBW; LMJ406; FA7X; ALBLFRK; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and with Company. At 0045 aircraft transitioned into Canadian airspace. Communications re-established at 0053.	
0053	NORDO; ATSC (FAA HQ DEN); ZJX; N411GG; MO20; FXEFTY; Aircraft reported on course, at assigned altitude. Attempting contact on Guard and previous frequencies. No satellite phone available. Communications re-established at 0105.	
0136	LASER; ATSC (FAA HQ DEN); ZOB; HAPPY63; K35R; Green laser illuminated Boom operator station between FL190B210, 15 miles E Briggs. ACFT W bound, no injuries reported.	
0142 0200 0200 0200	EMERGENCY- MEDICAL; ATSC (FAA HQ DEN); ZAB; DAL999; B752; MSP.,PHX; Sick PAX.	
0200 0206	LASER; ATSC (FAA HQ DEN); IAH; BVN7759; C208; 0151 ACFT reported a green LASER illuminated cockpit from right side while eastbound at 2,000 feet, 5 W of IAH. No injuries reported.	
0215 0215	LASER; ATSC (FAA HQ DEN); IAH; ASQ4450; E145; IAHGPT; 0149 ACFT reported a green LASER illuminated cockpit from right side of ACFT, while eastbound at 2,000 feet, 5 W of IAH. No injuries reported.	
0227	LASER; ATSC (FAA HQ DEN); PHL; RPA3437; E170; PHLCLE; 0155 ACFT reported a blue LASER illuminated the cockpit from right side at 10,000 feet while northwestbound 20 N of PHL. No injuries reported.	

Page 5

This document belongs to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552



Date: 04/30/2013

Element:	Created by:	Created on:	Checked by:
ALL	RGotz,	05/01/2013 0400Z	RV

_og:		
Time (UTC)	Remarks	
0236	LASER; ATSC (FAA HQ DEN); PCT; GTl2040; B744; DOVEDFH; 0150 ACFT reported a green LASER illuminated the cockpit from left side while eastbound at 11,000 feet, 7 NE of BWI. No injuries reported.	
0250	LASER; ATSC (FAA HQ DEN); PHL; NJT635; C680; 0155 ACFT reported cockpit was illuminated by a blue LASER from left side while northeast bound at 10,000 feet 20 NE of PHL. No injuries reported.	
0254	LASER; ATSC (FAA HQ DEN); ABQ; SWA502; B737; LASABQ; 0234 ACFT reported the cockpit illuminated by a green LASER from left side while southeastbound at the ABQ040015 at 8,500 feet. No injuries reported.	
0256 0330	7일 	
0333 0355	COD; ATSC (FAA HQ DEN); ZBW; UAL82; B772; EWRVIDP New Destination: EWR; Maintenance issue. COD; ATSC (FAA HQ DEN); ZFW; FDX1311; A306; DENMEM New Destination: MCI; Company request.	
0359		

Page 6

This document beloings to the Federal Aviation Administration and may be used for official Government purposes only. It may not be released without the expressed permission of the Federal Aviation Administration. Refer requests for this document to: Director, System Operations Security, Rm. 300 West, 800 Independence Ave., S.W., Washington, D.C. 20591. Public availability to be determined under 5 US C 552